TWR-17546-1



Flight Motor Set 360L007 (STS-33R) Final Report

June 1990

Prepared for

National Aeronautics and Space Administration George C. Marshall Space Flight Center Marshall Space Flight Center, Alabama 35812

 Contract No.
 NAS8-30490

 DR No.
 3-5

 WBS No.
 4B601-03-08

 ECS No.
 1015

Thickol CORPORATION SPACE OPERATIONS

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

Publications No. 90407

(NASA-CE-103272) ELICAT MUTCH SET BUDLOU7 89 (STS-259) Finel Report (Thiskol Corp.) (SCL 21H


x?0-25051

Unclus 63/20 0294710

CR-183977

Thickol CORPORATION SPACE OPERATIONS

ORIGINAL PAGE BLACK AND WHITE PHOTOGRAPH



STS-33R (Discovery), carrying a DoD payload, was successfully launched at 6:23 p.m. CST, 22 Nov 1989

Thickol CORPORATION SPACE OPERATIONS

TWR-17546-1

Flight Motor Set 360L007 (STS-33R) **Final Report**

Prepared by:

Jarecht Test Planning and Reporting

Space Engineering Deputy Director

Requirements Manager

Approved by: Program Manager

Thuc System Safety

<u>Project Engineer</u>

PC 1 k 10-4-90 Data Management

Frid Duirsch p. 26 Fib 90 Reliability

Thickol CORPORATION SPACE OPERATIONS

Listed below are the contributors to the major sections of this report, along with an acceptance signature from a section representative.

Mass Properties C. Richards

Aero/Thermal

R. Buttars H. Huppi J. Maw D. Ruddell

Julacher Brian Ballistics

A. Drendel K. Speas

For owe Seals

D. Rowsell K. Baker

L.E. Wil

Nozzles R. George L. Wilkes

tes

Insulation Design J. Passman S. Hicken

Fowell For · · / Case Component

ase Compone R. Mackley

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | ii |

ABSTRACT

Flight motor set 360L007 was launched at approximately 6:23 p.m. central standard time (89:327:00:23:30.000 Greenwich mean time) on 22 Nov 1989 as part of NASA space shuttle mission STS-33R. As with all previous redesigned solid rocket motor launches, overall motor performance was excellent. There were no debris concerns for either motor. Both motors exhibited unbonds on one factory joint weatherseal.

All ballistics contract end item specification parameters were verified, with the exception of ignition interval and rise rates. Ignition interval and rise rates could not be verified due to the elimination of developmental flight instrumentation from fourth flight and subsequent, but the low sample rate data that were available showed nominal propulsion performance. All ballistic and mass property parameters closely matched the predicted values and were well within the required contract end item specification levels that could be assessed.

All 108 GEI measurements performed properly throughout the prelaunch phase. Evaluation of the ground environment instrumentation measurements again verified thermal model analysis data and showed agreement with predicted environmental effects. No launch commit criteria thermal violations occurred. All joint heaters operated normally, but a high voltage reading was noted on the left hand aft heater, which was immediately determined to be a voltage sensor error and not a heater anomaly due to no current increase. See Section 4.10.2 for details.

Postflight inspection again verified superior performance of the insulation, phenolics, metal parts, and seals. The igniter seals, which were replaced preflight due to subsurface seal void concerns, showed no anomalous conditions. Postflight evaluation indicated both nozzles performed as expected during flight. All combustion gas was contained by insulation in the field and case-to-nozzle joints.

Recommendations were made concerning improved thermal modeling and measurements. The rationale for these recommendations and detailed results are contained in this report.

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | iii |

Thickol CORPORATION SPACE OPERATIONS

CONTENTS

| <u>Section</u> | | | <u>Page</u> |
|----------------|--|--|--------------------------------------|
| 1 | INTRODUC | CTION | 1 |
| 2 | OBJECTIV | ES | 3 |
| 3 | RESULTS : RECOMME | SUMMARY, CONCLUSIONS, AND | 7 |
| | 3.1.1 In-Fl: 3.1.2 Mass 3.1.3 Prop 3.1.4 S&A 3.1.5 Ascen 3.1.6 Exten 3.1.6 Exten 3.1.7 Aero 3.1.8 Instr 3.1.9 Postf | JLTS SUMMARY ight Anomalies Properties ulsion Performance (ballistics) Device nt Loads and Structural Dynamics rnal TPS Joint Heater Evaluation /Thermal Evaluation umentation light Hardware Assessment | 7 7 8 8 8 8 9 9 |
| | 3.2 CON | CLUSIONS | 10 |
| | 3.3 REC 3.3.1 Aero | OMMENDATIONS | 25 25 |
| 4 | FLIGHT E | VALUATION RESULTS AND DISCUSSION | 27 |
| | 4.1 RSR | M IN-FLIGHT ANOMALIES | 27 |
| | 4.2.1 SRM | M CONFIGURATION SUMMARY | |
| | Char | and OMRSD Changes | 27 27 |
| | 4.3.1 Segu | MASS PROPERTIES | |
| | Data | | 38 43 |
| | 4.4.1 High | M PROPULSION PERFORMANCE | |
| | 4.4.2 SRM 4.4.3 Mate 4.4.4 Perfe 4.4.5 Ignit | parisons | 43 43 48 48 |
| | 4.5 RSR | M NOZZLE TVC PERFORMANCE | 48 |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | |
| | | iV |

Thiokol corporation space operations

CONTENTS (Cont)

Section

Page

| 4.6 | RSRM ASCENT LOADSSTRUCTURAL ASSESSMENT | 49 |
|--|---|---------------------------------|
| 4.7 | RSRM STRUCTURAL DYNAMICS | 50 |
| 4.8 4.8.1 4.8.2 4.8.3 4.8.4 | RSRM TEMPERATURE AND TPS PERFORMANCE Introduction | 50 50 50 54 124 |
| 4.9 | MEASUREMENT SYSTEM PERFORMANCE DEVELOPMENT FLIGHT INSTRUMENTATION | 126 |
| 4.10 4.10.1 4.10.2 4.10.3 4.10.4 | MEASUREMENT SYSTEM PERFORMANCEInstrumentation SummaryGEI/OFI PerformanceHeater Sensor PerformanceS&A Rotation Times | 127 127 127 129 129 |
| 4.11 4.11.1 4.11.2 4.11.3 4.11.4 | RSRM HARDWARE ASSESSMENT | 129 129 141 143 147 |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAG | E |
| | | v |

Thickol CORPORATION SPACE OPERATIONS

FIGURES

<u>Figure</u>

| | | 00 |
|--------|--|----|
| 4.2-1 | Hardware Reuse Summary360L007A (LH) Case | 28 |
| 4.2-2 | Hardware Reuse Summary360L007B (RH) Case | 29 |
| 4.2-3 | Hardware Reuse Summary360L007A (LH) Igniter | 30 |
| 4.2-4 | Hardware Reuse Summary360L007B (RH) Igniter | 31 |
| 4.2-5 | Hardware Reuse Summary360L007A (LH) Nozzle | 32 |
| 4.2-6 | Hardware Reuse Summary360L007B (RH) Nozzle | 33 |
| 4.2-7 | Hardware Reuse Summary360L007A (LH) Stiffener | |
| | Rings at Normal Joints | 34 |
| 4.2-8 | Hardware Reuse Summary360L007A (LH) Stiffener | |
| | Rings at Systems Tunnel Joint | 35 |
| 4.2-9 | Rings at Systems Tunnel Joint | |
| | Rings at Normal Joints | 36 |
| 4.2-10 | Rings at Normal Joints | |
| | Rings at Systems Tunnel Joint | 37 |
| 4.4-1 | HPM/RSRM Nominal Thrust Versus CEI Specification | 46 |
| 4.8-1 | Ambient Temperatures at Camera Site No. 3 | 60 |
| 4.8-2 | Windspeed at Camera Site No. 3 (overlaid with ambient) | 60 |
| 4.8-3 | Wind Direction at Camera Site No. 3 (overlaid with | |
| 1.0 0 | ambient) | 61 |
| 4.8-4 | Humidity at Camera Site No. 3 (overlaid with ambient) | 61 |
| 4.8-5 | Barometric Pressure at Camera Site No. 3 (overlaid | |
| 4.0-0 | with ambient) | 62 |
| 4.8-6 | Forward Dome GEI | 66 |
| 4.8-7 | Case GEI | 67 |
| 4.8-8 | Case GEI Reference Angles | 68 |
| 4.8-9 | Nozzle/Exit Cone GEI | 69 |
| 4.8-10 | Aft Exit Cone GEI | 70 |
| 4.8-11 | RH SRM Ignition System RegionHeater and GEI Sensor | |
| 4.0-11 | Temperature Prediction | 71 |
| 4.8-12 | RH SRM Forward Field JointHeater Sensor | |
| 4.0-12 | Temperature Prediction | 71 |
| 4.8-13 | RH SRM Center Field JointHeater Sensor | |
| 4.0-10 | Temperature Prediction | 72 |
| 4.8-14 | RH SRM Aft Field JointHeater Sensor Temperature | |
| 4.0-14 | Prediction | 72 |
| 4.8-15 | RH SRM Nozzle RegionGEI Sensor Temperature | |
| 4.0-15 | Prediction | 73 |
| 4 9 16 | RH SRM Forward Case AcreageGEI Sensor | |
| 4.8-16 | Temperature Prediction | 73 |
| 4 0 17 | RH SRM Forward Center Case AcreageGEI Sensor | |
| 4.8-17 | Temperature Prediction | 74 |
| 4.8-18 | RH SRM Aft Center Case AcreageGEI Sensor | _ |
| 4.0-10 | Temperature Prediction | 74 |
| 4.8-19 | RH SRM Aft Case AcreageGEI Sensor Temperature | |
| 4.0-13 | Prediction | 75 |
| | | |
| | | |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | vi |

REVISION

90407-10.3

Thickol corporation space operations

<u>Figure</u>

| 4.8-20 | RH SRM Forward Dome Factory JointGEI Sensor | 75 |
|--------|--|-----|
| | Temperature Prediction | 70 |
| 4.8-21 | RH SRM Forward Factory JointGEI Sensor | 76 |
| | Temperature Prediction | 10 |
| 4.8-22 | RH SRM Aft Factory JointGEI Sensor Temperature | 80 |
| | Prediction | 76 |
| 4.8-23 | RH SRM Aft Dome Factory JointGEI Sensor | |
| | Temperature Prediction | 77 |
| 4.8-24 | RH SRM Tunnel BondlineGEI Sensor Temperature | |
| 1.01 | Prediction | 77 |
| 4.8-25 | RH SRM ET Attach RegionGEI Sensor Temperature | |
| 4.0-20 | Prediction | 78 |
| 4.8-26 | LH SRM Ignition System RegionHeater and GEI Sensor | |
| 4.0-20 | Temperature Prediction | 78 |
| 4.0.07 | LH SRM Forward Field JointHeater Sensor | |
| 4.8-27 | Temperature Prediction | 79 |
| | LH SRM Center Field JointHeater Sensor | |
| 4.8-28 | LH SKM Center Fleid Johnfleater Sensor | 79 |
| | Temperature Prediction | 15 |
| 4.8-29 | LH SRM Aft Field JointHeater Sensor Temperature | 80 |
| | Prediction | 00 |
| 4.8-30 | LH SRM Nozzle RegionGEI Sensor Temperature | 00 |
| | Prediction | 80 |
| 4.8-31 | LH SRM Forward Case AcreageGEI Sensor | ~ 1 |
| | Temperature Prediction | 81 |
| 4.8-32 | LH SRM Forward Center Case AcreageGEI Sensor | |
| 1.0 02 | Temperature Prediction | 81 |
| 4.8-33 | LH SRM Aft Center Case AcreageGEI Sensor | |
| 1.0 00 | Temperature Prediction | 82 |
| 4.8-34 | LH SRM Aft Case AcreageGEI Sensor Temperature | |
| 4.0-04 | Prediction | 82 |
| 4.8-35 | LH SRM Forward Dome Factory JointGEI Sensor | |
| 4.0-00 | Temperature Prediction | 83 |
| 4.0.00 | LH SRM Forward Factory JointGEI Sensor | |
| 4.8-36 | Temperature Prediction | 83 |
| 4.0.07 | LH SRM Aft Factory JointGEI Sensor Temperature | 00 |
| 4.8-37 | D 1' the | 84 |
| | Prediction | 01 |
| 4.8-38 | LH SRM Aft Dome Factory JointGEI Sensor | 84 |
| | Temperature Prediction | 04 |
| 4.8-39 | LH SRM Systems Tunnel BondlineGEI Sensor | 85 |
| | Temperature Prediction | 00 |
| 4.8-40 | LH SRM ET Attach RegionGEI Sensor Temperature | 05 |
| | Prediction | 85 |
| 4.8-41 | LH SRM Igniter Joint Temperatures (overlaid with | 07 |
| | ambient) | 87 |
| 4.8-42 | RH SRM Igniter Joint Temperature (overlaid with | 07 |
| | ambient) | 87 |
| | | |

| REVISION | DOC NO. | TWR-1754 | 6-1 | VOL |
|----------|---------|----------|--------|-----|
| | SEC | | PAGE V | ii |

Thickol CORPORATION SPACE OPERATIONS

| Figur | ro |
|-------|-----|
| rigu | L C |

| 4.8-43 | | 88 |
|---------|--|----|
| 40.44 | with ambient) | 00 |
| 4.8-44 | with ambient) | 88 |
| 4.8-45 | | 00 |
| 4.0-40 | with ambient) | 89 |
| 4.8-46 | | |
| 4.0-40 | with ambient) | 89 |
| 4.8-47 | | |
| 4.0-47 | ambient) | 90 |
| 4.8-48 | | |
| 1.0 10 | ambient) | 90 |
| 4.8-49 | | |
| 110 10 | with ambient) | 91 |
| 4.8-50 | | |
| | with ambient) | 91 |
| 4.8-51 | | |
| | (overlaid with ambient) | 92 |
| 4.8-52 | | |
| | (overlaid with ambient) | 92 |
| 4.8-53 | | |
| | (overlaid with ambient) | 93 |
| 4.8-54 | RH SRM Systems Tunnel Bondline Temperature (overlaid | |
| | with ambient) | 93 |
| 4.8-55 | | |
| | with ambient) | 94 |
| 4.8-56 | | |
| | with ambient) | 94 |
| 4.8-57 | | |
| | (overlaid with ambient) | 95 |
| 4.8-58 | | 05 |
| | (overlaid with ambient) | 95 |
| 4.8-59 | | 96 |
| | (overlaid with ambient) | 90 |
| 4.8-60 | | 96 |
| 4 0 01 | (overlaid with ambient) | 90 |
| 4.8-61 | RH SRM Case Acreage Temperature at Station 931.5 | 97 |
| 4.0.00 | (overlaid with ambient) | 91 |
| 4.8-62 | RH SRM Case Acreage Temperature at Station 1091.5 (overlaid with ambient) | 97 |
| 10.00 | | 51 |
| 4.8-63 | (overlaid with ambient) | 98 |
| 4.8-64 | | |
| -1.0-04 | (overlaid with ambient) | 98 |
| 4.8-65 | | |
| 4.0-00 | with ambient) | 99 |
| | | |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|------|
| SEC | PAGE | viii |

Thickol CORPORATION SPACE OPERATIONS

| <u>Figure</u> | | |
|---------------|---|-------------|
| 4.8-66 | LH SRM Case Across T | <u>Page</u> |
| 4.8-67 | LH SRM Case Acreage Temperature at 135 Deg (overlaid with ambient) LH SRM Case Acreage Temperature at 215 Deg (overlaid | 00 |
| 4.8-68 | LH SRM Case Arm | 99 |
| 4.8-69 | with ambient) of the period at 270 Deg (overlaid | 100 |
| 4.8-70 | | 100 |
| 4.8-71 | | 101 |
| 4.8-72 | with ambient) I when at 155 Deg (overlaid | 101 |
| 4.8-73 | with ambient) | 102 |
| 4.8-74 | will amplent) | 102 |
| 4.8-75 | with ambient) competitute at 525 Deg (overlaid | .03 |
| 4.8-76 | (overlaid with ambient) | 03 |
| 4.8-77 | (overlaid with ambient) and Temperature at Station 1535.0 | 04 |
| 4.8-78 | (overlaid with ambient) (overlaid with ambient) | 04 |
| 4.8-79 | (overlaid with ambient) (overlaid with ambient) |)5 |
| 4.8-80 | with ambient) | 5 |
| 4.8-81 | LH SRM Aft Factory Joint Temperature at Station 1701.0 | 6 |
| 4.8-82 | (overlaid with ambient) | 3 |
| | with ambient) 107 | 7 |
| 4.8-83 | (overlaid with ambiant) Joint Temperature at Station 1701 o | , |
| 4.8-84 | (overlaid with ambient) Joint Temperature at Station 1821.0 | |
| 4.8-85 | (overlaid with ambient) 108 | |
| 4.8-86 | (overlaid with ambient) Temperature at Station 1950 0 | |
| 4.8-87 | (overlaid with ambient) 109 | |
| 4.8-88 | RH SRM Norgio D | |
| | (overlaid with ambient) | |

DOC NO. TWR-17546-1 VOL SEC PAGE IX

REVISION _

-

.

Thickol CORPORATION SPACE OPERATIONS

| Figure | | Page |
|---------|---|-------|
| 4.8-89 | LH SRM Forward Field Joint Temperature (overlaid with | 111 |
| 4.8-90 | heater voltage) | |
| 4.8-91 | heater voltage) | |
| 4.8-92 | heater voltage) | |
| 4.8-93 | heater voltage) | |
| 4.8-94 | heater voltage) | |
| 4.8-95 | heater voltage) | |
| 4.8-96 | with heater voltage) | |
| 4.8-97 | heater voltage) | |
| 4.8-98 | with ambient) | |
| 4.8-99 | Postflight Prediction (B06T7085A, 1gn1ter) | |
| 4.8-100 | Versus Postflight Prediction (B0617060A, 15 deg) | |
| 4.8-101 | Versus Postflight Prediction (B0617061A, 135 deg) | |
| 4.8-102 | RH SRM Forward Field Joint TemperatureMeasured | |
| 4.8-103 | RH SRM Case-to-Nozzle Joint TemperatureMeasured | |
| 4.8-104 | LH SRM Systems Tunnel Bondline TemperatureMeasured | |
| 4.8-105 | Versus Postflight Prediction (B06T7031A, aft) RH SRM Case Acreage Temperature at Station 931.5 | . 119 |
| 4.0-105 | Measured Versus Postflight Prediction (B06T8010A, 135 deg) | . 119 |
| 4.8-106 | RH SRM Case Acreage Temperature at Station 931.5 Measured Versus Postflight Prediction (B06T8011A, | |
| 4.8-107 | 45 deg) | . 120 |
| 7,0-101 | Measured Versus Postflight Prediction (B0618012A, | . 120 |
| 4.8-108 | RH SRM Case Acreage Temperature at Station 931.5 Measured Versus Postflight Prediction (B06T8013A, | |
| | 270 deg) | . 121 |

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | x |

REVISION

90407-10.7

Thiokol Corporation

<u>Figure</u>

| \mathbf{P} | a | g | e | |
|--------------|---|---|---|--|
| | | | | |

| 4.8-109 | RH SRM Case Acreage Temperature at Station 931.5 Measured Versus Postflight Prediction (B06T8014A, | |
|---------|--|-----|
| | 325 deg) | 121 |
| 4.8-110 | LH SRM ET Attach Region Temperature at Station 1511.0 Measured Versus Postflight Prediction (B06T7027A, | |
| | 274 deg) | 122 |
| 4.8-111 | RH SRM Aft Factory Joint Temperature at Station | |
| 4.0-111 | 1701 9Measured Versus Postflight Prediction | |
| | (B06T8032A, 150 deg) | 122 |
| 4.8-112 | RH SRM Aft Factory Joint Temperature at Station | |
| | 1701.9Measured Versus Postflight Prediction | 123 |
| 4 0 110 | (B06T8033A, 30 deg) RH SRM Aft Factory Joint Temperature at Station | 120 |
| 4.8-113 | 1701.9Measured Versus Postflight Prediction | |
| | (B06T8034A 270 deg) | 123 |
| 4.8-114 | Aft End Temperature Prediction | 125 |
| 4.10-1 | LH SRM Aft Field Joint Temperature (overlaid with | |
| | heater voltage) | 128 |
| 4.11-1 | Sketch of Overall Field Joint Fretting Observations | 142 |

| DOC NO | TWR-17546-1 | VOL |
|--------|-------------|-----|
| SEC | PAGE | xi |

Thickol CORPORATION SPACE OPERATIONS

TABLES

<u>Table</u>

| | | 2 |
|--------|--|-----|
| 1-1 | Component Volume Release Schedule | 39 |
| 4.3-1 | 360L007A (LH) Sequential Mass Properties | 40 |
| 4.3-2 | 360L007B (RH) Sequential Mass Properties | 40 |
| 4.3-3 | 360L007A (LH) Sequential Mass PropertiesPredicted | 41 |
| | Versus Actual Comparisons | 41 |
| 4.3-4 | 360L007B (RH) Sequential Mass PropertiesPredicted | 10 |
| | Versus Actual Comparisons | 42 |
| 4.3-5 | 360L007A (LH) Predicted Versus Actual Weight | |
| 110 0 | Comparisons | 44 |
| 4.3-6 | 360L007B (RH) Predicted Versus Actual Weight | |
| 4.0-0 | Comparisons | 45 |
| 4.4-1 | RSRM Propulsion Performance Assessment | 47 |
| 4.4-2 | SRM Thrust Imbalance Assessment | 48 |
| 4.4-2 | SRM Performance Comparisons | 49 |
| 4.4-5 | STS-33R RSRM External Performance Summary (TPS | |
| 4.0-1 | erosion)Both Motors | 51 |
| 4.8-2 | STS-33R Actual GEI Countdown and Historically | |
| 4.0-2 | Predicted On-Pad November Temperatures (LCC | |
| | timeframe temperatures also included) | 53 |
| 4.8-3 | SRB Flight-Induced Design Thermal Environments | 55 |
| | STS-33R SRM External Performance Summary (both | |
| 4.8-4 | motors) | 56 |
| | STS-33R T-5 Min On-Pad Temperatures (represents | |
| 4.8-5 | end of LCC timeframe) | 64 |
| | STS-33R Analytical Timeframes for Estimating Event | • - |
| 4.8-6 | STS-33R Analytical Timetranes for Estimating Event Sequencing of November Historical Joint Heater and | |
| | GEI Sensor Predictions | 86 |
| | GEI Sensor Predictions | 127 |
| 4.10-1 | 360L007 (STS-33R) Instrumentation | 130 |
| 4.10-2 | GEI List360L007A (LH) | 132 |
| 4.10-3 | GEI List360L007B (RH) | 134 |
| 4.10-4 | 75 Percent Calibration Results | 135 |
| 4.10-5 | Field Joint Heater Temperature Sensors | 136 |
| 4.10-6 | S&A Arm and Safe Delta Times | 100 |
| 4.10-7 | S&A Activity Times for 360L007 (STS-33R) at | 137 |
| | T-5 Minutes | 191 |

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | xii |

Thiokol corporation space operations

ACRONYMS AND ABBREVIATIONS

| CCP | carbon-cloth phenolic |
|---|---|
| CDS | Central Databasing Service |
| CDS | contract end item |
| | center of gravity |
| cg | ethylene-propylene-diene monomer |
| EPDM | external tank |
| FBMBT | flex bearing mean bulk temperature |
| FEWG | Flight Evaluation Working Group |
| FMEA | failure modes and effects analysis |
| FSEC | Florida Solar Energy Center |
| GCP | glass-cloth phenolic |
| GEI | ground environment instrumentation |
| HOSC | Huntsville Operations Support Center |
| HPM | high-performance motor |
| IFA | in-flight anomaly |
| IPR | interim problem report |
| IR | infrared |
| IVBC | integrated vehicle baseline configuration |
| JPS | joint protection system |
| KSC | Kennedy Space Center |
| LCC | launch commit criteria |
| LRU | line replaceable unit |
| LSC | linear shaped charge |
| MSFC | Marshall Space Flight Center |
| MSID | measurement stimulation identification number |
| NSI | NASA standard initiator |
| NSTS | National Space and Transportation System |
| OBR | outer boot ring |
| OD | outside diameter |
| OFI | operational flight instrumentation |
| OPT | operational pressure transducer |
| $\mathbf{PMBT} \ldots \ldots \ldots \ldots \ldots \ldots \ldots \ldots \ldots $ | propellant mean bulk temperature |
| RSRM | redesigned solid rocket motor |
| RSRML | lightweight redesigned shuttle solid rocket motor |
| $\mathbf{RTD} \ldots \ldots \ldots \ldots \ldots \ldots \ldots \ldots \ldots $ | resistance temperature detector |
| \mathbf{RTV} | room temperature vulcanizing (rubber) |
| S&A | safety and arming device |
| sec | second |
| SF | safety factor shuttle standard initiator |
| $SSI \ldots \ldots \ldots \ldots \ldots$ | |
| sps | samples per second solid rocket booster |
| SRB | solid rocket motor |
| SRM | space shuttle main engine |
| SSME | shuttle thermal imager |
| STI | three dimensional |
| 3-D | thermal protection system |
| TPS | thrust vector control |
| | United Space Boosters, Inc. |
| USBI | vehicle assembly building |
| VAB | venicie abbenibily bundling |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|------|
| SEC | PAGE | xiii |

Thickol CORPORATION SPACE OPERATIONS

1

INTRODUCTION

Solid rocket booster (SRB) ignition command for flight motor set 360L007 was given at 89:327:00:23:30.000 GMT (approximately 6:23 p.m. CST) on 22 Nov 1989 at Kennedy Space Center (KSC), Florida. This flight was the 32nd space shuttle mission (mission designation STS-33R) and the seventh redesigned solid rocket motor (RSRM) flight. The individual motor identification numbers were 360L007A (left-hand (LH)) and 360L007B (right-hand (RH)), indicating that both cases were lightweight. Additional case configuration details are addressed in Section 4.2.

This volume (Volume I) of this report contains the Thiokol Flight Evaluation Working Group (FEWG) inputs submitted to United Space Boosters, Inc. (USBI) for incorporation into the shuttle prime contractors' FEWG report (Document MSFC-RPT-1579). An executive summary of the entire RSRM flight set performance and a oneto-one correlation of conclusions by objectives (and contract end item (CEI) paragraphs) are also included in this report. The detailed component volumes of this report (and the approximate timeline for volume release from the launch date) are listed in Table 1-1. TWR-60063 is a flow report that starts with receipt of hardware at KSC. It documents aft booster buildup and RSRM stacking, including processing milestones and highlights, stacking configuration, and significant discrepancy reports, problem reports, etc.

The subsections of this report volume that were submitted to USBI as part of the FEWG report are so designated with the FEWG report paragraph number.

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAG | 1 |

Thickol corporation space operations

Table 1-1. Component Volume Release Schedule

| Volume | Description/ <u>Component</u> | Interim <u>Release</u> | Final <u>Release</u> |
|--------|--|--|---|
| I | Systems overview | NA | Approximately 60 days after launch |
| II | Case/seals | NA | 60 days after washout of last segment at H-7 (Clearfield, Utah) |
| III | Internal insula- tion | 60 days after last joint de- mate at KSC | 60 days after washout of last segment at H-7 |
| IV | TPS/JPS/heat- ers/systems tun- nel | NA | 60 days after hydrolase is complete at KSC |
| V | Nozzle | NA | 60 days after nozzle phenolic sectioning is complete |
| VI | Igniter | NA | 60 days after washout of last igniter chamber at H-7 |
| VII | Performance/ mass properties | NA | 60 days after launch |

DOC NO TWR-17546-1 VOL SEC PAGE 2

Thickol CORPORATION SPACE OPERATIONS

2

OBJECTIVES

Flight objectives for the seventh Thiokol RSRM flight set were intended to satisfy the requirements of CPW1-3600A as listed in parenthesis below. A one-to-one correlation of conclusions by objectives (and CEI paragraphs) is included in Section 3.2 of this report.

Qualification Objectives

- A. The ignition interval shall be between 202 and 262 ms with a 40 ms environmental delay after ignition command to the solid rocket motor (SRM) shuttle standard initiators (SSI) in the safe and arm device (S&A) up to a point at which the headend chamber pressure has built up to 563.5 psia (3.2.1.1.1.1).
- B. The maximum rate of pressure buildup shall be 115.9 psi for any 10-ms interval (3.2, 1.1, 1.2).
- C. Verify that the thrust-time performance falls within the requirements of the nominal thrust-time curve (3.2.1.1.2.1, Table I).
- D. Certify that the measured motor performance parameters, when corrected to a 60°F propellant mean bulk temperature (PMBT), fall within the nominal value, tolerance, and limits for individual flight motors (3.2.1.1.2.2, Table II).
- E. With a maximum PMBT difference of 1.4°F between the two RSRMs on a shuttle vehicle, the differential thrust between the two RSRMs shall not be greater than the values given in Table III at any time during the periods shown. These differentials are applicable over the PMBT range of +40° to +90°F (3.2.1.1.2.3).
- F. Certify that the thrust-time curve complies with impulse requirements (3.2.1.1.2.4).
- G. Certify that specified temperatures are maintained in the case-to-nozzle joint region during the countdown launch commit criteria (LCC) time period (3.2.1.2.1.f).
- H. The case segment mating joints shall contain a pin retention device (3.2.1.3.g).
- I. Certify the performance of the igniter heater so it maintains the igniter gasket rubber seals between 64° and 130°F (3.2.1.5.3).
- J. Verify that the S&As perform as required, using the specified power supply (3.2.1.6.1.2).
- K. Verify that the operational flight instrumentation (OFI) is capable of launch readiness checkout after the ground system has been connected on the launch pad (3.2.1.6.2).
- L. Certify the proper operation of the operational pressure transducer (OPT) during flight (3.2.1.6.2.1).

DOC NO TWR-17546-1 VOL SEC PAGE 3

Thickol corporation

- M. The ground environment instrumentation (GEI) shall monitor the temperature of the SRBs while on the ground at the pad. It is not required to function during flight. These instruments will be monitored on the ground through cables with lift-off breakaway connectors (3.2.1.6.2.3).
- N. When exposed to the thermal environments of 3.2.7.2, the systems tunnel floorplates and cables will be maintained at a temperature at or below that specified in ICD 3-44002 (3.2.1.10.1).
- O. Certify the performance of the field joint heater and sensor assembly so that it maintains the case field joint at 75°F minimum. Field joints shall not exceed 130°F (3.2.1.11.a).
- P. Certify that each field joint heater assembly meets all performance requirements (3.2.1.11.1.2).
- Q. Demonstrate isolation of subsystem anomalies if required on seventh flight (360L007) hardware (3.2.3.3).
- R. Demonstrate the RSRM capability of vertical disassembly if required (3.2.5.1).
- S. The RSRM and its components will be adequately protected, by passive means, against natural environments during transportation and handling (3.2.8.c).
- T. Demonstrate the remove and replacement capability of the functional line replaceable unit (LRU) (3.4.1).

Objectives by Inspection

- A. Inspect all RSRM seals for performance (3.2.1.2).
- B. Inspect the seals for satisfactory operation within the specified temperature range that results from natural and induced environments (3.2.1.2.1.b).
- C. Inspect the factory joint insulation for accommodation of structural deflections and erosion (3.2.1.2.2.a).
- D. Inspect the factory joint insulation for operation within the specified temperature range (3.2.1.2.2.b).
- E. Verify that at least one virgin ply of insulation exists over the factory joint at the end of motor operation (3.2.1.2.2.d).
- F. Verify that no leakage occurred through the insulation (3.2.1.2.2.e).
- G. Verify that the flex bearing seals operate within the specified temperature range (3.2,1.2,3.b).
- H. Verify that the flex bearing maintained a positive gas seal between its internal components (3.2.1.2.3.d).

DOC NO TWR-17546-1 VOL SEC PAGE 4

Thickol CORPORATION SPACE OPERATIONS

- I. Verify that the ignition system seals operate within the specified temperature range (3.2.1.2.4.b).
- J. Verify that the nozzle internal seals and exit cone field joint seals operate within the specified temperature range (3.2.1.2.5.b).
- K. Inspect the risers for damage or cracks that would degrade the pressure holding capability of the case (3.2.1.3.c).
- L. Inspect the flex bearing for damage due to water impact (3.2.1.4.6).
- M. Verify that the environmental protection plug will withstand space shuttle main engine (SSME) shutdown, if incurred (3.2.1.4.7.b).
- N. Verify the performance of the nozzle liner (3.2.1.4.13).
- O. Inspect the ignition system seals for evidence of hot gas leakage (3.2.1.5.a).
- P. Inspect the igniter for evidence of debris formation or damage (3.2.1.5.2).
- Q. Inspect the seals for visible degradation from motor combustion gas (3.2.1.8.1.1.d).
- R. Verify by inspection that the insulation met all performance requirements (3.2.1.8.1.1.e).
- S. Inspect insulation material for shedding of fibrous or particulate matter (3.2.1.8.1.1.f).
- T. Inspect the joint insulation for evidence of slag accumulation (3.2.1.8.1.1.g).
- U. Inspect the thermal protection system (TPS) to insure that there was no environmental damage to the RSRM components (3.2.1.8.2).
- V. Inspect for thermal damage to the igniter chamber and the adapter metal parts (3.2.1.8.3).
- W. Verify that the case components are reusable (3.2.1.9.a).
- X. Verify that the nozzle metal parts are reusable (3.2.1.9.b).
- Y. Verify through flight demonstration and a postflight inspection that the flex bearing is reusable (3.2.1.9.c).
- Z. Verify that the igniter components are reusable (3.2.1.9.d).
- AA. Verify by inspection that the S&A is reusable (3.2.1.9.e).
- AB. Verify by inspection that the OPTs are reusable (3.2.1.9.f).
- AC. Inspect the case factory joint external seal for moisture (3.2.1.12).

| DOC NO TWR-17546 | | 6-1 | VOL |
|------------------|--|------|-----|
| SEC | | PAGE | 5 |

Thickol corporation

- AD. Inspect the hardware for damage or anomalies as identified by the failure modes and effects analyses (FMEA) (3.2.3).
- AE. Determine the adequacy of the design safety factors (SF), relief provisions, fracture control, and safe life and/or fail-safe characteristics (3.2.3.1).
- AF. Determine the adequacy of subsystem redundancy and fail-safe requirements (3.2.3.2).
- AG. Inspect the identification numbers of each reusable RSRM part and material for traceability (3.3.1.5).
- AH. Verify the structural SF of the case/insulation bond (3.3.6.1.1.2.a).
- AI. Verify by inspection the remaining insulation thickness of the case insulation (3.3.6.1.2.2, 3.3.6.1.2.3, 3.3.6.1.2.4, 3.3.6.1.2.6).
- AJ. Verify by inspection the remaining nozzle ablative thicknesses (3.3.6.1.2.7).
- AK. Verify the nozzle SFs (3.3.6.1.2.8).
- AL. Inspect metal parts for presence of stress corrosion (3.3.8.2.b).

| DOC NO. TWR-17546-1 | VOL |
|---------------------|-----|
| SEC PAGE | 6 |

Thickol corporation

RESULTS SUMMARY, CONCLUSIONS, AND RECOMMENDATIONS

3.1 RESULTS SUMMARY

This section contains an executive summary of the key results from the flight data evaluation and postflight inspection. Additional information and details can be found in the referenced report sections or in the separate component volumes of this report.

3.1.1 In-Flight Anomalies

There were no in-flight anomalies (IFA) relating to RSRM motor set 360L007.

3.1.2 Mass Properties

All SRM weight values were well within the CEI specification limits, as has been the case on all previous RSRM motor sets. Complete mass property values are included in Section 4.3 of this volume and Volume VII of this report.

3.1.3 Propulsion Performance (ballistics)

3.1.3.1 <u>Propellant Burn Rates/Specific Impulse</u>. The delivered burn rate (at 71°F and 625 psia) for flight motor set 360L007 was 0.368 ips for the LH motor, which matched the prediction, and 0.369 ips for the RH motor (0.001 ips higher than predicted). The reconstructed vacuum specific impulse values were 268.2 lbf*sec/lbm for the LH motor and 267.6 lbf*sec/lbm for the RH motor at 71°F, which was within 0.3 percent of the predicted value of 268.5 lbf*sec/lbm.

3.1.3.2 <u>CEI Specification Values.</u> All impulse values, time parameters, and pressure thrust levels (all corrected to 60°F) again showed excellent agreement with the motor nominal performance requirements. Actual value variations from the allowable CEI specification limits were all within 2 percent, significantly less than the allowable 3-sigma variation. Thrust imbalance was also well within the specification limits for the required time periods.

Due to the elimination of DFI after STS-29R (360L003), no high sample rate pressure data were available. Therefore, the CEI specification requirement to verify ignition interval, pressure rise rate, and ignition time thrust imbalance could not be addressed. A complete evaluation of all ballistic parameters is included in Section 4.4 of this volume.

> DOC NO TWR-17546-1 VOL SEC PAGE 7

REVISION

90407-4.1

SPACE OPERATIONS

3.1.4 S&A Device

The S&A safe-to-arm rotation times were all within the minimum 2-sec requirement during the actual launch, although there was some concern that the S&As might perform more slowly than expected when a delayed rotation time of 2.6 sec was revealed during prelaunch functionality testing. An interim problem report (IPR) (No. 33RV-0165) was written, and to close it an additional S&A functionality test was performed. S&A times are in Section 4.10.4.

3.1.5 Ascent Loads and Structural Dynamics

Due to elimination of DFI after STS-29R (360L003), no evaluation of the RSRM loading or vibration characteristics is possible.

3.1.6 External TPS/Joint Heater Evaluation

Postflight assessment results stated all TPS components to be in very good to excellent condition, with typical flight heat effects and erosion. National Space and Transportation System (NSTS) debris criteria for all missing TPS were not violated. Retrieval and towback were delayed 24 hr by high sea states.

All six field joint heaters performed adequately and as expected throughout the required operating periods, but a high voltage reading was noted on the LH aft heater. The high voltage was not accompanied by a current increase, so it was determined that the high reading was a sensor anomaly. See Section 4.10.2 for details. Prior to launch, a launch commit criteria (LCC) contingency was created to lower the minimum redline temperature at any field joint from 85° to 69°F in the event of primary and secondary heater failure. A detailed TPS and heater evaluation is in Section 4.8 of this volume.

3.1.7 Aero/Thermal Evaluation

3.1.7.1 <u>On-Pad Local Environments/Thermal Model Verification</u>. The on-pad local environments were lower than November conditions (62 • to 73 • F), with ambient temperatures ranging from 50 • to 76 • F. Windspeeds were lower than the historical conditions. Wind direction oscillated from east to south during the LCC timeframe.

No extreme outward cooling effects from external tank (ET) cryogenic loading were noted.

3.1.7.2 <u>LCC/Infrared (IR) Readings</u>. No LCC thermal violations were noted; all field and igniter joint heaters performed adequately. The aft skirt purge was activated

> DOC NO. TWR-17546-1 VOL SEC PAGE 8

approximately 15.5 hr prior to launch. The LH case-to-nozzle joint temperature was at the minimum LCC limit of 75°F at the beginning of the LCC window due to the delayed aft skirt purge start.

IR measurements taken by the IR gun during the T-3 hr ice/debris pad inspection were not consistent with GEI and shuttle thermal imager (STI) readings. Due to this inconsistency, which has been noted during previous countdowns, the data were not used or recorded by the ice team. The STI temperature measurements were used along with GEI measurements to monitor SRM surface temperatures.

No ascent and reentry thermal evaluation of the aft skirt area (as was done on RSRM Flights 1 through 3) was possible due to DFI elimination. A complete aero/thermal evaluation is in Section 4.8 of this volume.

3.1.8 Instrumentation

All 108 GEI measurements performed properly throughout the prelaunch phase. All GEI are disconnected by breakaway umbilicals at SRB ignition and are not operative during flight. All OPTs functioned properly during flight and successfully passed the prelaunch calibration checks. A complete discussion of GEI and all instrumentation is in Section 4.10 of this volume.

3.1.9 Postflight Hardware Assessment

3.1.9.1 <u>Insulation</u>. Postflight evaluation again verified excellent insulation performance, showing that the insulation effectively contained the motor combustion gas in the two case-to-nozzle joints and six field joints. Two of the 14 weatherseals on this flight set were unbonded. No gas paths through the case-to-nozzle joint polysulfide adhesive or any other anomalous joint conditions were identified. The internal insulation in all six of the case field joints also performed as designed, with no anomalous conditions. There were no recordable clevis edge separations (over 0.1 in.). No evidence of hot gas penetration through any of the acreage insulation was found, and no severe erosion patterns were identified. A complete insulation performance evaluation is in Section 4.11.1 of this volume and Volume III of this report.

3.1.9.2 <u>Case</u>. The case field joint surface conditions were as expected. Field joint fretting on this flight ranged from none on one joint to locally medium on two joints. The RH center field joint had no fretting. The LH center and RH forward joints had the worst fretting. No further damage was noted on the previously fretted hardware flown.

DOC NO. TWR-17546-1 VOL SEC PAGE 9

90407-4.3

SPACE OPERATIONS

Complete case evaluation results are in Section 4.11.2 of this volume and Volume II of this report.

3.1.9.3 <u>Seals</u>. The RH and LH inner and outer igniter gaskets were replaced preflight because of concerns about subsurface defects in the gasket elastomer seal. After this changeout, the RH igniter was again removed because the putty layup used was similar to procedures used on 360L006 (STS-34) igniter changeouts. (360L006 putty layup was suspect because putty was observed in the seal area of the outer gasket during disassembly.) The outer gasket was inspected for putty contamination in the seal area. The LH igniter putty was not suspect because it was held to the new, tighter dimension requirements. Putty was observed on the LH inner gasket (inner edge) from 20 to 65 deg.

All internal seals performed well, with no heat effects, erosion, or hot gas leakage evident. No motor pressure reached the field or case-to-nozzle joint seals. There was no putty on the forward or aft faces of the igniter gaskets. A complete evaluation of seals performance is in Section 4.11.3 of this volume and Volume II of this report.

3.1.9.4 <u>Nozzle/Thrust Vector Control (TVC) Performance</u>. Postflight evaluation indicated both nozzles performed as expected during flight, with typical smooth and uniform erosion profiles. A complete evaluation is in Section 4.11.4 of this volume and Volume V of this report.

3.2 CONCLUSIONS

Listed below are the conclusions as they relate specifically to the objectives and the CEI paragraphs. Also included with the conclusion is the section from this report (in parenthesis) where additional information can be found.

<u>Objective</u>

Certify that the thrust-

time performance falls

of the nominal thrust-

time curve.

within the requirements

CEI Paragraph

3.2.1.1.2.1 (see nominal thrust-time curve)

Conclusions

Certified. The thrusttime performance was within the nominal thrust-time curve (Figure 4.4-1).

| DOC NO. | TWR-1754 | WR-17546-1 | |
|---------|----------|------------|----|
| SEC | | PAGE | 10 |

REVISION

90407-4.4

Thickol CORPORATION SPACE OPERATIONS

Certify that the measured motor performance parameters, when corrected to a 60°F PMBT, fall within the nominal value, tolerance and limits for individual flight motors.

Certify that the thrusttime curve complies with impulse requirements.

Certify that specified temperatures are maintained in the case-to-nozzle joint region during the countdown LCC time period.

Certify that the ignition interval is between 202 and 262 ms with a 40 ms environmental delay after ignition command.

Certify that the pressure rise rate meets specification requirements.

3.2.1.1.2.2

The delivered performance values for each individual motor when corrected to a 60°F PMBT shall not exceed the limits specified...

3.2.1.1.2.4--Impulse Gates Total Time Impulse (sec) (10E6 lb-sec) 20 63.1 Minimum 60 172.9 -1, +3% Action time (AT): 293.8 minimum

3.2.1.2.1.f

Case-to-nozzle joint O-rings shall be maintained within the temperature range as specified in ICD 2-0A002 (75° to 115°F).

3.2.1.1.1.1

The ignition interval shall be between 202 and 262 ms with a 40 ms environmental delay after ignition command to the SSI in the S&A up to a point at which the headend chamber pressure has built up to 563.5 psia.

3.2.1.1.1.2 The maximum rate of pressure buildup shall be 115.9 psi for any 10 ms interval.

Partially Certified. All measurable motor performance values were well within the specification requirements (Tables 4.4-2 and 4.4-3). The ignition interval and rise rates could not be measured due to DFI elimination.

Certified. The nominal thrust-time curve values are listed below. Value Time RH LH (sec) 64.78 65.18 20 60 173.11 173.36 296.75 296.04 AT (Table 4.4-1)

Certified. Temperature ranges in the case-tonozzle joint region are listed below. RH 78° - 85°F LH 75° - 83°F (due to later aft skirt purge) (Table 4.8-4)

Unable to certify due to DFI elimination (high sample rate pressure transducers).

Unable to certify due to DFI elimination (high sample rate pressure transducers).

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----------------|
| SEC | PAG | ^ε 11 |

Thickol corporation SPACE OPERATIONS

Certify that the motor thrust differential meets specification requirements.

Certify the performance

maintains the igniter

gasket rubber seals be-

tween 64° and 130°F.

of the igniter heater so it

3.2.1.1.2.3

With a maximum PMBT difference of 1.4°F between the two RSRMs on a shuttle vehicle, the differential thrust between the two RSRMs shall not be greater than the values given in Table III at any time during the periods shown. These differentials are applicable over a PMBT range of +40° to +90°F.

3.2.1.5.3

The igniter heater shall maintain the igniter gasket rubber seals between 64• and 130•F.

Certify that the S&As perform as required using the specified power supply.

Certify that the OFI is capable of launch readiness checkout after the ground system has been connected on the launch pad.

Certify proper operation of the OPT during flight. 3.2.1.6.1.2--Power Supply. The S&A shall meet all performance requirements....in accordance with ICD 3-44005.

3.2.1.6.2--Instrumentation. The OFI shall be capable of launch readiness checkout after ground system connection on the launch pad.

3.2.1.6.2.1 The OPT shall monitor the chamber pressure of the RSRMs over the range from 0 to 1,050 ±15 psi. They shall operate in accordance with ICD 3-44005... The thrust differential values were near the nominal values experienced by previous flight SRMs (Table 4.4-2).

Certified. The igniter heater maintained the igniter sensors between 74° and 96°F (RH) and 72° and 96°F (LH). Sensor temperatures between 66° and 123°F ensure O-ring temperatures of 64° to 130°F (Table 4.8-4).

Certified. The rotation and arming times of both S&As were within the required limits (Section 4.10).

Certified. The 0 percent and 75 percent calibration checks of the OFI verified launch readiness after ground system connection on the launch pad (Section 4.10).

Certified. The OPTs properly monitored the chamber pressure and operated in accordance with ICD 3-44005. Recorded pressure data and values are discussed in Section 4.4 of this volume.

| DOC NO. TWR-17546-1 | | VOL | |
|---------------------|------|-----|--|
| SEC | PAGE | 12 | |

Thickol corporation

Certify that the systems tunnel properly : 1) attaches to the case, 2) accommodates the government-furnished equipment (GFE) and linear shaped charge (LSC), and 3) provides OFI, GEI, and heater cables.

Certify the performance of the field joint heater and the sensor assembly so it maintains the case field joint at 75°F minimum. Field joints shall not exceed 130°F.

Certify that each field joint heater assembly meets all performance requirements.

Demonstrate isolation of subsystem anomalies if required on seventh flight (360L007) hardware. 3.2.1.10.1

When exposed to the thermal environments of 3.2.7.2, the tunnel floorplates and tunnel cables will be maintained at a temperature at or below that specified in ICD 3-44002.

3.2.1.11.a

The case field joint external heater and sensor assembly shall maintain the case field joint O-ring seals between 75° and 130°F at launch...

3.2.1.11.1.2--Power Supply. Each field joint external heater assembly shall meet all performance requirements... as defined in ICD 3-44005.

3.2.3.3 Isolation of anomalies of time-critical functions shall be provided such that a faulty subsystem element can be deactivated without disrupting its own or other subsystems. Certified. Postflight evaluation showed no evidence of heat damage to the systems tunnel or adjacent cork, cables, and seams (Table 4.8.3). Proper case attachment and accommodation of the GFE, LSC, and cabling was also verified. A detailed systems tunnel evaluation is in Volume IV of this report.

Certified. The joint heaters maintained all field joint sensors between 90° and 108°F during the prelaunch period. Sensor temperatures between 85° and 122°F ensure O-ring temperatures are between 75° and 130°F.

Certified. All field joint external heaters met all the performance requirements. A high voltage spike was noted on the LH aft heater but was determined to be a sensor error (Section 4.8.3).

No subsystem anomalies of time critical functions were detected on flight set 360L007.

| DOC NO | TWR-17546-1 | VOL |
|--------|-------------|-----|
| SEC | PAGE | 13 |

Thickol CORPORATION SPACE OPERATIONS

Demonstrate RSRM capability of assembly/ disassembly in both the vertical and horizontal positions.

Demonstrate that the RSRM and its components are protected against environments during transportation and handling.

Demonstrate remove and replace capability to the functional LRU.

Certify by inspection all RSRM seal performance.

3.2.5.1

The RSRM shall be capable of assembly/ disassembly in both the vertical and horizontal positions. The RSRM shall be capable of vertical assembly in a manner to meet the alignment criteria of USBI-10183-0022 without a requirement for optical equipment.

3.2.8.c

The RSRM and its components...are adequately protected, by passive means, against natural environments during transportation and handling.

3.4.1

The maintenance concept shall be to "remove and replace"...in a manner which will...prevent deterioration of inherent design levels of reliability and operating safety at minimum practical costs.

3.2.1.2

Redundant, verifiable seals shall be provided for each pressure vessel leak path. Both the primary and secondary seals shall provide independent sealing capability through the entire ignition transient and motor burn without evidence of blowby or erosion. RSRM vertical assembly in accordance with USBI-10183-0022 was demonstrated in the vehicle assembly building (VAB) prior to pad rollout. No vertical disassembly was required. Postflight horizontal disassembly was accomplished at the Hangar AF facilities.

There were no anomalous readings from the transportation monitor units, demonstrating that the RSRM and its components are protected against environments during transportation and handling.

360L007 RH and LH inner and outer igniter gaskets were replaced at KSC due to concerns about subsurface defects in gasket elastomer seal (Section 3.1.9.3).

Certified. No motor pressure reached any of the field or case-to-nozzle joint seals (Section 4.11.3).

| DOC NO | TWR-17546-1 | VOL |
|--------|-------------|-----|
| SEC | PAGE | 14 |

Thickol CORPORATION SPACE OPERATIONS

Inspect the factory joint insulation for accommodation of structural deflections and erosion.

Certify that at least one virgin ply of insulation exists over factory joint at end of motor operation.

Certify that the field and case-to-nozzle joint seals, factory joint insulation, flex bearing seals, ignition system seals, and nozzle internal seals operate within the specified temperature range resulting from the natural and induced environments.

Certify that no leakage occurred through the insulation.

3.2.1.2.2.a

Sealing shall accommodate any structural deflections or erosion which may occur.

3.2.1.2.2.d

The insulation shall provide one or more virgin ply coverage at end of motor operation. The design shall perform the seal function throughout SRM operation.

3.2.1.2.1.b--Field and Nozzle/Case Joint Seals... 3.2.1.2.2.b--Factory Joint Insulation... 3.2.1.2.3.b--Flex Bearing Seals... 3.2.1.2.4.b--Ignition System Seals... 3.2.1.2.5.b--Nozzle Internal Seals... ...shall be capable of operating within a temperature range resulting from all natural and induced environments ...all manufacturing processes, and any motor induced environments.

3.2.1.2.2.e

The insulation used as a primary seal shall be adequate to preclude leaking through the insulation. The factory joint insulation remained sealed and accommodated all deflection and erosion (Section 4.11.1).

Certified. Preliminary inspections indicate adequate factory joint insulation ply coverage (Section 4.11.1). Detailed insulation inspection results are in Volume III of this report.

Certified. All field joint and case-to-nozzle joint seals, ignition system seals, and internal nozzle seals operated within all induced environments and showed no evidence of heat effects. erosion, or blowby (Section 4.11.3). Evaluation indicates no anomalies with the factory joint insulation (Section 4.11.1) or the flex bearing internal seals. Detailed flex bearing evaluation is in Volume V of this report.

Certified. Preliminary inspections showed no evidence of leakage through the factory joint insulation (Section 4.11.1). Detailed post flight evaluations are completed at the H-7 (Clearfield, Utah) facility. Detailed results are in Volume III of this report.

| DOC NO. | TWR-17546-1 voi | |
|---------|-----------------|----|
| SEC | PAGE | 15 |

Thickol corporation SPACE OPERATIONS

Verify by inspection that no gas leaks occurred between the flex bearing internal components.

Inspect the risers for damage or cracks that would degrade the pressure holding capability of the case.

Inspect the case segment mating joints for the pin retention device.

Inspect the flex bearing for damage due to water impact.

Inspect the nozzle for the presence of the environmental protection plug. 3.2.1.2.3.d The flex bearing shall maintain a positive gas seal between its internal components.

3.2.1.3.c The case shall contain risers for attaching the ET/SRB aft attach ring as defined in ICD 3-44004. The risers shall be part of the pressurized section of the case and shall not degrade the integrity of the case.

3.2.1.3.g The case segment mating joints shall contain a pin retention device.

3.2.1.4.6 The nozzle assembly shall incorporate a nozzle snubbing device suitable for preventing flex bearing damage resulting from water impact and shall not adversely affect the nozzle assembly vectoring capa-

bility.

3.2.1.4.7.a The nozzle assembly shall contain a covering and/or plug to protect the RSRM...during storage after assembly. Partially verified.

Preliminary inspection indicates the flex bearing maintained a positive seal within its internal components. Detailed inspection to be completed during flex bearing acceptance testing.

No damage or adverse effects to the ET attach risers was noted during post-test inspection. Preliminary case inspection results are in Section 4.11.2, and the final case evaluation is in Volume II of this report.

The pin retention device on all joints performed as designed (Section 4.11.2). Detailed results are in Volume II of this report.

Preliminary inspections indicate no anomalous conditions in the 360L007A or 360L007B flex bearings.

Both nozzle assemblies contained an environmental protection plug, which burst into multiple pieces upon motor ignition.

DOC NO TWR-17546-1 VOL SEC PAGE 16

Thickol CORPORATION SPACE OPERATIONS

Certify that the environmental protection plug will withstand SSME shutdown, if incurred.

Certify the performance of the nozzle liner.

<u>Note:</u> SCN 49 has been approved and changes the CEI paragraph wedgeout requirement from "greater than 0.250 in. deep" to "yield a positive margin of safety".

Inspect the ignition system seals for evidence of hot gas leakage.

Inspect the igniter for evidence of debris formation or damage.

Certify that the GEI can monitor the temperature of the SRBs while on the ground at the pad.

3.2.1.4.7.b

The nozzle assembly shall contain a covering and/or plug to protect the RSRM...in the event of an on-pad SSME shutdown prior to SRB ignition.

3.2.1.4.13

The nozzle flame front liners shall prevent the formation of: a. Pockets greater than 0.250 in. deep (as measured from the adjacent nonpocketed areas), b. Wedgeouts greater than 0.250 in. deep, c. Prefire anomalies except as allowed by TWR-16340.

3.2.1.5.a The ignition system shall preclude hot gas leakage during and subsequent to motor ignition.

3.2.1.5.2 ...the igniter hardware and materials shall not form any debris...

3.2.1.6.2.3 The GEI shall monitor the temperature of the SRBs while on the ground.... Not required to certify. No SSME shutdown was required during the actual launch sequence.

Certified. No nozzle flame front liner erosion pockets greater than 0.25 in. were noted. All wedgeouts observed occurred postburn and do not affect liner performance. No prefire anomalies were found (Section 4.11.4).

No ignition system seals, gaskets, or sealing surfaces showed any evidence of heat effects, erosion, or blowby (Section 4.11.3).

Preliminary indications showed no evidence of any igniter debris formation. A complete evaluation is in Volume VI of this report.

Certified. Extensive monitoring of the GEI was done during the countdown to access the SRM thermal environment and LCC. Detailed results are discussed in Section 4.8.

| DOC NO | TWR-1754 | 6-1 | νοι |
|--------|----------|------|-----|
| SEC | | PAGE | 17 |

Thickol CORPORATION SPACE OPERATIONS

Inspect the seals for visible degradation from motor combustion gas.

3.2.1.8.1.1.d Insulation shall protect

primary and secondary seals from visible degradation from motor combustion gas.

Certify by inspection that the insulation met all performance requirements.

Inspect insulation material for shedding of fibrous or particulate matter.

Inspect the joint insulation for evidence of slag accumulation.

Inspect the TPS to ensure that there was no environmental damage to the RSRM components. 3.2.1.8.1.1.e The insulation shall...meet all performance requirements under worst manufacturing tolerances and geometry changes during and after assembly and throughout motor operation.

3.2.1.8.1.1.f Insulation materials shall not shed fibrous or particulate matter during assembly which could prevent sealing.

3.2.1.8.1.1.g The joint insulation shall withstand slag accumulation during motor operation.

3.2.1.8.2 TPS shall insure that the mechanical properties of the RSRM components are not degraded when exposed to the environments... All motor combustion gas was contained by the insulation J-leg on the six field joints and the polysulfide adhesive on the two case-to-nozzle joints. No seals showed evidence of motor combustion gas degradation (Section 4.11.1).

Certified. Preliminary inspection indicates the insulation met all the performance requirements (Section 4.11.1). Detailed inspection results are in Volume III of this report.

No shedding of fibrous or particulate matter during assembly was detected (Section 4.11.1 of this volume and Volume III of this report).

No evidence of insulation damage due to slag accumulation was observed (Section 4.11.1 of this volume and Volume III of this report).

Postflight inspection revealed excellent TPS condition with no violation of any NSTS debris criteria. No thermal degradation of any RSRM component was noted (Section 4.8.3).

| DOC NO. | TWR-1754 | 6-1 | νοι | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 18 | |

Thickol CORPORATION SPACE OPERATIONS

Inspect for thermal damage to the igniter chamber and the adapter metal parts.

Certify that the case components are reusable.

3.2.1.8.3

The igniter insulation shall provide thermal protection for the main igniter chamber and adapter metal parts to ensure that RSRM operation does not degrade their functional integrity or make them unsuitable for refurbishment.

3.2.1.9.a--Reusability of... Case. Cylindrical segments, stiffener segments, attach segments, forward and aft segments (domes), stiffener rings, clevis joint pins.

Certify that the nozzle metal parts are reusable.

3.2.1.9.b, Reusability of... Nozzle Metal Parts--Boss attach bolts. Preliminary investigation revealed no thermal damage to the igniter due to lack of insulation functionality. Igniter details are in Volume VI of this report.

Cannot be completely certified at this time. All case component previous use history is in Section 4.2. No damage was noted to any cylindrical segments, attach segments, forward and aft domes, clevis joint pins, or the stiffener rings and segments on 360L007B (RH) or 360L006A (LH). Reuse criteria are not established until after refurbishment. Detailed case component inspection results are in Volume II of this report.

Cannot be completely certified at this time. All nozzle metal part previous use history is in Section 4.2. Preliminary observations showed no damage or corrosion to any nozzle reusable metal parts (Section 4.11.4). Any nozzle metal parts that are determined not to be reusable are discussed in Volume V of this report.

| DOC NO. | TWR-17546-1 | | VOL | |
|---------|-------------|------|-----|--|
| SEC | | PAGE | 19 | |

Thickol CORPORATION SPACE OPERATIONS

Certify through flight demonstration and a postflight inspection that the flex bearing is reusable.

3.2.1.9.c Reusability of... Flex bearing system - Reinforced shims and end rings, elastomer materials.

Certify that the igniter components are reusable 3.2.1.9.d--Reusability of ... Igniter. Chamber, adapter, igniter port, special bolts.

Certify by inspection that the S&A is reusable.

3.2.1.9.e--Reusability of ... Safe & Arm Device.

Cannot be completely certified at this time. The flex bearing previous use history is in Section 4.2. No apparent anomalies were observed with the 360L-007A (LH) or 360L007B (RH) flex bearing (Section 4.11.4). Final reuse criteria cannot be determined until after flex bearing acceptance testing.

Cannot be completely certified at this time. All igniter component previous use history is in Section 4.2. Preliminary postflight inspection revealed nothing that would adversely affect reuse of any igniter part. Detailed inspection results are in Volume VI of this report.

Cannot be completely certified at this time. The S&A previous use history is in Section 4.2. Preliminary postflight inspection revealed nothing that would adversely affect reuse of any S&A part. Detailed inspection results are in Volume VI of this report.

| DOC NO | TWR-17546-1 | νοι |
|--------|-------------|-----|
| SEC | PAGE | 20 |

Thickol corporation SPACE OPERATIONS

Certify by inspection that the OPTs are reusable.

3.2.1.9.f--Reusability of... Transducers

Inspect the case factory joint external seal for moisture.

Inspect the hardware for damage or anomalies as identified by the failure modes and effects analyses (FMEA).

Determine the adequacy of the design SF, relief provisions, fracture control, and safe life and/or fail-safe characteristics.

3.2.1.12

The factory joint external seal shall prevent the prelaunch intrusion of rain into the factory joints from the time of assembly of the segment until launch... The factory joint seal shall remain intact through flight and, as a goal, through recovery.

3.2.3

The design shall minimize the prob-ability of failure taking into consideration the potential failure modes identified and defined by FMEA.

3.2.3.1

The primary structure, thermal protection, and pressure vessel subsystems shall be designed to preclude failure by use of adequate design SFs, relief provisions, fracture control, and safe life and/or fail safe characteristics. Cannot be completely certified at this time. The OPT previous use history is in Section 4.2. All pressure data and preliminary postflight inspection indicate no issues that would adversely affect OPT reuse. Final OPT reuse criteria are established after refurbishment and calibration by the metrology lab.

The external weatherseal protected the case adequately from assembly until launch. Two of the 14 factory joint weatherseals showed signs of unbonds. A detailed weatherseal evaluation is in Volume III of this report.

No hardware damage or anomalies identified by FMEAs were found. Specific inspection results are in the individual component volumes of this report.

Postflight inspections verified adequate design SFs, relief provisions, fracture control, and safe life and/or fail-safe characteristics for the primary structure, thermal protection, and pressure vessel subsystems as documented in this volume and the component volumes of this report.

| DOC NO | TWR-17546-1 | | VOL |
|--------|-------------|------|-----|
| SEC | | PAGE | 21 |

REVISION

90407-4.15

Thickol CORPORATION SPACE OPERATIONS

Determine the adequacy of subsystem redundancy and fail-safe requirements.

Demonstrate isolation of subsystem anomalies if required on seventh flight (360L007) hardware.

Demonstrate RSRM capability of assembly/ disassembly in both the vertical and horizontal positions.

Demonstrate that the RSRM and its components are protected against environments during transportation and handling.

3.2.3.2

The redundancy requirements for subsystems...shall be established on an individual subsystem basis, but shall not be less than fail-safe...

3.2.3.3

Isolation of anomalies of time-critical functions shall be provided such that a faulty subsystem element can be deactivated without disrupting its own or other subsystems.

3.2.5.1

The RSRM shall be capable of assembly/ disassembly in both the vertical and horizontal positions. The RSRM shall be capable of vertical assembly in a manner to meet the alignment criteria of USBI-10183-0022 without a requirement for optical equipment.

3.2.8.c

The RSRM and its components...are adequately protected, by passive means, against natural environments during transportation and handling. No primary subsystem failure was noted; thus, subsystem redundancy and fail-safe requirements were not determined.

No subsystem anomalies of time-critical functions were detected on flight set 360L007.

RSRM vertical assembly in accordance with US-BI-10183-0022 was demonstrated in the VAB prior to pad rollout. No vertical disassembly was required. Postflight horizontal disassembly was accomplished at the Hangar AF (KSC) facilities.

There were no anomalous readings from the transportation modular units, demonstrating that the RSRM and its components are protected against environments during transportation and handling.

| DOC NO. | TWR-1754 | 6-1 | νοι |
|---------|----------|------|-----|
| SEC | | PAGE | 22 |

Thickol corporation SPACE OPERATIONS

Inspect the identification numbers of each reusable RSRM part and material for traceability.

Verify the structural SF of the case-to-insulation bond.

Verify by inspection the remaining thickness of the case insulation.

Previous objective continued

Previous objective continued

REVISION

3.3.1.5

Traceability shall be provided by assigning a traceability identification to each RSRM part and material and providing a means of correlating each to its historical records...

3.3.6.1.1.2.a The structural SF for the case-to-insulation bonds shall be 2.0 minimum during the life of the RSRM.

3.3.6.1.2.2 The case insulation shall have a minimum design SF of 1.5, assuming normal motor operation, and 1.2, assuming loss of a castable inhibitor.

3.3.6.1.2.3 Case insulation adjacent to metal part field joints, case-to-nozzle joints, and extending over factory joints shall have a minimum SF of 2.0.

3.3.6.1.2.4 Case insulation in sandwich construction regions (aft dome and center segment aft end) shall have a minimum SF of 1.5. Inspection numbers for traceability of each RSRM part and material are provided and are maintained in the Automatic Data Collection and Retrieval (ADCAR) computer system. The past history of all RSRM parts used is in Section 4.2.

Verification of a 2.0 SF cannot be done by inspection; however, flight performance verified an SF of at least 1.0. Case-to-insulation bond and adhesive bond SF of 2.0 are verified by analysis and documented in TWR-16961.

Preliminary insulation thickness measurements indicate adequate thermal SF near the igniter boss. A final evaluation will be made after the internal insulation thicknesses are measured at the Clearfield (H-7) facility. (Results and verification of SFs are in Volume III of this report.)

See above statement.

See above statement.

DOC NO TWR-17546-1 VOL SEC PAGE 23

90407-4.17

Thickol corporation

Previous objective continued

Verify by inspection the remaining nozzle ablative thicknesses.

Verify the nozzle SFs.

Inspect metal parts for presence of stress corrosion.

Demonstrate remove and replace capability of the functional LRU.

3.3.6.1.2.6

Insulation performance shall be calculated using actual pre- and post-motor operation insulation thickness measurements.

3.3.6.1.2.7

The minimum design SFs for the nozzle assembly primary ablative materials shall be as listed below... (Values not included here, as detailed results are not available at this writing.)

3.3.6.1.2.8 The nozzle performance margins of safety shall be zero or greater...

3.3.8.2.b

The criteria for material selection in the design to prevent stress corrosion failure of fabricated components shall be in accordance with MSFC-SPEC-522 and SE-019-094-2H.

3.4.1

The maintenance concept shall be to "remove and replace"...in a manner which will...prevent deterioration of inherent design levels of reliability and operating safety at minimum practical costs. Standard measurement techniques were used for final evaluation, as discussed in Volume III of this report.

Preliminary inspections indicate nozzle ablative thicknesses were within design SFs (Section 4.11.4). Detailed results are in Volume V of this report.

Verification of SFs cannot be done by inspection. Nozzle margins of safety will be discussed in Volume V of this report.

Inspection of metal parts for the presence of stress corrosion cannot be done visually but will be accomplished during refurbishment. Any stress corrosion found will be reported in Volume II of this report.

360L007 RH and LH inner and outer ignitergaskets were replaced at KSC due to concerns about subsurface defects in the gasket elastomer seal (Section 3.1.9.3).

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 24 |

90407-4.18

Thickol CORPORATION

SPACE OPERATIONS

3.3 RECOMMENDATIONS

Following is a summary of the recommendations made concerning flight set 360L007. Additional background information can be found in the referenced sections.

Aero/Thermal Recommendations 3.3.1

(Additional information is in Section 4.8.4.)

3.3.1.1 GEI Prediction. Aero/Thermal is anticipating a submodel development effort for the areas of the ET attach ring, field joint, factory joint, systems tunnel, igniter, and nozzle regions to improve predictions. These areas would be encompassed by the global model. The nodes need to be made smaller to refine the model. If the model cannot be satisfactorily refined, all systems with heaters will remain separate models, since at this time these separate models are more accurate.

3.3.1.2 GEI Accuracy. Gage range has been reduced on all joint heater sensors, resulting in better data resolution. It is recommended that the data collection accuracy of all GEI be increased by reducing the gage range and increasing the digital word length. The real fidelity of the KSC ground support equipment (GSE) could then be quantified and conceivably replaced if determined to be inadequate.

3.3.1.3 Local Chilling. Based on data from STS-28R (360H005), STS-29R (360L003), and STS-30R (360T004), local cooling does occur. Due to dissimilar ambient environments on launch day and the day prior to launch, it was not possible to determine local chilling on this flight. A method is being developed by Thiokol personnel to accurately quantify and predict the chill effect.

3.3.1.4 IR Measurements. STI data continue to be much more reliable than IR gun measurements. Comparisons with GEI are within acceptable margins for STI data but are questionable and unpredictable for IR gun data. Future efforts should be made in specifying locations for additional stationary STI cameras to assist in the eventual replacement of the outboard GEI. (Inboard GEI will need to be maintained because the STI cannot reach these blind regions.)

3.3.1.5 SRM Hardware Thermal Assessment. The SRM TPS design, from a thermal perspective, continues to suggest that the worst-case flight design environments of the Integrated Vehicle Baseline Configuration (IVBC-3) and SRB reentry are for the most

| DOC NO. | TWR-1754 | 6-1 | VOL | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 25 | |

90407-4.19

Thickol CORPORATION SPACE OPERATIONS

part overly conservative. An exception to this is the environment in the nozzle base region during reentry when excessive nozzle flame heating and hydrazine fires are present. (See TWR-17542, Vol. 1, STS-29R (360L003) Final Report.) USBI is currently obtaining updated thermal environments for the base region. A followthrough will be made concerning this request.

| DOC NO. | TWR-17546 | 6-1 | VOL |
|---------|-----------|------|-----|
| SEC | | PAGE | 26 |

Thickol corporation

4

FLIGHT EVALUATION RESULTS AND DISCUSSION

4.1 RSRM IN-FLIGHT ANOMALIES (FEWG report Paragraph 2.1.2)

No IFAs pertaining to flight set 360L007 were identified.

4.2 RSRM CONFIGURATION SUMMARY (FEWG report Paragraph 2.1.3.2)

4.2.1 SRM Reuse Hardware

The case segment reuse history for flight motors 360L007A and 360L007B is shown in Figures 4.2-1 and 4.2-2, respectively. Figures 4.2-3 through 4.2-6 show the LH and RH igniter and nozzle parts reuse, respectively. Nozzle snubber segments were new. Stiffener ring reuse is shown in Figures 4.2-7 through 4.2-10.

4.2.2 Approved RSRM Changes and Hardware Changeouts

A summary of the changes made since 360L006 (STS-34) is below. Complete descriptions of these changes are documented in Thiokol document TWR-50134, Redesigned Solid Rocket Motor Flight Readiness Review--Level II.

Two Class I hardware changes since 360L006 (STS-34):

- a. Change leak check port from angled design to straight design (ECP SRM-1612R1) to reduce stress at leak check port location.
- b. Eliminate thermocouple wires and associated K5NA closeout from factory joint weatherseal (ECP SRM-1958R2, Crit 1) to prevent seawater from entering factory joint weatherseal after splashdown.


4.2.3 LCC and OMRSD Changes

a. ECP 2219: Revise the contingency procedures for the S&A and the OPT. Add contingency procedures for the field joint temperature, case-to-nozzle joint temperature, nozzle bondline temperature, igniter joint temperature, and case acreage temperature. The reason for the change is to establish an approved contingency procedure for recovering from RSRM LCC redline violations. The change will be incorporated into MSFC document SIE-019-190-214, Solid Rocket Booster Recommended Actions for SRB Redline Violations.

| DOC NO | TWR-17546-1 | vol |
|--------|-------------|-----|
| SEC | PAGE | 27 |

90407-5.1


Thickol corporation SPACE OPERATIONS



A025845a

Thickol corporation SPACE OPERATIONS

Total



REVISION

Figure 4.2–2. Hardware Reuse Summary—360L007B (RH) Case

VOL

29


TWR-17546-1

PAGE

DOC NO

SEC

A025846a



A025847a

Figure 4.2–3. Hardware Reuse Summary–360L007A (LH) Igniter


PAGE


30

SEC

Thickol CORPORATION

SPACE OPERATIONS







REVISION


A025849a

PAGE 32





A025851a



REVISION

PAGE


VOL

35

A025852a

Figure 4.2-8. Hardware Reuse Summary-360L007A (LH) Stiffener Rings at Systems Tunnel Joint

TWR-17546-1 DOC NO. SEC





180 deg View 270 deg 90 deg T-Section 1U52502-07 0 deg Forward Conclusion: There are no fleet leader components in this assembly °°° 0000 0000 ••• 0000 00 T-Section 1U52502-08 Denotes fleet leader status 2 0 Splice Plate P/N 1U52503-05 S/N 0000042 Previous Use: New S/N 0000043 Previous Use: New S/N 0000045 **Previous Use: New** 0 4 Stiffener Ring — Attachment Stub Adapter Plate P/N 1U52504-05 S/N 0000173 Previous Use: New S/N 0000175 Previous Use: New S/N 0000176 Previous Use: New S/N 0000165 Previous uses Previous Use: New S/N 0000167 **Previous Use: New** Previous Use: New S/N 0000170

REVISION

DOC NO

SEC

VOL

37

A025881a

Figure 4.2-10. Hardware Reuse Summary-360L007B (RH) Stiffener Rings at Systems Tunnel Joint

TWR-17546-1

Thickol CORPORATION SPACE OPERATIONS

This ECP was disapproved with the rationale that document SE-109-190-2H is not applicable to the RSRM due to Thiokol's flight-by-flight issuance of a TWR, the Prelaunch Countdown Data Book.

b. ECP 2278: Add note to field joint and igniter LCC to implement generic minimum redline temperatures for field joint and igniter joint in the event of primary and secondary heater failure. The reason for the change is that analysis of worst-case tolerance combinations of seal, case, and igniter hardware have established that 78°F for the field joint and 66°F for the igniter joint are the minimum redline temperatures at which the CEI requirement for seal tracking can be maintained. These minimum redline temperatures are effective for any RSRM igniter and field joint if primary and redundant heaters are not operating.

This ECP was disapproved with the rationale that the change does not give a sufficient temperature margin. In the event both heaters fail, a waiver will be submitted for the specific effectivity.

c. ECP 2323: To establish a minimum temperature to maintain seal tracking margins for flight 360L007. In the event of heater malfunction, the minimum temperature sensor redline for the affected field joint becomes 69°F. This minimum is based on a minimum acceptable O-ring seal temperature using actual, as-built hardware dimensions in calculating O-ring squeeze (TWR-19824) and a +3°F differential temperature.

4.3 SRB MASS PROPERTIES (FEWG report Paragraph 2.2.0)

4.3.1 Sequential Mass Properties

Tables 4.3-1 and 4.3-2 provide 360L007 (STS-33R) LH and RH reconstructed sequential mass properties, respectively. Those mass property sequential times reported after separation reflect delta times from actual separation.

4.3.2 Predicted Data Versus Postflight Reconstructed Data

Table 4.3-3 compares the LH lightweight redesigned shuttle rocket motor (RSRML) predicted sequential weight and center of gravity (cg) data with the postflight reconstructed data. Table 4.3-4 compares the RH RSRML predicted sequential weight and cg data with the postflight reconstructed data. Actual 360L007 (STS-33R) mass properties may be obtained from Mass Properties History Log Space Shuttle 360L007--LH (TWR-17346, dated 5 Aug 1989) and 360L007--RH (TWR-17347, dated 5 Aug 1989).

REVISION _____ DOC NO TWR-17546-1 VOL _____ SEC PAGE 38

Table 4.3-1. 360L007A (LH) Sequential Mass Properties

8637.606 30752.785 21743.039 6674.883 12032.954 6606.839 42357.445 8060.360 0637.983 7328.929 6576.228 6555.698 6552.926 6552.870 6550.907 6550.787 6549.843 6549.290 6354.084 42400.661 6351.729 Yaw Moment of Inertia 382.862 146.915 879.679 878.307 762.178 628.000 551.070 516.028 332.405 244.152 174.248 46.494 46.134 46.088 46.087 46.054 46.052 46.037 46.028 141.418 141.380 Roll 6550.080 12399.784 6606.016 6552.044 6549.016 12356.568 30751.911 8059.498 6674.024 2032.106 10637.140 8636.771 7328.101 6575.401 6554.871 6552.099 5549.959 6548.463 21742.171 5353.277 5350.922 Pitch 0.006 0.008 0.010 0.011 0.012 0.018 0.030 0.043 0.053 0.053 0.052 0.052 0.052 0.052 0.052 0.006 0.021 0.051 0.051 Vert Center of Gravity 0.203 0.286 0.408 0.059 0.110 0.120 0.492 0.495 0.496 0.496 0.496 0.496 0.496 0.059 0.073 0.093 0.172 0.496 0.496 0.495 0.495 Lat 1317.337 1317.319 1317.319 1317.306 1315.655 1317.306 1317.300 231.315 171.348 207.838 1226.654 214.945 213.710 225.613 266.063 317.334 171.216 1229.061 317.297 307.130 307.111 Long 255,355.9 ,256,048.8 610,938.0 420,824.4 144,580.9 665,382.3 251,484.4 175,040.2 ,015,275.1 794,930.3 356,709.3 143,975.4 143,568.3 43,516.0 43,515.0 143,478.2 143,475.9 43,458.3 41,218.7 141,175.7 143,448.1 Weight (Ib) Main Chute Second Disreefing = 390.20 Main Chute First Disreefing = 384.30 Drogue Chute Deployment = 351.80 Main Chute Line Stretch = 374.20 Nose Cap Deployment = 351.20 End of Action Time = 123.66Intermediate Burn = 100.00 Intermediate Burn = 60.00 ntermediate Burn = 20.00 ntermediate Burn = 40.00 Intermediate Burn = 80.00 Frustum Release = 372.90 Max Reentry Q = 321.20Nozzle Jettison = 390.90Splashdown = 416.20Web Burn = 111.32Separation = 126.20Prelaunch = 0.00Event Time (sec) Max Q = 54.00Max G = 87.00Lift-Off = 0.23

Thiokol CORPORATION SPACE OPERATIONS

90407-7.4

TWR-17546-1 DOC NO VOL SEC

39

PAGE

Table 4.3-2. 360L007B (RH) Sequential Mass Properties

6613.074 6553.516 5552.572 6552.019 6336.130 5333.773 (6600.515 6579.236 6558.428 6555.656 6555.599 5553.637 11949.516 8574.382 7290.133 12347.179 (7998.605 10568.051 12390.379 30645.321 21668.031 Yaw Moment of Inertia 141.375 146.008 46.006 145.990 513.597 380.140 241.007 172.022 146.905 146.427 146.088 146.041 146.041 145.981 141.337 549.660 879.649 760.912 626.698 329.693 878.338 Roll 6578.410 6557.602 6554.828 6554.773 5552.810 6552.689 6551.745 6551.192 5335.324 6332.967 7289.306 21667.162 7997.742 6599.656 11948.669 10567.208 8573.547 6612.251 12389.502 12346.302 **30644.446** Pitch 0.052 0.052 0.052 0.052 0.044 0.053 0.052 0.018 0.022 0.031 0.051 0.010 0.013 0.051 0.006 0.006 0.008 0.011 Vert Center of Gravity 0.496 0.496 0.495 0.495 0.496 0.496 0.496 0.496 0.495 0.059 0.093 0.120 0.174 0.205 0.290 0.413 0.492 0.496 0.073 0.059 0.111 Lat 1267.708 1226.139 314.887 **316.776** 1316.747 1316.729 316.728 1316.716 316.715 **I316.709** I316.706 305.696 213.587 305.677 171.515 231.457 228.979 226.456 1214.597 1171.384 208.341 Long 43,432.9 43,422.7 141,193.3 (41,150.3 247,943.8 172,737.8 143,923.4 143,542.9 143,490.6 43,489.6 43,452.8 43.450.6 662,986.9 608,331.0 353,346.2 255,330.2 .013,170.6 417,272.6 144,619.1 792,736.1 ,256,025.1 Weight (Ib) Main Chute Second Disreefing = 390.20 Main Chute First Disreefing = 384.30 Drogue Chute Deployment = 351.80 Main Chute Line Stretch = 374.20 Nose Cap Deployment = 351.20End of Action Time = 123.12Intermediate Burn = 100.00 Frustum Release = 372.90 Intermediate Burn = 60.00 intermediate Burn = 80.00 ntermediate Burn = 40.00 ntermediate Burn = 20.00 Max Reentry Q = 321.20Nozzle Jettison = 390.90Splashdown = 416.20Web Burn = 111.23Separation = 126.20Prelaunch = 0.00Event Time (sec) Max G = 87.00Max O = 54.00ift-Off = 0.23

REVISION

SEC

Thickol corporation SPACE OPERATIONS

| | | 11/2:2F: (1F) | (4 | | | Longitudinal cg (in.) | cg (in.) | |
|------------------------------|------------|---------------|-------|-----------|------------|-----------------------|----------|-----------------|
| | Predicted* | <u>Actual</u> | Delta | Error (%) | Predicted* | Actual | Delta | <u>Error (%</u> |
| | 1 256 049 | 1 256.049 | 0 | 0.00 | 1,171.216 | 1,171.216 | 0.000 | 0.00 |
| Preignition | 1.250,020 | 1 255 356 | -58 | 0.00 | 1,171.342 | 1,171.348 | + 0.006 | 0.00 |
| Litt-ott | 114 345 | 144 581 | +236 | 0.16 | 1,313.212 | 1,315.655 | +2.443 | 0.19 |
| Action Time | 142.617 | 143.975 | +358 | 0.25 | 1,315.166 | 1,317.334 | +2.168 | 0.16 |
| Separation** | 142,024 | 143 516 | + 482 | 0.34 | 1,315.519 | 1,317.319 | + 1.800 | 0.14 |
| Nose Cap Deployment | 142.033 | 143 515 | + 482 | 0.34 | 1,315.519 | 1,317.319 | + 1.800 | 0.14 |
| Drogue Chute Deployment | 147 004 | 143.476 | + 482 | 0.34 | 1,315.505 | 1,317.306 | + 1.801 | 0.14 |
| Main Chute Line Stretch | 7/0 CV1 | 143.458 | + 482 | 0.34 | 1,315.499 | 1,317.300 | +1.801 | 0.14 |
| Main Chute First Disreeting | 147 066 | 143 448 | + 482 | 0.34 | 1,315.496 | 1,317.297 | + 1.801 | 0.14 |
| Main Chute Second Disreeting | 140,727 | 141 219 | + 482 | 0.34 | 1,305.258 | 1,307.130 | + 1.872 | 0.14 |
| Nozzle Jettison | 140,694 | 141,176 | + 482 | 0.34 | 1,305.239 | 1,307.111 | + 1.872 | 0.14 |

*Based on Mass Properties History Log--Space Shuttle 360L007 (LH), 5 Aug 1989 (TWR-17346) **The separation longitudinal cg of 1,317.334 is 66 percent of the vehicle length

| Table 4.3 | Table 4.3-4. 360L007B (RH) Sequential Mass PropertiesPredicted Versus Actual Comparisons | kH) Sequenti | al Mass P | ropertiesPredi | cted Versus Act | ual Comparisc | SUC | |
|------------------------------|--|--------------|--------------|----------------|-----------------|-----------------------|--------------|-----------|
| | | Weight (Ib) | (ql | ! | | Longitudinal cg (in.) | cg (in.) | |
| Event | Predicted* | Actual | <u>Delta</u> | Error (%) | Predicted* | <u>Actual</u> | <u>Delta</u> | Error (%) |
| Preionition | 1,256,025 | 1,256,025 | 0 | 0.00 | 1,171.384 | 1,171.384 | 0.000 | 0.00 |
| L ift-off | 1,255,391 | 1,255,330 | -61 | 00.00 | 1,171.511 | 1,171.515 | + 0.004 | 0.00 |
| Action Time | 144,320 | 144,619 | + 299 | 0.21 | 1,312.626 | 1,314.887 | + 2.261 | 0.17 |
| Senaration ** | 143,591 | 143,923 | +332 | 0.23 | 1,314.577 | 1,316.776 | +2.199 | 0.17 |
| Nose Can Denlovment | 143,009 | 143,491 | + 482 | 0.34 | 1,314.927 | 1,316.729 | + 1.802 | 0.14 |
| Droome Chute Deployment | 143,008 | 143,490 | + 482 | 0.34 | 1,314.927 | 1,316.728 | + 1.801 | 0.14 |
| Main Chute Line Stretch | 142,969 | 143,451 | + 482 | 0.34 | 1,314.913 | 1,316.715 | +1.802 | 0.14 |
| Main Chute First Disreefing | 142,951 | 143,433 | + 482 | 0.34 | 1,314.907 | 1,316.709 | +1.802 | 0.14 |
| Main Chute Second Disreefing | 142,941 | 143,423 | + 482 | 0.34 | 1,314.904 | 1,316.706 | + 1.802 | 0.14 |
| Nozzle Jettison | 140,711 | 141,193 | + 482 | 0.34 | 1,303.818 | 1,305.696 | + 1.878 | 0.14 |
| Splashdown | 140,668 | 141,150 | + 482 | 0.34 | 1,303.833 | 1,305.677 | +1.844 | 0.14 |

*Based on Mass Properties History Log, Space Shuttle 360L007 (RH), 5 Aug 1989 (TWR-17347) **The separation longitudinal cg of 1,316.776 is 66 percent of the vehicle length

TWR-17546-1 VOL DOC NO PAGE SEC 42

Thickol CORPORATION

Some of the mass properties data used have been taken from average actual data presented in the 5 Jun 1989 Mass Properties Quarterly Status Report (TWR-10211-91). Postflight reconstructed data reflect ballistics mass flow data from the 12.5 sample per second (sps) measured pressure traces and a predicted slag weight of 2,000 lb.

4.3.3 CEI Specification Requirements

Tables 4.3-5 and 4.3-6 present CEI specification requirements and predicted and actual weight comparisons. Mass properties data for both RSRMs comply with the CEI specification requirements (CPW1-3600A, Addendum G, Part I).

4.4 RSRM PROPULSION PERFORMANCE (FEWG report Paragraph 2.3.0)

4.4.1 High-Performance Motor (HPM)/RSRM Performance Comparisons

The reconstructed thrust-time traces of flight motor set 360L007 at standard conditions were averaged with the HPM/RSRM population and compared to the CEI specification limits. The results are shown in Figure 4.4-1.

4.4.2 SRM Propulsion Performance Comparisons

The reconstructed RSRM propulsion performance is compared to the predicted performance in Table 4.4-1. The following comments are to explain the table value. The RSRM ignition interval is to be between 202 and 302 ms after ignition command to the NASA standard initiator (NSI) in the S&A. The ignition interval ends when the headend chamber pressure has increased to a value of 563.5 psia. The maximum rate of headend chamber pressure buildup during the ignition transient is required to be less than 115.9 psia for any 10-ms interval. However, no high sample rate ignition data were available for this flight due to the elimination of DFI. Therefore, no rise rate or ignition interval is reported.

Separation is based upon the 50-psia cue from the last RSRM, plus 4.9 sec plus a time delay between the receipt and execution of the command to separate. No time delay is assumed in the prediction. The decay time intervals are measured from the time motor headend chamber pressure has decayed to 59.4 psia to the time corresponding to 85,000 lb of thrust.

4.4.3 Matched Pair Thrust Differential

Table 4.4-2 shows the thrust differential during steady state and tailoff. All the thrust differential values were near the nominal values experienced by previous flight SRMs

 DOC NO
 TWR-17546-1
 VOL

 sec
 PAGE
 43

Table 4.3-5. 360L007A (LH) Predicted Versus Actual Weight Comparisons (lb)

| Item | <u>Minimum</u> | Maximum | Predicted*** | Actual | <u>Delta</u> | Error (%) |
|---|--|---|---|---|-----------------------------|------------------------------|
| Inerts Prefire, Controlled* | | 151,076 | 149,539 | 149,539 | 0 | 0.00 |
| Propellant* Usable** To Lift-Off Lift-Off to Action** | 1,104,714 | | $\begin{array}{c} 1,106,493\\ 1,105,634\\ 535\\ 1,105,099\end{array}$ | $\begin{array}{c} 1,106,493\\ 1,105,880\\ 592\\ 1,105,288\end{array}$ | 0 + 246 + 57 + 189 | 0.00 0.02 9.63 0.02 |
| Unusable Action to Separation After Separation | | | 859 669 190 | 613 546 67 | -246 -123 -123 | 40.13 22.53 183.58 |
| Slag** | | | 1,518 | 2,000 | + 482 | 24.10 |
| *Requirement per CPW1-3600A, Addendum G, Part I (RSRM CEI specification) **Slag included in usable propellant, lift-off to action ***Based on Mass Properties History Log, Space Shuttle 360L007 (LH), 5 Aug 1989 (TWR-17346) | 00A, Addendui pellant, lift-off History Log, S | m G, Part I (R. to action pace Shuttle 36 | SRM CEI specifi 0L007 (LH), 5 A | cation) ug 1989 (TWR | -17346) | |

DOC NO TWR-17546-1 VOL SEC PAGE 44

90407-8.3


REVISION

Thiokol corporation space operations

Table 4.3-6. 360L007B (RH) Predicted Versus Actual Weight Comparisons (lb)

| ltem | Minimum | Maximum | Predicted*** | Actual | <u>Delta</u> | Error (%) |
|--|-----------|---------|--------------------------------|--|--------------------------|------------------------------|
| Inerts Prefire, Controlled* | | 151,076 | 149,538 | 149,538 | 0 | 0.00 |
| Propellant* Usable** To Lift-Off Lift-Off to Action** | 1,104,714 | | 1,106,4871,105,6295351,105,094 | 1,106,487 1,105,811 594 1,105,217 | 0 +182 +59 +123 | 0.00 0.02 9.93 0.01 |
| Unusable Action to Separation After Separation | | | 858 668 190 | 676 635 41 | -182 -33 -149 | 26.92 5.20 363.41 |
| Slag** | | | 1,518 | 2,000 | + 482 | 24.10 |

*Requirement per CPW1-3600A, Addendum G, Part I (RSRM CEI specification) **Slag included in usable propellant, lift-off to action ***Based on Mass Properties History Log, Space Shuttle 360L007 (RH), 5 Aug 1989 (TWR-17347)



Thickol corporation SPACE OPERATIONS

| Table 4.4-1. | RSRM | Propulsion | Performance | Assessment |
|--------------|------|------------|-------------|------------|
|--------------|------|------------|-------------|------------|

| | <u>LH Moto</u> Predicted | r (71 deg) _Actual | <u>RH Motor</u> Predicted | (71 deg) Actual |
|--|---|-------------------------------|---|--|
| Impulse Gates | | | | |
| I-20 (10^{6} lbf-sec) I-60 (10^{6} lbf-sec) I-AT (10^{6} lbf-sec) | 65.00 173.59 297.14 | 64.78 173.11 296.75 | 64.99 173.58 297.14 | $\begin{array}{c} 65.18 \\ 173.36 \\ 296.04 \end{array}$ |
| Vacuum I _{sp} (lbf*sec/lbm) | 268.5 | 268.2 | 268.5 | 267.6 |
| Burn Rate (in./sec) (60°F) | 0.368 | 0.368 | 0.368 | 0.369 |
| Event Times (sec)* | | | | |
| Ignition Interval Web Time* Time of 50-psia Cue Action Time* | $\begin{array}{c} 0.232 \\ 110.9 \\ 120.8 \\ 122.9 \end{array}$ | NA 111.1 121.3 123.4 | $\begin{array}{c} 0.232 \\ 110.9 \\ 120.8 \\ 122.9 \end{array}$ | NA 111.0 120.2 122.9 |
| Separation Command (sec) | 125.7 | 126.2 | 125.7 | 126.2 |
| PMBT (°F) | 73.0 | 71.0 | 73.0 | 71.0 |
| Maximum Ignition Rise Rate (psia/10 ms |) 91.9 | NA | 91.9 | NA |
| Decay Time (sec) (59.4 psia to 85 K) | 2.8 | 2.8 | 2.8 | 3.4 |
| Tailoff Imbalance | <u>Predicted</u> | Actual | | |
| Impulse Differential (klbf-sec) | NA | + 693 | | |

Note: Impulse imbalance = LH motor - RH motor

*All times are referenced to ignition command time except where noted by an *. These times are referenced to lift-off time (ignition interval)

| DOC NO | TWR-17546-1 | νοι |
|--------|-------------|-----|
| SEC | PAGE | 47 |

Thickol corporation space operations

and were well within the CEI specification limits. The thrust values used for the assessment were reconstructed at the delivered conditions of each motor.

| <u>Event</u> | Imbalance Specification (klbf) | Maximum Imbalance (klbf) | Time of Maximum Imbalance (sec) |
|---|--------------------------------------|--------------------------------|---------------------------------------|
| Steady state (1.0 sec to first web time minus 4.5 sec, lbf, 4-sec average) | 85 | + 29.4 | 106.5 |
| Transition (first web time minus 4.5 sec to first web time, lbf) | 85 - 268 (linear) | + 83.0 | 111.0 |
| Tailoff (first web time to last action time) | 710 | + 110.3 | 119.6 |

Table 4.4-2. SRM Thrust Imbalance Assessment

4.4.4 Performance Tolerances

A comparison of the LH and RH motor calculated and reconstructed parameters at PMBT of 60°F with respect to the nominal values and the SRM CEI specification maximum 3-sigma requirements is given in Table 4.4-3.

4.4.5 Igniter Performance

Due to the elimination of DFI, no evaluation of the igniter performance is possible. Also, no evaluation of the ignition interval, pressure rise rate, and ignition thrust imbalance requirements was possible.

4.5 RSRM NOZZLE TVC PERFORMANCE (FEWG report Paragraph 2.4.3)

The nozzle torque values for motor set 360L007 could not be determined due to DFI elimination on Flight 4 (STS-30R) and subsequent. This section is reserved pending any future motors that incorporate DFI.

| EVISION | |
|---------|--|
| | |

| DOC NO | TWR-1754 | 6-1 | VOL |
|--------|----------|------|-----|
| SEC | | PAGE | 48 |

Thickol CORPORATION SPACE OPERATIONS

| | SRM CEI (+/-) Max 3-sigma Variation (%) | Nominal <u>Value*</u> | <u>LH</u> (60°F) | Motor Variation (%)** | <u>RH</u> (60°F) | Motor Variation (%)** |
|---|--|--------------------------|---------------------|-----------------------------|---------------------|-----------------------------|
| Web Time | 5.0 | 111.7 | 112.4 | +0.63 | 112.3 | +0.54 |
| (sec) Action Time | 6.5 | 123.4 | 124.8 | +1.13 | 124.3 | +0.73 |
| (sec) Web Time Avg | 5.3 | 660.8 | 655.4 | -0.82 | 655.6 | -0.79 |
| Pressure (psia) Max Headend | 6.5 | 918.4 | 904.0 | -1.57 | 911 | -0.81 |
| Pressure (psia) Max Sea Level | 6.2 | 3.06 | 3.03 | -0.98 | 3.05 | -0.33 |
| Thrust (Mlbf) Web Time Avg | 5.3 | 2.59 | 2.57 | -0.77 | 2.57 | -0.77 |
| Vac Thrust (Mblf) Vac Del Specific Impulse | 0.7 | 267.1 | 268.1 | +0.37 | 267.4 | +0.11 |
| (lbf*sec/lbm) Web Time Vac Total Impulse | 1.0 | 288.9 | 288.6 | -0.10 | 288.5 | -0.14 |
| (Mlbf*sec) Action Time Vac Total Impulse (Mlbf*sec) | 1.0 | 296.3 | 296.4 | +0.03 | 295.7 | -0.20 |

| Table 4.4-3. | SRM | Performance | Comparisons |
|--------------|-----|-------------|-------------|
|--------------|-----|-------------|-------------|

*QM-4 static test and SRM-8A and 8B, SRM-9A, SRM-10A and 10B, SRM-11A, SRM-13A and 13B flight average at standard conditions

**Variation = ((RSRM-7A - nominal)/nominal) * 100

((RSRM-7B - nominal)/nominal) * 100

4.6 RSRM ASCENT LOADS--STRUCTURAL ASSESSMENT (FEWG report Paragraph 2.5.2)

Motor set 360L007 did not have any DFI installed to evaluate the motor structural performance. This section is reserved pending any future motors that incorporate DFI.

| DOC NO. | TWR-1754 | 46-1 | | VOL | |
|---------|----------|------|---|-----|--|
| SEC | | PAGE | 4 | 9 | |

Thickol CORPORATION SPACE OPERATIONS

4.7 RSRM STRUCTURAL DYNAMICS (FEWG report Paragraph 2.6.2)

No accelerometer data were available due to the elimination of DFI on Flight 4 (STS-30R) and subsequent. This section is reserved pending the installation of accelerometers on future flight motors.

4.8 RSRM TEMPERATURE AND TPS PERFORMANCE (FEWG report Paragraph 2.8.2)

4.8.1 Introduction

This section documents the thermal performance of the 360L007 (STS-33R) SRM external components and TPS determined by postflight hardware inspection. Assessments of debris, mean bulk temperature predictions, on-pad ambient/local induced environments, LCC, and GEI/joint heater sensor data are also included. Performance of SRM internal components (insulation, case components, seals, and nozzles) is reported in Paragraph 4.11.

4.8.2 Summary

4.8.2.1 <u>Postflight Hardware Inspection</u>. Postflight inspection of the TPS revealed no anomalies or unexpected problems due to flight heating environments. The condition of both SRMs was similar to that of previous flight sets. Table 4.8-1 provides an overall summary of SRM TPS condition. Nozzle erosion is discussed in Section 4.11.4.

4.8.2.2 <u>Debris Assessment</u>. NSTS debris criteria for missing TPS were not violated. The TPS cork pieces that were missing were all caused by nozzle severance debris and/or splashdown loads and debris. A complete SRM debris assessment is given in Section 4.8.3.2.

4.8.2.3 <u>Mean Bulk Temperature Predictions</u>. These temperature predictions were made at different times during the countdown. A discussion of these predictions is presented in Section 4.8.3.3. The final postflight predictions from reconstructed data yielded a PMBT of 71°F and a flex bearing mean bulk temperature (FBMBT) of 75°F.

4.8.2.4 <u>On-Pad Environment Evaluations</u>. The ambient temperature recorded during a 66-hr period prior to launch varied from 50° to 76°F. The normal temperature range experienced during the month of November is from a low of 62°F to a high of 73°F. The 51°F temperature, which occurred over a 6-hr period from midnight to 6:00 a.m. on November 21, represents a minus 1- to minus 2-sigma deviation from the historical

DOC NO TWR-17546-1 VOL SEC PAGE 50

Thickol corporation SPACE OFFRATIONS

| Component | TPS Material | <u>Maximur</u> Predi <u>cted</u> | <u>n Erosion (in.)</u> <u>Measured</u> |
|------------------|--------------|-------------------------------------|---|
| Field Joints | Cork | 0.003 | None |
| Factory Joints | EPDM | 0.014 | Not measurable* |
| Systems Tunnel | Cork | 0.014 | None |
| Stiffener Rings | EPDM | 0.009 | Not measurable* |
| GEI Closeout | Cork | 0.036 | Not measurable* |
| Nozzle Exit Cone | Cork | 0.104 | NA** |

Table 4.8-1.STS-33R RSRM External Performance Summary
(TPS erosion)--Both Motors

*All evidences of minor erosion were apparent only on the inboard region of the aft segment, where the flight-induced thermal environments are the most severe

**Nozzle exit cones are not recovered

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 51 |

Thickol CORPORATION SPACE OPERATIONS

November temperature for the same timeframe. The windspeeds during this same timeframe were lower than historical conditions. See Table 4.8-2 for environmental conditions prior to launch.

4.8.2.5 <u>LCC</u>. No LCC thermal violations were noted. Measured GEI and heater sensor data, as compared with the LCC requirements, are discussed in Section 4.8.3.5. Highlights of the heating operations are summarized as follows.

The igniter heaters were activated for 18 hr, 20 minutes, and maintained the required temperatures. However, the igniter temperature control band was changed from $95^{\circ} \pm 5^{\circ}$ F to $95^{\circ} \pm 1^{\circ}$ F. This resulted in more frequent cycling and better heater control. Cooldown, after heater shutoff, occurred over an approximate 7-hr, 13-minute period, and resulted in T-5-minute igniter sensor temperatures from 73° to 76° F. These temperatures were only 5.5° F higher than the preactivation temperatures.

The six field joint heaters performed adequately and as expected with a 17° F sensor temperature range from 90° to 107° F during the LCC timeframe. All 24 field joint sensors recorded temperatures in the expected range. Prior to launch, an LCC contingency was created to lower the minimum redline temperature at any field joint from 85° to 69°F in the event of a complete heater failure. An IPR was written against the LH aft field joint heater voltage, which read 290 V instead of the nominal 209 V. This IPR was dispositioned when it was determined that the voltage must have been nominal because the current reading was nominal. In addition, the heater circuit breaker was not tripped as it would have been had the voltage actually been 290 V.

The SRB aft skirt purge operation was activated approximately 15.5 hr prior to launch. When the LCC timeframe began nearly 6 hr later, all six case-to-nozzle joint temperature readings were 75°F or above. There was concern that the minimum 75°F LCC temperature would not be reached prior to the LCC timeframe, and appropriate action was taken to avoid this occurrence. At the end of the LCC timeframe the temperature range of the case-to-nozzle joint sensors was 82° to 85°F.

4.8.2.6 Prelaunch Thermal Data Evaluation

<u>IR Temperature Measurements</u>. IR measurements from the STI were compared with GEI measurements. IR measurements taken by the IR gun during the T-3-hr ice/debris pad inspection were not reported. The STI temperature measurements were used along with the GEI measurements to monitor SRM surface temperatures.

> DOC NO. TWR-17546-1 VOL SEC PAGE 52

Thickol CORPORATION SPACE OPERATIONS

Table 4.8-2. STS-33R Actual GEI Countdown and Historically Predicted On-Pad November Temperatures (°F) (LCC timeframe temperatures also included)

| | Daily Cy | aling | Τ-6Η | <u> Ir to T - 5 N</u> | fin |
|----------------------|-------------------|---------|------------|-----------------------|---------|
| | November | Actual | November | Actual | |
| | | GEI | Historical | GEI | LCC |
| <u>Component</u> | <u>Historical</u> | GEI | Instorical | | |
| Igniter Joint | | | | F 4 0 0 | 66-123 |
| RH | 70-77 | 62-71 | 76-100 | 74-96 | |
| LH | 70-76 | 62-71 | 75-100 | 72-96 | 66-123 |
| Field Joint | | | | 00.100 | 85-122* |
| RH Forward | 62-77 | 58-76 | 95-107 | 93-108 | |
| LH Forward | 61-77 | 57-76 | 94-106 | 92-101 | 85-122 |
| RH Center | 62-77 | 57-72 | 96-107 | 90-108 | 85-122 |
| LH Center | 61-77 | 58-73 | 94-106 | 92-107 | 85-122 |
| RH Aft | 62-77 | 57-70 | 93-105 | 91-108 | 85-122 |
| LH Aft | 61-77 | 58-73 | 95-105 | 91-107 | 85-122 |
| Case-to-Nozzle Joint | | | | | 05 115 |
| RH | 65-73 | 64-66 | 74-79 | 78-85 | 75-115 |
| LH | 66-74 | 64-66 | 73-82 | 75-83 | 75-115 |
| Flex Bearing | | | | | |
| Aft End ring | | | | | NTA 110 |
| RH | 65-73 | 65-67 | 74-79 | 82-83 | NA-115 |
| LH | 66-74 | 65-69 | 73-82 | 82-85 | NA-115 |
| Case Acreage (deg) | | | | aa 5 0 | |
| RH 45 | 62-72 | 58-70 | 66-72 | 60-70 | |
| 135 | 62-75 | 58-72 | 66-75 | 59-72 | |
| 215 | 63-77 | 60-76 | 67-77 | 60-76 | |
| 270 | 63-75 | 59-69 | 67-75 | 59-67 | 35-NA |
| 325 | 62-73 | 58-67 | 66-73 | 59-67 | |
| LH 45 | 62-76 | 59-75 | 66-76 | 59-75 | |
| 135 | 62-73 | 59-69 | 65-73 | 59-67 | |
| 215 | 62-73 | 58-67 | 65-73 | 59-67 | |
| 270 | 63-74 | 59-70 | 67-76 | 59-67 | 35-NA |
| 325 | 63-76 | 59-72 | 67-76 | 59-72 | |
| Local Environment | | | | | 00.00 |
| Temperature | 62-73 | 50-76 | 65-70 | 59-73 | 38-99 |
| Windspeed (kt) | 12 | 2-13 | 12 | 2-13 | 24 |
| Wind Direction | Ň | All dir | N | NE-W | SW-SE |
| Cloud Cover | | Clear | | Clear | |

*Field joint sensor lower limit will drop from 85° to 69°F in the case of a complete heater failure

| DOC NO. TWR-17546- | | 6-1 | VOL |
|--------------------|--|------|-----|
| SEC | | PAGE | 53 |

Thickol CORPORATION SPACE OPERATIONS

Temperatures varied between 64° and 66°F during the T-3-hr pad inspection for both STI and GEI temperatures. A complete evaluation of the IR data is found in Section 4.8.3.6.

4.8.2.7 Prelaunch Hardware Anomalies. There were no prelaunch hardware anomalies.

4.8.3 <u>Results Discussion</u>

4.8.3.1 <u>Postflight Hardware Inspection</u>. Following the recovery of the STS-34R SRBs, a postflight inspection of the external hardware was conducted at the SRB disassembly facility (Hangar AF). TPS performance was considered to be excellent in all areas, with external heating and recession effects being less than predicted (Table 4.8-1). Predictions due to the worst-case design trajectory environments (Table 4.8-3) will be documented in the SRB Thermal Design Data Book, SE-019-068-2H.

The condition of both motors appeared to be similar to previous flight motors, with most of the heat effects seen on the aft segments on the inboard side of the SRBs. The aft segment inboard regions facing the ET experienced high aerodynamic heating normal to protuberance components. They also received the high plume radiation and recirculation heating induced by the adjacent SRB and SSMEs on aftfacing surfaces. In this area there was slight charring of the TPS over the factory joints, the stiffener rings and stubs, and GEI cabling runs. A concise summary of the external hardware condition is shown in Table 4.8-4.

Field Joints. All field joints on both motors were in excellent condition. There were no signs of ablation on any of the joint protection systems (JPS), with only slight paint blistering on the cork cover. The paint on the K5NA closeout aft of the cork was also slightly darkened and blistered, with occasional pitting. This was probably due to aerodynamic heating and the result of aft edge hits from water impact and nozzle severance debris. All K5NA repair locations were intact over the trunnion/vent valve locations, with the exception of the LH aft field joint which had two circumferential cracks at the 30-deg trunnion location. The cracks were about 2 in. long and did not exhibit loose material or any heat effects. The LH forward field joint had two small impact marks on the forward edge and a series of small surface cracks in between. These also were not heat affected.

<u>Factory Joints</u>. The factory joints on each of the motors were in very good condition. The only signs of heat effect experienced on the factory joints were located on the aft

| DOC NO. | TWR-1754 | 6-1 | VOL | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 54 | |

90407-5.9

Thiokol corporation space operations

Table 4.8-3. SRB Flight-Induced Design Thermal Environments


| Thermal Environment | Related Document | | |
|------------------------------|---|--|--|
| Ascent Heating | Document No. STS 84-0575, dated 24 May 1985 | | |
| | Change Notice 2, SE-698-D, dated 30 Apr 1987 | | |
| | Data on computer tapes No. DN 4044 and DN 9068 | | |
| | Change Notice 3, SE-698-D, dated 30 Oct 1987. Tape No. DP 5309 | | |
| Base Recirculation | Document No. STS 84-0259, dated Oct 1984 | | |
| Heating | Change Notice 1, SE-698-D, dated 30 Sep 1987 | | |
| SSME and SRB Plume | Document No. STS 84-0259, dated Oct 1984 | | |
| Radiation | Change Notice 1, SE-698-D, dated 30 Sep 1987 | | |
| SSME Plume Impinge- | Document No. STS 84-0259, dated Oct 1984 | | |
| ment After SRB Separation | Change Notice 1, SE-698-D, dated 30 Sep 1987 | | |
| Reentry Heating | Document No. SE-0119-053-2H, Rev D, dated August 1984, and Rev E, dated 12 Nov 1985 | | |

| DOC NO. | TWR-1754 | 6-1 | VOL | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 55 | |

| - |
|----------------|
| ્ટ |
| ē |
| h moi |
| 5 |
| ť |
| <u>م</u> |
| $\overline{}$ |
| Ē. |
| na |
| : Summary (bo |
| , E |
| formance S |
|) C |
| lar |
| E |
| ſ |
| er |
| d . |
| lal |
| 11 |
| xte |
| щ |
| 2 |
| R |
| S |
| R |
| 33 |
| Ş. |
| STS-33R SRM Ex |
| •, |
| 4 |
| ¢. |
| र 0 |
| pľ |
| La |
| |

REVISION

| <u>Recovered Hardware Performance Assessment</u> | All JPS in excellent condition; slight paint blistering; pitting on aft edge of JPS K5NA closeout; all but one K5NA repair intact over trunnion/vent valve locations; two circumferential cracks on 1 a.6.6.0.1 | 30-deg trunnion locations | All factory joints in very good condition; typical heat- affected areas on aft segment joints on inboard side of both motors; forward and aft edge unbonds on two (one on each motor) weatherseals with no evidence of sooting; a 1 in. circumferential by 2 in. axial by 1/2-indeep gouge occurred on the aft end of forward center factory joint at or after solashdown | In a mich approximation of the | Cork TPS adjacent to tunnel floor plate in JPS excellent condition; very little paint blistering; K5NA closeout in excellent condition on both cables and seams | | appearance; charring and discoloration on all edges and inboard top surfaces; Instafoam ramps chunked out on all rings at outboard locations of both motors due to water impact; cracks observed in the KSNA of both middle stiffeners |
|--|--|---------------------------|---|--------------------------------|--|-----------------|--|
| <u>Performance</u> | Typical | | Typical | | Typical | Typical | |
| TPS Material | Cork | EBDW | | 0 | COTK/NOVA | EPDM | |
| <u>Component</u> Field Toises | | Factory Joints | | Systems Thunel | Heater Cable | Stiffener Rings | |





Thickol corporation

Table 4.8-4. STS-33R SRM External Performance Summary (both motors) (Cont)

| Recovered Hardware Performance Assessment | Very good condition, with slight paint blistering; a few small cork pieces missing on GEI cable runsAll within established NSTS debris criteria and all caused by nozzle severance and/or splashdown loads and debris | Good condition from thermal perspective; shielded from radiation by kick ring; no splashdown damage; nozzle exit cone cork unknown; aft exit cones not recovered | No hot spots or abnormal discoloration of the case paint due to external or internal heating; aft segments extensively sooted |
|--|---|---|---|
| Performance | Typical | Typical | Typical |
| TPS Material | Cork/K5NA | Cork | NA |
| Component | GEI Closeout | Aft Kick Ring Joint | Motor Case |

Thiokol corporation space operations

| DOC NO. | TWR-17546 | VOL | |
|---------|-----------|------|----|
| SEC | | PAGE | 57 |

.

Thickol CORPORATION SPACE OPERATIONS

segments of each motor. There was only slight ablation, charring, and discoloration on the inboard regions of the aft segment factory joints. This occurred between approximately 220 and 320 deg circumferentially on each motor. Again, these are all normal occurrences that have been consistently observed on previous flight motors. Two weatherseals (one on each motor) showed signs of both forward and aft edge unbond regions. No evidence of sooting was found under these unbonds.

<u>Systems Tunnel</u>. The cork TPS adjacent to the systems tunnel floor plate was in excellent condition. There was very little paint blistering. All K5NA closeouts over cables and tunnel seams were in excellent condition.

Stiffener Rings. The stiffener ring TPS was generally in very good condition with only slight thermal degradation. The major heat-affected area was again predominantly in the 220- to 320-deg sector, with the EPDM on the outer flange showing signs of brown charring. This region was subjected to aeroheating along the outboard tip forward face, while the aft face and top surfaces experienced radiant heating. The K5NA TPS on the top surfaces of the stubs was also slightly charred in the same regions, with intermittent pitting around the whole circumference.

GEI Closeout. The cork and K5NA TPS covering the GEI and cableways was generally in good condition. Very little heat effect was observed, consisting of only slight paint discoloration and blistering. Some of the GEI cable runs had small areas of missing cork on the aft edges of the runs at intermittent regions. These minor cork losses were all attributed to aft edge hits caused by nozzle severance debris impact during reentry, splashdown loads, and handling problems.

4.8.3.2 <u>Debris Assessment</u>. NSTS debris criteria for missing TPS were not violated. The TPS cork pieces that were missing were all caused by nozzle severance debris and/or splashdown loads and debris. There were a total of four aft edge hits--three on the LH motor and one on the RH motor. The largest GEI cork piece missing was approximately 2.5 by 2.5 by 0.5 in., or 3.1 in.³. This piece was located at Station 691 at approximately 240 deg. It was either a handling or a splashdown scrape and left a clean substrate.

This flight set is the first flight to use stencils in place of labels to mark the GEI measurement stimulation identification number (MSID) locations on the case

DOC NO. TWR-17546-1 VOL SEC PAGE 58

Thickol CORPORATION

surface. The action of removing these labels resulted from debris concerns raised during STS-30R postflight inspection, when many labels were missing. The epoxy closeout over the GEI MSID labels, generally up to 0.125 in. thick, became the material of debris concern.

4.8.3.3 <u>Mean Bulk Temperature Predictions</u>. Mean bulk temperature predictions were performed at various times with respect to the launch of STS-33R. They were predicted for the time of launch and are summarized as follows:

| | <u>Historical</u> | L-9 Days <u>13 Nov 1989</u> | L-2 Days <u>20 Nov 1989</u> | L-24 hr <u>21 Nov 1989</u> | <u>Postflight</u> |
|-------------------------|-------------------|--------------------------------|--------------------------------|-------------------------------|-------------------|
| PMBT (°F) FBMBT (°F) | 69 74 | 73 74 | 73 | 73 | 71 75 |

The final postflight predictions from reconstructed data yield a PMBT of 71°F and an FBMBT of 75°F. The prelaunch predicted PMBT was 2°F higher than the postflight predicted PMBT using reconstructed ambient data.

All predictions were based on the following four sources of data:

1. Thiokol Launch Support Services (LSS) office (faxed weather data)

2. KSC weather station (modem transmission)

3. Florida Solar Energy Center (FSEC) (modem transmission)

4. Central Databasing Service (CDS) data collected at HOSC (faxed weather data)

The data from the Thiokol LSS office were used wherever possible and were the primary source of environmental data. The ambient temperature from the KSC weather station was used as the next source along with windspeed and direction from the FSEC. The ambient temperature data from the FSEC were used only when the other sources were unavailable. The FSEC, however, was the sole source for sky temperature and solar flux. The CDS data collected at HOSC during the countdown was the ambient temperature data used during the 66 hr prior to launch.

The FBMBT calculations were not conducted prior to launch since prelaunch estimations indicated that the FBMBT would be approximately 74°F. Postflight predictions placed the FBMBT at 75°F.

4.8.3.4 <u>On-Pad Environment Evaluations</u>. Actual environmental data for the final 24 hr prior to launch can be visualized in Figures 4.8-1 through 4.8-5 and summarized together with GEI in Table 4.8-2. The ambient temperature recorded during a 66-hr

DOC NO. TWR-17546-1 VOL SEC PAGE 59

90407-5.11

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-2. Windspeed at Camera Site No. 3 (overlaid with ambient)

DOC NO. TWR-17546-1 VOL SEC PAGE 60

Thiokol CORPORATION SPACE OPERATIONS






Figure 4.8-3. Wind Direction at Camera Site No. 3 (overlaid with ambient)





| DOC NO. | TWR-1754 | VOL | |
|---------|----------|------|----|
| SEC | | PAGE | 61 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-5. Barometric Pressure at Camera Site No. 3 (overlaid with ambient)

| DOC NO. | TWR-1754 | 6-1 | VOL | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 62 | |

Thickol CORPORATION

period prior to launch varied from 50° to 76° F. The normal temperature range experienced during the month of November is from a low of 62° F to a high of 73° F. The 51° F temperature, which occurred over a 6-hr period from midnight to 6:00 a.m. on 21 November, represents a minus 1- to minus 2-sigma deviation from the historical November temperature for the same timeframe. The windspeeds during this same timeframe were lower than historical conditions.

The local on-pad environment due to November historical predictions suggests an average 1°F temperature suppression while the ET is loaded and when winds are from the north. The actual wind direction during the LCC timeframe oscillated from the east to the south. From GEI assessments, there was no evidence of temperature suppression due to ET cooling effects.

4.8.3.5 <u>LCC</u>. No LCC thermal violations were noted. Measured GEI and heater sensor data for the end of the LCC timeframe (T-5 minutes) are presented in Table 4.8-5 and are compared with the LCC requirements.

The igniter heaters were activated for 18 hr, 20 minutes, and maintained the required temperatures. However, the igniter temperature control band was changed from $95^{\circ} \pm 5^{\circ}$ to $95^{\circ} \pm 1^{\circ}$ F. This resulted in more frequent cycling and better heater control. Cooldown, after heater shutoff, occurred over an approximate 7-hr, 13-minute period and resulted in T-5 minute igniter sensor temperatures from 73° to 76° F. These temperatures were only 5.5° F higher than the preactivation temperatures.

The six field joint heaters performed adequately and as expected with a 17° F sensor temperature range of 90° to 107° F during the LCC timeframe. All 24 field joint sensors recorded temperatures in the expected range. Prior to launch, an LCC contingency was created to lower the minimum redline temperature at any field joint from 85° to 69°F in the event of a complete heater failure. An IPR was written against the LH aft field joint heater voltage, which read 290 V instead of the nominal 209 V. This IPR was dispositioned when it was determined that the voltage must have been nominal because the current reading was nominal. In addition, the heater circuit breaker was not tripped as it would have been had the voltage actually been 290 V.

The SRB aft skirt purge operation was activated approximately 15.5 hr prior to launch. When the LCC timeframe began, nearly 6 hr later, all six case-to-nozzle joint

DOC NO. TWR-17546-1 VOL SEC PAGE 63

90407-5.12

Thickol CORPORATION

SPACE OPERATIONS

| <u>Component</u> | L-12 Hr <u>Predictions</u> * | November <u>Historical</u> | Actual <u>GEI</u> | LCC |
|---------------------------|---------------------------------|-------------------------------|----------------------|------------------|
| Igniter Joint RH LH | 73-77 73-77 | 86-88 86-88 | 73-74 74-76 | 66-123 66-123 |
| Field Joint | | | | |
| RH Forward | 96-102 | 97-103 | 98-100 | 85-122** |
| LH Forward | 96-102 | 97-103 | 94-97 | 85-122 |
| RH Center | 96-102 | 97-103 | 96-100 | 85-122 |
| LH Center | 96-102 | 97-103 | 98-101 | 85-122 |
| RH Aft | 96-102 | 97-103 | 93-98 | 85-122 |
| LH Aft | 96-102 | 97-103 | 97-102 | 85-122 |
| Nozzle/Case Joint | | | | |
| RH | 82-88 | 85-87 | 82-85 | 75-115 |
| LH | 82-88 | 85-87 | 82-82 | 75-115 |
| Flex Bearing Aft | | | | |
| End Ring | | | | |
| RH | 82-90 | 85-87 | 80-86 | NA-115 |
| LH | 82-88 | 85-87 | 83-83 | NA-115 |
| Case Acreage (deg) | | | | |
| RH 45 | | 64-65 | 66-67 | |
| 135 | | 64-65 | 64-67 | |
| 215 | | 67-68 | 64-70 | |
| 270 | 62-66 | 67-68 | 66-67 | 35-NA |
| 325 | | 64-65 | 66-67 | |
| LH 45 | | 65-66 | 64-67 | |
| 135 | | 64-65 | 66-67 | |
| 215 | | 64-65 | 66-69 | |
| 270 | 62-66 | 66-67 | 66-67 | 35-NA |
| 325 | | 66-67 | 64-65 | |
| Local Environment | | | | |
| Temperature | 59 | 65 | 66 | 38-99 |
| Wind Speed (kn) | | 12 | 6-8 | 24 |
| Wind Direction | | N | SW | SW-SE |
| Cloud Cover | | | Clear | |

Table 4.8-5. STS-33R T-5 Min On-Pad Temperatures (°F) (represents end of LCC timeframe)

*Predictions for anticipated launch window at T-5 min **Field joint sensor lower limit will drop from 85° to 69°F in the case of a complete heater failure

| DOC NO. | TWR-1754 | 6-1 | VOL | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 64 | |

Thickel corporation space operations

temperature readings were 75°F or above. There was concern that the minimum 75°F LCC temperature would not be reached prior to the LCC timeframe and appropriate action was taken to avoid this occurrence. At the end of the LCC timeframe the temperature range of the case-to-nozzle joint sensors was 82° to 85°F.

IR measurements taken by the IR gun during the T-3-hr ice/debris pad inspection were not reported. The STI temperature measurements were used along with the GEI measurements to monitor SRM surface temperatures. Temperatures varied between 64° and 66°F during the T-3-hr pad inspection for both STI and GEI temperatures.

4.8.3.6 <u>Prelaunch Thermal Data Evaluation</u>. Figures 4.8-6 through 4.8-10 show locations of the GEI and joint heater sensors for the igniter adapter, field joints, case acreage, nozzle region, and aft exit cone, respectively. Figures 4.8-11 through 4.8-40 present November historical predictions. These predictions are based on event sequencing, as specified in Table 4.8-6. Figures 4.8-41 through 4.8-97 show actual STS-33R countdown data.

The ambient temperature was 1- to 2-sigma below the historical value while the vehicle was on the pad. The ambient temperatures the day before launch were about 5°F colder than the normal November temperatures. Despite the actual and historical ambient temperature differences, the November historical on-pad predictions were quite accurate. Only in the ET attach and igniter joint regions did the historical predictions differ significantly from the actual GEI data. The LCC time period (T-6 hr to T-5 minutes) predictions were about 5°F higher than the actual data because the ambient temperatures were about 5°F lower than the historical values (Table 4.8-2). The T-5 minute historical versus actual temperature comparisons were in close agreement except for the actual igniter joint temperatures which were 12° to 14°F lower than the historical average (Table 4.8-5). The L-12-hr predictions of launch time conditions, which incorporate an environmental update for the last 24 hr prior to launch, were in good agreement with the GEI.

Postflight reconstructed predictions of GEI and igniter/field joint heater response were performed using the actual environmental data from the 24 hr prior to launch. A few examples of the predictions, compared with actual measured sensor data, are found in Figures 4.8-98 through 4.8-113. Reasonable agreement is apparent in all areas except the ET attach ring, the left SRB systems tunnel, and the case-to-nozzle

> DOC NO. TWR-17546-1 VOL SEC PAGE 65

Thickol corporation SPACE OPERATIONS




Figure 4.8-6. Forward Dome GEI


*One of two required for LCC compliance

DOC NO. TWR-17546-1 VOL SEC PAGE 66

REVISION

A025839a

Thickol CORPORATION SPACE OPERATIONS




A-25841a


PAGE

67


SEC







A025843a



Thickol CORPORATION SPACE OPERATIONS






Figure 4.8-12. RH SRM Forward Field Joint--Heater Sensor Temperature Prediction

| DOC NO. | TWR-17546-1 | | | VOL | |
|---------|-------------|------|---|-----|--|
| SEC | | PAGE | 7 | /1 | |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-13. RH SRM Center Field Joint--Heater Sensor Temperature Prediction




Figure 4.8-14. RH SRM Aft Field Joint--Heater Sensor Temperature Prediction

| DOC NO | TWR-1754 | 6-1 | VOL |
|--------|----------|------|-----|
| SEC | | PAGE | 72 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-15. RH SRM Nozzle Region--GEI Sensor Temperature Prediction






Figure 4.8-16. RH SRM Forward Case Acreage--GEI Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-18. RH SRM Aft Center Case Acreage--GEI Sensor Temperature Prediction

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 74 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-19. RH SRM Aft Case Acreage--GEI Sensor Temperature Prediction




Figure 4.8-20. RH SRM Forward Dome Factory Joint--GEI Sensor Temperature Prediction

TWR-17546-1 DOC NO PAGE SEC

75

VOL

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-21. RH SRM Forward Factory Joint--GEI Sensor Temperature Prediction




Figure 4.8-22. RH SRM Aft Factory Joint--GEI Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-23. RH SRM Aft Dome Factory Joint--GEI Sensor Temperature Prediction







Figure 4.8-24. RH SRM Tunnel Bondline--GEI Sensor Temperature Prediction


Thickol CORPORATION SPACE OPERATIONS













| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 78 |

Thickol CORPORATION SPACE OPERATIONS










Figure 4.8-28. LH SRM Center Field Joint--Heater Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS











Figure 4.8-30. LH SRM Nozzle Region--GEI Sensor Temperature Prediction


| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 80 |


Thickol CORPORATION SPACE OPERATIONS













Thickol CORPORATION SPACE OPERATIONS





BASED ON KSC MONTHLY HISTORICAL ENVIRONMENTAL DATA OCTOBER 78 76 AI 74 Ø, Ē ī//ì 5 72 TEMPERATURE 70 68 66 64 62 60 40 50 60 ZERO REF AT MIDNIGHT 70 80 20 30 TIME (HOURS) 10 0 •NOTE: ASSUMED TIME OF LAUNCH AT 68.0 HOURS INTO THE SCENARIO HEATERS START AT 56.16667 HOURS ET INDUCED ENVIRONMENT AT 59.8333 HOUR 215 AMBIENT

Figure 4.8-34. LH SRM Aft Case Acreage--GEI Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-35. LH SRM Forward Dome Factory Joint--GEI Sensor Temperature Prediction

BASED ON KSC MONTHLY HISTORICAL ENVIRONMENTAL DATA OCTOBER




Figure 4.8-36. LH SRM Forward Factory Joint--GEI Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-37. LH SRM Aft Factory Joint--GEI Sensor Temperature Prediction

BASED ON KSC MONTHLY HISTORICAL ENVIRONMENTAL DATA OCTOBER 78 ЪĠ 76 74 TEMPERATURE (F) 72 70 68 66 Δ //m 64 ß 尒 E G 62 60 80 40 50 60 ZERO REF AT MIDNIGHT 70 20 30 TIME (HOURS) 10 0 LOCATION (DEG) AT STA 1817.6 *NOTE: ASSUMED TIME OF LAUNCH AT 68.0 HOURS INTO THE SCENARIO HEATERS START AT 56.16667 HOURS ET INDUCED ENVIRONMENT AT 59.8333 HOUR

Figure 4.8-38. LH SRM Aft Dome Factory Joint--GEI Sensor Temperature Prediction

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-39. LH SRM Systems Tunnel Bondline--GEI Sensor Temperature Prediction




Figure 4.8-40. LH SRM ET Attach Region--GEI Sensor Temperature Prediction

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 85 |

Thickol corporation SPACE OPERATIONS

Table 4.8-6. STS-33R Analytical Timeframes for Estimating Event Sequencing of November Historical Joint Heater and GEI Sensor Predictions

| <u>Time (hr)</u> | Countdown Events in Analysis |
|------------------|---|
| 0:01 | 12:01 a.m. KSC EST (20 Nov 1989) |
| 44:00 | Igniter joint heater operation begins on 21 Nov 1989 (L-24 hr) |
| 54:10 | Aft skirt conditioning oepration begins on 22 Nov 1989 (T-13 hr, 50 min) |
| 56:10 | Field joint heater operation begins on 22 Nov 1989 (L-11 hr, 50 min) |
| 59:00 | Induced environments due to ET refrigeration effects begins on 22 Nov 1989 (approximately L-9 hr) |
| 61:10 | Igniter heater shutoff/start cooldown on 22 Nov 1989 (L-6 hr, 50 min) |
| 68:00 | Assumed time of Launch 22 Nov 1989, 8:00 p.m. KSC EST |
| | s 4.8-11 through 4.8-40 consist of a plus 22-hr scenario |

| DOC NO. | TWR-17546-1 | VOL | |
|---------|-------------|-----|----|
| SEC | PA | GE | 86 |

REVISION

90407-9.4

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-41. LH SRM Igniter Joint Temperatures (overlaid with ambient)




Figure 4.8-42. RH SRM Igniter Joint Temperature (overlaid with ambient)

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-43. LH SRM Forward Field Joint Temperature (overlaid with ambient)




Figure 4.8-44. RH SRM Forward Field Joint Temperature (overlaid with ambient)

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-45. LH SRM Center Field Joint Temperature (overlaid with ambient)




Figure 4.8-46. RH SRM Center Field Joint Temperature (overlaid with ambient)

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 89 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-47. LH SRM Aft Field Joint Temperature (overlaid with ambient)





Figure 4.8-48. RH SRM Aft Field Joint Temperature (overlaid with ambient)

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 90 |

Thickol CORPORATION SPACE OPERATIONS










Figure 4.8-50. RH SRM Case-to-Nozzle Joint Temperature (overlaid with ambient)

| DOC NO. | TWR-17546-1 | VOL | |
|---------|-------------|-----|--|
| SEC | PAGE | 91 | |

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-52. RH SRM Flex Bearing Aft End Ring Temperature (overlaid with ambient)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 92 |

Thickol CORPORATION SPACE OPERATIONS






Figure 4.8-53. LH SRM Systems Tunnel Bondline Temperature (overlaid with ambient)





Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-55. LH SRM Field Joint Temperature at 285 Deg (overlaid with ambient)





Figure 4.8-56. RH SRM Field Joint Temperature at 285 Deg (overlaid with ambient)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 94 |

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-58. LH SRM Case Acreage Temperature at Station 1091.5 (overlaid with ambient)

| DOC NO | TWR-17546-1 | | VOL | | |
|--------|-------------|------|-----|---|--|
| SEC | | PAGE | 9 | 5 | |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-59. LH SRM Case Acreage Temperature at Station 1411.5 (overlaid with ambient)






Figure 4.8-60. LH SRM Case Acreage Temperature at Station 1751.5 (overlaid with ambient)

DOC NO. TWR-17546-1 VOL SEC PAGE 96

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-62. RH SRM Case Acreage Temperature at Station 1091.5 (overlaid with ambient)

DOC NO. TWR-17546-1 VOL SEC PAGE 97

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-63. RH SRM Case Acreage Temperature at Station 1411.5 (overlaid with ambient)






Figure 4.8-64. RH SRM Case Acreage Temperature at Station 1751.5 (overlaid with ambient)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 98 |

Thickol CORPORATION SPACE OPERATIONS

REVISION ____











Figure 4.8-66. LH SRM Case Acreage Temperature at 135 Deg (overlaid with ambient)


| DOC NO. | TWR-17546-1 | | | VOL | |
|---------|-------------|------|---|-----|--|
| SEC | | PAGE | 9 | 9 | |

Thickol CORPORATION SPACE OPERATIONS









| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 100 |

Thickol CORPORATION SPACE OPERATIONS







Figure 4.8-69. LH SRM Case Acreage Temperature at 325 Deg (overlaid with ambient)








| DOC | NO. TWR-1754 | 6-1 | VOL |
|-----|--------------|------|-----|
| SEC | | PAGE | 101 |

Thickol CORPORATION SPACE OPERATIONS









DOC NO. TWR-17546-1 VOL SEC PAGE 102

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-73. RH SRM Case Acreage Temperature at 270 Deg (overlaid with ambient)




Figure 4.8-74. RH SRM Case Acreage Temperature at 325 Deg (overlaid with ambient)

| DOC NO | TWR-1754 | 6-1 | VOL |
|--------|----------|------|-----|
| SEC | | PAGE | 103 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-75. LH SRM ET Attach Region Temperature at Station 1511.0 (overlaid with ambient)




Figure 4.8-76. LH SRM ET Attach Region Temperature at Station 1535.0 (overlaid with ambient)

| DOC NO. TWR- | | VOL |
|------------------|------|-----|
| SEC | PAGE | 104 |

Thickol CORPORATION SPACE OPERATIONS





Figure 4.8-77. RH SRM ET Attach Region Temperature at Station 1511.0 (overlaid with ambient)





| | DOC NO. | TWR-17546-1 | VOL |
|----------|---------|-------------|-----|
| REVISION | SEC | PAGE | 105 |

Thickol CORPORATION SPACE OPERATIONS






Figure 4.8-79. LH SRM Forward Factory Joint Temperature (overlaid with ambient)





| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 106 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-81. LH SRM Aft Factory Joint Temperature at Station 1821.0 (overlaid with ambient)




Figure 4.8-82. RH SRM Forward Factory Joint Temperature (overlaid with ambient)

| DOC NO. | TWR-17546-1 | | VOL | |
|---------|-------------|------|-----|--|
| SEC | | PAGE | 107 | |

Thickol CORPORATION SPACE OPERATIONS






Figure 4.8-83. RH SRM Aft Factory Joint Temperature at Station 1701.9 (overlaid with ambient)






| DOC NO. | TWR-17546 | -1 | VOL |
|---------|-----------|------|-----|
| SEC | | PAGE | 108 |

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-86. LH SRM Nozzle Region Temperature at Station 1950.0 (overlaid with ambient)

| DOC NO. | TWR-17546- | 1 | VOL |
|---------|------------|-----|-----|
| SEC | P | AGE | 109 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-87. RH SRM Nozzle Region Temperature at Station 1845.0 (overlaid with ambient)






Figure 4.8-88. RH SRM Nozzle Region Temperature at Station 1950.0 (overlaid with ambient)

| | DOC NO. | TWR-17546-1 | VOL |
|---|---------|-------------|-----|
| _ | SEC | PAGE | 110 |

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-90. RH SRM Forward Field Joint Temperature (overlaid with heater voltage)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 111 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-91. LH SRM Center Field Joint Temperature (overlaid with heater voltage)






Figure 4.8-92. RH SRM Center Field Joint Temperature (overlaid with heater voltage)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 112 |

Thickol CORPORATION SPACE OPERATIONS










Figure 4.8-94. RH SRM Aft Field Joint Temperature (overlaid with heater voltage)

| DOC NO | TWR-1754 | 6-1 | | νοι |
|--------|----------|------|---|-----|
| SEC | | PAGE | 1 | 13 |

Thickol CORPORATION SPACE OPERATIONS








Figure 4.8-96. RH SRM Igniter Joint Temperature (overlaid with heater voltage)

| DOC | NO. TWR- | 17546-1 | VOL |
|-----|----------|---------|-----|
| SEC | | PAGE | 114 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-97. Aft Skirt Purge Temperature and Pressure (overlaid with ambient)

| DOC NO TWR-17546-1 | | VOL | | |
|--------------------|--|------|-----|--|
| SEC | | PAGE | 115 | |

Thickol CORPORATION SPACE OPERATIONS







Figure 4.8-98. LH SRM Igniter Joint Temperatures--Measured Versus Postflight Prediction (B06T7085A, igniter)








| DOC NO. | TWR-1754 | VOL | | |
|---------|----------|------|-----|--|
| SEC | | PAGE | 116 | |

Thickol CORPORATION SPACE OPERATIONS









| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 117 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-102. RH SRM Forward Field Joint Temperature--Measured Versus Postflight Prediction (B06T8063A, 285 deg)




Figure 4.8-103. RH SRM Case-to-Nozzle Joint Temperature--Measured Versus Postflight Prediction (B06T8049A, 180 deg)

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 118 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-104. LH SRM Systems Tunnel Bondline Temperature--Measured Versus Postflight Prediction (B06T7031A, aft)




Figure 4.8-105. RH SRM Case Acreage Temperature at Station 931.5--Measured Versus Postflight Prediction (B06T8010A, 135 deg)

| DOC NO | TWR-17546-1 | VOL |
|--------|-------------|-----|
| SEC | PAGE | 119 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-106. RH SRM Case Acreage Temperature at Station 931.5--Measured Versus Postflight Prediction (B06T8011A, 45 deg)




Figure 4.8-107. RH SRM Case Acreage Temperature at Station 931.5--Measured Versus Postflight Prediction (B06T8012A, 215 deg)

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 120 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-108. RH SRM Case Acreage Temperature at Station 931.5--Measured Versus Postflight Prediction (B06T8013A, 270 deg)




Figure 4.8-109. RH SRM Case Acreage Temperature at Station 931.5--Measured Versus Postflight Prediction (B06T8014A, 325 deg)

| DOC NO | TWR-17546-1 | VOL |
|--------|-------------|-----|
| SEC | PAGE | 121 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-110. LH SRM ET Attach Region Temperature at Station 1511.0--Measured Versus Postflight Prediction (B06T7027A, 274 deg)




Figure 4.8-111. RH SRM Aft Factory Joint Temperature at Station 1701.9--Measured Versus Postflight Prediction (B06T8032A, 150 deg)

| DOC NO | TWR-1754 | VOL | |
|--------|----------|------|-----|
| SEC | | PAGE | 122 |

Thickol CORPORATION SPACE OPERATIONS




Figure 4.8-112. RH SRM Aft Factory Joint Temperature at Station 1701.9--Measured Versus Postflight Prediction (B06T8033A, 30 deg)




Figure 4.8-113. RH SRM Aft Factory Joint Temperature at Station 1701.9--Measured Versus Postflight Prediction (B06T8034A, 270 deg)

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 123 |

Thickol CORPORATION SPACE OPERATIONS

joint regions. In the future, modeling improvements (environment and detail) need to be made in these regions.

Figure 4.8-114 shows the postflight FBMBT prediction created from reconstructed ambient temperature and aft skirt purge data. The prediction is not shown compared to the data.

4.8.3.7 Prelaunch Hardware Anomalies. There were no prelaunch hardware anomalies.

4.8.4 Conclusions and Recommendations

A summary of these recommendations was previously presented in Section 3.3. A more detailed explanation is provided here.

4.8.4.1 <u>Postflight Hardware Inspection</u>. Based on the quick-look external inspection, the SRM TPS performed adequately on STS-33R. No unexpected heating effects were noted.


4.8.4.2 <u>Debris</u>. No SRM violations of NSTS debris criteria were noted. The problem of losing the TPS cork caps covering the GEI cables due to poor cork bonds appears to have been alleviated. The K5NA closeout in place of the cork caps is performing excellently and as expected. All TPS cork pieces (generally small) are due to nozzle severance debris and/or splashdown loads and debris.

Stencils marking the GEI MSID locations have replaced the original labels with epoxy closeout. This will eliminate epoxy closeout as a debris concern.

During STS-34R ascent film review, indications suggested that there are debris particles coming out of the SRM nozzle prior to separation. The likelihood of these being chunks of propellant and/or insulation is still under investigation.

4.8.4.3 <u>GEI Prediction</u>. Additional model enhancement is recommended for certain motor regions in order to improve predictions. It should be noted, however, that the attainment of actual solar radiation data for recent STS flights has improved postflight predictions significantly. Submodel development effort for the areas of the ET attach ring, field joint, factory joint, systems tunnel, igniter, and nozzle regions is anticipated. These tasks would be encompassed by the global model. It is also recommended that all these models, including the 3-D SRM model, be made available for use at MSFC. This would allow Thiokol thermal personnel the opportunity to support launch countdowns at the HOSC with real-time PMBT, GEI, and component

> DOC NO. TWR-17546-1 VOL SEC PAGE 124



A025882a

Thickol CORPORATION SPACE OPERATIONS

prediction updates. This would also allow MSFC thermal personnel the same modeling capabilities.

4.8.4.4 <u>GEI Accuracy</u>. Gage range has been reduced on all of the joint heater sensors, resulting in better data resolution. It is recommended that the data collection accuracy of all GEI be increased by reducing the gage range and increasing the digital word length. The real fidelity of the KSC GSE could then be quantified and conceivably replaced if determined to be inadequate.

4.8.4.5 <u>Local Chilling</u>. Based on data from STS-28, STS-29R, and STS-30R local cooling does occur. Due to dissimilar ambient environments on launch day and the day prior to launch, it was not possible to determine the local chilling for this flight. It is recommended that a method be developed to accurately quantify the chill effect.

4.8.4.6 <u>Infrared Measurements</u>. STI data continue to be much more reliable than IR gun measurements. Comparisons with GEI are within acceptable margins for STI data but are questionable and unpredictable for IR gun data. Future efforts should be made in specifying locations for additional stationary STI cameras to assist in the eventual replacement of the outboard GEI. (Inboard GEI will need to be maintained since the STI cannot reach these blind regions.)

4.8.4.7 <u>Ice/Debris Team Support</u>. Thiokol personnel who support the ice/debris team from flight to flight should be maintained.

4.8.4.8 <u>SRM Hardware Thermal Assessment</u>. The SRM TPS design, from a thermal perspective, continues to suggest that the worst-case flight design environments of IVBC-3 and SRB reentry are for the most part overly conservative. An exception to this is the environment in the nozzle base region during reentry, when excessive nozzle flame heating and hydrazine fires are present. (See STS-29R final report, TWR-17542, Vol I). USBI is in the process of obtaining updated thermal environments for the base region. However, a followthrough needs to be made concerning the request.

4.9 MEASUREMENT SYSTEM PERFORMANCE--DEVELOPMENT FLIGHT INSTRUMENTATION (DFI) (FEWG report Paragraph 2.9.5)

Motor set 360L007 did not have any DFI installed. This section is reserved pending any future motors that incorporate DFI.

| DOC NO. | TWR-1754 | VOL | |
|---------|----------|------|-----|
| SEC | | PAGE | 126 |

Thickol corporation space operations

4.10 MEASUREMENT SYSTEM PERFORMANCE (FEWG report Paragraph 2.9.7)

4.10.1 Instrumentation Summary

Table 4.10-1 shows the location and amount of instrumentation for 360L007. Note that the igniter heater sensors are classified as GEI, whereas the field joint heater sensors are listed under a separate category. The OFI consists of the three OPTs which are used to determine the SRB separation time and provide the ballistic performance assessment.

| Table 4.10-1. | 360L007 | (STS-33R) | Instrumentation |
|---------------|---------|-----------|-----------------|
|---------------|---------|-----------|-----------------|

| | LH Motor | | RH Motor | | | | |
|-------------|------------|------------|----------------|------------|------------|----------------|--------------|
| | <u>OFI</u> | <u>GEI</u> | <u>Heaters</u> | <u>OFI</u> | <u>GEI</u> | <u>Heaters</u> | <u>Total</u> |
| Pressure | 3 | | | 3 | | | 6 |
| Temperature | | 54* | 12 | | 54* | 12 | 132 |


*Includes igniter heater sensors

4.10.2 GEI/OFI Performance

The GEI instrumentation on flight set 360L007 consisted of 108 temperature sensors, resistance temperature detectors (RTD) which monitor motor case temperature while the motor is on the pad. OFI consists of three OPTs on each forward dome. All GEI gages were functioning and all were within the allowable variation before launch. When the field joints were powered up, the LH aft heater voltage read nominal (204 V) for about 8 minutes, then jumped to 290 V. The voltage again returned to normal following igniter heater deactivation. No deviation in the heater current was observed during this time period. A bad solder joint was later dispositioned to be the problem in problem report No. PV6-147103. Troubleshooting showed the solder connections in the voltage transducer to be broken. The bad joints were resoldered and the system retested; the system is now functional. Upon further investigation, it was discovered that the solder joint in question was within the power supply of the instrument itself rather than in the electrical supply line as initially reported in the problem report. It is suspected that the momentary interruption of power (as the igniter heaters were shut down) restored continuity in the solder joint and returned the heater voltage to a nominal reading (Figure 4.10-1). (All GEI are disconnected by breakaway umbilicals at

| DOC NO. | TWR-1754 | WR-17546-1 | | |
|---------|----------|------------|-----|--|
| SEC | | PAGE | 127 | |

Thickol CORPORATION SPACE OPERATIONS



PAGE

128

SEC

Thickol CURPORATION SPACE OPERATIONS

SRB ignition and are not operative during flight.) Tables 4.10-2 and 4.10-3 are the GEI instrumentation lists and include gages which consistently read differently from surrounding gages. Figures 4.8-6 and 4.8-8 through 4.8-10 show GEI/OFI locations.

The OFI consists of three OPTs on each forward dome. The results of the 75 percent calibration (performed at T-1.5 hr) verified readings were well within the 740 to 804-psia allowable range and are listed in Table 4.10-4. B47P2302C was adjusted prior to the 75 percent calibration sequence to reflect a more nominal value. The transducer provided marginal readings at the beginning of the countdown due to the use of the generic launch processing system calibration offset of -11.3 psi rather than the actual OPT offset of -4.1 psi.

4.10.3 Heater Sensor Performance

Evaluation of the field joint heaters and heater sensor performance was discussed previously in Section 4.8.3. Table 4.10-5 and Figure 4.8-7 list the joint heater sensors and show the gage locations, respectively.

4.10.4 <u>S&A Rotation Times</u>

Table 4.10-6 includes the arm and safe delta times for the S&A functional test performed prior to the 360L007 (STS-33R) countdown. There was some concern that the S&As may perform slower than expected when a delayed rotation time of 2.6 sec was revealed during testing, causing an IPR (No. 33RV-0165) to be written. To close that IPR an additional S&A functionality test was performed. Table 4.10-7 lists the arm and safe times during the actual launch sequence (at T-5 minutes). All values are less that 2.0 sec.

4.11 RSRM HARDWARE ASSESSMENT (FEWG report Paragraph 2.11.2)

4.11.1 Insulation Performance

4.11.1.1 <u>Summary</u>. No gas paths through the case-to-nozzle joint polysulfide adhesive or any other anomalous joint conditions were identified. The internal insulation in all six of the case field joints also performed as designed, with no anomalous conditions. There were no recordable clevis edge separations (over 0.1 in.). No evidence of hot gas penetration through any of the acreage insulation or severe erosion patterns were identified. A complete insulation performance evaluation is in Volume III of this report.

> DOC NO. TWR-17546-1 VOL SEC PAGE 129

Table 4.10-2. GEI List--360L007A (LH)

| Instrument No. | Location (deg) | Station | Range (°F) | Case Location |
|-------------------|--|----------------|------------------------|------------------------|
| | | 534.5 | +200 | Forward segment |
| B06T7003A | $\begin{array}{c} 270\\ 45\end{array}$ | 694.5 | ± 200 ± 200 | Forward segment |
| B06T7004A | 45 135 | 694.5 694.5 | ± 200 | Forward segment |
| B06T7005A | | 694.5 694.5 | ± 200 | Forward segment |
| B06T7006A | 325 | | ± 200 ± 200 | Forward segment |
| B06T7007A | 270 | 694.5 | | |
| B06T7008A | 215 | 694.5 | ± 200 | Forward segment |
| B06T7009A | 90 | 778.98 | ±200 | Forward segment |
| Deemaaaaa | | 001 40 | 1000 | (systems tunnel) |
| B06T7010A | 45 | 931.48 | ±200 | Forward center segment |
| B06T7011A | 135 | 931.48 | ± 200 | Forward center segment |
| B06T7012A | 325 | 931.48 | ± 200 | Forward center segment |
| B06T7013A | 270 | 931.48 | ±200 | Forward center segment |
| B06T7014A | 215 | 931.48 | ±200 | Forward center segment |
| B06T7015A | 45 | 1091.48 | ±200 | Forward center segment |
| B06T7016A | 135 | 1091.48 | ± 200 | Forward center segment |
| B06T7017A | 325 | 1091.48 | ± 200 | Forward center segment |
| B06T7018A | 270 | 1091.48 | ± 200 | Forward center segment |
| B06T7019A | 215 | 1091.48 | ± 200 | Forward center segment |
| B06T7020A | 90 | 1258.98 | ± 200 | Aft center segment |
| | | | | (systems tunnel) |
| B06T7021A | 45 | 1411.48 | ± 200 | Aft center segment |
| B06T7022A | 135 | 1411.48 | ± 200 | Aft center segment |
| B06T7023A | 325 | 1411.48 | ± 200 | Aft center segment |
| B06T7024A | 270 | 1411.48 | ± 200 | Aft center segment |
| B06T7025A | 215 | 1411.48 | ± 200 | Aft center segment |
| B06T7026A | 220 | 1511 | ± 200 | ET attach ring |
| B06T7027A | 274 | 1511 | ± 200 | ET attach ring |
| B06T7028A | 320 | 1511 | ± 200 | ET attach ring |
| B06T7029A | 45 | 1535 | ±200 | Aft segment |
| B06T7030A | 135 | 1535 | ± 200 | Aft segment |
| B06T7031A | 90 | 1565 | ±200 | Aft segment |
| | | | | (systems tunnel) |
| B06T7032A | 30 | 1701.86 | ±200 | Aft segment |
| B06T7033A | 150 | 1701.86 | ± 200 | Aft segment |
| B06T7034A | 270 | 1701.86 | ± 200 | Aft segment |
| B06T7035A | 45 | 1751.5 | ±200 | Aft segment |
| B06T7036A | 135 | 1751.5 | ± 200 | Aft segment |
| B06T7037A | 325 | 1751.5 | ±200 | Aft segment |
| B06T7038A | 270 | 1751.5 | ±200 | Aft segment |
| B06T7039A | 215 | 1751.5 | ± 200 | Aft segment |
| B06T7040A | 30 | 1821 | ±200 | Aft segment |
| B06T7041A | 150 | 1821 | ± 200 | Aft segment |
| B06T7042A | 270 | 1821 | ±200 | Aft segment |
| B06T7043A | 0 | 1847 | ±200 | Flex bearing |
| B06T7043A | 0 | 1845 | ± 200 | Nozzle throat |
| B06T7044A | 120 | 1843 | ± 200 | Flex bearing |
| B06T7046A | 120 | 1845 | ± 200 | Nozzle throat |
| B06T7040A | 240 | 1845 | ± 200 | Flex bearing |
| B06T7048A | 240 240 | 1845 | ± 200 ± 200 | Nozzle throat |
| DUUI 1040A | 2 40 | 10-10 | 1200 | ATTURNO UNITAL |

REVISION

 DOC NO.
 TWR-17546-1
 VOL

 SEC
 PAGE
 130

90407-8.5

| Instrument <u>No.</u> | Location (deg) | <u>Station</u> | <u>Range (°F)</u> | Case Location |
|--------------------------|-------------------|----------------|-------------------|----------------------|
| B06T7049A | 0 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T7050A | 120 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T7051A | 240 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T7052A | 0 | 1950 | ±200 | Exit cone |
| B06T7053A | 120 | 1950 | ±200 | Exit cone |
| B06T7054A | 240 | 1950 | ±200 | Exit cone |
| B06T7085A | 184.5 | 486.4 | -4 to +158 | Igniter |
| B06T7086A | 355.5 | 486.4 | -4 to +158 | Igniter |

Table 4.10-2. GEI List--360L007A (LH) (Cont)

| DOC NO. | TWR-1754 | VOL | | |
|---------|----------|------|-----|---|
| SEC | | PAGE | 131 | - |

90407-8.6

Table 4.10-3 GEI List--360L007B (RH)

| Instrument | Location | | | |
|------------|--------------|----------------|------------------------|-------------------------------------|
| <u>No.</u> | <u>(deg)</u> | <u>Station</u> | <u>Range (°F)</u> | Case Location |
| B06T8003A | 270 | 534.5 | ±200 | Forward segment |
| B06T8004A | 135 | 694.5 | ±200 | Forward segment |
| B06T8005A | 45 | 694.5 | ±200 | Forward segment |
| B06T8006A | 215 | 694.5 | ±200 | Forward segment |
| B06T8007A | 270 | 694.5 | ±200 | Forward segment |
| B06T8008A | 325 | 694.5 | ±200 | Forward segment |
| B06T8009A | 90 | 778.98 | ±200 | Forward segment |
| | | | | (systems tunnel) |
| B06T8010A | 135 | 931.48 | ±200 | Forward center segment |
| B06T8011A | 45 | 931.48 | ±200 | Forward center segment |
| B06T8012A | 215 | 931.48 | ± 200 | Forward center segment |
| B06T8013A | 270 | 931.48 | ± 200 | Forward center segment |
| B06T8014A | 325 | 931.48 | ± 200 | Forward center segment |
| B06T8015A | 135 | 1091.48 | ±200 | Forward center segment |
| B06T8016A | 45 | 1091.48 | ±200 | Forward center segment |
| B06T8017A | 215 | 1091.48 | ± 200 | Forward center segment |
| B06T8018A | 270 | 1091.48 | ±200 | Forward center segment |
| B06T8019A | 325 | 1091.48 | ±200 | Forward center segment |
| B06T8020A | 90 | 1258.98 | ±200 | Aft center segment (systems tunnel) |
| B06T8021A | 135 | 1411.48 | ±200 | Aft center segment |
| B06T8022A | 45 | 1411.48 | ±200 | Aft center segment |
| B06T8023A | 215 | 1411.48 | ± 200 | Aft center segment |
| B06T8024A | 270 | 1411.48 | ±200 | Aft center segment |
| B06T8025A | 325 | 1411.48 | ± 200 | Aft center segment |
| B06T8026A | 320 | 1511 | ±200 | ET attach ring |
| B06T8027A | 266 | 1511 | ± 200 ± 200 | ET attach ring |
| B06T8028A | 220 | 1511 | ±200 | ET attach ring |
| B06T8029A | 135 | 1535 | ±200 | Aft segment |
| B06T8030A | 45 | 1535 | ± 200 | Aft segment |
| B06T8031A | 90 | 1565 | ± 200 ± 200 | Aft segment (systems tunnel) |
| B06T8032A | 150 | 1701.86 | ± 200 ± 200 | Aft segment |
| B06T8033A | 30 | 1701.86 | ± 200 ± 200 | Aft segment |
| B06T8034A | 270 | 1701.86 | ± 200 | Aft segment |
| B06T8035A | 135 | 1701.86 | ±200 | Aft segment |
| B06T8036A | 45 | 1751.5 | ± 200 | Aft segment |
| B06T8037A | 215 | 1751.5 | ± 200 | Aft segment |
| B06T8038A | 270 | 1751.5 | ± 200 | Aft segment |
| B06T8039A | 325 | 1751.5 | ± 200 | Aft segment |
| B06T8040A | 150 | 1821 | ± 200 | Aft segment |
| B06T8041A | 30 | 1821 | ± 200 ± 200 | Aft segment |
| B06T8042A | 270 | 1821 | ± 200 | Aft segment |
| B06T8043A | 180 | 1847 | ±200 | Flex bearing |
| B06T8044A | 180 | 1845 | ±200 | Nozzle throat |
| B06T8045A | 60 | 1847 | ±200 | Flex bearing |
| B06T8046A | 60 | 1845 | ± 200 | Nozzle throat |
| B06T8047A | 300 | 1847 | ± 200 | Flex bearing |
| B06T8048A | 300 | 1845 | ± 200 | Nozzle throat |
| DUCTOURIN | 000 | 1010 | 1400 | ATOLAIC UIITUUT |

| DOC NO. | TWR-1754 | 6-1 | | VOL | |
|---------|----------|------|---|-----|--|
| SEC | | PAGE | 1 | 32 | |

| Instrument <u>No.</u> | Location (deg) | Station | <u>Range (°F)</u> | Case Location |
|-----------------------|-------------------|---------|-------------------|----------------------|
| B06T8049A | 180 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T8050A | 60 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T8051A | 300 | 1876.6 | ±200 | Case-to-nozzle joint |
| B06T8052A | 180 | 1950 | ±200 | Exit cone |
| B06T8053A | 60 | 1950 | ±200 | Exit cone |
| B06T8054A | 300 | 1950 | ±200 | Exit cone |
| B06T8085A | 355.5 | 486.4 | -4 to +158 | Igniter |
| B06T8086A | 184.5 | 486.4 | -4 to $+158$ | Igniter |

Table 4.10-3 GEI List--360L007B (RH) (Cont)

| REVISION | DOC NO. | TWR-1754 | VOL | |
|----------|---------|----------|------|-----|
| | SEC | | PAGE | 133 |

_

-

-

_

Table 4.10-4. 75 Percent Calibration Results

| LH N | lotor | RH Motor | | | | | | |
|-----------|----------------|-----------|----------------|--|--|--|--|--|
| Gage | Reading (psia) | Gage | Reading (psia) | | | | | |
| B47P1300C | 765.8 | B47P2300C | 765.8 | | | | | |
| B47P1301C | 765.8 | B47P2301C | 769.8 | | | | | |
| B47P1302C | 767.8 | B47P2302C | 765.8 | | | | | |

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 134 |

90407-13.1

Table 4.10-5. Field Joint Heater Temperature Sensors

~

| Remarks | List | Forward heater | Forward heater | Forward heater | Forward heater | Center heater | Center heater | Center heater | Center heater | Aft heater | Aft heater | Aft heater | Aft heater | List | Forward heater | Forward heater | Forward heater | Forward heater | Center heater | Center heater | Center heater | Center heater | Aft heater | Aft heater | Aft heater | Aft heater |
|-----------------------------|---------------------------------------|----------------|----------------|----------------|----------------|---------------|---------------|---------------|---------------|------------|------------|------------|------------|---------------------------------------|----------------|----------------|----------------|----------------|---------------|---------------|---------------|---------------|------------|------------|------------|------------|
| <u>Digital</u> * | rre Sensor | 1 | 1 | 1 1 | 1 | 1 | 1 | 1 | 1 | Ч | 1 | | 1 | ure Sensor | 1 | 1 | 1 | 1 | 1 | | 1 | 1 | 1 | 1 | 1 | 1 |
| Required Accuracy (%) | r Temperati | +1 | +1 | +1 | +1 | +1 | +1 1 | +1 | +1 | + - | +1 1 | +1 | +1 | er Temperati | + +1 | +1 | +1 | +1 1 | +1 1 | + 1 | +1 1 | +1 | + 1 | +1 | +1 | +1 |
| Range (°F) | LH SRM Heater Temperature Sensor List | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | RH SRM Heater Temperature Sensor List | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 | -4 to +158 |
| Station | | 851.5 | 851.5 | 851.5 | 851.5 | 117.15 | 1171.5 | 1171.5 | 1171.5 | 1491.5 | 1491.5 | 1491.5 | 1491.5 | ЖI | 851.5 | 851.5 | 851.5 | 851.5 | 1171.5 | 1171.5 | 1171.5 | 1171.5 | 1491.5 | 1491.5 | 1491.5 | 1491.5 |
| Location (deg) | | 15 | 135 | 195 | 285 | 15 | 135 | 195 | 285 | 15 | 135 | 195 | 285 | | 15 | 135 | 195 | 285 | 15 | 135 | 195 | 285 | 15 | 135 | 195 | 285 |
| Instrument No. | | B06T7060 | B06T7061 | B06T7062 | B06T7063 | B06T7064 | B06T7065 | B06T7066 | B06T7067 | B06T7068 | B06T7069 | B06T7070 | B06T7071 | | B06T8060 | B06T8061 | B06T8062 | B06T8063 | B06T8064 | B06T8065 | B06T8066 | B06T8067 | B06T8068 | B06T8069 | B06T8070 | B06T8071 |

*Sampling rate given in samples per minute (SPM)

90407-7.3

REVISION

Thickol corporation space operations

Thickol CORPORATION SPACE OPERATIONS

.....

Table 4.10-6. S&A Arm and Safe Delta Times

SRB IGNITION SIA ROTATION - STG-33R (8475R9.070 - IGNITION SIA FUNCTIONAL TEST)

| E I | I | GMT 1 | | BHT I | RESPONSE 1 | | LEFT I | RIGHT I | LEFT I | RIGHT |
|-----|--------|---|--|--------------|--|--------------------|-------------------|---------------|----------------|--------------|
| | 1 | | E BSSH380011-LH ARM [| | BSSX1842X1-LH ARM I | | 2.627 1 | 1 | 1 | |
| 1 | I | 58936.848 | l BSSK4000X1-RH ARM 1 | 58937.755 1 | 855X2842X1-RH ARM [| 0.307 I | I | 6, 907-1 | I | |
| | I | 50945.685 | I BSSK308211-LH SAFE 1 | | BS51164311-UH SAFE I | | I | 1 | 8.748 I | |
| | 1 | 58945.968 | I BSSK400211-RH SAFE I | 58946.755 1 | 8551284311-84 SAFE 1 | 8.787 I | | 1 | l | 0,7 |
| | 1 | | I BSSK3866XI-LH ARM I | | BSSX1842X1-LH RRM I | | 1.068 1 | 1 | 1 | |
| 5 | I | | I 855K4890X1-RH ARM 1 | | BSSX2842X1-RH ARM | | I | 8.947 1 | 1 | |
| | 1 | | I BSSK3082X1-LH SAFE I | | BSSX1843X1-LH SAFE I | | 1 | i | 8.827 1 | |
| | ! | 61357.248 | I BSSK400211-RH SAFE 1 | 61357.955 1 | 8551284311-RH SAFE I | 0.707 1 | <u>ا</u> | 1 | | •.7 |
| _ | L | | 855K386811-LH ARM 1 | | BSSX1042X1-LH ARM I | | 0.787 1 | 1 | 1 | |
| 3 | 1 | | I B55K4000X1-RH ARM 1 | | BSSX2842X1-RH ARM I | | I | 0.867 1 | 1 | |
| | 1 | | I BOSKOBBEXT-LH SAFE I | | BSSI164311-LH SAFE I | | ļ | | 0.828 1 | |
| | | 61507.868 1 | 1 855K4082X1-RH SAFE 1 | 61366.733 1 | 8551284311-RH SAFE [| 8.867 I | <u>ا</u> | i | t | |
| | 1 | | I BSSK3806X1-LH ARM 1 | | BESTIBARTI-LH ANN 1 | | 8,787 1 | 1 | | |
| 4 | 1 | | I B55K4990X1-RH ARM I | | B22X2842X1-RH ARM I | | I | 0.827 I | - | |
| | 1 | | I BSSK300211-LH SAFE 1 | | BOSX1843X1-LH SAFE I | | 1 | 1 | | |
| | 1 | 61554.969 | I BSSK4002X1-RH SAFE I | 61555.755 1 | 855X2843X1-RH SRFE 1 | 0.785 1 | 1 | 1 | <u> </u> | 1. 7 |
| _ | 1 | | I BSSK3808X1-LH ARM I | | 8551184211-UH ARM 1 | | 8,987 1 | 1 | | |
| 5 | 1 | | I BSSK400011-RH ARM I | | BS5X2B42X1-RH ARH I | | I | 0.787 1 | | |
| | I I | | I BISKIBBEXI-UH SAFE I I BISKIBBEXI-RH SAFE I | | RSSX1843X1-LH SAFE I | | 1 | 1 | - | |
| | , | 000.00010 | 1 3.45 KM 11-2004 MC 1 | B1097.333 1 | BSS12843X1-RH SAFE I | 6.787 1 | 1 | | | •••• |
| | 1 | | 1 855K386811-LH ARM 1 | 61737.635 I | BSSX1842X1-LH ARH | 0.857 1 | 0.66 7 l | I | I | |
| 6 | 1 | | I B55K4000X1-RH ARM I | | 855x2842x1-NH ARM 1 | | I | 8, 747-1 | | |
| | 1 | | 1 BSSK3882X1-LH SAFE I | | BOSX1043X1-LH SPFE I | | 1 | 1 | | |
| | 1 | 61744.528 | I BSSK4082X1-RH SAFE I | 61745.355 I | BS512B4311-RH SAFE I | 0.82 7 I | 1 | 1 | 1 | 0.8 |
| | 1 | 61832.768 | I BSSK3808X1-LH ARM [| 61833.635 1 | BSSX1842X1-LH ARM 1 | 8.867 I | 9.85 7 I | 1 | 1 | |
| 7 | 1 | | BSSKACCOLL-RH ARM | | B22X2B42X1-BH RRN I | | 1 | 8,747 1 | | |
| | 1 | | I 855K3002X1-LH SAFE I I 855K4002X1-RH SAFE I | | B551184311-LH SAFE I B551284311-RH SAFE I | | I I | 1 | | |
| | | | | | | | | | | |
| - | ļ | | I BSSK3000XI-LH ARM I | | BSSX1842X1-LH ARM I | | 0.987 [| I | | |
| • | I | | I BSSK4000XI-RH ARN I I BSSK3002XI-LH SAFE I | | B55X2642X1-RH ARM 1 B55X1643X1-LH SAFE 1 | | 1 1 | 0.788 I 1 | | |
| | i | | I BOOKANNEXI-RH SAFE I | | BS5X2843X1-RH SAFE I | | i | i | | |
| | 1 | CIDEE 760 1 | I BSSK3888X1-LH ARM I | 61056 676 1 | 8551184211-LH ARM 1 | 0.868 1 | 0.86A I | | I | |
| 9 | i | | E BUSK4000X1-RH ARM I | | 853X2842X1-RH ARH 1 | | 4. cas 1 | 8.748 1 | | |
| - | i | | I BSSKJØBEXI-LH SAFE I | | BSSX1843X1-LH SAFE I | | i | 1 | | |
| | I | 62083.528 | I BSSK400211-RH SAFE 1 | 62004.336 I | B55X2B43X1-RH SAFE I | 0.628 I | 1 | 1 | 1 | 0.1 |
| | 1 | 62035.088 | I BSSK3808X1-LH ARM 1 | 62835.835 1 | 855X1842X1-LH ANH 1 | 8,747 1 | 8. 747 1 | | 1 | |
| 18 | 1 | 62935.328 | I BSSK4000X1-RH ARM I | | 8551284211-RH ARM 1 | | 1 | 9.82 7 | 1 | |
| | I | 62842.888 | i BSSK3002X1-LH SAFE I | 62843.635 1 | BSSX1843X1-LH SAFE I | 8.747 1 | 1 | I | 0.747 1 | |
| | 1 | 62843, 128 | I BSSKNBOZII-RH SAFE I | 62843.956 1 | B5512843X1-RH SAFE I | 8.828 1 | 1 | <u>ا</u> | I | •.1 |
| | | | | | **** | | | | | |
| | 1 | 52453.448 I | 855K3999X1-LH ARM | 62454.235 1 | 8551164211-LH ARM [| 8.787 1 | 8, 787-1 | 1 | 1 | |
| 11 | 1 | | BOSKARGOX1-RH ARM 1 | | 1 MRA HR-1154851268 | 8.867 1 | | 8.867 1 | | |
| | 1 | | BSSK3882X1-LH SAFE I | | BSSTIGA3X1-LH SAFE 1 | 8.867 [| 1 | 1 | | |
| | 1 | 1 6.001 100.79 | BSSK4002X1-RH SAFE I | 663982,133 I | 8551284311-RH SAFE 1 | 0.745 1 | | | 1 | 0.74 |
| | ! | | 855K3800X1-LH ARM E | | BTSX1842X1-LH ARM I | 0.787 I | 0.787 1 | 1 | 1 | |
| 12 | I | | BOSKARROXI-RH ARN I | | BOSIZBAZII-RH ARH | 0.668 1 | | 0.868 1 | 1 | |
| | 1 | | BSSK3082X1-LH SAFE I BSSK4882X1-RH SAFE I | | BSSX1843X1-UH SAFE I BSSX2843X1-9H SAFE I | 0.867 L 0.745 L | 1 1 | 1 | 8.867 I I | 9. 74 |
| | | | | | | | ••••••••••••••••• | | <u> </u> | |
| | 1 | | BSSK3000X1-LH ARM | | BSSX1842X1-LH ARM I | 8.867 L | 0.867 1 | 1 | 1 | |
| 13 | 1 | | BSSK4008X1-RH ARM I | | I WAR HR-IXSHOULD BE | 8. 707 1 | 1 | 0.707 1 | 1 | |
| | 1 | | BSSK3882X1-LH SAFE [| | BSSX1843X1-LH SAFE L | 0.788 l | 1 | ! | 9.788 1 | |
| | 1 | 626.1J. 368 I | BUCKA982X1-RH SAFE I | 525.94,735 I | BOSX2843X1-RH SAFE I | 0.787 t | 1 | 1 | I | 0.75 |
| | | the second se | | | | | | | | |

REVISION

ORIGINAL PAGE IS OF POOR QUALITY
 DOC NO
 TWR-17546-1
 VOL

 SEC
 PAGE
 136

Thickol CORPORATION SPACE OPERATIONS

Table 4.10-7. S&A Activity Times for 360L007 (STS-33R) at T-5 Minutes

Rotation Times* (arm command to arm indication)

| LH motor | 1.085 sec |
|----------|-----------|
| RH motor | 0.965 sec |

*The data sample rate is five times per second; therefore, the actual rotation times could be ± 0.200 sec sooner. The command times are as indicated

| REVISION | DOC NO. | TWR-17546-1 | VOL |
|----------|---------|-------------|-----|
| | SEC | PAGE | 137 |

Thickol CORPORATION SPACE OPERATIONS

4.11.1.2 External Insulation

Factory Joint Weatherseals. Two of the 14 factory joint weatherseals were unbonded. The LH aft segment stiffener-to-stiffener factory joint weatherseal was unbonded on the aft edge over approximately 70 percent of the circumference. The depth of the unbond measured from 0.8 to 0.9 in., which was to the pin retainer band. The unbond exhibited failure between the Chemlok[®] 205 and the case. There was no evidence of soot or heat effects on the unbonds. Paint was peeled from the case and attached to the edge of the weatherseal intermittently along the unbond. Corrosion was evident on the case under the peeled paint and under the unbonded weatherseal. A forward edge unbond was also noted near 310 deg; it measured 0.5 in. longitudinally by about 0.75 in. circumferentially.

Two insulation-to-case unbonds were identified on the forward edge of the RH forward segment cylinder-to-cylinder weatherseal. The weatherseal was unbonded at 160 deg for 14 in. to a depth ranging from 1.0 to 1.5 in. and at 135 deg for 11 in. to a depth of 0.1 inch. An aft edge unbond was noted at 210 deg and measured 0.6 in. longitudinally by about 1.0 in. circumferentially. All unbonds were at the Chemlok[®] 205-to-case interface.

All other factory joint weatherseals were in excellent condition. Normal small debris impact damage from reentry was evident intermittently on the aft edges of the weatherseals. Normal heat effects and discoloration were evident on the weatherseals of both aft segments. No significant areas of missing ethylene-propylene-diene monomer (EPDM) insulation were noted. The K5NA closeouts over the thermocouple wires were in good condition, with no indications of leaking water.

Stiffener Stubs and Rings. The insulation over the stiffener stubs and rings was in good condition. Normal heat effects and discoloration were evident on all surfaces in the 220- to 320-deg region. There were no significant areas of missing material. The EPDM was well bonded to the stiffener stubs and appeared to be well bonded to the stiffener rings. There was very little stiffener ring damage due to the high sea state at splashdown. The K5NA repair on the outboard edge of the forward stiffener stubs showed normal erosion and some small missing chunks intermittently around the circumference.

4.11.1.3 <u>Case-to-Nozzle Joints</u>. Based on the visual evaluation, both case-to-nozzle joints performed well. No gas paths through the polysulfide adhesive were identified.

DOC NO. TWR-17546-1 VOL SEC PAGE 138

Thickel corporation SPACE OPERATIONS

The disassembled joints showed the failure mode was 83 percent cohesive at disassembly in the LH polysulfide bondline, while the RH motor failed 89 percent cohesive. One small void was identified in the polysulfide adhesive at 109 deg on the LH case-to-nozzle joint, measuring 1.6 in. longitudinally by 0.25 in. wide. The void extended across the step but did not reach the wiper O-ring and was not penetrated by hot gas. Porosity was evident on both joints in the step region. The polysulfide vent slot fill on these motors was 32 percent and 84 percent for the LH and RH motors, respectively.

4.11.1.4 <u>Field Joints</u>. The internal insulation in all six field joints performed as designed, and no anomalous conditions were noted. J-leg tip contact was evident and the full circumference at each joint. Wet soot deposits extending down the bondline were noted on all of the field joints, generally to a depth of 0.2 to 0.7 in. radially into the bondline (outboard from the remaining material). The maximum depth of the wet soot was 1.35 in. on the RH center field joint. No heat effects were evident under the soot. Similar wet sooting has been noted on previous RSRM joints and is believed to occur at reentry or splashdown during joint flexing.

There were no clevis edge separations that were recordable (over 0.10 in. deep). Some tang edge separations were visible on the field joints, which will be evaluated further when the segments reach the Clearfield H-7 facility.

Clevis insulation cracks were noted on the radius region insulation on four out of six field joints. Some cracks were noted on prefire problem reports. The cracks did not have any effect on the function of the joint. Cracks and crazing will be further evaluated when the segments reach the Clearfield H-7 facility.

4.11.1.5 Ignition System Insulation. The igniter chamber insulation, as well as the igniter-to-case joint insulation for both igniter joints, showed normal erosion. One blowhole through the putty of the LH igniter adapter-to-case joint was present at 332 deg. The putty in the RH joint had no blowhole, and putty was extruded up to and on the adapter intermittently around the circumference. The igniter adapter-to-igniter chamber joint on the RH motor had a blowhole through the putty at 340 deg. Soot was in the putty from 315 to 350 deg but did not extend to the gasket. No adverse effects on joint performance resulted from either blowhole.

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 139 |

Thickol CORPORATION SPACE OPERATIONS

4.11.1.6 <u>Internal Acreage Insulation</u>. The acreage insulation, including the internal insulation over each of the factory joints, appeared in good condition. No evidence of hot gas penetration through the insulation was identified.

<u>Forward Segments</u>. The stress relief flap was present full circumference on both forward segments but was heat affected and eroded. The castable inhibitors were completely missing over the full circumference. The flaps had a scalloped appearance similar to that seen on previous RSRM flight forward segment flaps. The acreage insulation was in normal condition. The 11-point star pattern was easily distinguishable in the liner.

Both forward domes near the igniter boss were extensively inspected for excessive erosion and thin insulation. No gas paths or areas of abnormal erosion were identified. Preliminary insulation thickness measurements indicated adequate thermal SFs near the igniter boss. The insulation in this area was also removed, and no indication of folds or voids at the insulation-to-case interface were noted.

A final evaluation of the thermal performance of the insulation will be accomplished after internal thicknesses are measured at the Clearfield H-7 facility.

<u>Center Segments</u>. Only two inhibitor tears greater than 3 in. radially were noted in either aft center segment inhibitor stub. Both were noted on the RH aft center segment and measured 4.0 and 4.5 in. in length.

Some radial tears were noted in the forward center segment nitrile butadiene rubber (NBR) inhibitor stubs (nine on the LH motor and eight on the RH motor). The tears in the forward center segments ranged from 5.0 to 11.75 in. radially. The radial extent and frequency of the tears identified in the inhibitor stubs are within the range of tears noted on past flight motors. The edges of the tears demonstrated no material loss or erosion, indicating that the tears occurred after motor burn.

The flap and acreage insulation exhibited normal erosion. The castable inhibitor was completely missing on all four center segments. The flap and capture feature/EPDM was completely eroded to the flap bulb on the aft center segments and partially eroded on the forward center segments.

<u>Aft Segments</u>. Four to six small blisters were identified on the capture feature/ EPDM in the LH aft dome. The largest blister measured 1.75 in. axially by 0.25 in.

| DOC NO | TWR-17546-1 | | VOL |
|--------|-------------|------|-----|
| SEC | | PAGE | 140 |

circumferentially. This was significantly less than was seen on the previous flight set and is considered a normal condition.

The aft segment NBR inhibitor stubs exhibited scalloped erosion around the circumference. These areas had a very short inhibitor stub with intermittent inhibitor pieces taller than adjacent areas. This condition has been noted on all previous flight RSRM aft segments. This uneven erosion was not typically seen to this extent on HPM motors, but it does not appear to be a problem. There were no tears in either inhibitor. The aft segment acreage insulation was in normal condition. There were no gouges, separations, cuts, missing material, excessive erosion, or other areas of blisters.

4.11.2 Case Component Performance

4.11.2.1 <u>Summary</u>. Evaluation of the steel case indicated the hardware performed as expected during flight. Complete case evaluation results are in Volume II of this report.

4.11.2.2 <u>Stiffener Stubs</u>, <u>Stiffener Rings</u>, and <u>ET Attach Stubs</u>. The stiffener rings and case stubs had no apparent water impact damage. No cracks or warpage was found. No deformed boltholes were observed. No web cracks were noted and no bolts were missing or elongated.

Based on missing Instafoam, the cavity collapse load centerlines for the RH and LH motors were estimated to be at 340 and 100 deg, respectively.


4.11.2.3 <u>Field Joints</u>. The case field joint surface conditions were as expected. Fretting ranged from none on one joint to locally medium on two joints. The RH center field joint had no fretting. The LH center and RH forward joints had the worst. Figure 4.11-1 provides a subjective summary of the fretting.

4.11.2.4 <u>Case-to-Nozzle Joint</u>. The case-to-nozzle joint on both motors was in excellent condition. There were no signs of metal damage to any of the sealing surfaces or boltholes, and there was no heat-affected metal, corrosion, or damaged bolts.

4.11.2.5 <u>Igniter-to-Forward Dome Joint</u>. The igniter-to-forward dome joint on both motors was in excellent condition. There were no signs of metal damage to any sealing surface or boltholes, and there was no heat-affected metal, corrosion, or damaged bolts.

| DOC NO. | TWR-1754 | 6-1 | VOL |
|---------|----------|------|-----|
| SEC | | PAGE | 141 |

Thickol CORPORATION SPACE OPERATIONS



REVISION _____ DOC NO. TWR-17546-1 VOL SEC PAGE 142

Thickol CORPORATION

4.11.2.6 Factory Joint External Surfaces. Light corrosion was found at the weatherseal unbond location on the RH forward cylinder-to-cylinder joint. Medium to heavy corrosion was observed under the unbonded weatherseal on the LH aft stiffener-tostiffener joint. Light corrosion was also seen on the RH forward dome-to-cylinder joint. No corrosion was seen on any other joints.

4.11.2.7 <u>Miscellaneous Case Surfaces</u>. All cork, K5NA, cables, and gauges associated with the GEI were removed at Hangar AF because of corrosion pits observed on previous case segments from an instrumentation spot band. These spot bands are for lightning protection and use silver-filled epoxy (Eccobond 56C). The instrumentation is then covered with K5NA and Hypalon paint. During SRB reentry, the Hypalon paint blisters, allowing sea water to soak into the K5NA, producing a galvanic cell between the case and the silver-filled epoxy. The case surfaces under the removed GEI runs had light corrosion. No pits were observed at any GEI spot bond location.

4.11.2.8 <u>OPTs, Special Bolts, and Special Bolt Plugs</u>. Soot deposits were observed on the threads on the tip of the OPTs and up to the primary seals. The physical condition of the OPTs was excellent.

All LH and RH igniter special bolts experienced typical light sooting up to the primary O-ring and on the ends of the special bolts.

4.11.2.9 <u>Vent Port and Leak Check Port Plugs</u>. The metal surfaces of the plugs were free of soot, debris, and corrosion.

4.11.2.10 <u>Joint Heaters</u>. Both RH and LH igniter heaters were evaluated before and after removal. No discoloration or warping was noted, indicating proper installation and nominal performance.

4.11.3 Seals Performance

4.11.3.1 <u>Summary</u>. Evaluation of the field joints indicated the internal seals performed as expected during flight. All internal seals, including the redesigned field joint seals and case-to-nozzle joint seals, appeared to have performed well, with no hot gas leakage evident. A complete evaluation is in Volume II of this report.

4.11.3.2 Exit Cone Field Joint. The assessment team was not notified of exit cone disassembly, so the in-groove inspection of the O-rings and joint area was not done. The LH primary O-ring was damaged at about 0 deg with 30 in. of O-ring missing. At splashdown, the glass-cloth phenolic (GCP) delaminated in the primary O-ring groove

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 143 |

Thickol CORPORATION SPACE OPERATIONS

from 292 through 0 to 4 deg, probably causing the O-ring damage. The metal surfaces of both aft exit cones had intermittent medium corrosion on the outer edge of the forward face and between the O-ring grooves. The RH aft exit cone had a concentration of medium corrosion between 115 and 155 deg.

4.11.3.3 <u>Case Field Joints</u>. Inspection of the field joint seals revealed no anomalous conditions. All motor pressure was contained by the insulation J-joint. There was no corrosion or damage found on any of the O-ring sealing surfaces. The V₂ filler was also found to be in excellent condition. None of the vent ports were obstructed by the V_2 filler. The grease application was nominal.

4.11.3.4 OPT, Special Bolts, and Special Bolt Plug Seals. There was no evidence of gas leakage past the primary seals on any of the OPTs. The LH and RH primary seals saw pressure but there was no soot observed on them. Soot deposits were observed on the tips of the transducer threads and up to the primary seals. All of the seals performed nominally.

Special bolt primary seals were in excellent condition and performed as expected. Special bolt plug seals were also in excellent condition. All LH and RH igniter special bolts experienced typical light soot up to the primary O-ring and on the end of the special bolts.

4.11.3.5 Ignition System Joint. The igniter removal on this flight set was performed using dynamometers and guide pins in order to monitor the loads involved and minimize the putty disturbance during disassembly.

The seals of the S&A, igniter outer, and igniter inner gaskets revealed no erosion or heat effect.

The LH igniter outer putty had a blowhole in the outer putty at 332 deg. Soot was observed on the entire circumference of the inner edge of the outer gasket. Soot to the primary seal was observed on the forward face from 330 to 0 deg. Soot to the primary seal was also observed on the aft face from 270 to 279 deg. No soot was observed past the primary seal on either face. Two very small dimples (less than 0.003 in. in diameter) were observed on the forward face. One was on the primary seal at 235 deg and the other was on the secondary seal at 144 deg. Also, traces of touchup paint were seen on the environmental seal outer edge.

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 144 |

Thickol CORPORATION SPACE OPERATIONS

The LH inner gasket had soot on the outside edge of the aft gasket face from 210 through 0 to 130 deg. Soot did not reach the outer seal. No soot was observed on the forward face. Putty was observed on the inner edge from 20 to 65 deg. No putty was on the forward or aft gasket face.

The RH igniter outer putty had no blowhole. Putty was on the outer gasket inner edge from 18 to 101 and from 207 to 270 deg. No putty was observed on either forward or aft gasket face.

The RH inner putty had a terminated blowhole at 340 deg. No soot reached the inner gasket. A small depression was observed on the outer seal aft face crown at 10 deg. It was approximately 0.002 in. deep by 0.004 in. wide. Detailed inspection verified that the flaw was within the acceptance criteria of 0.002 in. deep by 0.005 in. wide. Putty was on the outside gasket diameter intermittently around the entire circumference.

The LH and RH igniter inner joint packing with retainers (Stat-O-Seals[®]) were in good condition. None had any apparent damage.

4.11.3.6 <u>Case-to-Nozzle Joint</u>. The overall joint condition was excellent on both motors. Motor pressure was halted at the polysulfide adhesive, leaving the fluoro-carbon O-rings untouched. No obvious disassembly damage was noted on the O-rings.

The grease on the RH fixed housing sealing surface was light to nonexistent. Three radial bolthole plugs were damaged on disassembly.

The LH and RH case-to-nozzle joint Stat-O-Seals were in good condition, with no disassembly damage.

4.11.3.7 <u>Vent Port Plugs</u>. The case field joint and case-to-nozzle joint vent port plugs and seals on each motor were in excellent condition. The vent port plug O-rings showed no evidence of heat effects. The fluorocarbon O-rings, glands, and metal surfaces of the plugs were free of soot, debris, and corrosion.

4.11.3.8 <u>Leak Check Port Plugs</u>. The leak check port plugs and seals on the LH and RH motors in the case field joints, case-to-nozzle joints, aft exit cone joints, and the ignition system joints were in good condition. None of the leak check port plug O-rings showed any evidence of heat effects. The fluorocarbon O-rings, glands, and metal surfaces of the plugs were free of soot, debris, and corrosion.

| DOC NO. | TWR-17546-1 | | VOL | |
|---------|-------------|------|-----|----|
| SEC | | PAGE | 1 | 45 |

Thickol CORPORATION SPACE OPERATIONS

4.11.3.9 Internal Nozzle Seals

Forward End Ring-to-Nose Inlet Housing Joint. Inspection of the joint did not reveal any obvious pressure paths through the RTV/adhesive of the joint interface. Scallopshaped sooting of the grease was observed around the full circumference of the joint about halfway between the edge of the aluminum housing and the primary O-ring groove situated between boltholes. Heavy sooting was observed at 96 through 138 and 228 through 318 deg on the LH motor and 334 through 0 through 18 and 120 through 150 deg on the RH motor. No soot or blowby was observed up to or past the primary O-ring on the LH motor, but light soot was seen on the RH motor to the primary Oring at 126 through 162 and 198 through 258 deg. No soot or evidence of blowby was observed past the primary on the RH motor. No apparent damage to the primary or secondary O-rings was found during preliminary inspection, and the sealing surfaces showed no assembly or disassembly damage. Typical light corrosion was observed intermittently on the secondary O-ring sealing surface of the RH motor.

<u>Nose Inlet Housing-to-Throat Support Housing</u>. A pressure path through the RTV at 140 deg was noted on the LH motor. No soot or evidence of blowby was present past the primary O-ring. A terminated void in the RTV was noted at 100 deg on the RH motor. No soot or evidence of blowby was present up to or past the primary O-ring. No apparent damage was found during preliminary inspection of the primary or secondary O-rings. Inspection of the sealing surfaces revealed no signs of damage. Typical light corrosion was found intermittently on the nose inlet housing at the adhesive-to-metal interface at 90 through 140 deg on the LH motor and 95 through 105 and 228 through 318 deg on the RH motor.

Forward Exit Cone-to-Throat Support Housing. Inspection of the joint revealed no pressure paths through the RTV backfill. No apparent damage to the primary or secondary O-rings was found during preliminary inspection and the sealing surfaces showed no assembly/disassembly damage. No corrosion was found on any of the joint sealing surfaces. Typical light corrosion was found on the bevel of the throat of the RH motor from 2.5 to 5 deg. This corrosion coincides with the bondline separations on the forward exit cone.

<u>Fixed Housing-to-Aft End Ring Joint</u>. Inspection of the joint revealed no pressure paths through the RTV. The RTV was observed up to the land forward of the primary O-ring at 40 through 127.5 deg on the LH motor. RTV was observed up to the

| DOC NO. | TWR-17546-1 | | VOL |
|---------|-------------|------|-----|
| SEC | | PAGE | 146 |

Thickol CORPORATION SPACE OPERATIONS

primary O-ring at 103 through 133, 145 through 165, and 245 through 310 deg on the RH motor. No damage was found during preliminary inspection of the primary and secondary O-rings and the sealing surfaces showed no signs of damage. Typical light corrosion was observed on the inside diameter lip of the aft end ring.

4.11.4 Nozzle Performance

4.11.4.1 <u>Summary</u>. Postflight evaluation indicated both nozzles performed as expected during flight. Phenolic erosion was smooth and normal. Complete evaluation is in Volume V of this report.

4.11.4.2 <u>360L007A (LH) Nozzle</u>

<u>Aft Exit Cone.</u> The aft exit cone was severed by the LSC during parachute descent. The radial cut through the GCP appeared nominal, with no anomalies observed. Some carbon-cloth phenolic (CCP) liner was missing and portions of the GCP insulator were torn and delaminated. These are typical postflight phenomena that occur during exit cone severance and at splashdown. The exposed GCP plies showed no signs of heat effect.

The only observation outside the RSRM nozzle experience was the thermal curtain retainer screw helical coil inserts on the compliance ring. Thirty-six of the 192 required on the nozzle were pulled out above the outside diameter (OD) surface of the compliance ring.

The actuator brackets showed only minor paint scratches, scrapes, and chips due to actuator removal. The primer remained intact and no metal damage or loose bolts were observed.

Four separations were observed between the polysulfide and the aft exit cone shell. Postflight measurements of the polysulfide groove radial width showed that the GCP insulator did not pull away from the aluminum shell during cooldown.

The RTV backfill was below the joint charline on the nozzle 360 deg circumferentially. No voids were noted. RTV reached the primary O-ring for 70 percent of the joint circumference.

<u>Forward Exit Cone Assembly</u>. The CCP liner was intact from 110 to 345 deg, with smooth erosion for the forward 11 inches. Moving aft, the next 17 in. had missing

| DOC NO. | TWR-17546-1 | | | VOL |
|---------|-------------|------|---|-----|
| SEC | | PAGE | 1 | .47 |

90407-5.26

Thickol CORPORATION SPACE OPERATIONS

CCP, but no heat effect to the GCP. The aft 6 in. had CCP intact with typical dimpled erosion approximately 0.1 in. deep radially.

<u>Throat Assembly</u>. The throat assembly had smooth erosion on the throat inlet and the forward 9 in. of the throat ring, with typical rippled erosion on the aft 7 inches. Typical inlet ring forward edge postburn CCP wedgeouts were found intermittently around the circumference, measuring 0.70 in. axially by 1.0 in. radially.

<u>Nose Inlet Assembly</u>. The -503 ring had smooth erosion and a large number of impact marks, typically 0.2 to 0.3 in. in diameter and 0.05 to 0.1 in. deep. Some marks had slag in them. The -504 ring had smooth erosion, no impact marks and no wedgeouts or pop-ups.

The nose cap had smooth erosion with minor wash areas on the forward 12 in. (0.05 in. deep radially). Slag deposits were noted on the forward 18 in. from 90 to 270 deg. Typical postburn impact marks on the forward end (some with slag deposits) were noted intermittently around the circumference. Typical postburn wedgeouts of charred CCP were found on the aft 2 in. intermittently around the circumference.

<u>Cowl Ring</u>. The cowl ring showed typical ridged erosion (0.06 in. deep). This is due to the low ply angle. Postburn wedgeouts of charred CCP were observed on the aft 2.5 in. from 18 to 260 deg, measuring 1.0 in. deep radially.

<u>Outer Boot Ring (OBR)</u>. The OBR had postburn wedgeouts on the forward 1.5 in. of the ring from 105 to 118 and from 239 to 265 deg. They were 0.7 in. deep radially. The same area showed popped up, charred CCP plies intermittently around the circumference. There were typical postburn delaminations in the aft end along the 0 deg ply wraps. These were 0.6 to 1.9 in. deep axially. The aft tip adjacent to the flex boot was typically fractured and wedged out.

<u>Fixed Housing Assembly</u>. The fixed housing insulation erosion was smooth and uniform. The forward 2 in. of the fixed housing showed typical postburn wedgeouts of charred CCP intermittently around the circumference with some slag deposits on exposed plies. The maximum radial depth of the wedgeouts was 1.5 inches.

4.11.4.3 <u>360L007B (RH) Nozzle</u>

<u>Aft Exit Cone</u>. The aft exit cone was severed by the LSC during parachute descent. The radial cut through the GCP appeared nominal, with no anomalies observed.

| DOC NO. | TWR-17546-1 | VOL |
|---------|-------------|-----|
| SEC | PAGE | 148 |

Thickol CORPORATION

All of the CCP liner was missing and portions of the GCP insulator were torn and delaminated. These are typical postflight phenomena that occur during exit cone severance and at splashdown. The exposed GCP plies showed no signs of heat effect.

The only observation outside the RSRM nozzle experience was the thermal curtain retainer screw helical coil inserts on the compliance ring. Eighty-one of the 192 required were pulled out above the OD surface of the compliance ring.

The actuator brackets showed only minor paint scratches, scrapes, and chips due to actuator removal. The primer remained intact and no metal damage or loose bolts were observed.

Two separations were observed between the polysulfide and the aft exit cone shell. Postflight measurements of the polysulfide groove radial width showed that the GCP insulator did not pull away from the aluminum shell during cooldown.

The RTV backfill was below the joint charline on the nozzle 360 deg circumferentially. No voids were noted. RTV reached the primary O-ring for 95 percent of the circumference.

Forward Exit Cone Assembly. The CCP liner was intact, with smooth erosion for the forward 10 in. and with one 0.75-in.-wide axial wedgeout at the forward end from 300 to 330 deg. Moving aft, the next 13 in. had missing CCP, but no heat effect to the GCP. The aft 12 in. had CCP intact with typical dimpled erosion approximately 0.1 in. deep radially.

<u>Throat Assembly</u>. The throat assembly had smooth erosion on the throat inlet and the forward 10 in. of the throat, with typical rippled erosion on the aft 6 in. of the throat ring. There were two erosion wash areas found on the aft 6 in. of the throat ring at 200 and 300 deg measuring approximately 3 in. circumferentially by 6 in. axially by 0.16 in. radially. There were no wedgeouts or pop-ups.

<u>Nose Inlet Assembly.</u> The -503 ring had smooth erosion and intermittent minor impact marks, typically 0.3 in. in diameter and 0.05 in. deep. The -504 ring had smooth erosion, no impact marks, and no wedgeouts or pop-ups.

The nose cap had smooth erosion with minor wash areas on the forward 8 in. (0.05 in. deep radially). Slag deposits were noted on the forward 18 in. from 270 through 0 to 90 deg. Typical postburn impact marks on the forward end (some with

> DOC NO TWR-17546-1 VOL SEC PAGE 149

90407-5.28

Thickol CORPORATION SPACE OPERATIONS

slag deposits) were noted intermittently around the circumference. Typical postburn wedgeouts of charred CCP were found on the aft 2 in. intermittently around the circumference.

<u>Cowl Ring</u>. The cowl ring showed typical ridged erosion (0.1 in. deep) on the forward 5 inches. Wedgeouts were found on the aft 2.5 in. from 260 through 0 to 56 deg. They measured 1.0 in. deep radially.

<u>Outer Boot Ring</u>. The OBR had popped plies on the forward 1.3 in. from 4 to 10 deg. No wedgeouts were noted. Typical postburn delaminations were found in the aft end along the 0-deg ply wraps and were 0.5 in. deep. Ninety-four percent of the aft tip adjacent to the flex boot was typically fractured and wedged out.

<u>Fixed Housing Assembly</u>. The fixed housing insulation erosion was smooth and uniform. The forward 2 in. of the fixed housing showed typical postburn wedgeouts of charred CCP intermittently around the circumference, with some slag deposits on exposed plies. The maximum radial depth of the wedgeouts was 0.5 inches.

| PAGE 150 | |
|----------|----------|
| | PAGE 150 |

REVISION

Thickol CORPORATION

DISTRIBUTION

| <u>Recipient</u> | No. of <u>Copies</u> | Moil St. |
|--------------------------|-------------------------|------------------|
| N. Black | 1 | <u>Mail Stop</u> |
| R. Buttars | 1 1 | L71 |
| A. Drendel | 1 | L63 |
| F. Duersch | 1 | L63 |
| D. Garecht | 2 | 851 |
| R. George | ĩ | L71 |
| S. Hicken B. Jurewicz | ī | L62 |
| J. Keller | 1 | L62 |
| R. Mackley | 1 | L70 |
| B. McQuivey | 1 | E62C |
| T. Morgan | 1 | L61 L72 |
| L. Nelsen | 1 | L72 L52 |
| R. Papasian | 1 | L52 L61C |
| J. Passman | 45 | E62 |
| C. Richards | 1 | L62 |
| G. Ricks | 1 | L63 |
| K. Sanofsky | 1 | L71 |
| J. Sutton | 1 1 | 851 |
| Print Crib | 5 | L72 |
| Data Management | 5 | Q51B1 |
| | 0 | L72B |

| DOC NO. |
|---------|
| SEC |
| |

TWR-17546-1

PAGE

VOL

151

REVISION _____ 90407-14.1

-