

# **INDEPENDENT ORBITER ASSESSMENT**

## **ANALYSIS OF THE REACTION CONTROL SYSTEM Vol. 1 of 3**

**19 JANUARY 1987**



MCDONNELL DOUGLAS ASTRONAUTICS COMPANY  
HOUSTON DIVISION

SPACE TRANSPORTATION SYSTEM ENGINEERING AND OPERATIONS SUPPORT

WORKING PAPER NO. 1.0-WP-VA86001-27

INDEPENDENT ORBITER ASSESSMENT  
ANALYSIS OF THE REACTION CONTROL SYSTEM

19 January 1987

This Working Paper is Submitted to NASA under  
Task Order No. VA86001, Contract NAS 9-17650

PREPARED BY:

V.J. Burkemper  
V.J. Burkemper  
Lead Electrical Analyst  
Independent Orbiter  
Assessment

PREPARED BY:

D.J. Paul  
D.J. Paul  
RCS Subsystem Lead  
Independent Orbiter  
Assessment

PREPARED BY:

W.A. Hauffler  
W.A. Hauffler  
Electrical Analyst  
Independent Orbiter  
Assessment

APPROVED BY:

G.W. Knori  
G.W. Knori  
Technical Manager  
Independent Orbiter  
Assessment

PREPARED BY:

R.A. O'Donnell  
R.A. O'Donnell  
Electrical Analyst  
Independent Orbiter  
Assessment

APPROVED BY:

W.F. Huning  
W.F. Huning  
Deputy Program Manager  
STSEOS





CONTENTS		Page
1.0	EXECUTIVE SUMMARY	1
2.0	INTRODUCTION	4
2.1	Purpose	4
2.2	Scope	4
2.3	Analysis Approach	4
2.4	RCS Ground Rules and Assumptions	5
3.0	SUBSYSTEM DESCRIPTION	6
3.1	Functional and Hardware Description	6
3.2	Redundancy Management	32
3.3	Interfaces and Locations	40
3.4	Hierarchy	41
4.0	ANALYSIS RESULTS	42
4.1	Analysis Results - Helium Pressurization Subsystem	53
4.2	Analysis Results - Propellant Storage and Distribution Subsystem	53
4.3	Analysis Results - Thruster Subsystem	54
4.4	Analysis Results - Electrical Power Distribution and Control System	55
5.0	REFERENCES	57
APPENDIX A ACRONYMS		A-1
APPENDIX B DEFINITIONS, GROUND RULES, AND ASSUMPTIONS		B-1
B.1	Definitions	B-2
B.2	Project Level Ground Rules and Assumptions	B-4
B.3	RCS Ground Rules and Assumptions	B-6
APPENDIX C DETAILED ANALYSIS		C-1
APPENDIX D POTENTIAL CRITICAL ITEMS		D-1

## List of Figures

		Page
Figure 1	- RCS OVERVIEW ANALYSIS SUMMARY	2
Figure 2	- REACTION CONTROL SYSTEM (RCS)	7
Figure 3	- FORWARD RCS HARDWARE BREAKDOWN HIERARCHY	8
Figure 4	- AFT RCS HARDWARE BREAKDOWN HIERARCHY	9
Figure 5	- FORWARD RCS EPD&C BREAKDOWN HIERARCHY	10
Figure 6	- AFT RCS EPD&C BREAKDOWN HIERARCHY	11
Figure 7	- FORWARD RCS SCHEMATIC	12
Figure 8	- AFT RCS SCHEMATIC	13
Figure 9	- HELIUM ISOLATION VALVE	15
Figure 10	- HELIUM PRESSURE REGULATOR ASSEMBLY	17
Figure 11	- QUAD CHECK VALVE ASSEMBLY	19
Figure 12	- AFT AND FORWARD RCS PROPELLANT TANKS	20
Figure 13	- PRESSURE RELIEF VALVE ASSEMBLY	21
Figure 14	- AC MOTOR VALVE	23
Figure 15	- VERNIER MANIFOLD ISOLATION VALVE	26
Figure 16	- VERNIER AND PRIMARY THRUSTERS	28
Figure 17	- PRIMARY AND VERNIER THRUSTER VALVES	29
Figure 18	- INJECTOR HEAD ASSEMBLY	31

## List of Tables

		Page
Table 3 - I	- MANIFOLD STATUS	38
Table 3 - II	- MANIFOLD SETS FOR POWER FAILURE DETERMINATION	38
Table I	- SUMMARY OF IOA FAILURE MODES AND CRITICALITIES (FRCS HW)	43
Table II	- SUMMARY OF IOA FAILURE MODES AND CRITICALITIES (ARCS HW)	44
Table III	- SUMMARY OF IOA FAILURE MODES AND CRITICALITIES (FRCS EPD&C)	45
Table IV	- SUMMARY OF IOA FAILURE MODES AND CRITICALITIES (ARCS EPD&C)	47
Table V	- SUMMARY OF IOA POTENTIAL CRITICAL ITEMS (FRCS HW)	49
Table VI	- SUMMARY OF IOA POTENTIAL CRITICAL ITEMS (ARCS HW)	50
Table VII	- SUMMARY OF IOA POTENTIAL CRITICAL ITEMS (FRCS EPD&C)	51
Table VIII	- SUMMARY OF IOA POTENTIAL CRITICAL ITEMS (ARCS EPD&C)	52

# Independent Orbiter Assessment Analysis of the Reaction Control System

## 1.0 EXECUTIVE SUMMARY

The McDonnell Douglas Astronautics Company (MDAC) was selected in June 1986 to perform an Independent Orbiter Assessment (IOA) of the Failure Modes and Effects Analysis (FMEA) and Critical Items List (CIL). Direction was given by the STS Orbiter and GFE Projects Office to perform the hardware analysis using the instructions and ground rules defined in NSTS 22206, Instructions for Preparation of FMEA and CIL, 10 October 1986. The IOA approach features a top-down analysis of the hardware to determine failure modes, criticality, and potential critical items. To preserve independence, this analysis was accomplished without reliance upon the results contained within the NASA FMEA/CIL documentation. This report documents (Appendix C) the independent analysis results for the Reaction Control System.

Although the aft Reaction Control System (RCS) and Orbital Maneuvering System (OMS) are housed in the same pod, this report only addresses the RCS, both aft and forward. The OMS report addresses the analysis of the OMS separately.

The purpose of the RCS is to provide thrust in and about the X, Y, Z axes for External Tank (ET) separation; orbit insertion maneuvers; orbit translation maneuvers; onorbit attitude control; rendezvous; proximity operations (payload deploy and capture); deorbit maneuvers; and abort attitude control. The RCS is situated in three independent modules, one forward in the orbiter nose and one in each OMS/RCS pod. Each RCS module consists of the following subsystems:

- o Helium Pressurization Subsystem
- o Propellant Storage and Distribution Subsystem
- o Thruster Subsystem
- o Electrical Power Distribution and Control Subsystem

Figure 1 presents a summary of the failure criticalities for each of the major divisions of the RCS. A summary of the number of failure modes, by criticality, is also presented below with Hardware (HW) criticality first and Functional (F) criticality second.

Summary of IOA Failure Modes By Criticality (HW/F)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
Number :	70	106	137	288	448	1223	2272




Figure 1 - RCS OVERVIEW ANALYSIS SUMMARY

For each failure mode identified, the criticality and redundancy screens were examined to identify critical items. A summary of Potential Critical Items (PCIs) is presented as follows:

Summary of IOA Potential Critical Items (HW/F)						
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	TOTAL
Number :	70	106	137	131	146	590

Of the failure modes analyzed, 307 could potentially result in a loss of life and/or loss of vehicle.

## 2.0 INTRODUCTION

### 2.1 Purpose

The 51-L Challenger accident prompted the NASA to readdress safety policies, concepts, and rationale being used in the National Space Transportation System (NSTS). The NSTS Office has undertaken the task of reevaluating the FMEA/CIL for the Space Shuttle design. The MDAC is providing an independent assessment of the Orbiter FMEA/CIL reevaluation results for completeness and technical accuracy.

### 2.2 Scope

The scope of the independent FMEA/CIL assessment activity encompasses those Shuttle Orbiter subsystems and GFE hardware identified in the Space Shuttle Independent FMEA/CIL Assessment Contractor Statement of Work. Each subsystem analysis addresses hardware, functions, internal and external interfaces, and operational requirements for all mission phases.

### 2.3 Analysis Approach

The independent analysis approach is a top-down analysis utilizing as-built drawings to divide the respective subsystem into components and low-level hardware items. Each hardware item is evaluated for failure mode, effects, and criticality. These data are documented in the respective subsystem analysis report, and are used to assess the NASA and Prime Contractor FMEA/CIL reevaluation results. The IOA analysis approach is summarized in the following Steps 1.0 through 3.0. Step 4.0 summarizes the assessment of the NASA and Prime Contractor FMEAs/CILs that is performed and documented at a later date.

#### Step 1.0 Subsystem familiarization

- 1.1 Define subsystem functions
- 1.2 Define subsystem components
- 1.3 Define subsystem specific ground rules and assumptions

#### Step 2.0 Define subsystem analysis diagram

- 2.1 Define subsystem
- 2.2 Define major assemblies
- 2.3 Develop detailed subsystem representations

#### Step 3.0 Failure events definition

- 3.1 Construct matrix of failure modes
- 3.2 Document IOA analysis results

Step 4.0 Compare IOA analysis data to NASA FMEA/CIL

4.1 Resolve differences

4.2 Review in-house

4.3 Document assessment issues

4.4 Forward findings to Project Manager

## 2.4 RCS Ground Rules and Assumptions

The RCS specific ground rules and assumptions used in the IOA analysis are presented in Appendix B.

### 3.0 SUBSYSTEM DESCRIPTION

#### 3.1 Functional and Hardware Description

The Shuttle Orbiter includes three RCS packages, one forward and two aft, one in each of the left and right OMS/RCS pods (Figure 2). Each RCS package consists of the following subsystems:

- o Helium Pressurization
- o Propellant Storage and Distribution
- o Thruster
- o Electrical Power Distribution and Control

Figures 3 through 6 present an overview of the RCS breakdown hierarchy utilized in this analysis.

During a typical Shuttle mission, the RCS jets are used during External Tank (ET) separation, orbit insertion, orbital operations, deorbit maneuver, and entry. The Aft RCS (ARCS) is active from prelaunch through the transition to aerosurface control during entry. The Forward RCS (FRCS) is active from prelaunch through the post-deorbit propellant dump and is disabled for entry. Figures 7 and 8 are hardware schematics of the FRCS and ARCS, respectively.

The RCS jets are first used in the mission after Main Engine Cutoff (MECO) to maintain vehicle attitude until ET separation. The RCS provides a translation maneuver during ET separation to ensure Orbiter separation from the ET. The RCS is also used to control roll in the event of the failure of two main engines during ascent.

After OMS-1 burn cutoff, the vehicle goes into attitude hold. The crew uses the Translational Hand Controller (THC) to command RCS translational maneuvers to null any residual velocity. Attitude hold is maintained until the maneuver to OMS-2 burn attitude which is performed manually by the crew using the Rotational Hand Controller (RHC). The RCS +X jets can be used to complete either the OMS-1 or OMS-2 burns or to perform the OMS-2 burn entirely in the case of OMS engine failures. In this case, the OMS-to-RCS interconnect capability will be used to feed OMS propellant to the four +X RCS thrusters.

Once in orbit, after the OMS-2 burn is completed, RCS maneuvers are performed to control the vehicle attitude according to the flight plan. For onorbit attitude control the crew may select either primary or vernier jets.

During deorbit, the RCS is used to maneuver to the OMS deorbit burn attitude, null any residual velocity, dump excess propellant for center-of-gravity control, and maneuver to the Entry Interface (EI) attitude. In case both OMS engines malfunction,






Figure 2 - REACTION CONTROL SYSTEM (RCS)




Figure 3 - FORWARD RCS HARDWARE BREAKDOWN HIERARCHY




Figure 4 - AFT RCS HARDWARE BREAKDOWN HIERARCHY




Figure 5 - FORWARD RCS EPD&C BREAKDOWN HIERARCHY




Figure 6 - AFT RCS EPD&C BREAKDOWN HIERARCHY




Figure 7 - FORWARD RCS SCHEMATIC




Figure 8 - AFT RCS SCHEMATIC

the RCS can be used to perform or complete the deorbit burn. In this case, the OMS-to-RCS interconnect will be selected to feed OMS propellant to the four +X RCS thrusters.

Once the deorbit burn is completed, the vehicle is maneuvered to the EI attitude.

From EI (400,000 ft) to approximately 262,000 ft, the vehicle is controlled in roll, pitch, and yaw with the ARCS jets. The GPCs disable the roll thrusters below this altitude, since the vehicle is captured and stable in the roll axis. Shortly after entering blackout, the pitch thrusters are disabled. From this time on, the elevons are used to control pitch and banking. The yaw thrusters are still used to assist the rudder. This mode of control will be used until the vehicle slows to Mach 1 where the yaw thrusters are disabled. Total vehicle control is then accomplished by the aerodynamic control surfaces through landing.

### 3.1.1 Helium Pressurization Subsystem

The pressurization subsystem regulates and distributes helium to the propellant tanks. This subsystem consists of two helium storage tanks, isolation valves, pressure regulators, check valves, and the lines necessary for filling, draining, and distributing the helium.

#### 3.1.1.a Helium Storage Tanks

The high pressure helium supply is contained in two 1.761 cubic ft spherical storage tanks in each module. The tanks are made of a titanium liner overwrapped with fiberglass. One tank supplies helium pressure to the fuel propellant tank while the other helium tank supplies pressure to the oxidizer propellant tank. The helium tank's maximum operating pressure is 4000 psig and is proof-pressure tested to 4480 psig.

#### 3.1.1.b Helium Isolation Valve

For each propellant there are two helium isolation valves in parallel between the helium tanks and the pressure regulators which are used to isolate the high-pressure gaseous helium from the remainder of the pressurization subsystem (Figure 9).

The helium isolation valves are operated by two solenoids, one of which is momentarily energized to magnetically latch the valve open. The second solenoid magnetically unlatches the valve, allowing spring and helium pressure to force the valve closed.

The switching logic for the helium isolation valves is contained in the Forward and Aft Load Control Assemblies (FLCA and ALCA). Solenoid and power logic






Figure 9 - HELIUM ISOLATION VALVE

is provided by the Power Control Assemblies (PCA), which are located within the LCAs. The LCAs and PCAs must be powered up in order to operate the helium isolation valves.

The helium isolation valves are controlled by the FWD RCS, AFT LEFT RCS, and AFT RIGHT RCS HE PRESS A/B switches on panels O7 and O8. These are permanent position switches (OPEN, GPC, CLOSE), but only apply momentary power to the solenoid due to the logic in the LCA. Each switch controls two isolation valves, one in the helium oxidizer line and one in the helium fuel line.

These valves contain microswitches which are activated when the valves are fully open or closed. When commanded, the switch logic allows a one-second delay for the valves to reach the command position before sending a position indication signal to the GPCs, telemetry, and a position indicator (talkback) above each switch. Power is then removed from the solenoids. The talkback logic displays barberpole when the valves are in motion or when there is a position mismatch between the fuel and oxidizer helium valves. Otherwise, the talkback shows OP for open valves and CL for closed valves.

The GPC can command the isolation valve to open and close to maintain the system pressurization and to prevent overpressurization when the isolation valve switch is in the GPC position. In the event of a switch failure in the GPC position, the crew can open or close the valves using the GPC memory read/write procedures.

The valve's nominal operating pressure is 200 to 4000 psig and limits the flow to 81 scfm.

#### 3.1.1.c Pressure Regulator Assembly

Helium pressure regulation is accomplished by two regulator assemblies connected in parallel and located downstream of each helium isolation valve (Figure 10). Each assembly contains two regulators, primary and secondary, connected in series so that if the primary regulator fails open, the secondary regulator can regulate the pressure within acceptable limits. The regulators cannot be controlled manually or by the GPC.

The primary and secondary regulators regulate the tank pressure to 245 psig and 256 psig, respectively. The flow rate is limited to 81 scfm for 500 to 1400 psig inlet pressure, and 150 scfm for 1400 to 4000 psig inlet pressure.




Figure 10 - HELIUM PRESSURE REGULATOR ASSEMBLY

#### 3.1.1.d Check Valve Assembly

A check valve assembly, located between the pressure regulator assemblies and each relief valve, is used to preclude backflow of helium or propellant vapors or liquids (Figure 11). Each assembly contains four independent check valves connected in series-parallel. The check valves cannot be controlled manually or by the GPC.

The valve's normal operating pressure is 355 psig, with a maximum of 370 psig.

#### 3.1.2 Propellant Storage and Distribution Subsystem

The propellant subsystem distributes the fuel and oxidizer to the thrusters. This subsystem consists of propellant tanks, pressure relief valves, tank isolation valves, crossfeed valves, manifold isolation valves, and the lines and couplings necessary for filling, draining, and distributing the propellant.

##### 3.1.2.a Propellant Tanks

Each RCS module contains two titanium 39.2-inch spherical propellant tanks, one for fuel and one for oxidizer (Figure 12). Each tank contains an internally-mounted surface-tension screen Propellant Acquisition Device (PAD) which acquires and delivers the propellant to the RCS thrusters on demand. The surface-tension device also prevents the helium pressurant gas from entering the propellant or the propellant distribution lines prior to propellant depletion. The forward propellant tanks have PADs which are designed to operate primarily in a low-g environment. The aft propellant tanks are designed to operate in both high and low-g regimes.

##### 3.1.2.b Pressure Relief Valve Assembly

The helium pressure relief valve assembly is located between each check valve assembly and the propellant tank, and will vent excess pressure overboard before it can over pressurize the propellant tanks (Figure 13). The assembly consists of a burst diaphragm, filter, and relief valve. The burst diaphragm is of the non-fragmentation type, but the filter is further insurance that fragmentation or particles will not reach the relief valve seat. The relief valve cannot be controlled manually or by the GPC.

The burst disk ruptures at 332 psig. The relief valve reseats at 310 psig.




Figure 11 - QUAD CHECK VALVE ASSEMBLY




Figure 12 - AFT AND FORWARD RCS PROPELLANT TANKS




Figure 13 - PRESSURE RELIEF VALVE ASSEMBLY

### 3.1.2.c Tank Isolation, Crossfeed, and Manifold 1/2/3/4 Isolation Valves

The RCS propellant tank isolation, crossfeed, and manifold 1/2/3/4 isolation valves are all AC motor valves. Once a valve reaches the open or closed position, an open or close microswitch is automatically closed to remove AC power from the valve motor. A signal is also sent to the GPC, to the ground, and to the valve position indicator (talkback), located above each switch. The talkback logic displays barberpole when the valves are in motion or when there is a position mismatch between the fuel and the oxidizer valves. Otherwise, the talkback shows "OP" for open valves and "CL" for closed valves.

The tank isolation valves are located between the propellant tanks and the manifold isolation valves, and are used to isolate the propellant tanks from the remainder of the subsystem (Figure 14).

The tank isolation valves are AC motor-operated and contain a lift-off ball-flow control device. For each module, one valve isolates each propellant tank from the 1/2 manifold. Two valves in parallel isolate each propellant tank from the 3/4/5 manifold line in the aft modules, and one valve isolates each propellant tank from the 3/4/5 manifold line in the forward module.

The tank isolation valves are controlled by the FWD RCS, AFT LEFT RCS, and AFT RIGHT RCS TANK ISOLATION 1/2 and 3/4/5 switches on panels O7 and O8. These are permanent position switches (OPEN, GPC, CLOSE). Switch logic, relay logic, and motor logic for the isolation valves are contained in the Forward and Aft Motor Control Assemblies (FMCA and AMCA). Therefore, it is necessary to have the MCAs powered up to operate the tank isolation valves.

The tank isolation valves are normally maintained open throughout the mission with the switch in the GPC position. With the switch in the GPC position, the logic in the MCA is designed to receive computer commands to control the valves. The GPC reconfigures the aft tank isolation valves and the RCS and OMS crossfeed valves in case of OMS-to-RCS interconnect, or for RCS/RCS crossfeed operations. Manual configuration is required in the case of manual RCS/RCS crossfeed and on orbit/deorbit OMS-to-RCS interconnect. In the event of a switch failure in the GPC position, the crew can open or close the valves using GPC memory read/write procedures.






Figure 14 - AC MOTOR VALVE

The RCS crossfeed valves are contained only in the ARCS pods, and are used to isolate the RCS propellant crossfeed lines from the OMS interconnect lines (Figure 14). They are located between the tank isolation valves and the manifold isolation valves.

The RCS crossfeed valves are AC motor-operated and contain a lift-off ball-flow control device. One pair of valves, one fuel and one oxidizer valve, isolate the RCS crossfeed lines from the 1/2 propellant lines. One pair of valves isolate the RCS crossfeed lines from the 3/4/5 propellant lines. The RCS crossfeed valves are controlled by the LEFT, RIGHT RCS CROSSFEED 1/2 and 3/4/5 switches on panel 09. These are permanent position switches (OPEN, GPC, CLOSE). Switch logic, relay logic, and motor logic for the isolation valves are contained in the AMCA. Therefore, it is necessary to have the MCAs powered up to operate the RCS crossfeed valves.

The RCS crossfeed valves are normally maintained closed throughout the mission, with the switch in the GPC position. With the switch in the GPC position, the logic in the MCA is designed to receive computer commands to control the valves. The GPC reconfigures these valves, the OMS crossfeed valves, and the tank isolation valves in case of OMS-to-RCS interconnect during aborts, or for RCS/RCS crossfeed operations. Manual configuration is required in the case of manual RCS/RCS crossfeed and on orbit/deorbit OMS-to-RCS interconnect. In the event of a switch failure in the GPC position, the crew can open or close the valves using GPC memory read/write procedures.

The primary manifold isolation valves are located between the tank isolation valves, downstream of the RCS crossfeed valves, and the primary thrusters (Figure 14). They are used to isolate the primary thrusters from the propellant subsystem.

The primary manifold isolation valves are AC motor-operated and contain a lift-off ball flow control device. For each module, one valve isolates each manifold from each propellant. The primary manifold isolation valves are controlled by the FWD RCS, AFT LEFT RCS, and AFT RIGHT RCS MANIFOLD ISOLATION 1, 2, 3, and 4 switches on panels 07 and 08. These are permanent position switches (OPEN, GPC, CLOSE). Switch logic, relay logic, and motor logic for the isolation valves are contained in the FMCA and AMCA. Therefore, it is necessary to have the MCAs powered up to operate the manifold isolation valves.

Redundancy Management (RM) is used to monitor the microswitches in these valves, and can cause the valves to be declared closed, and the jets on that manifold to be removed from the Jet Available Table. The crew can override the RM by CRT keyboard entries and reselect the manifold and its jets.

The primary manifold isolation valves are normally maintained open throughout ascent and entry, with the switch in the GPC position. With the switch in the GPC position, the logic in the MCA is designed to receive computer commands to control the valves. These valves are controlled by the GPC during aborts and are controlled by RM at all times. In the event of a switch failure in the GPC position, the crew can open or close the valves using GPC memory read/write procedures.

### 3.1.2.d Vernier Manifold Isolation Valves

The vernier manifold isolation valves are located between the tank isolation valves, downstream of the RCS crossfeed valves, and the vernier thrusters (Figure 15). They are used to isolate the thrusters from the propellant subsystem.

The vernier manifold isolation valves are DC solenoid operated. One valve isolates each vernier manifold from each propellant. The manifold isolation valves are controlled by the FWD RCS, AFT LEFT RCS, and AFT RIGHT RCS MANIFOLD 5 ISOLATION switches on panels O7 and O8. These are permanent position switches (OPEN, GPC, CLOSE). Switch logic for the vernier manifold valves is contained in the FLCA and ALCA. Solenoid logic and power logic is provided by the Power Control Assemblies (PCAs). Therefore, it is necessary to have the LCAs powered up to operate the manifold isolation valves.

Once a valve reaches the open or closed position, a microswitch is automatically closed to remove DC power from the valve solenoid. A signal is also sent to the GPC, to the ground, and to the valve position indicator (talkback) located above each switch. The talkback logic displays barberpole when the valves are in motion or when there is a position mismatch between the fuel and the oxidizer valves. Otherwise, the talkback shows "OP" for open valves and "CL" for closed valves. Redundancy Management (RM) is used to monitor the microswitches in these valves, and can cause the valves to be declared closed, and the vernier jets to be deselected. The crew can override the RM by CRT keyboard entries and reselect the vernier jets.




Figure 15 - VERNIER MANIFOLD ISOLATION VALVE

The vernier manifold isolation valves are normally maintained open throughout orbit and closed during ascent and entry, with the switch in the GPC position. With the switch in the GPC position, the logic in the LCAs and PCAs is set up to receive computer commands to control the valves. The GPC controls these valves by RM at all times. In the event of a switch failure in the GPC position, the crew can open or close the valves using the GPC memory read/write procedures.

### 3.1.3 Thruster Subsystem

The RCS jet thrusters are pressure-fed, bipropellant, hypergolic engines. There are two types of thrusters in the Shuttle: the primary thrusters, and the vernier thrusters (Figure 16). Both types of thrusters contain a fuel and oxidizer bipropellant solenoid valve, injector head assembly, combustion chamber, expansion nozzle, and an electrical junction box and can be operated in either pulse mode or steady-state mode.

#### 3.1.3.a Bipropellant Valves

The bipropellant control valves control the flow of propellants to the thrusters by opening and closing in response to electrical fire commands (Figure 17). Each primary jet engine assembly contains two injector solenoid pilot poppet valves, one for fuel and one for oxidizer. They are operated by coaxially-wound coils which are energized open by a fire command, and are spring-loaded closed. When the pilot valves open, the propellant's hydraulic pressure opens the main poppet valves to allow the propellants into the injector. The vernier jets use single-stage, solenoid-operated poppet valves.

The fuel and oxidizer valves on the primary jet thrusters are mechanically linked. The pilot valve is activated by a 80 msec pulse sent from the Reaction Jet Driver. Commands are issued every 80 msec, so the minimum on or off time is 80 msec. The vernier bipropellant valves are operated similarly by a mechanically linked torque motor.

During normal operations, if the isolation and manifold valves are properly configured, a fire command to a jet will cause that jet's bipropellant valves to open. Removal of the fire command will cause the bipropellant valves to close.




Figure 16 - VERNIER AND PRIMARY THRUSTERS





Figure 17 - PRIMARY AND VERNIER THRUSTER VALVES

### 3.1.3.b Injector Head Assembly

Each RCS jet contains an injector head assembly which directs the propellant flow from the bipropellant control valves to the combustion chamber (Figure 18). The injector is welded to the combustion chamber.

For the primary jets, injector holes are arranged in two concentric rings (outer fuel, inner oxidizer) which are canted to cause impingement of the hypergolic propellants within the combustion chamber. Separate fuel holes near the outer edge of the injector plate provide cooling for the combustion chamber wall. Spaced between these fuel inlet holes are acoustic cavities which are of varied depth to prevent acoustic resonance when the jet is fired.

For the vernier jets, fuel and oxidizer enter the combustion chamber through a single pair of injector holes which are also canted to provide impingement of the fuel and oxidizer streams for combustion. The combustion chamber wall is cooled by making the fuel stream more divergent than the oxidizer stream.

Unlike stream impingement is used to improve propellant mixing in the combustion chamber with a mixture ratio of 1.6 lbs oxidizer to 1.0 lbs fuel for both the primary and vernier jets.

The primary jets operate at 152 psia, produce 870 lbs (vacuum) thrust, and have a specific impulse of 280 seconds. The vernier jets operate at 106 psia, produce 25 lbs (vacuum) thrust, and have a specific impulse of 265 seconds.

### 3.1.3.c Combustion Chamber and Nozzle

The combustion chamber and nozzle are made of columbium C-103 with a R512A Disilicide coating 0.003-inches thick. Behind the columbium is Dynaflex molded insulation covered with 0.02-inch thick titanium on the outside.

### 3.1.4 Electrical Power Distribution and Control Subsystem

#### 3.1.4.a Electrical Junction Box

The electrical junction box on each RCS thruster contains an electric heater and thermostat, a chamber pressure transducer, a propellant leak detection device, and the electrical connections to the bipropellant valves. The electrical heater contains one heating element and is thermostatically controlled.





The thermostat is set to a predetermined range, and will regulate the on and off cycles of the heater as long as voltage is present. The heaters are controlled by the RCS/OMS HEATERS switches on panel A14. These are two-position switches, OFF and AUTO, and the heater is controlled by the thermostat when this switch is in the AUTO position.

### 3.2 Redundancy Management

The RCS Redundancy Management (RM) monitors the RCS jets' chamber pressures, temperatures, reaction jet driver output discretes and jet fire commands, and manifold valves status. It also provides a limited amount of automatic jet deselection and alerts the crew when a fault is detected.

The Data Processing System (DPS) software provides status information on I/O errors to the RCS RM software, referred to as commfaults (communications faults). Commfault indicators are set as the result of bus masking, Bus Control Element (BCE) bypasses, and Bus Terminal Unit (BTU) bypasses. When an I/O error is detected on a BCE chain by any GPC, the data on the entire chain is flagged as invalid (commfaulted) for the applications software. On subsequent transactions, if the problem is isolated, only the faulty element is flagged as invalid. In a similar way, if a bus mask is set all BCEs and data associated with that bus is indicated via commfault as being in error. In any case, the commfault will be set or latched when it is present for two consecutive passes.

Commfaults are included in the RCS RM requirements to help prevent the redundant GPCs from moding to dissimilar software, to optimize the number of jets available for use, and to prevent the RCS RM from generating additional alerts to the Flight Control Operational Software (FCOS) generated alerts associated with commfaults. The RCS RM uses the MDM and Line Replaceable Unit (LRU) commfaults (where LRU is defined to be either one RCS jet or one RCS manifold), and will reconfigure for commfaults, regardless of whether the commfault is permanent, permanent and subsequently removed, or transient. The MDM and LRU commfaults are set in the FCOS software when a commfault is present for two cycles. There are 44 jet LRU commfaults and 15 manifold LRU commfaults.

All input signals associated with any one LRU (where LRU is defined as either one RCS jet or one RCS manifold) will be within the same BCE, and the FCOS will set a BCE flag for a BCE if it determines an I/O problem at the BCE level. This flag will be used by the manifold status monitor in determining the commfault state of the RCS LRU, and/or input signals for the LRU. A jet with an LRU commfault will not have any of its status flags or counters modified as long as the fault exists, except by subsequent crew action. An MDM commfault will set all LRU

commfaults for each BCE associated with the MDM commfault, thus suspending the operation of the RCS RM failure monitors. An I/O reset on a CRT keyboard will reset any latched commfaults. LRU commfaults or transducer failures will cause the quantity monitor to use substitute measurements or constants, and the CRTs will show on "M" to indicate missing data. If a substitute is not available or a constant is used, the calculations are suspended, a down arrow appears on the CRT, and a class 3 alarm is output.

All input signals associated with an LRU are required to be within the same BCE. The input signals associated with each RCS jet are a chamber pressure discrete, fuel and oxidizer injector temperatures, and reaction jet driver output discrete. The input signals associated with each manifold are the open and close discretely for the fuel and oxidizer manifold isolation valves.

### 3.2.1 Jet Failed-On Monitor

The Jet Failed Monitor uses the Reaction Jet Driver (RJD) output discretely and the jet fire command discretely provided by the RCS CMD SOP to detect jets failed on.

The Jet Failed-On Monitor uses the jet fire command A discretely, the reaction jet driver output discretely, the jet RM inhibit discretely, and the jet LRU commfault discretely as inputs, and outputs the jet failed-on indicator discretely and the jet failed on counter discretely. There are 44 of each of these discretely.

The Jet Failed-On Monitor's logic ANDs the reaction jet driver output discrete with the complement of the jet fire command A discrete, and declares the jet failed-on if this calculation is true for three consecutive cycles. Consecutive passes are not affected by commfaults or by cycles in which there are fire commands for the affected jets. The three consecutive cycle logic will be reset; however, if the noncommanded jet has its reaction jet driver output discrete reset to indicate the jet is not firing. A jet failed-on declaration will not cause automatic deselection of the jet by RM, nor will the Digital Autopilot (DAP) reconfigure the Jet Priority Table.

A jet failed-on determination will set the jet failed-on indicator discrete and the jet failed-on counter discrete. These discretely will be reset when the associated jet's RM inhibit discrete is reset. The Jet Failed-On Monitor outputs the jet failed-on indicators to displays and controls and to the Jet Fault Limit Module.

The Jet Failed-On Monitor's design is valid for a minimum jet fire command pulse of 80 msec on and 80 msec off. The crew will be alerted by a class 2 alarm, the backup C&W

lights and RCS jet light on the C&W matrix on panel F7, a fault message on the CRT fault message line, and jet-on indications on the RCS SPEC display and the GNC SYS SUM 1 and 2 displays.

The Jet Failed-On Monitor is active in OPS 1, 2, 3, 6, and 8 in the PASS, and 1, 3, and 6 for the BFS, but only if BFS is engaged.

### 3.2.2 Jet Failed-Off Monitor

The Jet Failed-Off Monitor uses the jet fire command discretes provided by the RCS Command SOP, and the jet chamber pressure feedback discretes provided by the RJDs to detect jets failed off.

The Jet Failed-Off Monitor uses the jet fire command A discretes, the jet chamber pressure discretes, the jet RM inhibit discretes, and the jet LRU commfault discretes as inputs, and outputs the jet failed-off indicator discretes and the jet failed-off counter discretes. There are 44 of each of these discretes.

The Jet Failed-Off Monitor's logic ANDs the jet fire command A discrete with the complement of the jet chamber pressure discrete, and declares the jet failed off if this calculation is true for three consecutive cycles. Consecutive passes are not affected by commfaults or by cycles in which there are no fire commands for the affected jets. However, consecutive passes leading to a failed-off indication must begin anew if, prior to reaching the third consecutive cycle, the fire command and its associated pressure discrete indicates that the jet has fired. The RCS RM will automatically deselect a jet which has failed off, and the DAP will reconfigure jet selection accordingly. (See section 3.6.1 for the DAP Jet Select Logic description.)

A failed-off jet determination will set the associated jet failed-off indicator and the jet failed-off counter discretes. These discretes will be reset when the associated jet's RM inhibit discrete is reset. The Jet Failed-Off Monitor outputs these jet failed-off indicator discretes to the Jet Fault Limit Module and to displays and controls. The Jet Failed-Off Monitor will be inhibited for the jet which has failed off until the crew resets the RM inhibit discrete.

The Jet Failed-Off Monitor design is valid for a minimum jet fire command pulse mode of 80 msec on and 80 msec off. The crew is alerted to a failure by a class 2 alarm, the backup C&W light and RCS jet light on the C&W matrix on panel F7, a fault message on the CRT fault message line, and a jet-off

indication on the RCS SPEC display and the GNC SYS SUM 1 and 2 displays. The Jet Failed Off Monitor is active in OPS 2, 3, 6, and 8 in the PASS, and 1, 3, and 6 for the BFS, but only if BFS is engaged.

### 3.2.3 Jet Leak Monitor

The Jet Leak Monitor uses the jet fuel and oxidizer injector temperature transducer outputs of each jet to detect a leaking jet.

The Jet Leak Monitor uses the jet fuel and oxidizer injector temperatures, the jet RM inhibit discretes, and the jet LRU commfault discretes as inputs, and outputs the jet failed leak indicator discretes and the jet failed leak counter discretes. There are 44 of each of these discretes.

The Jet Leak Monitor's Logic compares the jet fuel and oxidizer injector temperatures with the specified temperature limit of 30 degrees F, and declares the Jet Failed Leak if either of the temperatures are less than 30 degrees F for three consecutive cycles. Consecutive passes leading to a Jet Failed Leak indication will begin anew if the fuel and oxidizer temperatures are both greater than 30 degrees F before the jet leak counter reaches three. The RCS RM will automatically deselect a jet which is declared leaking and the DAP will reconfigure jet selection accordingly.

A Jet Failed Leak determination will set the associated jet failed leak indicator and jet failed leak counter discretes. These discretes will be reset when the associated jets RM inhibit discrete is reset. The Jet Leak Monitor outputs the Jet Failed Leak indicator discretes to the Jet Fault Limit Module and to crew displays.

The crew is alerted to a failure by a class 2 alarm, the backup C&W light and the RCS jet light on the C&W matrix on panel F7, a fault message on the CRT fault message line, and a Jet Failed Leak indication on the RCS SPEC display and the GNC SYS SUM 1 and 2 displays.

The Jet Leak Monitor is active in OPS 2, 3, and 8 for the PASS, and 1, 3, and 6 for the BFS, but only if BFS is engaged.

### 3.2.4 Jet Fault Limit Module

The Jet Fault Limit module limits the number of jets which can be automatically deselected in response to failures detected by RCS RM. The limits are modifiable by crew input on the RCS SPEC display (RCS F, L, R Jet Fail Limit integers - one integer per pod). This module also reconfigures a jet's availability status (jet deselect output discretes

(44)) in response to crew inputs on the RCS SPEC display (jet RM inhibit discretes (44) and jet deselect input discretes (44)).

An automatic deselection of a jet occurs if all of the following are satisfied:

- o Jet Failed-Off or Jet Failed Leak (Jet Failed-On failures do not result in automatic deselection)
- o Jet select/deselect status is "SELECT"
- o Jet's manifold status is "OPEN"
- o RM is not inhibited for this jet
- o Jet failure has not been overridden
- o The number of automatic deselections of primary jets on this pod is less than the associated Jet Fail Limit (no limit on vernier jets)

All jet failures detected will be announced to the crew even if they do not cause automatic jet deselection. If multiple failures occur on a jet, only the last failure will be annunciated. Failure indicators are the same as in the Jet Failed Off and Jet Failed Leak Monitors.

The jet fail limit counter is incremented by the number of jets which have been automatically deselected for that pod by the RCS RM and is decremented by one for each automatically deselected jet that is reselected. The vernier jets do not increment or decrement the jet fail limit counter. The Jet Fail Limit valves are individually changeable in major modes 2 and 3 on the RCS SPEC display. An increase in the Jet Fail Limit allows previously failed jets to be deselected, providing the above requirements are met. A decrease in the Jet Fail Limit will not cause a change in the status of any jet. Note that setting the Jet Fail Limit equal to or less than the number of jets which have been automatically deselected will effectively inhibit the RCS RM for that pod.

A jet's status can be changed from deselect to select only by item entry on the RCS SPEC page. Failure resets or reductions in the Jet Fail Limit will not cause the status to be reset to select. The select item entries cause the override to be invoked if there is a declared failure for that jet, and will make those failures inoperative in the Jet Fault Limit module. An overridden failure will remain overridden until the applicable failure is reset.

Automatic deselection of a jet can be prevented by the use of the Inhibit item entries on the RCS SPEC page. Changing the Inhibit to Not Inhibited will reset a jet's failures, but will not cause the Jet Fail Limit to be incremented or decremented. Reset by use of the RM Inhibit of a failure which has been overridden will reset the override. Jet failures are unordered; that is, if there are more candidates for automatic deselection than is permitted by the

Jet Fail Limit, there is no preference as to which of the candidates will be deselected.

### 3.2.5 Manifold Status Monitor

The Manifold Status Monitor uses the open and close discretes of the oxidizer and fuel manifold isolation valves (provided by the monitor control assemblies) to determine the open/close status for each jet manifold.

The Manifold Status Monitor uses the fuel and oxidizer manifold valve open discretes (15 of each discrete), the fuel and oxidizer close discretes (15 of each), the manifold status discrete (15 discretes), the manifold LRU commfault discretes (15 discretes), the MDM commfault discretes (8 discretes), and the manifold status override discrete (one discrete) as inputs, and outputs the manifold open/close status discretes (15 discretes), the RCS manifold RM dilemma discretes (15 discretes), and the RM power fail discrete (one discrete).

The Manifold Status Monitor monitors the open and close discretes for each manifold for any changes of state. A change of state in any one or more of these discretes will cause a redetermination of that manifold's open/close status, independent of status changes made by the crew. This redetermination also contains logic which will determine if a power failure has occurred and will determine whether a dilemma exists on a manifold (tables 3-I and 3-II). A power failure condition exists when all of the open and close discretes on a manifold are false for three consecutive cycles, and will cause the RM Power Fail Flag to be set. The manifold sets identified in Table 3-II are the only manifolds which require power failure determination. This flag will remain set until the GNC FDA module honors it, when it will then be reset. There is only one RM Power Fail Flag and all manifolds are capable of setting it, but each can set the flag only once. Whenever a dilemma exists for three consecutive passes, the RCS manifold RM Dilemma Flag for that manifold will be set. MDM or LRU commfaults will not modify the dilemma pass counter or the RM Dilemma Flag. The flag will be reset, however, if any of the four manifold open/close discretes change state.

TABLE 3-I - MANIFOLD STATUS

LOGICAL STATE OF:					MANIFOLD STATUS	RCS MANIFOLD RM DILEMMA
INPUT		DISCRETES		POWER FAILURE		
OPEN		CLOSE				
Fuel	Ox.	Fuel	Ox.			
0	0	0	0	Yes	(Previous)	No
0	0	0	0	No	Close	No
0	0	0	1	N/A	Close	No
0	0	1	0	N/A	Close	No
0	0	1	1	N/A	Close	No
0	1	0	0	N/A	Close	Yes
0	1	0	1	N/A	Close	Yes
0	1	1	0	N/A	Close	Yes
0	1	1	1	N/A	Close	No
1	0	0	0	N/A	Close	Yes
1	0	0	1	N/A	Close	Yes
1	0	1	0	N/A	Close	Yes
1	0	1	1	N/A	Close	No
1	1	0	0	N/A	Open	No
1	1	0	1	N/A	Open	No
1	1	1	0	N/A	Open	No
1	1	1	1	N/A	Close	Yes

The manifold status from the previous pass is to be maintained.

TABLE 3-II MANIFOLD SETS  
FOR POWER FAILURE DETERMINATION

- o Forward No. 3 and Forward No. 4
- o Aft Left No. 1 and Aft Right No. 1
- o Aft Left No. 2 and Aft Right No. 2
- o Aft Left No. 3 and Aft Right No. 3
- o Aft Left No. 4 and Aft Right No. 4



The transition of an MDM commfault discrete from false to true will cause the status of all affected manifolds to be set to close in all major modes. In major mode 1, the same is true of an LRU commfault. In major modes 2 and 3, the transition of an LRU commfault will cause no change in manifold statuses.

The crew is able to override the status of all manifolds on an individual basis by item entries on the RCS SPEC display via the Manifold Status Override. The setting of this discrete for a manifold will change the manifold's status to its complementary state and will then reset the discrete. The use of the Manifold Status Override feature will not inhibit or modify any of the other functions of the manifold status monitor. The module will continue to honor subsequent changes in the affected manifold's input signals (open/close discrettes, commfaults, override discrete) as specified in this section.

The Manifold Close Status Override is used in Major Modes 1 and 3 open all manifolds whose status is closed and whose open/close discrettes are in dilemma. This discrete can be set by item entry on the Override page, and will be reset to false after the reconfiguration is complete. The use of the Manifold Close Status Override feature will not inhibit or modify any of the other functions of the Manifold Status Monitor.

### 3.2.6 Available Jet Status Table

The Available Jet Status table module provides a list of jets available for use to the Jet Select Logic Module in the Flight Control System software.

The Available Jet Status Table uses the manifold open/close discrettes (15 discrettes) from the Manifold Status Monitor, and the jet deselect output discrettes (44 discrettes) from the Jet Fault Limit Module as inputs, and outputs the jet available discrettes (44 discrettes) and the jet status change discrete (one discrete).

The Available Jet Status Table's logic "AND"s the jet deselect output discrete with the manifold open/close status discrete and statuses a jet as available to the Flight Control System if the discrettes indicate select and open, respectively. The Available Jet Status Table will be computed each time that the jet status change discrete is true.

In the BFS, jet failures are detected only when BFS is engaged. The Jet Failed Leaking and Jets Failed-Off detection in the BFS is the same as in the PASS, but the jet chamber pressure feedback discrete is used for Jet Fail-On detection in the BFS rather than the RJD output discrete which is used in the PASS.

### 3.3 Interfaces and Locations

The RCS interfaces with the following systems: Data Processing System, Displays and Controls, Caution and Warning, Orbital Maneuvering System, Electrical Power Distribution and Control, and the Pulse Code Modulator. In addition, the RCS interfaces with the crew.

#### 3.3.1 Data Processing System

The RCS sends data consisting of pressures, temperatures, and valve positions to the Data Processing System (DPS) through the flight-critical Multiplexer Demultiplexers (MDMS) to have the data processed by the GPCs. The GPCs use this data to monitor and display the configuration and status of the RCS. The GPCs also provide valve configuration commands to the RCS and jet on/off commands to the RCS via the Reaction Jet Drivers Aft and Forward (RJDA and RJDF).

The Flight Control software uses the RCS Digital Automatic Pilot (DAP) to hold attitude or to accomplish an attitude maneuver by virtue of an error correction method. The State Estimator takes IMU data from the Attitude Processor software (ATT PROC), filters it, and sends it to a module called RCS Errors Phase Plane. In the RCS Errors module, attitude commands coming from the hand controller or from the Universal Pointing software (which runs the display by the same name) are compared with the actual attitude as computed by the State Estimator. The result is an attitude error and rate error which are passed on to the Phase Plane module. The Phase Plane Module generates positive or negative rate commands for each axis. These commands are sent to the RCS Activity Lights and to the Jet Select module.

The Jet Select Module uses a look-up table to determine how many jets are needed from each directional cluster. (A "directional cluster" is a group of jets located within the same pod, forward, left, or right, which provide thrust in the same axis and direction.) There are several such tables which take into account jet failures, propellant feed constraints, and usage of OMS propellant. A Jet Priority Table is used to determine the particular jets to be fired. Each jet in a directional cluster is assigned a priority permission. If RCS RM removes a jet from the Available Jet Status Table, the jet will be removed from the Jet Priority Table. Thus, the Jet Select Module logic will automatically select the next highest priority jet in that directional cluster. The crew has the capability to change a jet's priority on the Jet Priority Table or to override RM deselection of a jet from the Available Jet Status Table.

### 3.3.2 Displays and Controls

RCS data is sent to the Displays and Controls (D&C) to be displayed on dedicated displays. Switches and circuit breakers in the D&C panels are used for manual valve configuration and power routing to the RCS.

### 3.3.3 Caution and Warning

A selected portion of the RCS parameters are sent to the Caution and Warning (C&W) unit, where they are limit sensed to determine if RCS anomalies exist. If system anomalies are found, the C&W issues signals that illuminate the proper light on the C&W panel, the master alarm pushbutton indicators (pbis), and turn on the C&W tone.

### 3.3.4 Orbital Maneuvering System

The ARCS modules are connected with each other and with the OMS by propellant interconnect lines so that either or both OMS module's propellants can be fed to either or both of the ARCS modules.

### 3.3.5 Electrical Power Distribution and Control System

The Electrical Power Distribution and Control System (EPD&C) provides both AC and DC power to the RCS.

### 3.3.6 Pulse Code Modulator

Data from the RCS is routed through the Input/Output (I/O) MDMS to the Pulse Code Modulator (PCM) for incorporation in the telemetry downlink to be sent to the ground and to the onboard recorders.

### 3.3.7 Crew

The crew monitors and controls the RCS performance through CRT displays, fault messages, keyboard item entries, C&W indications, and associated switches and indicators.

## 3.4 Hierarchy

Figures 3 through 6 illustrate the hierarchy of the RCS hardware components. Figures 7 through 18 depict the functional details of the RCS subsystem components.

#### 4.0 ANALYSIS RESULTS

Detailed analysis results for each of the identified failures are presented in Appendix C. Tables I and II present summaries of the failure criticalities for the three hardware subsystems of the forward and aft RCS, respectively. Tables III and IV present summaries of the failure criticalities for the Electrical Power Distribution and Control (EPD&C) subsystems of the forward and aft RCS, respectively. Further discussion of each of these subsystems and the applicable failure modes is provided in subsequent paragraphs. The RCS analysis hierarchy is illustrated in Figures 3 through 6.

Of the ninety-nine (99) forward RCS hardware failure modes analyzed, sixty-eight (68) were determined to be PCIs. Of the one hundred nine (109) aft RCS hardware failure modes analyzed, seventy-three (73) were determined to be PCIs. Summaries of the forward and aft RCS hardware PCIs are presented in Tables V and VI, respectively. Of the nine hundred ninety-four (994) forward RCS EPD&C failure modes analyzed, two hundred twenty-two (222) were determined to be PCIs. Of the one thousand seventy (1070) aft RCS EPD&C failure modes analyzed, two hundred twenty-seven (227) were determined to be PCIs. Summaries of the forward and aft RCS EPD&C PCIs are presented in tables VII and VIII, respectively.

Appendix D contains a cross reference between each PCI and analysis worksheet in Appendix C.

TABLE I Summary of IOA Failure Modes and Criticalities (FRCS HW)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
<u>HE PRESS SUBSYSTEM</u>							
STORAGE TANK	1	-	-	-	-	-	1
TANK ISOLATION VALVES	-	1	-	1	-	-	2
REGULATOR ASSEMBLIES	-	5	-	1	-	-	6
QUAD CHECK VALVE ASSEMBLY	-	2	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	3	-	-	-	3	6
COUPLINGS (DOUBLE SEAL)	-	-	-	1	-	1	2
LINES AND FITTINGS	2	2	-	-	-	-	4
<u>PROP STOR &amp; DIST SUBSYSTEM</u>							
PROPELLANT TANKS	1	-	-	-	-	-	1
PROPELLANT CHANNEL SCREENS	1	-	-	-	-	-	1
PROPELLANT FEEDOUT TUBES	1	-	-	-	-	-	1
PRESSURE RELIEF ASSEMBLIES	1	1	-	-	-	-	2
GROUND MANUAL ISOL VALVES	2	-	-	-	-	1	3
GIMBAL BELLOWS	2	-	-	-	-	-	2
TANK ISOL VALVES	2	2	-	-	-	2	6
MANIFOLD ISOL VLVS, PRIMARY	2	4	-	-	-	4	10
MANIFOLD ISOL VLVS, VERNIER	-	-	1	-	-	1	2
JET ALIGNMENT BELLOWS, PRIMARY	2	-	-	-	-	-	2
JET ALIGNMENT BELLOWS, VERNIER	2	-	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	12	-	-	-	12	24
COUPLINGS (DOUBLE SEAL)	-	-	-	1	-	1	2
LINES AND FITTINGS	2	-	-	-	-	-	2
<u>THRUSTER SUBSYSTEM</u>							
PRIMARY JETS							
BIPROP SOLENOID VALVES	6	1	-	-	2	-	9
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	-	1
VERNIER JETS							
BIPROP SOLENOID VALVES	4	-	1	-	-	-	5
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	-	1
TOTAL	33	33	2	4	2	25	99

TABLE II Summary of IOA Failure Modes and Criticalities (ARCS HW)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
<u>HE PRESS SUBSYSTEM</u>							
STORAGE TANK	1	-	-	-	-	-	1
TANK ISOLATION VALVES	-	1	-	1	-	-	2
REGULATOR ASSEMBLIES	-	5	-	1	-	-	6
QUAD CHECK VALVE ASSEMBLY	-	2	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	2	-	-	-	2	4
COUPLINGS (DOUBLE SEAL)	-	-	-	2	-	2	4
LINES AND FITTINGS	2	2	-	-	-	-	4
<u>PROP STOR &amp; DIST SUBSYSTEM</u>							
PROPELLANT TANKS	1	-	-	-	-	-	1
PROPELLANT CHANNEL SCREENS	1	-	-	-	-	-	1
PROPELLANT FEEDOUT TUBES	1	-	-	-	-	-	1
PRESSURE RELIEF ASSEMBLIES	1	1	-	-	-	-	2
GROUND MANUAL ISOL VALVES	2	-	-	-	-	1	3
GIMBAL BELLOWS	2	-	-	-	-	-	2
TANK ISOL VALVES	2	1	1	1	1	-	6
CROSSFEED VALVES	2	-	4	-	-	-	6
MANIFOLD ISOL VLVS, PRIMARY	2	-	-	4	-	4	10
MANIFOLD ISOL VLVS, VERNIER	-	-	1	-	-	1	2
JET ALIGNMENT BELLOWS, PRIMARY	2	-	-	-	-	-	2
JET ALIGNMENT BELLOWS, VERNIER	2	-	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	10	-	-	-	10	20
COUPLINGS (DOUBLE SEAL)	-	-	-	4	-	4	8
LINES AND FITTINGS	4	-	-	-	-	-	4
<u>THRUSTER SUBSYSTEM</u>							
PRIMARY JETS							
BIPROP SOLENOID VALVES	6	-	-	3	-	-	9
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	-	1
VERNIER JETS							
BIPROP SOLENOID VALVES	4	-	1	-	-	-	5
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	-	1
TOTAL	37	24	7	16	1	24	109

TABLE III Summary of IOA Failure Modes and Criticalities (FRCS EPD&C)

Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
<b>HE PRESS SUBSYSTEM</b>							
CONTROLS							
VALVES							
CONTROLLER	-	3	-	4	-	1	8
DIODE	-	4	-	4	-	4	12
DRIVER	-	3	-	6	-	3	12
FUSE	-	-	-	2	-	-	2
RESISTOR	-	-	-	-	-	16	16
SWITCH, TOGGLE	-	-	-	10	-	5	15
INSTRUMENTATION							
INDICATOR, POSITION	-	-	-	1	-	-	1
SENSOR, PRESSURE	-	-	-	-	-	8	8
SENSOR, TEMPERATURE	-	-	-	-	-	6	6
<b>PROP STOR &amp; DIST SUBSYSTEM</b>							
CONTROLS							
VALVES							
CONTROLLER	-	-	-	-	3	3	6
DIODE	-	4	-	50	4	114	172
DRIVER	-	4	1	-	3	28	36
FUSE	-	-	-	6	1	3	10
RELAY	-	16	-	4	-	20	40
RESISTOR	-	-	-	-	-	108	108
SWITCH, TOGGLE	-	-	-	10	23	48	81
INSTRUMENTATION							
INDICATOR, POSITION	-	-	-	5	1	-	6
SENSOR, PRESSURE	-	-	-	-	-	24	24
SENSOR, TEMPERATURE	-	-	-	-	-	14	14
<b>THRUSTER SUBSYSTEM</b>							
CONTROLS							
VALVES							
CONTROLLER	-	-	13	-	4	7	24
DIODE	-	-	4	-	19	15	38
DRIVER	-	-	8	-	3	1	12
FUSE	-	-	6	-	4	3	13
RELAY	-	-	3	-	-	3	6
RESISTOR	-	-	-	-	6	74	80
SWITCH, TOGGLE	-	-	23	-	31	20	74
INSTRUMENTATION							
SENSOR, CONTINUITY	-	-	-	-	-	4	4
SENSOR, PRESSURE	-	-	-	-	10	-	10
SENSOR, TEMPERATURE	-	-	-	-	10	-	10

TABLE III Summary of IOA Failure Modes and Criticalities(FRCS EPD&C)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
THERMAL CONTROL SUBSYSTEM							
THRUSTERS							
FUSE	-	-	5	-	-	-	5
HEATER	-	-	2	2	4	-	8
RESISTOR	-	-	-	-	-	10	10
SWITCH, THERMAL	-	4	1	1	2	-	8
SWITCH, TOGGLE	-	-	14	10	5	11	40
POD							
DRIVER	-	-	-	-	24	-	24
FUSE	-	-	-	-	12	-	12
HEATER	-	-	-	-	12	-	12
RELAY	-	-	-	-	4	-	4
RESISTOR	-	-	-	-	4	12	16
SWITCH, TOGGLE	-	-	-	-	3	-	3
THERMOSTAT	-	-	-	-	4	-	4
TOTAL	-	38	80	115	196	565	994



TABLE IV Summary of IOA Failure Modes and Criticalities (ARCS EPD&C)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
HE PRESS SUBSYSTEM							
CONTROLS							
VALVES							
CONTROLLER	-	-	-	16	-	-	16
DIODE	-	-	-	8	-	12	20
DRIVER	-	2	-	18	-	4	24
FUSE	-	-	-	4	-	-	4
RESISTOR	-	-	-	-	-	32	32
SWITCH, TOGGLE	-	-	-	10	-	5	15
INSTRUMENTATION							
INDICATOR, POSITION	-	-	-	1	-	-	1
SENSOR, PRESSURE	-	-	-	-	-	8	8
SENSOR, TEMPERATURE	-	-	-	-	-	4	4
PROP STOR & DIST SUBSYSTEM							
CONTROLS							
VALVES							
CONTROLLER	-	-	-	-	3	3	6
DIODE	-	3	-	3	9	25	40
DRIVER	-	-	4	4	5	39	52
FUSE	-	-	-	6	9	2	17
RELAY	-	-	12	15	10	11	48
RESISTOR	-	-	-	-	-	158	158
SWITCH, TOGGLE	-	2	-	22	42	43	109
INSTRUMENTATION							
INDICATOR, POSITION	-	-	-	3	1	-	4
SENSOR, PRESSURE	-	-	-	-	-	8	8
SENSOR, TEMPERATURE	-	-	-	-	-	4	4
THRUSTER SUBSYSTEM							
CONTROLS							
VALVES							
CONTROLLER	-	-	2	-	24	10	36
DIODE	-	-	2	-	50	20	72
DRIVER	-	-	4	-	16	4	24
FUSE	-	-	-	-	19	-	19
RELAY	-	-	-	-	3	3	6
RESISTOR	-	-	-	-	9	113	122
SWITCH, TOGGLE	-	-	8	-	48	56	112
INSTRUMENTATION							
SENSOR, CONTINUITY	-	-	-	-	-	5	5
SENSOR, PRESSURE	-	-	-	8	-	12	20
SENSOR, TEMPERATURE	-	-	-	3	1	8	12

TABLE IV Summary of IOA Failure Modes and Criticalities (ARCS EPD&C)							
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	3/3	TOTAL
THERMAL CONTROL SUBSYSTEM							
THRUSTERS							
DRIVER	-	-	1	9	-	-	10
FUSE	-	-	2	4	-	-	6
HEATER	-	-	2	6	-	-	8
RESISTOR	-	-	-	-	-	10	10
SWITCH, THERMAL	-	4	1	3	-	-	8
SENSOR, TOGGLE	-	-	10	10	-	10	30
TOTAL	-	11	48	153	249	609	1070

TABLE V Summary of IOA Potential Critical Items (FRCS HW)						
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	TOTAL
<u>HE PRESS SUBSYSTEM</u>						
STORAGE TANK	1	-	-	-	-	1
TANK ISOLATION VALVES	-	1	-	-	-	1
REGULATOR ASSEMBLIES	-	5	-	-	-	5
QUAD CHECK VALVE ASSEMBLY	-	2	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	3	-	-	-	3
LINES AND FITTINGS	2	2	-	-	-	4
<u>PROP STOR &amp; DIST SUBSYSTEM</u>						
PROPELLANT TANKS	1	-	-	-	-	1
PROPELLANT CHANNEL SCREENS	1	-	-	-	-	1
PROPELLANT FEEDOUT TUBES	1	-	-	-	-	1
PRESSURE RELIEF ASSEMBLIES	1	1	-	-	-	2
GROUND MANUAL ISOL VALVES	2	-	-	-	-	2
GIMBAL BELLOWS	2	-	-	-	-	2
TANK ISOL VALVES	2	2	-	-	-	4
MANIFOLD ISOL VLVS, PRIMARY	2	4	-	-	-	6
MANIFOLD ISOL VLVS, VERNIER	-	-	1	-	-	1
JET ALIGNMENT BELLOWS, PRIMARY	2	-	-	-	-	2
JET ALIGNMENT BELLOWS, VERNIER	2	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	12	-	-	-	12
LINES AND FITTINGS	2	-	-	-	-	2
<u>THRUSTER SUBSYSTEM</u>						
PRIMARY JETS						
BIPROP SOLENOID VALVES	6	1	-	-	-	7
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	1
VERNIER JETS						
BIPROP SOLENOID VALVES	4	-	1	-	-	5
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	1
TOTAL	33	33	2	-	-	68

TABLE VI Summary of IOA Potential Critical Items (ARCS HW)						
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	TOTAL
<u>HE PRESS SUBSYSTEM</u>						
STORAGE TANK	1	-	-	-	-	1
TANK ISOLATION VALVES	-	1	-	-	-	1
REGULATOR ASSEMBLIES	-	5	-	-	-	5
QUAD CHECK VALVE ASSEMBLY	-	2	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	2	-	-	-	2
LINES AND FITTINGS	2	2	-	-	-	4
<u>PROP STOR &amp; DIST SUBSYSTEM</u>						
PROPELLANT TANKS	1	-	-	-	-	1
PROPELLANT CHANNEL SCREENS	1	-	-	-	-	1
PROPELLANT FEEDOUT TUBES	1	-	-	-	-	1
PRESSURE RELIEF ASSEMBLIES	1	1	-	-	-	2
GROUND MANUAL ISOL VALVES	2	-	-	-	-	2
GIMBAL BELLOWS	2	-	-	-	-	2
TANK ISOL VALVES	2	1	1	-	1	5
CROSSFEED VALVES	2	-	4	-	-	6
MANIFOLD ISOL VLVS, PRIMARY	2	-	-	4	-	6
MANIFOLD ISOL VLVS, VERNIER	-	-	1	-	-	1
JET ALIGNMENT BELLOWS, PRIMARY	2	-	-	-	-	2
JET ALIGNMENT BELLOWS VERNIER	2	-	-	-	-	2
COUPLINGS (SINGLE SEAL)	-	10	-	-	-	10
LINES AND FITTINGS	4	-	-	-	-	4
<u>THRUSTER SUBSYSTEM</u>						
PRIMARY JETS						
BIPROP SOLENOID VALVES	6	-	-	-	-	6
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	1
VERNIER JETS						
BIPROP SOLENOID VALVES	4	-	1	-	-	5
COMBUSTION CHAMBER OR NOZZLE	1	-	-	-	-	1
TOTAL	37	24	7	4	1	73

TABLE VII Summary of IOA Potential Critical Items (FRCS EPD&C)						
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	TOTAL
HE PRESS SUBSYSTEM						
CONTROLS						
VALVES						
CONTROLLER	-	3	-	-	-	3
DIODE	-	4	-	4	-	8
DRIVER	-	3	-	2	-	5
FUSE	-	-	-	1	-	1
SWITCH, TOGGLE	-	-	-	5	-	5
PROP STOR & DIST SUBSYSTEM						
CONTROLS						
VALVES						
DIODE	-	4	-	42	2	48
DRIVER	-	4	1	-	-	5
RELAY	-	16	-	4	-	20
SWITCH, TOGGLE	-	-	-	6	12	18
THRUSTER SUBSYSTEM						
CONTROLS						
VALVES						
CONTROLLER	-	-	13	-	-	13
DIODE	-	-	4	-	19	23
DRIVER	-	-	8	-	-	8
FUSE	-	-	6	-	-	6
RELAY	-	-	3	-	-	3
RESISTOR	-	-	-	-	6	6
SWITCH, TOGGLE	-	-	23	-	-	23
THERMAL CONTROL SUBSYSTEM						
THRUSTERS						
FUSE	-	-	5	-	-	5
HEATER	-	-	2	-	-	2
SWITCH, THERMAL	-	4	1	-	-	5
SWITCH, TOGGLE	-	-	14	1	-	15
TOTAL	-	38	80	65	39	222

TABLE VIII Summary of IOA Potential Critical Items (ARCS EPD&C)						
Criticality:	1/1	2/1R	2/2	3/1R	3/2R	TOTAL
HE PRESS SUBSYSTEM						
CONTROLS						
VALVES						
CONTROLLER	-	-	-	6	-	6
DIODE	-	-	-	8	-	8
DRIVER	-	2	-	4	-	6
SWITCH, TOGGLE	-	-	-	5	-	5
PROP STOR & DIST SUBSYSTEM						
CONTROLS						
VALVES						
CONTROLLER	-	-	-	-	2	2
DIODE	-	3	-	3	9	15
DRIVER	-	-	4	4	2	10
RELAY	-	-	12	13	8	33
SWITCH, TOGGLE	-	2	-	6	19	27
THRUSTER SUBSYSTEM						
CONTROLS						
VALVES						
CONTROLLER	-	-	2	-	-	2
DIODE	-	-	2	-	50	52
DRIVER	-	-	4	-	-	4
FUSE	-	-	-	-	7	7
RESISTOR	-	-	-	-	9	9
SWITCH, TOGGLE	-	-	8	-	-	8
THERMAL CONTROL SUBSYSTEM						
THRUSTERS						
DRIVER	-	-	1	9	-	10
FUSE	-	-	2	4	-	6
HEATER	-	-	2	-	-	2
SWITCH, THERMAL	-	4	1	-	-	5
SWITCH, TOGGLE	-	-	10	-	-	10
TOTAL	-	11	48	62	106	227

#### 4.1 Analysis Results - Helium Pressurization Subsystem

##### 4.1.1 Analysis Results - Forward Helium Pressurization Subsystem

Twenty-three (23) failure modes were analyzed in the forward helium pressurization subsystem and sixteen (16) were identified as PCIs. All sixteen of the PCIs are single point failures which could result in possible damage to surrounding components, inability to repressurize the propellant tanks, system overpressurization, or migration of propellants into helium lines.

These critical failures are caused by helium tank structural failure, helium leakage due to structural failure of components or lines, flow path loss due to failure-to-open of components or system contamination, and check valve failures.

##### 4.1.2 Analysis Results - Aft Helium Pressurization Subsystem

Twenty-three (23) failure modes were analyzed in the aft helium pressurization subsystem and fifteen (15) were identified as PCIs. All fifteen of the PCIs are single point failures which could result in possible damage to surrounding components, inability to repressurize the propellant tanks, system overpressurization, or migration of propellants into helium lines.

These critical failures are caused by helium tank structural failure, helium leakage due to structural failure of components or lines, flow path loss due to failure-to-open of components or system contamination, and check valve failures.

#### 4.2 Analysis Results - Propellant Storage and Distribution Subsystem

##### 4.2.1 Analysis Results - Forward Propellant Storage and Distribution Subsystem

Sixty (60) failure modes were analyzed in the forward propellant storage and distribution subsystem, of which thirty-eight (38) were identified as PCIs. All thirty-eight of the PCIs are single point failures which could result in leakage of propellant, loss of propellant flow path, inability to use or deplete propellant, system overpressurization, loss of manifolds, and loss of thrusters.

These critical failures are caused by structural failure of the propellant tank, components, and propellant lines, seal failures, contamination, failure of valves to operate, failure of the pressure relief assembly, and propellant tank screen structural failures.

#### 4.2.2 Analysis Results - Aft Propellant Storage and Distribution Subsystem

Seventy (70) failure modes were analyzed in the aft propellant storage and distribution subsystem, of which forty-five (45) were identified as PCIs. Forty (40) of the forty-five PCIs are single point failures which could result in leakage of propellant, loss of propellant flow path, inability to use or deplete propellant, system overpressurization, loss of manifolds or crossfeed valves, loss of thrusters, and loss of vehicle control. The remaining five (5) PCIs could result in loss of life or vehicle during an RTLS abort due to the inability to complete OMS or RCS propellant dumps leading to possible violations of pod structural constraints or vehicle entry center-of-gravity limits.

These critical failures are caused by structural failure of the propellant tank, components, and propellant lines, seal failures, contamination, failure of valves to operate, failure of the pressure relief assembly, and propellant tank screen structural failures.

#### 4.3 Analysis Results - Thruster Subsystem

##### 4.3.1 Analysis Results - Forward Thruster Subsystem

Sixteen (16) failure modes were analyzed in the forward thruster subsystem, of which fourteen (14) were identified as PCIs. All of the fourteen PCIs are single point failures resulting in excessive propellant usage, leakage of propellant, loss of propellant flow path, engine explosion or burnthrough, loss of thruster on-off control, and inability to deplete propellants leading to Orbiter center-of-gravity limit violations during entry.

These critical failures are caused by loss of vernier jets, structural failure of components and propellant lines, seal failures, contamination, failure to open or close of thruster valves, deselection of opposite-firing thrusters by Redundancy Management, improper propellant mixture ratios, and structural failures of the injector assembly, combustion chamber, and nozzle extension.

##### 4.3.2 Analysis Results - Aft Thruster Subsystem

Sixteen (16) failure modes were analyzed in the aft thruster subsystem, of which thirteen (13) were identified as PCIs. All of the thirteen PCIs are single point failures resulting in excessive propellant usage, leakage of propellant, loss of propellant flow path, engine explosion or burnthrough, loss of thruster on-off control, or loss of vehicle control.

These critical failures are caused by loss of vernier jets, structural failure of components and propellant lines, seal failures, contamination, failure to open or close of thruster



valves, deselection of opposite-firing thrusters by Redundancy Management, improper propellant mixture ratios, and structural failures of the injector assembly, combustion chamber, and nozzle extension.

#### 4.4 Analysis Results - Electrical Power Distribution and Control Subsystem

##### 4.4.1 Analysis Results - Controls

##### 4.4.1.1 Analysis Results - Forward Controls

Seven hundred sixty-five (765) failure modes were analyzed in the forward EPD&C controls subsystem, of which one hundred ninety-five (195) were identified as PCIs. Of the 195 PCIs, ninety-two (92) are single point failures since their failure resulted in critical valves being stuck open or closed. Another sixty-four (64) of the 195 PCIs could result in loss of vehicle/ life if all redundancy were lost. The remaining thirty-nine (39) PCIs could result in loss of mission if all redundancy were lost.

Criticalities assigned to forward EPD&C failure modes were derived from the effect the failure had on the component being controlled, which was one or more valves, in all cases. Therefore, critical EPD&C failure modes caused critical valves to be stuck open or closed resulting in inability to use or deplete propellant, system overpressurization, zots, loss of manifolds, and loss of thrusters.

##### 4.4.1.2 Analysis Results - Aft Controls

Nine hundred thirty-two (932) failure modes were analyzed in the aft EPD&C controls subsystem, of which one hundred ninety-four (194) were identified as PCIs. Of the 194 PCIs, thirty-nine (39) are single point failures since their failure resulted in critical valves being stuck open or closed. Another forty-nine (49) of the 194 PCIs could result in loss of vehicle/life if all redundancy were lost. The remaining one hundred six (106) PCIs could result in loss of mission if all redundancy were lost.

Criticalities assigned to aft EPD&C failure modes were derived from the effect the failure had on the component being controlled, which was one or more valves, in all cases. Therefore, critical EPD&C failure modes caused critical valves to be stuck open or closed resulting in inability to use or deplete propellant, system overpressurization, zots, loss of manifolds, loss of thrusters, and loss of vehicle control.

##### 4.4.2 Analysis Results - Instrumentation

##### 4.4.2.1 Analysis Results - Forward Instrumentation

Eighty-three (83) failure modes have been analyzed in the forward EPD&C instrumentation subsystem, of which zero (0) were PCIs.

#### 4.4.2.2 Analysis Results - Aft Instrumentation

Sixty-six (66) failure modes have been analyzed in the aft EPD&C instrumentation subsystem, of which zero (0) were PCIs.

#### 4.4.3 Analysis Results - Thermal Control

##### 4.4.3.1 Analysis Results - Forward Thermal Control

Seventy-five (75) failure modes were analyzed in the forward pod thermal control subsystem, of which zero (0) were identified as PCIs.

Seventy-one (71) failure modes were analyzed in the forward thruster thermal control subsystem, of which twenty-seven (27) were identified as PCIs. Twenty-six (26) of the 27 PCIs are single point failures resulting in thruster explosion or loss of thruster thermal control and unplanned changes in mission operations. The remaining one (1) PCI could result in loss of life or vehicle after the failure of all redundancy.

##### 4.4.3.2 Analysis Results - Aft Thermal Control

All of the OMS/RCS pod heaters and thermostats were analyzed in the OMS analysis and are presented in the OMS report.

Seventy-two (72) failure modes were analyzed in the aft thruster thermal control subsystem, of which thirty-three (33) were identified as PCIs. Twenty (20) of the 33 PCIs are single point failures resulting in thruster explosion or loss of thruster thermal control and unplanned changes in mission operations. The remaining thirteen (13) PCIs could result in loss of life or vehicle after the loss of redundancy.

## 5.0 REFERENCES

Reference documentation available from NASA and Rockwell was used in the analysis. The documentation used included the following:

1. Reaction Control System Workbook, RCS 2102, March 3, 1980
2. Reaction Control System Shuttle Flight Operations Manual, Volume 8D, March 31, 1980
3. OMS/RCS Systems Briefs Handbook, October 1, 1984
4. STS Operational Flight Rules Rationale, December 16, 1985 and PCN-1, February 14, 1986
5. NSTS 22206, Instructions for Preparation of FMEA and CIL, October 10, 1986.
6. Reliability Desk Instruction, No. 100-2G, Flight Hardware FMEA & CIL, 1-31-84.
7. VS70-942102 Rev. G, 6-7-84, FRCS Integrated System Schematics, 102, RI Level III.
8. VS70-942099 Rev. D, EOD01, 8-30-84, FRCS Integrated System Schematics, 099, 103, 104, RI Level III.
9. VS70-943099, Rev. B, EOB12, 7-22-85, OMS/RCS Integrated System Schematics, 099, 103, 104, RI Level III.
10. VS70-943102, Rev. C, 10-29-80, OMS/RCS Integrated System Schematics, 102, RI Level III.
11. MB0160-007, Rev M, 3-11-80, Steel Tubing, Mat'l spec., RI.
12. MC276-0017, Rev D, 6-23-84, Helium High Pressure Coupling, Proc. spec., RI.
13. MC276-0018, Rev B, 2-14-84, Hypergolic Service Coupling, Proc. spec., RI.
14. MC282-0082, Rev D, 3-17-82, Pressurant Storage Tank, Proc. spec., RI.
15. MC284-0421, Rev E, 5-3-82, Pressure Relief Valve, Proc. spec., RI.
16. MC284-0430, Rev E, 6-22-81, AC Motor Valve, Proc. spec., RI.
17. MC284-0480, Rev C, 5-3-82, Manual Operated Valve, Proc. spec., RI.
18. MC284-0481, Rev B, 6-23-84, Quad Check Valve, Proc. spec., RI

19. MC363-0031, Rev C, 3-15-78, Electrical Heater, Detail Proc. spec., RI.
20. ME276-0032, Rev B, 7-20-79, Test Point Coupling, Spec. Control Dwg., RI.
21. AMS5562A, 7-15-80, Steel Tubing, Mat'l spec., SAE.
22. 73P550015, Rev B, 3-22-82, Gimbal Bellows, Proc. spec., MDAC.
23. 73P550003 Alignment Bellows Drawing, MDAC.
24. MC282-0061, Rev. G, RCS Propellant Tank, Proc. Spec., MDAC.
25. MC271-0095, RCS Propellant Line Flexible Assembly, Proc. Spec., MDAC.
26. MC467-0029, Rev. G, RCS Vernier Thruster Assembly, Proc. Spec., MDAC.
27. VS70-420309, Rev. D, 6-4-84, Aft RCS Subsystem Control Left OMS Pod Schematic Diagram.
28. JSC-11174, Space Shuttle Systems Handbook, Rev. C, DNC-5, 9-13-85.

# APPENDIX A ACRONYMS

AC	- Alternating Current
ALC	- Aft Load Controller
ALCA	- Aft Load Control Assembly
AMCA	- Aft Motor Control Assembly
AOA	- Abort-Once-Around
APC	- Aft Power Controller
ARCS	- Aft Reaction Control System (Subsystem)
ASSY	- Assembly
ATO	- Abort-To-Orbit
ATT	- Attitude
BCE	- Bus Control ELEMENT
BFS	- Backup Flight System
BTU	- Bus Terminal Unit
C&W	- Caution and Warning
CIL	- Critical Items List
CL	- Close (Closed)
CMD	- Command, Commander
CNTL	- Control
CNTLR	- Controller
CRIT	- Criticality
CRT	- Cathode-Ray Tube
D&C	- Displays and Controls
DAP	- Digital Autopilot
dc	- Direct Current
DOD	- Department of Defense
DPS	- Data Processing System (Subsystem)
DTO	- Detailed Test Objective
EI	- Entry Interface
EPDC	- Electrical Power Distribution and Control
ET	- External Tank
F	- Fahrenheit
F	- Functional
FA	- Flight Aft
FCOS	- Flight Control Operating System
FDA	- Fault Detection and Annunciation
FF	- Flight Forward
FLCA	- Forward Load Control Assembly
FLT	- Flight
FM	- Failure Mode
FMCA	- Forward Motor Control Assembly
FMEA	- Failure Modes and Effects Analysis
FRCS	- Forward Reaction Control System (Subsystem)
FSW	- Flight Software
ft	- Feet
FU	- Fuel
FUNC	- Function
FWD	- Forward
G	- Gravity
GFE	- Government Furnished Equipment
GNC	- Guidance, Navigation, and Control

GPC	-	General Purpose Computer
GSE	-	Ground Support Equipment
He	-	Helium
HW	-	Hardware
I/C	-	Interconnect
I/O	-	Input/Output
ID	-	Inside Diameter
IMU	-	Inertial Measurement Unit
IOA	-	Independent Orbiter Assessment
ISOL	-	Isolation
ISP	-	Initial Specific Impulse
JSC	-	Johnson Space Center
L	-	Left
LCA	-	Load Controller Assembly
LRU	-	Line Replaceable Unit
MAN	-	Manual
MCA	-	Motor Control Assembly
MCC	-	Mission Control Center (JSC)
MDAC	-	McDonnell Douglas Astronautics Company
MDM	-	Multiplexer/Demultiplexer
MECO	-	Main Engine Cutoff
MM	-	Major Mode
MMH	-	Monomethyl Hydrazine
msec	-	Millisecond
N2O4	-	Nitrogen Tetroxide
NA	-	Not Applicable
NASA	-	National Aeronautics and Space Administration
NSTS	-	National Space Transportation System
NTO	-	Nitrogen Tetroxide
OA	-	Operational Aft
OF	-	Operational Forward
OI	-	Operational Instrumentation
OMRSD	-	Operational Maintenance Requirements and Specifications Document
OMS	-	Orbital Maneuvering System
OP	-	Open
OPS	-	Operations Sequence
OX	-	Oxidizer
OXID	-	Oxidizer
P	-	Pitch
PAD	-	Propellant Acquisition Device
PASS	-	Primary Avionics Software System
PBI	-	Push-Button Indicator
Pc	-	Chamber Pressure
PCA	-	Power Control Assembly
PCI	-	Potential Critical Item
PCM	-	Pulse Code Modulation
PCMMU	-	Pulse Code Modulation Master Unit
PLS	-	Primary Landing Site
PRCS	-	Primary Reaction Control System (jet)
PRESS	-	Pressure
PROC	-	Processor
psi	-	Pounds per Square Inch
psia	-	Pounds per Square Inch Absolute

psid	- Pounds per Square Inch Differential
psig	- Pounds per Square Inch Gage
PTI	- Programmed Test Input
PWR	- Power
R	- Right
R	- Roll
RCS	- Reaction Control System
RHC	- Rotation Hand Controller
RI	- Rockwell International
RJD	- Reaction Jet Driver
RM	- Redundancy Management
RPC	- Remote Power Controller
RTLS	- Return-to-Launch Site
scfm	- Standard Cubic Feet per Minute
SFOM	- Shuttle Flight Operations Manual
SOP	- Subsystem Operating Program
SPEC	- Specification
SSSH	- Space Shuttle Systems Handbook
STS	- Space Transportation System
SUM	- Summary
SYS	- System
TAL	- Transatlantic Abort Landing
THC	- Translation Hand Controller
TK	- Tank
TPS	- Thermal Protection System
VERN	- Vernier
VLV	- Valve
VRCS	- Vernier Reaction Control System (jet)
Y	- Yaw





## APPENDIX B

### DEFINITIONS, GROUND RULES, AND ASSUMPTIONS

- B.1 Definitions
- B.2 Project Level Ground Rules and Assumptions
- B.3 Subsystem-Specific Ground Rules and Assumptions

APPENDIX B  
DEFINITIONS, GROUND RULES, AND ASSUMPTIONS

B.1 Definitions

Definitions contained in NSTS 22206, Instructions For Preparation of FMEA/CIL, 10 October 1986, were used with the following amplifications and additions.

INTACT ABORT DEFINITIONS:

RTLS - begins at transition to OPS 6 and ends at transition to OPS 9, post-flight

TAL - begins at declaration of the abort and ends at transition to OPS 9, post-flight

AOA - begins at declaration of the abort and ends at transition to OPS 9, post-flight

ATO - begins at declaration of the abort and ends at transition to OPS 9, post-flight

CREDIBLE (CAUSE) - an event that can be predicted or expected in anticipated operational environmental conditions. Excludes an event where multiple failures must first occur to result in environmental extremes

CONTINGENCY CREW PROCEDURES - procedures that are utilized beyond the standard malfunction procedures, pocket checklists, and cue cards

EARLY MISSION TERMINATION - termination of onorbit phase prior to planned end of mission

EFFECTS/RATIONALE - description of the case which generated the highest criticality

HIGHEST CRITICALITY - the highest functional criticality determined in the phase-by-phase analysis

MAJOR MODE (MM) - major sub-mode of software operational sequence (OPS)

MC - Memory Configuration of Primary Avionics Software System (PASS)

MISSION - assigned performance of a specific Orbiter flight with payload/objective accomplishments including orbit phasing and altitude (excludes secondary payloads such as GAS cans, middeck P/L, etc.)

MULTIPLE ORDER FAILURE - describes the failure due to a single cause or event of all units which perform a necessary (critical) function

OFF-NOMINAL CREW PROCEDURES - procedures that are utilized beyond the standard malfunction procedures, pocket checklists, and cue cards

OPS - software operational sequence

PRIMARY MISSION OBJECTIVES - worst case primary mission objectives are equal to mission objectives

PHASE DEFINITIONS:

PRELAUNCH PHASE - begins at launch count-down Orbiter power-up and ends at moding to OPS Major Mode 102 (liftoff)

LIFTOFF MISSION PHASE - begins at SRB ignition (MM 102) and ends at transition out of OPS 1 (Synonymous with ASCENT)

ONORBIT PHASE - begins at transition to OPS 2 or OPS 8 and ends at transition out of OPS 2 or OPS 8

DEORBIT PHASE - begins at transition to OPS Major Mode 301 and ends at first main landing gear touchdown

LANDING/SAFING PHASE - begins at first main gear touchdown and ends with the completion of post-landing safing operations

APPENDIX B  
DEFINITIONS, GROUND RULES, AND ASSUMPTIONS

B.2 IOA Project Level Ground Rules and Assumptions

The philosophy embodied in NSTS 22206, Instructions for Preparation of FMEA/CIL, 10 October 1986, was employed with the following amplifications and additions.

1. The operational flight software is an accurate implementation of the Flight System Software Requirements (FSSRs).

RATIONALE: Software verification is out-of-scope of this task.

2. After liftoff, any parameter which is monitored by system management (SM) or which drives any part of the Caution and Warning System (C&W) will support passage of Redundancy Screen B for its corresponding hardware item.

RATIONALE: Analysis of on-board parameter availability and/or the actual monitoring by the crew is beyond the scope of this task.

3. Any data employed with flight software is assumed to be functional for the specific vehicle and specific mission being flown.

RATIONALE: Mission data verification is out-of-scope of this task.

4. All hardware (including firmware) is manufactured and assembled to the design specifications/drawings.

RATIONALE: Acceptance and verification testing is designed to detect and identify problems before the item is approved for use.

5. All Flight Data File crew procedures will be assumed performed as written, and will not include human error in their performance.

RATIONALE: Failures caused by human operational error are out-of-scope of this task.

6. All hardware analyses will, as a minimum, be performed at the level of analysis existent within NASA/Prime Contractor Orbiter FMEA/CILs, and will be permitted to go to greater hardware detail levels but not lesser.

RATIONALE: Comparison of IOA analysis results with other analyses requires that both analyses be performed to a comparable level of detail.

7. Verification that a telemetry parameter is actually monitored during AOS by ground-based personnel is not required.

RATIONALE: Analysis of mission-dependent telemetry availability and/or the actual monitoring of applicable data by ground-based personnel is beyond the scope of this task.

8. The determination of criticalities per phase is based on the worst case effect of a failure for the phase being analyzed. The failure can occur in the phase being analyzed or in any previous phase, whichever produces the worst case effects for the phase of interest.

RATIONALE: Assigning phase criticalities ensures a thorough and complete analysis.

9. Analysis of wire harnesses, cables, and electrical connectors to determine if FMEAs are warranted will not be performed nor FMEAs assessed.

RATIONALE: Analysis was substantially complete prior to NSTS 22206 ground rule redirection.

10. Analysis of welds or brazed joints that cannot be inspected will not be performed nor FMEAs assessed.

RATIONALE: Analysis was substantially complete prior to NSTS 22206 ground rule redirection.

11. Emergency system or hardware will include burst discs and will exclude the EMU Secondary Oxygen Pack (SOP), pressure relief valves and the landing gear pyrotechnics.

RATIONALE: Clarify definition of emergency systems to ensure consistency throughout IOA project.

APPENDIX B  
DEFINITIONS, GROUND RULES, AND ASSUMPTIONS

B.3 RCS Ground Rules and Assumptions

The IOA analysis was performed to the component or assembly level. The analysis considered the worst case effects of the hardware or functional failure on the subsystem, mission, and crew and vehicle safety.

1. The function of an RCS thruster is to provide thrust in a certain axis and direction. Therefore, from a top down system analysis approach, thrusters which fire in the same axis and direction may be considered redundant to each other. The function of electrical systems is to provide power to the components of the RCS hardware systems. Redundancy, as applied to electrical systems, is considered to be redundant electrical paths, systems, or controls. Therefore, thrusters which fire in the same direction may not be considered redundant to an electrical failure. Thruster hardware and certain electrical components may be grouped by firing axes.
2. For the ARCS, entry criticalities are dependent on the number of pitch, yaw, and roll thrusters available (e.g., loss of pitch control results in loss of vehicle). Abort criticalities for both FRCS and ARCS are also dependent upon the number of thrusters available in certain axes. All aft RCS pitch, yaw, and roll thrusters and all forward RCS yaw thrusters are required for the successful completion of OMS/RCS propellant dumps during RTLS aborts. The time available to complete propellant dumps is less during RTLS than during other intact abort modes.
3. Only PASS software is considered in this analysis. BFS is not considered for flight or abort analyses. RCS Redundancy Management (RM), certain software sequences, and Software Operating Procedures (SOPs) are considered in the analysis.
4. Inability to accomplish DTOs or PTIs during entry due to an RCS failure can lead to loss of mission during the deorbit phase.
5. Internal leakage of a valve is fluid which leaks through the valve into the line. External leakage of a valve is fluid which leaks through the valve housing.

6. Coupling caps are considered redundancy for quick disconnect couplings. Leaks through poppet seals and coupling caps are assumed to be leaking overboard, not internally. Where it cannot be determined how many seals exist in a coupling, it will be assumed that only a poppet seal and a cap seal exist.
7. The pressure relief valve is considered to be an emergency system because it incorporates a burst disk.
8. If applicable, the redundancy and criticalities assigned to an electrical component may be tied to those assigned to hardware components affected by the failure of the electrical component.
9. Software capabilities which allow control over the operation of hardware components are considered to be redundant to electrical components which control the operation.
10. For the thermal control analysis it is assumed that, at the time of vehicle liftoff, all areas of the thermal environment are within redlines.
11. Instrumentation passage of screen B does not require the ability to discern between sensor or hardware failure, but on detection of the measurement being out of a predefined limit. The ability to differentiate between sensor and hardware failure will be reflected in the criticality assignment.
12. It is assumed that propellants leaking through RCS thrusters will not freeze during aborts due to the short duration of these phases.
13. It is assumed that after the failure of an RCS thruster, the RCS redundancy management will automatically deselect the opposite-firing thruster.
14. The Shuttle Launch Commit Criteria and Background (JSC 16007) and the Operational Maintenance Requirements and Specifications Document (OMRSD) will not be used to determine the passage of redundancy screens. The criteria for determining screen passage outlined in NSTS 22206 will be used as the basis for the passage or failure of the redundancy screens.





## APPENDIX C DETAILED ANALYSIS

This section contains the IOA analysis worksheets generated during the analysis of this subsystem. The information on these worksheets is intentionally similar to the NASA FMEAs. Each of these sheets identifies the hardware item being analyzed and parent assembly. For each failure mode, the possible causes are outlined, and the assessed hardware and functional criticality for each mission phase is listed, as described in the NSTS 22206, Instructions for Preparation of FMEA and CIL, 10 October 1986. Finally, effects are entered at the bottom of each sheet, and the worst case criticality is entered at the top.

### LEGEND FOR IOA ANALYSIS WORKSHEETS

-----

#### Hardware Criticalities:

- 1 = Loss of life or vehicle
- 2 = Loss of mission or next failure of any redundant item (like or unlike) could cause loss of life/vehicle
- 3 = All others

#### Functional Criticalities:

- 1R = Redundant hardware items (like or unlike) all of which, if failed, could cause loss of life or vehicle.
- 2R = Redundant hardware items (like or unlike) all of which, if failed, could cause loss of mission.

#### Redundancy Screen A:

- 1 = Is Checked Out PreFlight
- 2 = Is Capable of Check Out PreFlight
- 3 = Not Capable of Check Out PreFlight
- NA = Not Applicable

#### Redundancy Screens B and C:

- P = Passed Screen
- F = Failed Screen
- NA = Not Applicable

### LEGEND FOR IOA RCS MDAC ID

-----

- 100- 198 - Forward RCS Hardware
- 199- 307 - Aft RCS Hardware
- 308-1301 - Forward RCS EPD&C
- 1302-2371 - Aft RCS EPD&C

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	100	ABORT:	1/1

ITEM: HELIUM STORAGE TANK  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM STORAGE TANK
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	2/2	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: MECHANICAL SHOCK, HIGH PRESSURE, VIBRATION

EFFECTS/RATIONALE:

LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 C, D.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 101 ABORT: 2/1R

ITEM: HELIUM FILL COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM FILL COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL CAUSE LOSS OF HELIUM PRESSURIZATION  
CAPABILITY. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT  
OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE  
EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S  
WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 A, B.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	102	ABORT:	3/3

ITEM: HELIUM FILL COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM FILL COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 103 ABORT: 3/1R

ITEM: HE ISOL A & B VLVS  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN) OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE ISOL A & B VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
REDUNDANCY PROVIDED BY PRESSURE REGULATORS. FAILURE OF ALL  
REDUNDANCY WILL CAUSE OVERPRESSURIZATION AND RUPTURE OF TANKS  
AND/OR LINES, AND MAY CAUSE ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 104 ABORT: 2/1R

ITEM: HE ISOL A & B VLVS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE ISOL A & B VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

STANDBY REDUNDANCY. NEXT ASSOCIATED FAILURE (OTHER VALVE A OR B) WILL CAUSE LOSS OF HELIUM PRESSURIZATION CAPABILITY. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 C, D.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 105 ABORT: 1/1

ITEM: HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	2/2	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN HELIUM TANK AND QUAD CHECK VALVES  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

FAILURE WILL CAUSE LOSS OF HELIUM PRESSURIZATION CAPABILITY, WILL AFFECT ONORBIT OPERATIONS, AND WILL CAUSE THE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	106	ABORT:	1/1

ITEM: HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN HELIUM TANK AND QUAD CHECK VALVES  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 107 ABORT: 2/1R

ITEM: HE LINE, ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: BETWEEN HELIUM ISOLATION VALVES AND PRESSURE  
REGULATOR  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:  
REDUNDANCY PROVIDED BY CLOSING HELIUM ISOLATION VALVE, AND USING  
THE PARALLEL HELIUM SUPPLY PATH. FAILURE CAUSES LOSS OF HELIUM  
PRESSURIZATION. NEXT ASSOCIATED FAILURE WILL AFFECT ONORBIT  
OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE  
EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S  
WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 108 ABORT: 2/1R

ITEM: HE LINE, ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: BETWEEN HELIUM ISOLATION VALVES AND PRESSURE  
REGULATOR  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL HELIUM PATH. FAILURE MAY CAUSE  
UNACCEPTABLE PROPELLANT MIXTURE RATIO, RESULTING IN ZOTS AND/OR  
THRUSTER NOZZLE BURNTHROUGH AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 109 ABORT: 3/1R

ITEM: HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FUEL/OXIDIZER PRESSURE SYSTEM INTERNAL PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
FAILURE OF ALL REDUNDANCY WILL CAUSE LOSS OF HELIUM  
PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION WILL AFFECT  
ONORBIT OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE  
EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S  
WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 A, B.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	110	ABORT:	3/3

ITEM: HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER PRESSURE SYSTEM INTERNAL PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 111 ABORT: 3/1R

ITEM: HE PRESS REGULATOR ASSEMBLY  
FAILURE MODE: FAILS OPEN OR REGULATES AT HIGHER THAN NORMAL  
PRESSURE

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE PRESS REGULATOR ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/1R	RTLS: 3/1R
LIFTOFF:	3/1R	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
REDUNDANCY PROVIDED BY THE HELIUM ISOLATION VALVE AND THE SERIES  
PRESSURE REGULATOR. FAILURE OF ALL REDUNDANCY WILL CAUSE  
OVERPRESSURIZATION AND RUPTURE OF THE TANK AND LINES, AND MAY  
CAUSE ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 A, B.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 113 ABORT: 2/1R

ITEM: HE PRESS REGULATOR ASSEMBLY  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE PRESS REGULATOR ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, BLOCKAGE OF INLET FILTER

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL REGULATOR. RESTRICTED FLOW THROUGH REGULATORS MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIOS, WHICH MAY RESULT IN ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 115 ABORT: 2/1R

ITEM: HE PRESS REGULATOR PRIMARY SENSING PORT  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE PRESS REGULATOR PRIMARY SENSING PORT
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL HELIUM PATH AND MANUAL OPERATION OF THE HELIUM ISOLATION VALVE. NEXT ASSOCIATED FAILURE WILL RESULT IN LOSS OF HELIUM PRESSURIZATION CAUSING THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ENTRY OR ABORTS TO MEET THE CG SAFETY BOUNDARIES DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-50.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	117	ABORT:	2/1R

ITEM: HE PRESS REGULATOR OUTLET TEST PORT COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE PRESS REGULATOR OUTLET TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR CAP) WILL BE UNDETECTABLE. NEXT ASSOCIATED FAILURE WILL CAUSE LOSS OF HELIUM PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE EXCEEDED DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 B, H, I,  
6-50, 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 118 ABORT: 3/3

ITEM: HE PRESS REGULATOR OUTLET TEST PORT COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE PRESS REGULATOR OUTLET TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-50.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 119 ABORT: 2/1R

ITEM: QUAD CHECK VALVE ASSEMBLY  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN) OR LEAKS (REVERSE FLOW)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT HDW/FUNC
PRELAUNCH:	3/3	RTLS: 2/1R
LIFTOFF:	3/3	TAL: 2/1R
ONORBIT:	3/2R	AOA: 2/1R
DEORBIT:	2/1R	ATO: 2/1R
LANDING/SAFING:	3/1R	

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

NEXT ASSOCIATED FAILURE (VALVE IN SERIES WITH FAILED VALVE FAILS OPEN) WILL ALLOW PROPELLANT TO BACKFLOW INTO THE HELIUM PRESSURIZATION SYSTEM. THIS CAN CAUSE LOSS OF LIFE DURING GROUND SERVICING DUE TO INHALATION OF PROPELLANT VAPORS. CORROSION OF HELIUM REGULATORS AND/OR HELIUM ISOLATION VALVES BY PROPELLANT WHICH HAS BACKFLOWED MAY CAUSE LOSS OF HELIUM PRESSURIZATION CAPABILITY.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	120	ABORT:	2/1R

ITEM: QUAD CHECK VALVE ASSEMBLY  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: PIECE-PART STRUCTURAL FAILURE, LOW TEMPERATURE FREEZES  
PROPELLANT INSIDE VALVE

EFFECTS/RATIONALE:

NEXT ASSOCIATED FAILURE (PARALLEL VALVE FAILS CLOSED) WILL CAUSE  
LOSS OF HELIUM PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION  
CAPABILITY WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE CG  
SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO  
THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 C, D.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 121 ABORT: 2/1R

ITEM: QUAD CHECK VALVE TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL CAUSE LOSS OF HELIUM UNTIL CREW  
CLOSES HELIUM ISOLATION VALVES. FAILURE OF ALL REDUNDANCY WILL  
CAUSE LOSS OF HELIUM PRESSURIZATION, WILL AFFECT ONORBIT  
OPERATIONS, AND MAY CAUSE THE CG SAFETY BOUNDARIES TO BE EXCEEDED  
DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	122	ABORT:	3/3

ITEM: QUAD CHECK VALVE TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 123 ABORT: 1/1

ITEM: PROPELLANT TANK  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROPELLANT TANK
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: MECHANICAL SHOCK, HIGH PRESSURE, VIBRATION

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO THE POD/VEHICLE. LOSS  
OF PROPELLANT INTO THE POD CAN CAUSE CORROSION, LEADING TO  
ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	124	ABORT:	1/1

ITEM: PROP LINES, ALL  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP LINES, ALL
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

PRESSURE IN TANK AND LINE WILL FORCE PROPELLANT OUT OF LINE INTO POD/VEHICLE. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 125 ABORT: 1/1

ITEM: PROP LINES, ALL  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP LINES, ALL
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 127 ABORT: 3/3

ITEM: PROP FILL VENT REGULATOR CHECKOUT COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP FILL VENT REGULATOR CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	128	ABORT:	1/1

ITEM: PROP CHANNEL SCREENS  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP CHANNEL SCREENS
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 1/1
LIFTOFF:	1/1	TAL: 1/1
ONORBIT:	1/1	AOA: 1/1
DEORBIT:	1/1	ATO: 1/1
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PROPELLANT TANK INTERIOR  
PART NUMBER: FU & OX:

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

HELIUM INGESTION WILL CAUSE ZOTS AND/OR THRUSTER NOZZLE  
BURNTHROUGH. FAILURE IS NOT DETECTABLE UNTIL THRUSTERS FAIL DUE  
TO HELIUM INGESTION OR ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); RCS 2102, FIG. 3.1.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 129 ABORT: 1/1

ITEM: PROP FEEDOUT TUBE  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP FEEDOUT TUBE
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PROPELLANT TANK INTERIOR  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VACUUM, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 F  
APPLIES; RCS 2102, FIG. 3.1.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	130	ABORT:	2/1R

ITEM: PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT  
COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FRCS FRONT TRUNNION  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 E.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 131 ABORT: 3/3

ITEM: PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT  
COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FRCS FRONT TRUNNION  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 133 ABORT: 3/3

ITEM: PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 135 ABORT: 3/3

ITEM: PROP TK LOWER COMPARTMENT BULKHEAD BLEED COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT BULKHEAD BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	136	ABORT:	2/1R

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) **HARDWARE COMPONENTS**
- 2) **ASSEMBLIES**
- 3) **PROP STOR & DIST SUBSYSTEM**
- 4) **PROP TK VENT AND REGULATOR CHECKOUT COUPLING**
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

**C-38**

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 137 ABORT: 3/3

ITEM: PROP TK VENT AND REGULATOR CHECKOUT COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK VENT AND REGULATOR CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	138	ABORT:	1/1

ITEM: GIMBAL BELLOWS  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GIMBAL BELLOWS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: DOWNSTREAM OF PROPELLANT TANK  
PART NUMBER: FU & OX: 73P550015-1006

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

ASSUME THIS IS A SINGLE BARRIER FAILURE, THAT IS, NO INTERNAL LEAK PATH REDUNDANCY EXISTS. FAILURE RESULTS IN PROPELLANT LEAKING INTO THE POD/VEHICLE. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 139 ABORT: 1/1

ITEM: GIMBAL BELLOWS  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GIMBAL BELLOWS
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: DOWNSTREAM OF PROPELLANT TANK  
PART NUMBER: FU & OX: 73P550015-1006

CAUSES: CONTAMINATION, VACUUM, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 F.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 140 ABORT: 2/1R

ITEM: PRESSURE RELIEF ASSEMBLY  
FAILURE MODE: BURST DISK RUPTURES AT LOW PRESSURE, OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PRESSURE RELIEF ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FRCS POD

PART NUMBER: FU & OX:

CAUSES: MATERIAL FLAW, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (BURST DISK RUPTURE) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE (PRESSURE RELIEF VALVE) WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 A, B.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	141	ABORT:	1/1

ITEM: PRESSURE RELIEF ASSEMBLY  
FAILURE MODE: BURST DISK FAILS TO RUPTURE, RUPTURES AT A HIGHER THAN NOMINAL PRESSURE, OR POPPET VALVE FAILS CLOSED AFTER BURST DISK RUPTURES AT NOMINAL PRESSURE.

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PRESSURE RELIEF ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FRCS POD  
PART NUMBER: FU & OX:

CAUSES: MATERIAL FLAW, CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
OVERPRESSURIZATION OF PROPELLANT TANK AND LINES WILL CAUSE TANK AND/OR LINE RUPTURE. LOSS OF PROPELLANT INTO THE POD CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 143 ABORT: 3/3

ITEM: RELIEF VALVE TEST PORT COUPLING  
FAILURE MODE: PRESSURE RELIEF VALVE TEST PORT FAILS TO OPEN  
(FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RELIEF VALVE TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	144	ABORT:	3/3

ITEM: GROUND MANUAL ISOLATION VALVE  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GROUND MANUAL ISOLATION VALVE
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
MECHANICAL SHOCK (GROUND HANDLING)

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 145 ABORT: 1/1

ITEM: GROUND MANUAL ISOLATION VALVE  
FAILURE MODE: FAILS TO REMAIN OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GROUND MANUAL ISOLATION VALVE
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	2/2	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
MECHANICAL SHOCK (GROUND HANDLING)

EFFECTS/RATIONALE:

FAILURE RESULTS IN LOSS OF HELIUM PRESSURIZATION (VALVE IS  
UPSTREAM OF PROPELLANT TANKS). LOSS OF HELIUM PRESSURIZATION  
WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE CG SAFETY  
BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE  
TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 C, D.





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 147 ABORT: 1/1

ITEM: PROP TK ISOL VLVS 1/2 & 3/4/5  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ISOL VLVS 1/2 OR 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN PROPELLANT TANK AND MANIFOLD ISOLATION  
VALVES

PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE CAUSING  
CORROSION, WHICH CAN RESULT IN ELECTRICAL SHORTS AND PROPELLANT  
IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (43DC).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	148	ABORT:	1/1

ITEM: PROP TK ISOL VLVS 1/2 & 3/4/5  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ISOL VLVS 1/2 OR 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN PROPELLANT TANK AND MANIFOLD ISOLATION VALVES

PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (43DC).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 149 ABORT: 3/3

ITEM: PROP TK ISOL VLV 1/2  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ISOL VLV 1/2
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN PROPELLANT TANK AND MANIFOLD ISOLATION  
VALVES

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 151 ABORT: 3/3

ITEM: PROP TK ISOL VLV 3/4/5  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ISOL VLV 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN PROPELLANT TANK AND MANIFOLD ISOLATION  
VALVES  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 153 ABORT: 2/1R

ITEM: MANIFOLD 1/2 FILL & DRAIN/PURGE COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1/2 FILL & DRAIN/PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 E.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 154 ABORT: 3/3

ITEM: MANIFOLD 1/2 FILL & DRAIN/PURGE COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1/2 FILL & DRAIN/PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 155 ABORT: 2/1R

ITEM: MANIFOLD 3/4/5 FILL & DRAIN/PURGE COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3/4/5 FILL & DRAIN/PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: HELIUM/FUEL/OXIDIZER SERVICING PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT); FLIGHT RULE 6-41 E.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 157 ABORT: 3/3

ITEM: MANIFOLD 1, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	158	ABORT:	1/1

ITEM: MANIFOLD 1, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY IN ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION ON OTHER MANIFOLDS. NEXT ASSOCIATED FAILURE MAY RESULT IN INABILITY TO COMPLETE FRCS DUMP, LEADING TO POSSIBLE VIOLATION OF THE CG SAFETY BOUNDARY. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE FOUR PRIMARY JETS ON THIS MANIFOLD WILL AFFECT PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-942099 REV D EO D01 (42BN & 42BT); RCS SFOM, FIG. 3-4.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	159	ABORT:	2/1R

ITEM: MANIFOLD 1, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF THE MANIFOLD AND POSSIBLE LOSS OF  
LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY  
LEAKING PROPELLANT. FAILURE OF ALL REDUNDANCY MAY CAUSE THE  
INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE CG  
SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND  
CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

**INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET**

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	160	ABORT:	3/3

ITEM: MANIFOLD 1, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 161 ABORT: 3/3

ITEM: MANIFOLD 2, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	162	ABORT:	1/1

ITEM: MANIFOLD 2, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	2/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY IN ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION ON OTHER MANIFOLDS. NEXT ASSOCIATED FAILURE MAY RESULT IN INABILITY TO COMPLETE FRCS DUMP, LEADING TO POSSIBLE VIOLATION OF THE CG SAFETY BOUNDARY. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE FOUR PRIMARY JETS ON THIS MANIFOLD WILL AFFECT PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-942099 REV D EO D01 (43DE); RCS SFOM, FIG. 3-4.



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 163 ABORT: 2/1R

ITEM: MANIFOLD 2, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF THE MANIFOLD AND POSSIBLE LOSS OF  
LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY  
LEAKING PROPELLANT. FAILURE OF ALL REDUNDANCY MAY CAUSE THE  
INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE CG  
SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND  
CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 164 ABORT: 3/3

ITEM: MANIFOLD 2, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 165 ABORT: 3/3

ITEM: MANIFOLD 3, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 167 ABORT: 2/1R

ITEM: MANIFOLD 3, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF THE MANIFOLD AND POSSIBLE LOSS OF  
LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY  
LEAKING PROPELLANT. FAILURE OF ALL REDUNDANCY MAY CAUSE THE  
INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE CG  
SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND  
CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 168 ABORT: 3/3

ITEM: MANIFOLD 3, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 169 ABORT: 3/3

ITEM: MANIFOLD 4, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 171 ABORT: 2/1R

ITEM: MANIFOLD 4, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF THE MANIFOLD AND POSSIBLE LOSS OF  
LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY  
LEAKING PROPELLANT. FAILURE OF ALL REDUNDANCY MAY CAUSE THE  
INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE CG  
SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND  
CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 172 ABORT: 3/3

ITEM: MANIFOLD 4, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 173 ABORT: 3/3

ITEM: MANIFOLD 5, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/2
MDAC ID:	174	ABORT:	3/3

ITEM: MANIFOLD 5, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
FAILURE RESULTS IN LOSS OF VRCS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 175 ABORT: 2/1R

ITEM: MANIFOLD 5, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF THE MANIFOLD AND POSSIBLE LOSS OF  
LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY  
LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON THE  
GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	176	ABORT:	3/3

ITEM: MANIFOLD 5, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER MANIFOLD DRAIN, PURGE AND CHECKOUT  
PANEL  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
VALVE NORMALLY CLOSED.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 177 ABORT: 1/1

ITEM: MANIFOLD ISOL VLVS  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD ISOL VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE WHICH WILL  
CAUSE CORROSION, RESULTING IN ELECTRICAL SHORTS AND PROPELLANT  
IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 178

HIGHEST CRITICALITY  
FLIGHT: 1/1  
ABORT: 1/1

HDW/FUNC

ITEM: MANIFOLD ISOL VLVS  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD ISOL VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN TANK ISOLATION VALVES AND THRUSTERS  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, CAUSING ZOTS AND/OR NOZZLE BURNTROUGH, RESULTING IN LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-942099 REV D EO D01 (43DE).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 179 ABORT: 1/1

ITEM: JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER LINES LEADING INTO JET BIPROPELLANT VALVE

PART NUMBER: FU & OX:

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

THIS FAILURE CAUSES PROPELLANT TO LEAK INTO THE POD/VEHICLE.  
LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	180	ABORT:	1/1

ITEM: JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER LINES LEADING INTO JET BI-PROPELLANT VALVE

PART NUMBER: FU & OX:

CAUSES: VACUUM, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, RESULTING IN ZOTS AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 181 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN/ON)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

A FAILED-ON JET CAN CAUSE CONTACT WITH PAYLOADS DURING RENDEZVOUS, RESULTING IN LOSS OF VEHICLE AND/OR EVA CREW. RM WILL NOT DESELECT JET; MUST BE SECURED BY CREW CLOSING ITS MANIFOLD. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 182 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES  
FAILURE MODE: LEAKS EXTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE, CAUSING CORROSION, RESULTING IN ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 183

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 1/1  
ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/2R
MDAC ID:	184	ABORT:	3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, -X AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, -X AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE CANNOT BE  
DETECTED UNTIL JET TRIES TO FIRE. LOSS OF ALL REDUNDANCY AFFECTS  
ONORBIT OPERATIONS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 185 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, -X AXIS  
FAILURE MODE: LEAKS INTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, -X AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO COMBUSTION CHAMBER, WHICH CAN FREEZE, RESULTING IN LOSS OF THE JET. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF CREW IS CONTAMINATED BY PROPELLANTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 186 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, Y AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, Y AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE CANNOT BE  
DETECTED UNTIL JET TRIES TO FIRE. NEXT ASSOCIATED FAILURE  
ONORBIT MAY CAUSE CONTACT WITH PAYLOADS AND/OR EVA CREW  
AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING  
ABORTS AND ENTRY TO MEET THE CG SAFETY BOUNDARIES. FAILURE  
DURING RTLS MAY RESULT IN THE INABILITY TO COMPLETE A FRCS DUMP.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 187 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, Y AXIS  
FAILURE MODE: LEAKS INTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, Y AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/1R	ATO:	3/3
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO COMBUSTION CHAMBER, WHICH CAN FREEZE, RESULTING IN LOSS OF THE JET. FAILURE OF ALL REDUNDANCY MAY CAUSE INABILITY TO DUMP ENOUGH PROPELLANTS DURING ENTRY OR ABORTS TO MEET THE CG SAFETY BOUNDARIES. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF CREW IS CONTAMINATED BY PROPELLANTS. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/2R
MDAC ID:	188	ABORT:	3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, Z AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, Z AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE CANNOT BE  
DETECTED UNTIL JET TRIES TO FIRE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 189 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, PRIMARY, Z AXIS  
FAILURE MODE: LEAKS INTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, PRIMARY, Z AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/1R	ATO:	3/3
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO COMBUSTION CHAMBER, WHICH CAN FREEZE, RESULTING IN LOSS OF THE JET. INHALATION OF PROPELLANT ON THE GROUND CAN CAUSE LOSS OF LIFE. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF CREW IS CONTAMINATED BY PROPELLANTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 191 ABORT: 3/3

ITEM: JET ALIGNMENT BELLOWS, VERNIER, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, VERNIER, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXID LINES LEADING INTO JET BIPROP VALVE  
PART NUMBER: FU & OX:

CAUSES: VACUUM, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 192 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN/ON)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN LOSS OF VERNIER RCS. RM WILL NOT DESELECT JET, MUST BE SECURED BY CREW CLOSING ITS MANIFOLD. A FAILED ON JET CAN CAUSE CONTACT WITH PAYLOADS DURING RENDEZVOUS, RESULTING IN LOSS OF VEHICLE, AND/OR EVA CREW.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/2  
MDAC ID: 193 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:  
FAILURE RESULTS IN LOSS OF VERNIER RCS. RM WILL DESELECT JETS.  
FAILURE CANNOT BE DETECTED UNTIL JET IS COMMANDED TO FIRE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	194	ABORT:	1/1

ITEM: THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES  
FAILURE MODE: LEAKS EXTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE CAUSING CORROSION, RESULTING IN ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 195 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES  
FAILURE MODE: LEAKS INTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO COMBUSTION CHAMBER, WHICH CAN FREEZE, RESULTING IN LOSS OF THE VERNIER RCS. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF CREW IS CONTAMINATED BY PROPELLANT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 196 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLV, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 1/1  
MDAC ID: 197 ABORT: 1/1

ITEM: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION,  
PRIMARY, ALL AXES  
FAILURE MODE: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION  
BURNTHROUGH

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION, PRIMARY,  
ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: IMPROPER MIXTURE RATIO FROM RESTRICTED PROPELLANT FLOW,  
PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
HOT, HIGH PRESSURE GAS VENTS INTO POD.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	1/1
MDAC ID:	198	ABORT:	3/3

ITEM: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION,  
VERNIER, ALL AXES  
FAILURE MODE: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION  
BURNTHROUGH

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION, VERNIER,  
ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	1/1	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: IMPROPER MIXTURE RATIO FROM RESTRICTED PROPELLANT FLOW,  
PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE RESULTS IN LOSS OF VRCS. HOT, HIGH PRESSURE GAS VENTING  
INTO POD.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.6;  
VS70-942099 REV D EO D01 (42BN & 42BT).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 199 ABORT: 1/1

ITEM: HELIUM STORAGE TANK  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM STORAGE TANK
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	2/2	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC282-0082-0032,0031

CAUSES: MECHANICAL SHOCK, HIGH PRESSURE, VIBRATION

EFFECTS/RATIONALE:  
LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS AND  
MAY CAUSE THE TANK LANDING WEIGHT CONSTRAINTS AND CG SAFETY  
BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE  
TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-  
95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 201

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: HELIUM FILL COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM FILL COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL SERVICING PANEL  
PART NUMBER: FU & OX: MC276-0017-0402,0403

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 202 ABORT: 3/1R

ITEM: HE ISOL A & B VLVS  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN) OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE ISOL A & B VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0419-0012,0011 or 0022,0021

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE DUAL SERIES PRESSURE REGULATOR AND MANUAL OPERATION OF THE HELIUM ISOLATION VALVE. FAILURE OF ALL REDUNDANCY WILL CAUSE OVERPRESSURIZATION OF TANKS AND/OR LINES, AND MAY CAUSE ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).



DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	2/1R
MDAC ID:	203	ABORT:	2/1R

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE ISOL A & B VLVS
- 5)
- 6)
- 7)
- 8)
- 9)

REDUNDANCY SCREENS:    A [ 2 ]            B [NA ]            C [ P ]

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-8C, 6-41 G, H, I  
AND 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 205 ABORT: 1/1

ITEM: HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ALL EXCEPT ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: BETWEEN HELIUM TANK AND QUAD CHECK VALVE  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CA & 43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 206 ABORT: 2/1R

ITEM: HE LINE, ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		2/1R
LIFTOFF:	3/2R	TAL:		2/1R
ONORBIT:	3/2R	AOA:		2/1R
DEORBIT:	2/1R	ATO:		2/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: BETWEEN HELIUM ISOL VLVS AND PRESS REG  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL HELIUM PATH. NEXT ASSOCIATED FAILURE CAUSES LOSS OF HELIUM PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE TANK LANDING WEIGHT CONSTRAINTS AND/OR CG SAFETY BOUNDARIES TO BE EXCEEDED DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CA & 43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 207 ABORT: 2/1R

ITEM: HE LINE, ISOL VLV TO PRESS REGULATOR  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HE LINE, ISOL VLV TO PRESS REGULATOR
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL HELIUM PATH. FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CA & 43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 208 ABORT: 3/1R

ITEM: HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: ME276-0032-0021,0019

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
FAILURE OF ALL REDUNDANCY WILL CAUSE LOSS OF HELIUM  
PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION WILL AFFECT  
ONORBIT OPERATIONS, AND MAY CAUSE THE TANK LANDING WEIGHT  
CONSTRAINTS AND CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY  
OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-  
95.

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 209 ABORT: 3/3

ITEM: HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HIGH PRESSURE HELIUM TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: ME276-0032-0021,0019

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 210 ABORT: 3/1R

ITEM: HELIUM PRESSURE REGULATOR ASSEMBLY  
FAILURE MODE: FAILS OPEN OR REGULATES AT HIGHER THAN NORMAL  
PRESSURE

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/1R	RTLS: 3/1R
LIFTOFF:	3/1R	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0418-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE HELIUM ISOLATION VALVE AND THE SERIES PRESSURE REGULATOR. FAILURE OF ALL REDUNDANCY WILL CAUSE OVERPRESSURIZATION AND RUPTURE OF THE PROPELLANT TANK AND LINES, AND MAY CAUSE ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 211 ABORT: 2/1R

ITEM: HELIUM PRESSURE REGULATOR ASSEMBLY  
FAILURE MODE: FAILS CLOSED

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0418-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

STANDBY REDUNDANCY. NEXT ASSOCIATED FAILURE (PARALLEL REGULATOR OR PARALLEL HELIUM ISOLATION VALVE) WILL CAUSE LOSS OF HELIUM PRESSURIZATION CAPABILITY. LOSS OF HELIUM PRESSURIZATION WILL CAUSE THE TANK LANDING WEIGHT CONSTRAINTS AND THE CG SAFETY BOUNDARIES TO BE EXCEEDED DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 213 ABORT: 2/1R

ITEM: HELIUM PRESSURE REGULATOR ASSEMBLY  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0418-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL REGULATOR AND MANUAL OPERATION OF THE HELIUM ISOLATION VALVE. FAILURE OF ALL REDUNDANCY WILL RESULT IN LOSS OF HELIUM PRESSURIZATION, CAUSING THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ENTRY OR ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 214 ABORT: 2/1R

ITEM: HELIUM PRESSURE REGULATOR PRIMARY SENSING PORT  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR PRIMARY SENSING PORT
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: 73A620096-2001

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MANUAL OPERATION OF THE HELIUM ISOLATION VALVE AND THE PARALLEL HELIUM PATH. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE TANK LANDING CONSTRAINT AND CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT. THERE ARE NO VALVES OR CAPS IN THE SENSING PORT LINES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 215 ABORT: 2/1R

ITEM: HELIUM PRESSURE REGULATOR PRIMARY SENSING PORT  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR PRIMARY SENSING PORT
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	2/1R
LIFTOFF:	3/1R	TAL:	2/1R
ONORBIT:	3/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: 73A620096-2001

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY PARALLEL HELIUM PATH, AND OTHER SERIES PRESSURE REGULATOR. NEXT ASSOCIATED FAILURE WILL CAUSE REGULATION AT A HIGHER PRESSURE WHICH MAY CAUSE AN UNACCEPTABLE MIXTURE RATIO AND/OR RUPTURE OF THE PROPELLANT TANKS AND LINES. ZOTS MAY CAUSE THRUSTER VALVE DAMAGE, LEADING TO PROPELLANT IGNITION WITHIN THE POD AND/OR THRUSTER NOZZLE BURNTHROUGH.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-50.

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87. HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 216 ABORT: 2/1R

ITEM: HELIUM PRESSURE REGULATOR OUTLET TEST PORT  
COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR OUTLET TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER TEST PORT PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR CAP) WILL BE UNDETECTABLE. NEXT ASSOCIATED FAILURE WILL CAUSE LOSS OF HELIUM PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE TANK LANDING CONSTRAINT AND CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5; VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 217 ABORT: 3/3

ITEM: HELIUM PRESSURE REGULATOR OUTLET TEST PORT  
COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) HELIUM PRESSURE REGULATOR OUTLET TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL/OXIDIZER TEST PORT PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-50.





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 219 ABORT: 2/1R

ITEM: QUAD CHECK VALVE ASSEMBLY  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0481-0002,0001

CAUSES: PIECE-PART STRUCTURAL FAILURE, LOW TEMPERATURE FREEZES  
PROPELLANT INSIDE VALVE

EFFECTS/RATIONALE:

NEXT ASSOCIATED FAILURE (PARALLEL VALVE FAILS CLOSED) WILL CAUSE  
LOSS OF HELIUM PRESSURIZATION. LOSS OF HELIUM PRESSURIZATION  
CAPABILITY WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE TANK  
LANDING WEIGHT CONSTRAINTS AND THE CG SAFETY BOUNDARIES TO BE  
EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S  
WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-  
95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 220 ABORT: 3/1R

ITEM: QUAD CHECK VALVE TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: ME276-0032-0007,0008

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. FAILURE OF ALL REDUNDANCY WILL CAUSE LOSS OF HELIUM UNTIL CREW CLOSES HELIUM ISOLATION VALVES. LOSS OF HELIUM PRESSURIZATION WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE TANK LANDING WEIGHT CONSTRAINTS AND CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 221 ABORT: 3/3

ITEM: QUAD CHECK VALVE TEST PORT COUPLINGS A & B  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) HE PRESS SUBSYSTEM
- 4) QUAD CHECK VALVE TEST PORT COUPLINGS A & B
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: ME276-0032-0007,0008

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 223 ABORT: 1/1

ITEM: PROP LINES, ALL  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP LINES, ALL
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	1/1	RTLS: 1/1
LIFTOFF:	1/1	TAL: 1/1
ONORBIT:	1/1	AOA: 1/1
DEORBIT:	1/1	ATO: 1/1
LANDING/SAFING:	1/1	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

PRESSURE IN TANK AND LINE WILL FORCE PROPELLANT OUT OF LINE INTO POD/VEHICLE. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CA & 43DA; 43CH & 43DH).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 225 ABORT: 2/1R

ITEM: PROP FILL/VENT COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP FILL/VENT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS FUEL SERVICING PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR CAP) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF CREW FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 226 ABORT: 3/3

ITEM: PROP FILL/VENT COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP FILL/VENT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL SERVICING PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 227

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 1/1  
ABORT: 1/1

ITEM: PROP CHANNEL SCREENS  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP CHANNEL SCREENS
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PROPELLANT TANK INTERIOR  
PART NUMBER: FU & OX:

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

HELIUM INGESTION WILL CAUSE ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH. FAILURE IS NOT DETECTABLE UNTIL THRUSTERS FAIL DUE TO HELIUM INGESTION OR ZOTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); RCS 2102, FIG. 3.2.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 228

HIGHEST CRITICALITY  
FLIGHT: 1/1  
ABORT: 1/1

HDW/FUNC

ITEM: PROP FEEDOUT TUBE  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP FEEDOUT TUBE
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PROPELLANT TANK INTERIOR  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, VACUUM

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/1R
MDAC ID:	229	ABORT:	3/1R

ITEM: PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT  
COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: ME276-0032-0007,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. FAILURE OF ALL REDUNDANCY WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

**INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET**

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	230	ABORT:	3/3

ITEM: PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT  
COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK UPPER COMPARTMENT CHANNEL CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: ME276-0032-0007,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 231 ABORT: 2/1R

ITEM: PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: NOT SPECIFIED ON DRAWING  
PART NUMBER: FU & OX: MC276-0018-3451,3401

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	232	ABORT:	3/3

ITEM: PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT CHANNEL BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: NOT SPECIFIED ON DRAWING  
PART NUMBER: FU & OX: MC276-0018-3451,3401

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/1R
MDAC ID:	233	ABORT:	3/1R

ITEM: PROP TK LOWER COMPARTMENT CHECKOUT COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: ME276-0032-0007,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. FAILURE OF ALL REDUNDANCY WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	234	ABORT:	3/3

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK LOWER COMPARTMENT CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

REDUNDANCY SCREENS:    A [    ]            B [    ]            C [    ]

**CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE**

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 235 ABORT: 3/1R

ITEM: PROP TK PLENUM SCREEN CHECKOUT COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK PLENUM SCREEN CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: NOT SPECIFIED ON DRAWING  
PART NUMBER: FU & OX: ME276-0032-0007,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. FAILURE OF ALL REDUNDANCY WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	236	ABORT:	3/3

ITEM: PROP TK PLENUM SCREEN CHECKOUT COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK PLENUM SCREEN CHECKOUT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: NOT SPECIFIED ON DRAWING  
PART NUMBER: FU & OX: ME276-0032-0007,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 237 ABORT: 2/1R

ITEM: PROP TK ENTRY SUMP BLEED COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ENTRY SUMP BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS FUEL SERVICING PANEL  
PART NUMBER: FU & OX: MC276-0018-3452,3402

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	238	ABORT:	3/3

ITEM: PROP TK ENTRY SUMP BLEED COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TK ENTRY SUMP BLEED COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL SERVICING PANEL  
PART NUMBER: FU & OX: MC276-0018-3452,3402

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 239 ABORT: 1/1

ITEM: GIMBAL BELLOWS  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GIMBAL BELLOWS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: DOWNSTREAM OF PROPELLANT TANK  
PART NUMBER: FU & OX: 73P550015-1006

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

ASSUME THIS IS A SINGLE BARRIER FAILURE, THAT IS, NO INTERNAL LEAK PATH REDUNDANCY EXISTS. FAILURE RESULTS IN PROPELLANT LEAKING INTO THE POD/VEHICLE. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 240 ABORT: 1/1

ITEM: GIMBAL BELLOWS  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GIMBAL BELLOWS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: DOWNSTREAM OF PROPELLANT TANK  
PART NUMBER: FU & OX: 73P550015-1006

CAUSES: VACUUM, CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 J, K AND 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 241 ABORT: 2/1R

ITEM: PRESSURE RELIEF ASSEMBLY  
FAILURE MODE: BURST DISK RUPTURES AT LOW PRESSURE, OR LEAKS

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PRESSURE RELIEF ASSEMBLY
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0421-0012,0011

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (BURST DISC RUPTURE) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF CREW FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 243 ABORT: 3/1R

ITEM: RELIEF VALVE TEST PORT COUPLING  
FAILURE MODE: PRESSURE RELIEF VALVE TEST PORT FAILS TO CLOSE  
(FAILS OPEN) OR LEAKS OVERBOARD

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RELIEF VALVE TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: ME276-0032

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (BURST DISC RUPTURE) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING DEORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE POSSIBLE LOSS OF CREW FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. INHALATION OF PROPELLANT VAPORS ON GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-95.

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	244	ABORT:	3/3

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RELIEF VALVE TEST PORT COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

LOCATION: OMS/RCS FUEL/OXIDIZER CHECKOUT PANEL  
PART NUMBER: FU & OX: ME276-0032

EFFECTS/RATIONALE:  
NONE.

C-146

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 245 ABORT: 3/3

ITEM: GROUND MANUAL ISOLATION VALVE  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GROUND MANUAL ISOLATION VALVE
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0480-0002,0001

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
MECHANICAL SHOCK (GROUND HANDLING)

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	246	ABORT:	1/1

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GROUND MANUAL ISOLATION VALVE
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	2/2	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0480-0002,0001

**EFFECTS/RATIONALE:**

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA); FLIGHT RULE 6-41 G, H, I AND 6-  
95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	247	ABORT:	1/1

ITEM: GROUND MANUAL ISOLATION VALVE  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) GROUND MANUAL ISOLATION VALVE
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0480-0002,0001

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
MECHANICAL SHOCK (GROUND HANDLING)

EFFECTS/RATIONALE:  
FAILURE RESULTS IN LOSS OF PROPELLANT AND HELIUM. PROPELLANT  
WILL LEAK INTO THE POD. INHALATION OF PROPELLANT VAPORS ON THE  
GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DA).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	248	ABORT:	1/1

ITEM: PROP TANK ISOL VLVS 1/2 & 3/4/5  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLVS 1/2 & 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO THE POD/VEHICLE,  
CAUSING CORROSION, WHICH COULD RESULT IN ELECTRICAL SHORTS AND  
PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DC).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 249 ABORT: 1/1

ITEM: PROP TANK ISOL VLVS 1/2 & 3/4/5  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLVS 1/2 & 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DC).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/2R  
MDAC ID: 250 ABORT: 1/1

ITEM: PROP TANK ISOL VLV 1/2  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLV 1/2
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	3/2R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE 3/4/5 A & B ISOLATION VALVES. FAILURE  
WILL AFFECT CROSSFEED OPERATIONS AND ENTRY DTOs AND PTIs.  
FAILURE OF ALL REDUNDANCY MAY CAUSE THE INABILITY TO EXPEL ENOUGH  
PROPELLANTS DURING ENTRY OR ABORTS TO MEET THE TANK LANDING  
CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DC).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	2/1R
MDAC ID:	251	ABORT:	1/1

ITEM: PROP TANK ISOL VLV 1/2  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLV 1/2
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

## EFFECTS/RATIONALE:

REDUNDANCY DURING ALL PHASES EXCEPT RTLS IS PROVIDED BY THE 3/4/5 A & B ISOLATION VALVES. FIRST FAILURE WILL CAUSE LOSS OF SIX PRIMARY JETS WHICH WILL AFFECT ONORBIT CROSSFEED OPERATIONS, ENTRY DTOS AND PTIs, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS, AND/OR THE CG SAFETY BOUNDARIES. SIMILARLY, NEXT ASSOCIATED FAILURE MAY RESULT IN LOSS OF VEHICLE DURING ENTRY AND OTHER ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DC); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	2/2
MDAC ID:	252	ABORT:	1/1

ITEM: PROP TANK ISOL VLV 3/4/5/ A & B  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLV 3/4/5/ A & B
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/2	AOA:	2/1R
DEORBIT:	3/3	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

FAILURE OF THE PARALLEL 3/4/5 VALVE WILL AFFECT CROSSFEED  
OPERATIONS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH  
PROPELLANTS DURING ABORTS TO MEET THE TANK LANDING WEIGHT  
CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DB).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 253 ABORT: 2/1R

ITEM: PROP TANK ISOL VLV 3/4/5/ A & B  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) PROP TANK ISOL VLV 3/4/5/ A & B
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	3/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE PARALLEL 3/4/5 ISOLATION VALVE AND THE 1/2 ISOLATION VALVE. FAILURE OF BOTH VALVES ONORBIT WILL AFFECT CROSSFEED OPERATIONS AND ENTRY DTOs AND PTIs. FAILURE OF ALL REDUNDANCY WILL CAUSE LOSS OF SIX PRIMARY JETS WHICH MAY CAUSE INABILITY TO EXPEL ENOUGH PROPELLANT DURING RTLS TO MEET THE CG SAFETY BOUNDARIES. SIMILARLY, FAILURE OF ALL REDUNDANCY MAY RESULT IN LOSS OF VEHICLE DURING ENTRY AND OTHER ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DB); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 254 ABORT: 2/1R

ITEM: MANIFOLD 1/2 GROUND PURGE COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1/2 GROUND PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER DRAIN PURGE PANEL  
PART NUMBER: FU & OX: MC276-0018-3852,3802

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DD).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 255

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3  
HDW/FUNC

ITEM: MANIFOLD 1/2 GROUND PURGE COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1/2 GROUND PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL/OXIDIZER DRAIN PURGE PANEL  
PART NUMBER: FU & OX: MC276-0018-3852,3802

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DD).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 256 ABORT: 2/1R

ITEM: MANIFOLD 3/4/5 GROUND PURGE COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3/4/5 GROUND PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS FUEL/OXIDIZER DRAIN PURGE PANEL  
PART NUMBER: FU & OX: MC276-0018-3852,3802

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE POSSIBLE LOSS OF LIFE FOLLOWING EVA  
OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT.  
INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF  
LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DC).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 257 ABORT: 3/3

ITEM: MANIFOLD 3/4/5 GROUND PURGE COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3/4/5 GROUND PURGE COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS FUEL/OXIDIZER DRAIN PURGE PANEL  
PART NUMBER: FU & OX: MC276-0018-3852,3802

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DD).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 258 ABORT: 1/1

ITEM: RCS CROSSFEED VLV 1/2 OR 3/4/5  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RCS CROSSFEED VLV 1/2 OR 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD); RCS 2102, FIG. 7-2 AND 8-  
1. FLIGHT RULE 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 259 ABORT: 1/1

ITEM: RCS CROSSFEED VLV 1/2 OR 3/4/5  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RCS CROSSFEED VLV 1/2 OR 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
FAILURE RESULTS IN PROPELLANT LEAKING INTO THE POD/VEHICLE,  
CAUSING CORROSION, WHICH COULD RESULT IN ELECTRICAL SHORTS AND  
PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD); RCS 2102, FIG. 7-2 AND 8-  
1. FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	2/2
MDAC ID:	260	ABORT:	3/3

ITEM: RCS CROSSFEED VLV 1/2  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RCS CROSSFEED VLV 1/2
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
DURING ONORBIT, THIS MAY AFFECT CROSSFEED OPERATIONS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD); RCS 2102, FIG. 7-2 AND 8-  
1. FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/2  
MDAC ID: 261 ABORT: 1/1

ITEM: RCS CROSSFEED VLV 1/2  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RCS CROSSFEED VLV 1/2
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/2	AOA:	2/1R
DEORBIT:	3/3	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

FAILURE WILL AFFECT CROSSFEED OPERATIONS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANT DURING ABORTS TO MEET THE TANK LANDING CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES. THERE IS NO REDUNDANCY TO CROSSFEED TO THE 1/2 THRUSTERS ONORBIT, AND NO REDUNDANCY DURING RTLS BECAUSE OF THE FIXED RCS AND OMS DUMP LENGTHS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD); RCS 2102, FIG. 7-2 AND 8-1. FLIGHT RULE 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	2/2
MDAC ID:	263	ABORT:	1/1

ITEM: RCS CROSSFEED VLV 3/4/5  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) RCS CROSSFEED VLV 3/4/5
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/2	AOA:	2/1R
DEORBIT:	3/3	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

FAILURE WILL AFFECT CROSSFEED OPERATIONS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANT DURING ABORTS TO MEET THE TANK LANDING CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES. THERE IS NO REDUNDANCY TO CROSSFEED TO THE 3/4/5 THRUSTERS ONORBIT, AND NO REDUNDANCY DURING RTLS BECAUSE OF THE FIXED RCS AND OMS DUMP LENGTHS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD); RCS 2102, FIG. 7-2 AND 8-1. FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	264	ABORT:	1/1

ITEM: CROSSFEED LINES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) CROSSFEED LINES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, CAUSING ZOTS AND/OR NOZZLE BURNTHROUGH, RESULTING IN LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CD & 43DD).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 265

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 1/1  
ABORT: 1/1

ITEM: CROSSFEED LINES  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) CROSSFEED LINES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: ANY LINE BETWEEN PROPELLANT TANK AND THRUSTERS.  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, MECHANICAL SHOCK, HIGH PRESSURE

EFFECTS/RATIONALE:

PRESSURE IN TANK AND LINE WILL FORCE PROPELLANT OUT OF LINE INTO POD/VEHICLE. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43CA & 43DA; 43CH & 43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	266	ABORT:	3/3

ITEM: MANIFOLD 1, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 267 ABORT: 1/1

ITEM: MANIFOLD 1, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

## EFFECTS/RATIONALE:

REDUNDANCY FOR ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION FROM DIFFERENT MANIFOLDS. LOSS OF ALL REDUNDANCY MAY RESULT IN LOSS OF VEHICLE DURING ENTRY DUE TO INABILITY TO CONTROL VEHICLE. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE THE INABILITY TO EXPEL ENOUGH RCS AND/OR OMS PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE); RCS SFOM, FIG. 3-4.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 269 ABORT: 3/3

ITEM: MANIFOLD 1, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	270	ABORT:	3/3

ITEM: MANIFOLD 2, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/1R
MDAC ID:	271	ABORT:	1/1

ITEM: MANIFOLD 2, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY FOR ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION FROM DIFFERENT MANIFOLDS. LOSS OF ALL REDUNDANCY MAY RESULT IN LOSS OF VEHICLE DURING ENTRY DUE TO INABILITY TO CONTROL VEHICLE. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE THE INABILITY TO EXPEL ENOUGH RCS AND/OR OMS PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE); RCS SFOM, FIG. 3-4.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 272 ABORT: 2/1R

ITEM: MANIFOLD 2, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ NA ] C [ P ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED.  
NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING  
OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS,  
RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL  
REDUNDANCY WILL CAUSE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF  
EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. LOSS OF THE  
THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE INABILITY TO EXPEL  
ENOUGH PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS,  
AND/OR THE CG SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS  
ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 273 ABORT: 3/3

ITEM: MANIFOLD 2, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	274	ABORT:	3/3

ITEM: MANIFOLD 3, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DF).



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 275

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 1/1

ITEM: MANIFOLD 3, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

## EFFECTS/RATIONALE:

REDUNDANCY FOR ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION FROM DIFFERENT MANIFOLDS. LOSS OF ALL REDUNDANCY MAY RESULT IN LOSS OF VEHICLE DURING ENTRY DUE TO INABILITY TO CONTROL VEHICLE. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE THE INABILITY TO EXPEL ENOUGH RCS AND/OR OMS PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DF); RCS SFOM, FIG. 3-4.



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/3
MDAC ID:	277	ABORT:	3/3

ITEM: MANIFOLD 3, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 278 ABORT: 3/3

ITEM: MANIFOLD 4, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DF).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	3/1R
MDAC ID:	279	ABORT:	1/1

ITEM: MANIFOLD 4, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0430-0006,0005

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:

REDUNDANCY FOR ALL PHASES EXCEPT RTLS FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE IN THE SAME DIRECTION FROM DIFFERENT MANIFOLDS. LOSS OF ALL REDUNDANCY MAY RESULT IN LOSS OF VEHICLE DURING ENTRY DUE TO INABILITY TO CONTROL VEHICLE. DURING RTLS, JETS ON OTHER MANIFOLDS FIRING IN THE SAME DIRECTION AS THOSE ON THIS MANIFOLD ARE NOT CONSIDERED TO BE REDUNDANT, SINCE LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE THE INABILITY TO EXPEL ENOUGH RCS AND/OR OMS PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DF); RCS SFOM, FIG. 3-4.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 280 ABORT: 2/1R

ITEM: MANIFOLD 4, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE INABILITY TO EXPEL ENOUGH PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS, AND/OR THE CG SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 281 ABORT: 3/3

ITEM: MANIFOLD 4, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3851,3801

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/3  
MDAC ID: 282 ABORT: 3/3

ITEM: MANIFOLD 5, ISOL VLV  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS INTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0420-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DG).



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/2  
MDAC ID: 283 ABORT: 3/3

ITEM: MANIFOLD 5, ISOL VLV  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, ISOL VLV
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX: MC284-0420-0012,0011

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE,  
LOSS OF SIGNAL FROM MDM

EFFECTS/RATIONALE:  
FAILURE RESULTS IN LOSS OF VRCS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DG).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/1R  
MDAC ID: 284 ABORT: 2/1R

ITEM: MANIFOLD 5, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN), OR LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	2/1R	RTLS:	2/1R
LIFTOFF:	2/1R	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	2/1R		

REDUNDANCY SCREENS: A [ 2 ] B [NA ] C [ P ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3451,3401

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FIRST FAILURE (COUPLING OR COUPLING CAP) CANNOT BE DETECTED. NEXT ASSOCIATED FAILURE WILL RESULT IN PROPELLANT LEAKING OVERBOARD WHICH COULD IGNITE DURING ASCENT, ENTRY, OR ABORTS, RESULTING IN LOSS OF VEHICLE. DURING ONORBIT, LOSS OF ALL REDUNDANCY WILL CAUSE LOSS OF LIFE FOLLOWING EVA OPERATIONS IF EVA SUITS ARE CONTAMINATED BY LEAKING PROPELLANT. LOSS OF THE THREE PRIMARY JETS ON THIS MANIFOLD MAY CAUSE INABILITY TO EXPEL ENOUGH PROPELLANTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS, AND/OR THE CG SAFETY BOUNDARIES. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM: ARCS	FLIGHT:	3/3
MDAC ID: 285	ABORT:	3/3

ITEM: MANIFOLD 5, GROUND PURGE/DRAIN COUPLING  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, GROUND PURGE/DRAIN COUPLING
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS THRUSTER ACCESS PANEL  
PART NUMBER: FU & OX: MC276-0018-3451,3401

CAUSES: CONTAMINATION, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
NONE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	286	ABORT:	1/1

ITEM: MANIFOLD ISOL VLVS  
FAILURE MODE: LEAKS EXTERNALLY

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD ISOL VLVS, ALL
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE, CAUSING CORROSION WHICH CAN RESULT IN ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 287 ABORT: 1/1

ITEM: MANIFOLD ISOL VLVS  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD ISOL VLVS, ALL
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: OMS/RCS POD  
PART NUMBER: FU & OX:

CAUSES: VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DE).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 288 ABORT: 1/1

ITEM: JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER LINES LEADING INTO JET BI-PROPELLANT VALVE

PART NUMBER: FU & OX: 73P550003-1002,1001

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

THIS FAILURE CAUSES PROPELLANT TO LEAK INTO THE POD/VEHICLE. THERE ARE TWO ALIGNMENT BELLOWS PER PRCS JET. LOSS OF PROPELLANT CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5; VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 289 ABORT: 1/1

ITEM: JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXIDIZER LINES LEADING INTO JET BI-PROPELLANT VALVE

PART NUMBER: FU & OX: 73P550003-1002,1001

CAUSES: VACUUM, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO, RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 290 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN/ON)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY

PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

A FAILED ON JET CAN CAUSE CONTACT WITH PAYLOADS DURING RENDEZVOUS, RESULTING IN LOSS OF VEHICLE, AND/OR EVA CREW, AND CAN CAUSE LOSS OF VEHICLE DURING ENTRY OR ABORTS. RM WILL NOT DESELECT JET, MUST BE SECURED BY CREW CLOSING ITS MANIFOLD. INHALATION OF PROPELLANT VAPORS ON THE GROUND CAN CAUSE LOSS OF LIFE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 291 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES  
FAILURE MODE: LEAKS EXTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE, CAUSING CORROSION WHICH COULD RESULT IN ELECTRICAL SHORTS AND PROPELLANT IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 292 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC	
PRELAUNCH:	3/3	RTLS:	1/1	
LIFTOFF:	1/1	TAL:	1/1	
ONORBIT:	1/1	AOA:	1/1	
DEORBIT:	1/1	ATO:	1/1	
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 293 ABORT: 3/1R

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, +X AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, +X AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

## EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE MAY AFFECT  
ONORBIT OPERATIONS AND WILL AFFECT THE + X JET RCS DEORBIT  
CAPABILITY. FAILURE MAY ALSO AFFECT RCS AND OMS DUMPS  
DURING ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 294 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, +X AXIS  
FAILURE MODE: LEAKS INTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, +X AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	1/1	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	1/1	AOA: 3/3
DEORBIT:	3/1R	ATO: 3/3
LANDING/SAFING:	1/1	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN PROPELLANT LEAKING INTO COMBUSTION CHAMBER, WHERE IT CAN FREEZE, RESULTING IN LOSS OF THE JET. RM WILL ANNOUNCE THE JET AS FAILED LEAKING AND DESELECT THE JET. FAILURE WILL CAUSE LOSS OF RCS DEORBIT CAPABILITY. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF EVA CREW IS CONTAMINATED BY PROP. PROPELLANTS WILL NOT HAVE ENOUGH TIME TO FREEZE DURING ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 3/1R  
MDAC ID: 295 ABORT: 3/1R

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, Y AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, Y AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE MAY AFFECT  
ONORBIT OPS AND MAY RESULT IN LOSS OF VEHICLE CONTROL DURING  
ENTRY. FAILURE MAY ALSO AFFECT RCS AND OMS DUMPS  
DURING ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87  
SUBSYSTEM: ARCS  
MDAC ID: 297

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 3/1R

ITEM: THRUSTER BIPROP SOLENOID VLVS, PRIMARY, Z AXIS  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, PRIMARY, Z AXIS
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY THRUSTERS WHICH FIRE  
IN THE SAME DIRECTION. RM WILL DESELECT JET. FAILURE MAY AFFECT  
ONORBIT OPS AND MAY RESULT IN LOSS OF VEHICLE CONTROL DURING  
ENTRY. FAILURE MAY ALSO AFFECT RCS AND OMS DUMPS  
DURING ABORTS.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.





# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 299 ABORT: 1/1

ITEM: JET ALIGNMENT BELLOWS, VERNIER, ALL AXES  
FAILURE MODE: STRUCTURAL FAILURE (RUPTURE OR LEAK)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) PROP STOR & DIST SUBSYSTEM
- 4) JET ALIGNMENT BELLOWS, VERNIER, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FUEL/OXID LINES LEADING INTO JET BIPROP VALVE  
PART NUMBER: FU & OX:

CAUSES: HIGH PRESSURE, VIBRATION, PIECE-PART STRUCTURAL FAILURE

## EFFECTS/RATIONALE:

THIS FAILURE CAUSES PROP TO LEAK INTO THE POD/VEHICLE. LOSS OF PROP CAN CAUSE CORROSION, LEADING TO ELECTRICAL SHORTS AND PROP IGNITION. FAILURE CAUSES HAZARD TO GROUND CREW.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH)



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 301 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES  
FAILURE MODE: FAILS TO CLOSE (FAILS OPEN/ON)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:

FAILURE RESULTS IN LOSS OF VERNIER RCS. RM WILL NOT DESELECT JET; MUST BE SECURED BY CREW CLOSING ITS MANIFOLD. A FAILED ON JET CAN CAUSE CONTACT WITH PAYLOADS DURING RENDEZVOUS, RESULTING IN LOSS OF VEHICLE AND/OR EVA CREW.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 2/2  
MDAC ID: 302 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES  
FAILURE MODE: FAILS TO OPEN (FAILS CLOSED)

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE, LOSS OF  
SIGNAL FROM MDM, LOW TEMPERATURE FREEZES PROPELLANT IN VALVE

EFFECTS/RATIONALE:

FAILURE RESULTS IN LOSS OF VERNIER RCS. RM WILL DESELECT JET.  
FAILURE CANNOT BE DETECTED UNTIL JET IS COMMANDED TO FIRE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 303 ABORT: 1/1

ITEM: THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES  
FAILURE MODE: LEAKS EXTERNALLY, ONE PROPELLANT

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	1/1
LIFTOFF:	1/1	TAL:	1/1
ONORBIT:	1/1	AOA:	1/1
DEORBIT:	1/1	ATO:	1/1
LANDING/SAFING:	1/1		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE RESULTS IN PROPELLANT LEAKING INTO POD/VEHICLE, CAUSING  
CORROSION AND RESULTING IN ELECTRICAL SHORTS AND PROPELLANT  
IGNITION.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH)

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	304	ABORT:	3/3

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

- 1) **HARDWARE COMPONENTS**
- 2) **ASSEMBLIES**
- 3) **THRUSTER SUBSYSTEM**
- 4) **THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES**
- 5)
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	1/1	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	1/1		

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

FAILURE RESULTS IN PROPELLANT LEAKING INTO INTO COMBUSTION CHAMBER, WHERE IT CAN FREEZE, RESULTING IN LOSS OF THE VERNIER RCS. LEAKAGE ONORBIT CAN CAUSE LOSS OF LIFE FOLLOWING EVA IF CREW IS CONTAMINATED BY PROPELLANTS. INHALATION OF PROP VAPORS ON GROUND CAN CAUSE LOSS OF LIFE.

**C-206**

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 2/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: ARCS FLIGHT: 1/1  
MDAC ID: 305 ABORT: 3/3

ITEM: THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES  
FAILURE MODE: RESTRICTED FLOW

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER BIPROP SOLENOID VLVS, VERNIERS, ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: CONTAMINATION, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
FAILURE MAY CAUSE UNACCEPTABLE PROPELLANT MIXTURE RATIO,  
RESULTING IN ZOTS AND/OR THRUSTER NOZZLE BURNTHROUGH AND LOSS OF  
VEHICLE.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH)

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	306	ABORT:	1/1

ITEM: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION,  
PRIMARY, ALL AXES  
FAILURE MODE: THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION  
BURNTHROUGH

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) HARDWARE COMPONENTS
- 2) ASSEMBLIES
- 3) THRUSTER SUBSYSTEM
- 4) THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION, PRIMARY,  
ALL AXES
- 5)
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 1/1
LIFTOFF:	1/1	TAL: 1/1
ONORBIT:	1/1	AOA: 1/1
DEORBIT:	1/1	ATO: 1/1
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

CAUSES: IMPROPER MIXTURE RATIO, PIECE-PART STRUCTURAL FAILURE

EFFECTS/RATIONALE:  
HOT, HIGH PRESSURE GAS VENTS INTO POD.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH); FLIGHT RULE 6-95.



DATE:	2/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	ARCS	FLIGHT:	1/1
MDAC ID:	307	ABORT:	3/3

LEAD ANALYST: SUBSYS LEAD: D.J. PAUL

1) HARDWARE COMPONENTS  
2) ASSEMBLIES  
3) THRUSTER SUBSYSTEM  
4) THRUSTER COMBUSTION CHAMBER OR NOZZLE EXTENSION, VERNIER,  
ALL AXES  
5)  
6)  
7)  
8)  
9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	1/1	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]            B [    ]            C [    ]

LOCATION: JET ASSEMBLY  
PART NUMBER: FU & OX:

**CAUSES: IMPROPER MIXTURE RATIO, PIECE-PART STRUCTURAL FAILURE**

**EFFECTS/RATIONALE:**  
FAILURE RESULTS IN LOSS OF VRCS. HOT, HIGH PRESSURE GAS VENTS INTO POD.

REFERENCES: JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, 11.5;  
VS70-943099 REV B EO B12 (43DH).

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	308	ABORT:	2/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	2/1R
ONORBIT:	3/2R		AOA:	2/1R
DEORBIT:	2/1R		ATO:	2/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC27; 82V76A23RPC27

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVS FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 309

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 3/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC27; 82V76A23RPC27

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU & OX HE ISOL A/B VLVS BECOMING STUCK INTO OPEN POSITION. THEREFORE THE HELIUM TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 310 ABORT: 3/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC40; 82V76A23RPC39

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVs CLOSED USING CREW SWITCH OR GPC. WORST CASE RESULTS IN HE ISOL A/B VLVs BECOMING STUCK IN THE OPEN POSITION. THEREFORE THE HE TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 311 ABORT: 2/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC40; 82V76A23RPC39

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO COMMAND FU & OX HE ISOL A/B VLVs USING GPC.  
CREW SWITCH CAN STILL OPEN OR CLOSE VLVs. LOSS OF ALL REDUNDANCY,  
WORST CASE, RESULTS IN FU & OX HE ISOL A/B VLVs BECOMING STUCK IN  
THE CLOSED POSITION. FOR THIS CASE, LOSS OF ALL  
REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY  
RESULT IN PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO  
BE EXCEEDED.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 312 ABORT: 2/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, PCA 2; F BAY 3, PCA 3  
PART NUMBER: 82V76A23RPC26; 83V76A24RPC27

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVS FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 313 ABORT: 3/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, PCA 2; F BAY 3, PCA 3  
PART NUMBER: 82V76A23RPC26; 83V76A24RPC27

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU & OX HE ISOL A/B VLVS BECOMING STUCK INTO OPEN POSITION. THEREFORE THE HELIUM TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	314	ABORT:	3/1R

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC41; 82V76A23CR7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVS CLOSED USING CREW SWITCH OR GPC. WORST CASE RESULTS IN HE ISOL A/B VLVS BECOMING STUCK IN THE OPEN POSITION. THEREFORE THE HE TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 315 ABORT: 3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	HDW/FUNC
		ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22RPC41; 82V76A23CR7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO INHIBIT THE FU & OX HE ISOL A/B VLV "CLOSE"  
CMD. THE INHIBIT FUNCTION IS USED FOR POWER SAVINGS AND IN CASE  
OF A FAILED ON COMMAND. NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 316 ABORT: 3/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ F ]

LOCATION: F BAY 1, PCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16CR J1-85; 82V76A17CR J1-85

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVS CLOSED USING GPC. CREW SWITCH CAN STILL OPEN OR CLOSE VLVS. LOSS OF ALL REDUNDANCY IS POSSIBLE INABILITY TO ISOLATE HE SYSTEM LEADING TO OVERPRESSURIZATION AND POSSIBLE RUPTURE OF PROP TANKS OR LINES, FIRE/HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 317

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 3/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ F ]

LOCATION: F BAY 1, PCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16CR J1-85; 82V76A17CR J1-85

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN GPC AND CREW SWITCH CLOSE COMMANDS. THE FAILURE CAN RESULT IN LOSS OF THE GPC OR CREW SWITCH TO OPERATE THE FU & OX HE ISOL A/B VLVS. LOSS OF ALL REDUNDANCY IS POSSIBLE INABILITY TO ISOLATE HE SYSTEM LEADING TO OVERPRESSURIZATION AND POSSIBLE RUPTURE OF PROP TANKS OR LINES, FIRE/HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

C - 4/

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	318	ABORT:	3/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ P ]      C [ F ]

LOCATION:      F BAY 1, PCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16CR J2-79; 82V76A17CR J2-79

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVs CLOSED USING CREW SWITCH. GPC CAN STILL OPEN OR CLOSE VLVs. LOSS OF ALL REDUNDANCY IS POSSIBLE INABILITY TO ISOLATE HE SYSTEM LEADING TO OVERPRESSURIZATION AND POSSIBLE RUPTURE OF PROP TANKS OR LINES, FIRE/HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 319 ABORT: 3/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ F ]

LOCATION: F BAY 1, PCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16CR J2-79; 82V76A17CR J2-79

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN GPC AND CREW SWITCH CLOSE COMMANDS. THE FAILURE CAN RESULT IN LOSS OF THE GPC OR CREW SWITCH TO OPERATE THE FU & OX HE ISOL A/B VLVS. LOSS OF ALL REDUNDANCY IS POSSIBLE INABILITY TO ISOLATE HE SYSTEM LEADING TO OVERPRESSURIZATION OF PROP TANKS OR LINES, FIRE/HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	320	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER:    81V76A22CR37; 82V76A23CR8

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVS FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 321

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22CR37; 82V76A23CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
LOSE ISOLATION BETWEEN MAIN BUSES WHEN THE GPC CMDs THE FU & OX HE  
ISOL A/B VLVs OPEN. THE WORST CASE EFFECT IS LOSS OF THE GPC OR  
CREW SWITCH "OPEN" CMD. LOSS OF ALL REDUNDANCY, WORST CASE,  
RESULTS IN BOTH A & B HE ISOL VLVs BECOMING STUCK IN THE  
CLOSED POSITION. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE  
VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED  
FRCS PROPELLANTS CAUSING THE VEHICLE SAFETY CG BOUNDARIES TO BE  
EXCEEDED.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 322 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22CR13; 82V76A23RPC38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVs FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 323

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1; F BAY 2, PCA 2  
PART NUMBER: 81V76A22CR13; 82V76A23RPC38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN MAIN BUSES WHEN THE CREW SWITCH CMDS THE FU & OX HE ISOL A/B VLVs OPEN. THE WORST CASE EFFECT IS LOSS OF THE GPC OR CREW SWITCH "OPEN" CMD. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVs BECOMING STUCK IN THE CLOSED POSITION. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED FRCS PROPELLANTS CAUSING THE VEHICLE SAFETY CG BOUNDARIES TO BE EXCEEDED.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 324 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS3  
PART NUMBER: 33V73A8CR1; 82V76A17AR J4-55 TYPE II

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE FU & OX HE ISOL VLVS POSITION TALKBACK TO HARDWIRED CREW INDICATOR. NO IMPACT, VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 325 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS3  
PART NUMBER: 33V73A8CR1; 82V76A17AR J4-55 TYPE II

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 326 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS3  
PART NUMBER: 33V73A8CR2; 33V73A8CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE FU HE ISOL VLVs POSITION TALKBACK TO HARDWIRED CREW INDICATOR. NO IMPACT, VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 327 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS3  
PART NUMBER: 33V73A8CR2; 33V73A8CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 328 ABORT: 3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/1R
LIFTOFF:	3/1R		TAL:	3/1R
ONORBIT:	3/1R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-50 TYPE I; 82V76A17AR J4-50 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVs CLOSED USING CREW SWITCH OR GPC. WORST CASE RESULTS IN HE ISOL A/B VLVs BECOMING STUCK IN THE OPEN POSITION. THEREFORE THE HE TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 329

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 2/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 2/1R
LIFTOFF:	3/3	TAL: 2/1R
ONORBIT:	3/2R	AOA: 2/1R
DEORBIT:	2/1R	ATO: 2/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-50 TYPE I; 82V76A17AR J4-50 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO COMMAND FU & OX HE ISOL A/B VLVs USING GPC. CREW SWITCH CAN STILL OPEN OR CLOSE VLVs. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN FU & OX HE ISOL A/B VLVs BECOMING STUCK IN THE CLOSED POSITION. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 330 ABORT: 2/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	2/1R
ONORBIT:	3/2R		AOA:	2/1R
DEORBIT:	2/1R		ATO:	2/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-51 TYPE I; 82V76A17AR J4-51 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVs FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 331 ABORT: 3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-51 TYPE I; 82V76A17AR J4-51 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU & OX HE ISOL A/B VLVs BECOMING STUCK INTO OPEN POSITION. THEREFORE THE HELIUM TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 332 ABORT: 2/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, LCA 2; F BAY 3, LCA 3  
PART NUMBER: 82V76A17AR J4-57 TYPE I; 83V76A18R J1-92 (A)

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH SIGNAL TO OPEN FU & OX HE ISOL A/B VLV. VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN BOTH A & B HE ISOL VLVS FAILED CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN TRAPPED PROPELLANTS CAUSING THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ABORTS AND DEORBIT, LOSS OF LIFE/VEHICLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 333

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, LCA 2; F BAY 3, LCA 3  
PART NUMBER: 82V76A17AR J4-57 TYPE I; 83V76A18R J1-92 (A)

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU & OX HE ISOL A/B VLVS BECOMING STUCK INTO OPEN POSITION. THEREFORE THE HELIUM TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 334 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-53 TYPE II; 82V76A17AR J4-53 TYPE II

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION OF FU & OX HE ISOL A/B VLV MISMATCH (GPC HAS CORRECT POSITION); TALKBACK NOT MISSION CRITICAL. SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VLV ONCE IT HAS LATCHED; VALVE CAN WITHSTAND CONTINUOUS ENERGIZATION.

REFERENCES: VS70-942099 REV D EO D01; MC284-0420 REV C AMENDMENT SEQ 8

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 335 ABORT: 3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/1R
LIFTOFF:	3/1R		TAL:	3/1R
ONORBIT:	3/1R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16AR J4-53 TYPE II; 82V76A17AR J4-53 TYPE II

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FAILURE RESULTS IN A FALSE CREW (BARBER POLE) INDICATION OF VLV CLOSURE AND A FALSE CONTROL FEEDBACK WHICH INHIBITS ALL GPC AND CREW SWITCH "CLOSE" COMMANDS. THE FAILURE CAN RESULT IN ONE OF THE TWO FU & OX HE ISOL (A OR B) VLV'S BECOMING STUCK IN THE OPEN POSITION. THEREFORE THE HE TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND POSSIBLE RUPPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	336	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:            PNL 08 DS4  
PART NUMBER:    81V76A16AR J4-55 TYPE II; 33V73A8CR4

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION OF FU & OX HE ISOL A/B VLV MISMATCH (GPC HAS CORRECT POSITION); TALKBACK NOT MISSION CRITICAL. SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VLV ONCE IT HAS LATCHED; VALVE CAN WITHSTAND CONTINUOUS ENERGIZATION.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 337 ABORT: 3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/2R	RTLS: 3/1R
LIFTOFF:	3/3	TAL: 3/1R
ONORBIT:	3/2R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 3 ] B [ F ] C [ P ]

LOCATION: PNL 08 DS4  
PART NUMBER: 81V76A16AR J4-55 TYPE II; 33V73A8CR4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FAILURE RESULTS IN A FALSE CREW (BARBER POLE) INDICATION OF VLV OPENING AND A FALSE CONTROL FEEDBACK WHICH INHIBITS ALL GPC AND CREW SWITCH "OPEN" COMMANDS. THE FAILURE CAN RESULT IN ONE OF THE TWO (A OR B) HE ISOL VALVES FAILING CLOSED CASE. FOR THIS CASE, LOSS OF ALL REDUNDANCY TO THE VALVES WILL CAUSE LOSS OF HE PRESSURIZATION CAPABILITY, WHICH WILL AFFECT ONORBIT OPERATIONS AND MAY CAUSE THE VEHICLE CG SAFETY BOUNDARIES TO BE EXCEEDED DURING ENTRY OR ABORTS DUE TO THE TRAPPED PROPELLANT'S WEIGHT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	338	ABORT:	3/1R

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL 08 DS4  
PART NUMBER:    81V76A16AR J4-52 TYPE I; 82V76A17AR J4-52 TYPE I

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVs CLOSED USING CREW SWITCH OR GPC. WORST CASE RESULTS IN HE ISOL A/B VLVs BECOMING STUCK IN THE OPEN POSITION. THEREFORE THE HE TK CANNOT BE ISOLATED FROM THE PROPELLANT SYSTEM, NO IMMEDIATE EFFECT. LOSS OF ALL REDUNDANCY IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO OVERPRESSURIZATION AND RUPTURE OF PROP TANKS OR LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES:    VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 339 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS4  
PART NUMBER: 81V76A16AR J4-52 TYPE I; 82V76A17AR J4-52 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO INHIBIT THE FU & OX HE ISOL A/B VLV "CLOSE"  
CMD. THE INHIBIT FUNCTION IS USED FOR POWER SAVINGS AND IN CASE  
OF A FAILED ON COMMAND. NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 340 ABORT: 3/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/1R		RTLS:	3/1R
LIFTOFF:	3/1R		TAL:	3/1R
ONORBIT:	3/1R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ F ]

LOCATION: PNL 08 S16; PNL 08 S17  
PART NUMBER: 33V73A8F4; 33V73A8F23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND FU & OX HE ISOL A/B VLVs CLOSED USING CREW SWITCH. GPC CAN STILL OPEN OR CLOSE VLVs. LOSS OF ALL REDUNDANCY IS POSSIBLE INABILITY TO ISOLATE HE SYSTEM LEADING TO OVERPRESSURIZATION AND POSSIBLE RUPTURE OF PROP TANKS OR LINES, FIRE/HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 341 ABORT: 3/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/1R
LIFTOFF:	3/1R	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S16; PNL 08 S17  
PART NUMBER: 33V73A8F13; 33V73A8F28

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

LOSE ALL BUT ONE COMMAND (A GPC OPEN CMD) TO OPERATE FU & OX HE  
ISOL A/B VLVS. THE FAILURE RESULTS IN EITHER A OR B HE ISOL VALVE  
FAILED OPEN. THE EFFECT IS POSSIBLE LOSS OF LIFE/VEHICLE DUE TO  
OVERPRESSURIZATION AND POSSIBLE RUPTURE OF PROP TANKS  
LINES, FIRE/EXPLOSION HAZARD, AND HAZARD TO GROUND CREW. MAY ALSO  
CAUSE ZOTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	342	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-86 TO J2-79 (A); 82V76A17R J1-86 TO J2-79 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FRCS HE PRESS VLV A/B POSITION TALKBACK TO GPC. NO IMPACT, VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 343 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-86 TO J2-79 (A); 82V76A17R J1-86 TO J2-79 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	344	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-86 TO J2-79 (B); 82V76A17R J1-86 TO J2-79 (B)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 345 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-86 TO J2-79 (A); 82V76A17R J1-86 TO J2-79 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
LOSE FRCS HE PRESS VLV A/B POSITION TALKBACK TO GPC. NO IMPACT,  
VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	346	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, LCA 2; F BAY 3, LCA 3  
PART NUMBER: 82V76A17R J1-92 (A); 83V76A18AR J4-57 TYPE I

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FRCS HE PRESS VLV A/B POSITION TALKBACK TO GPC. NO IMPACT,  
VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 347 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, LCA 2; F BAY 3, LCA 3  
PART NUMBER: 82V76A17R J1-92 (A); 83V76A18AR J4-57 TYPE I

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 348 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-88; 82V76A17R J1-88

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE FU HE ISOL VLVs POSITION TALKBACK TO GPC. NO IMPACT,  
VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 349 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-88; 82V76A17R J1-88

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 350 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-90; 82V76A17R J1-90

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE FU HE ISOL VLVS POSITION TALKBACK TO GPC. NO IMPACT, VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 351 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-90; 82V76A17R J1-90

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 352 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-91; 82V76A17R J1-91

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE OX HE ISOL VLVS POSITION TALKBACK TO GPC. NO IMPACT,  
VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 353 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-91; 82V76A17R J1-91

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 354 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-89; 82V76A17R J1-89

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE THE OX HE ISOL VLVs POSITION TALKBACK TO GPC. NO IMPACT, VALVE TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 355 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J1-89; 82V76A17R J1-89

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	356	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:            F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER:    81V76A16R J1-104; 82V76A17R J2-104

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION: CREW HARDWARE TALKBACK WILL INDICATE FU & OX HE ISOL VLV MISMATCH AND GPC WILL INDICATE BOTH VALVES STUCK PARTIALLY OPEN/PARTIALLY CLOSED; VALVE TALKBACK NOT MISSION CRITICAL..

SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VALVE ONCE IT HAS LATCHED: VALVE CAN WITHSTAND CONTINUOUS ENERGIZATION.

REFERENCES:    VS70-942099 REV D EO D01; MC284-0420 REV C AMENDMENT  
SEQ 8

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 357 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1; F BAY 2, LCA 2  
PART NUMBER: 81V76A16R J2-104; 82V76A17R J2-104

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE TO HYBRID DRIVER LOGIC  
CIRCUIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	358	ABORT:	3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE PRESSURE REGULATOR AND THE PRESSURE RELIEF VALVE. IF THE SWITCH FAILS IN THE OPEN POSITION WHILE THE VALVE IS IN ANY POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY MDM COMMAND.

FAILURE OF ALL REDUNDANCY WILL RESULT IN THE OVERPRESSURIZATION AND RUPTURE OF THE PROPELLANT TANKS AND/OR LINES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 359 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/1R
LIFTOFF:	3/3		TAL:	3/1R
ONORBIT:	3/2R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS AND THE PARALLEL ISOL VALVE. IF THE SWITCH FAILS IN THE CLOSED POSITION WHILE THE VALVE IS IN ANY POSITION, THE VALVE WILL CLOSE. IF THE MDM OPEN COMMAND IS ALSO PRESENT, OR THE SWITCH OPEN COMMAND IS ALSO PRESENT, THE VALVE WILL CYCLE OPEN AND CLOSED UNTIL THE MDM OR SWITCH OPEN COMMAND IS REMOVED, OR UNTIL THE CONTROL BUS POWER IS REMOVED FROM EITHER OF THE SWITCH'S CLOSE CONTACTS. TO OPEN THE VALVE, CREW MUST REMOVE POWER FROM EITHER OF THE SWITCH'S CLOSE CONTACTS 5,6, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, AND WILL CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 361 ABORT: 3/3

ITEM: HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 1,  
2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 362 ABORT: 3/3

ITEM: HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 1,  
2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV D EO D01, CA, DA



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 363 ABORT: 3/3

ITEM: HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	364	ABORT:	3/3

ITEM: HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S16  
PART NUMBER:    33V73A8S16; S17

CAUSES:    CONTAMINATION,VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES:    VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87. HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 365 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS 5,  
6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	HDW/FUNC
PRELAUNCH:	3/1R	ABORT	RTLS: 3/1R
LIFTOFF:	3/1R		TAL: 3/1R
ONORBIT:	3/1R		AOA: 3/1R
DEORBIT:	3/1R		ATO: 3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION,VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM CLOSE COMMAND, THE PRESSURE  
REGULATOR, AND THE PRESSURE RELIEF VALVE. IF THE CLOSE CONTACTS  
FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL  
REMAIN IN THAT POSITION, CAN BE OPENED BY THE SWITCH OR BY THE MDM  
COMMAND, AND CANNOT BE CLOSED BY THE SWITCH COMMAND, ONLY BY THE  
MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL RESULT IN  
OVERPRESSURIZATION AND RUPTURE OF THE PROPELLANT TANKS AND/OR  
LINES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 366 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS  
5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

CRITICALITIES

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS, THE OTHER SWITCH CLOSE CONTACTS, AND THE PARALLEL ISOL VALVE. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE GPC OR CLOSED POSITION, THE VALVE WILL CLOSE, AND CANNOT BE OPENED BY MDM COMMAND, ONLY BY SWITCH COMMAND. IF THE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN POSITION, THE VALVE WILL REMAIN OPEN, AND CANNOT BE CLOSE BY MDM COMMAND, ONLY BY SWITCH COMMAND. TO OPEN THE VALVE WITH THE MDM COMMAND, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS 5,6, AND USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROP DURING ENTRY AND ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 367 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 7,  
8  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH OPEN CONTACTS 7, 8
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/1R
LIFTOFF:	3/3	TAL: 3/1R
ONORBIT:	3/2R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/1R	

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL O8 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS AND THE PARALLEL ISOL VALVE. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE CLOSED BY SWITCH OR MDM COMMAND, BUT CANNOT BE OPENED BY SWITCH COMMAND, ONLY BY MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, AND MAY RESULT IN THE INABILITY TO EXPEL ENOUGH PROPELLANT DURING ENTRY AND ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 369 ABORT: 3/3

ITEM: HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 9,  
10  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH GPC CONTACTS 9, 10
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK,  
OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMAND AND THE PARALLEL ISOLATION VALVE. IF THE GPC CONTACTS FAIL OPEN, THE VALVE CAN BE OPENED BY SWITCH OR MDM COMMAND, CAN BE CLOSED BY SWITCH COMMAND, AND CANNOT BE CLOSED BY MDM COMMAND UNLESS THE SWITCH IS IN THE CLOSED POSITION. FAILURE OF ALL REDUNDANCY WILL RESULT IN LOSS OF GPC CONTROL OF THE HELIUM PRESSURE.

REFERENCES: VS70-943099 REV D EO D01, CA, DA





# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 371 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS  
11, 12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/1R	RTLS:	3/1R
LIFTOFF:	3/1R	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/1R		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL O8 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE SWITCH GPC CONTACTS AND THE MDM CLOSE COMMAND, AND BY THE PRESSURE REGULATORS AND THE PRESSURE RELIEF VALVE. IF THE CLOSE CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE OPENED BY THE SWITCH OR MDM COMMAND, BUT CANNOT BE CLOSED BY THE SWITCH OR MDM CLOSE COMMAND. THE VALVE CAN BE CLOSED BY PLACING THE SWITCH IN THE GPC POSITION, AND THEN USING THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL RESULT IN THE OVERPRESSURIZATION AND RUPTURE OF THE PROPELLANT TANKS AND/OR LINES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 372 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS  
11, 12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVS
- 5) HE OX & FU ISOL VLV A OR B SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/1R
LIFTOFF:	3/3		TAL:	3/1R
ONORBIT:	3/2R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 3 ] B [ F ] C [ P ]

LOCATION: PNL 08 S16  
PART NUMBER: 33V73A8S16; S17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE OTHER SWITCH CLOSE CONTACTS AND THE PARALLEL ISOL VALVE. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, AND CAN BE CLOSED AND OPENED BY SWITCH OR MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ENTRY OR ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV D EO D01, CA, DA

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 373 ABORT: 3/3

ITEM: HE TK PRESS-2 PRESS SENSOR  
FAILURE MODE: INDICATES LOWER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE TK PRESS-2 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 374 ABORT: 3/3

ITEM: HE TK PRESS-2 PRESS SENSOR  
FAILURE MODE: INDICATES HIGHER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE TK PRESS-2 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 375 ABORT: 3/3

ITEM: HE FU TK PRESS-1 PRESS SENSOR  
FAILURE MODE: INDICATES LOWER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE FU TK PRESS-1 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 376 ABORT: 3/3

ITEM: HE FU TK PRESS-1 PRESS SENSOR  
FAILURE MODE: INDICATES HIGHER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE FU TK PRESS-1 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 377 ABORT: 3/3

ITEM: HE OX TK PRESS-1 PRESS SENSOR  
FAILURE MODE: INDICATES LOWER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK PRESS-1 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 378 ABORT: 3/3

ITEM: HE OX TK PRESS-1 PRESS SENSOR  
FAILURE MODE: INDICATES HIGHER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK PRESS-1 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC	
PRELAUNCH:	3/3	RTLS:	3/3	
LIFTOFF:	3/3	TAL:	3/3	
ONORBIT:	3/3	AOA:	3/3	
DEORBIT:	3/3	ATO:	3/3	
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 379 ABORT: 3/3

ITEM: HE OX TK PRESS-2 PRESS SENSOR  
FAILURE MODE: INDICATES LOWER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK PRESS-2 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 380 ABORT: 3/3

ITEM: HE OX TK PRESS-2 PRESS SENSOR  
FAILURE MODE: INDICATES HIGHER PRESSURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK PRESS-2 PRESS SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 381 ABORT: 3/3

ITEM: HE OX TK TEMP-1 TEMP SENSOR  
FAILURE MODE: INDICATES LOWER TEMPERATURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	382	ABORT:	3/3

ITEM: HE OX TK TEMP-1 TEMP SENSOR  
FAILURE MODE: INDICATES HIGHER TEMPERATURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 383 ABORT: 3/3

ITEM: HE OX TK TEMP-1 TEMP SENSOR  
FAILURE MODE: INDICATES LOWER TEMPERATURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	384	ABORT:	3/3

LEAD ANALYST: V.J. BURKEMPER                      SUBSYS LEAD: D.J. PAUL

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE OX TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

REDUNDANCY SCREENS:    A [    ]            B [    ]            C [    ]

**CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD**

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REPORT DATE 03/23/87

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 385 ABORT: 3/3

ITEM: HE FU TK TEMP-1 TEMP SENSOR  
FAILURE MODE: INDICATES LOWER TEMPERATURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE FU TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 386 ABORT: 3/3

ITEM: HE FU TK TEMP-1 TEMP SENSOR  
FAILURE MODE: INDICATES HIGHER TEMPERATURE THAN ACTUAL

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE TK
- 5) HE FU TK TEMP-1 TEMP SENSOR
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT HDW/FUNC
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: FWD FUSELAGE AREA 20  
PART NUMBER: 22V42MT2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FAILURE OF TANK TEMPERATURE SENSOR AND REDUNDANT PRESSURE SENSORS WILL CAUSE GROUND AND FLIGHT CREW DIFFICULTY IN DETECTING A TANK LEAK. CREW MAY MAKE BAD DECISION BASED ON ERRONEOUS DATA.

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE SYSTEMS HANDBOOK, PAGE 11.6



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 387 ABORT: 3/1R

ITEM: HE OX & FU ISOL VLV A OR B SWITCH TALKBACK  
FAILURE MODE: ERRONEOUS INDICATION (FAILS HIGH, FAILS LOW, FAILS  
MIDTRAVEL)

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) INSTRUMENTATION
- 3) HE PRESS SUBSYSTEM
- 4) HE OX & FU ISOL A & B VLVs
- 5) HE OX & FU ISOL VLV A OR B SWITCH TALKBACK
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 DS3, DS4  
PART NUMBER: 33V73A8DS3; DS4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

FWD RCS HE PRESS A/B POSITION INDICATION WOULD FALSELY SHOW A  
BARBERPOLE INDICATING EITHER THE FU OR OX A OR B VALVES ARE STUCK  
PARTIALLY OPEN/CLOSED OR THERE IS A POSITION MISMATCH BETWEEN THE  
TWO VALVES. LOSS OF ALL REDUNDANCY WOULD RESULT  
IN LOSS OF DIRECT VALVE TALKBACK TO CREW. WORST CASE WOULD BE  
FALSELY FAILING THE A OR B VALVE CLOSED RESULTING IN LOSS OF  
MISSION DUE TO SAFETY CONSIDERATIONS (ONE FAILURE AWAY FROM LOSS  
OF VEHICLE/LIFE).

REFERENCES: VS70-942099 REV D EO D01; JSC 11174, SPACE SHUTTLE  
SYSTEMS HANDBOOK, PAGE 11.6

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 388 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU TK ISOL 1/2 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01; MC482-0430 REV E AMENDMENT SEQ. 7

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 389

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS CA1 AND MNC WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 390 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR21

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 1/2 VALVE USING CREW SWITCH. THE VALVE IS STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS ABORTS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 391 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR21

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 392

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 2/1R
LIFTOFF:	3/3	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 1/2 VALVE USING CREW SWITCH. THE VALVE IS STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS ABORTS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 393 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	394	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE OX TK ISOL 1/2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	395	ABORT:	1/1

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ F ]      C [ P ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE OX ISOL 1/2 VALVE FAILING MIDTRAVEL WHEN COMMANDED OPEN. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	396	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	HDW/FUNC
PRELAUNCH:	3/3	ABORT	
LIFTOFF:	3/3	RTLS:	3/3
ONORBIT:	3/3	TAL:	3/3
DEORBIT:	3/3	AOA:	3/3
LANDING/SAFING:	3/3	ATO:	3/3

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU & OX TK ISOL 1/2 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 397 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	398	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 1/2 VALVE USING GPC CMDS. THE VALVE IS STILL FULLY OPERATIONAL USING CREW SWITCH. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS ABORTS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 399 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	
		ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 400

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OX ISOL 1/2 VALVE USING GPC CMDS. THE VALVE IS STILL FULLY OPERATIONAL USING CREW SWITCH. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS ABORTS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	401	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	402	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU & OX TK ISOL 1/2 VALVES USING GPC COMMANDS. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 403

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 405 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR18

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" CMDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF ABILITY TO CLOSE FU & OX TK ISOL 1/2 VALVES USING CREW SWITCH OR GPC. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND MANIFOLD ISOL 1 OR 2 BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

**INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET**

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	406	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

**EFFECTS/RATIONALE:**

LOSE CONTROL FEEDBACK FROM FU TK ISOL 1/2 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 407 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS CA1 AND MNC WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	408	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE FU TK ISOL 1/2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 409 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE OX ISOL 1/2 VALVE FAILING MIDTRAVEL WHEN COMMANDED CLOSED. THE EFFECT COULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 410 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU TK ISOL 1/2 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 411 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS CA1 AND MNC WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	412	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE FU TK ISOL 1/2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 413 ABORT: 1/1

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	1/1
LIFTOFF:	3/3		TAL:	2/1R
ONORBIT:	2/1R		AOA:	2/1R
DEORBIT:	2/1R		ATO:	2/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 3 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE FU ISOL 1/2 VALVE FAILING MIDTRAVEL WHEN COMMANDED OPEN. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 414 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU TK ISOL 1/2 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 415

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" CMDs. FAILURE COULD POSSIBLY RESULT IN LOSS OF ABILITY TO CLOSE FU & OX TK ISOL 1/2 VALVES USING CREW SWITCH OR GPC. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND MANIFOLD ISOL 1 OR 2 BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	416	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER:    83V76A113A1CR19

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE OX TK ISOL 1/2 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 417 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR19

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 418 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE OX TK ISOL 1/2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 419

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE FU ISOL 1/2 VALVE FAILING MIDTRAVEL WHEN COMMANDED CLOSED. THE EFFECT COULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	420	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM OX TK ISOL 1/2 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 421 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS CA2 AND MNC WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	422	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR20

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE OX TK ISOL 1/2 VALVES USING GPC COMMANDS. CREW SWITCH IS STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 423

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR20

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 1/2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVE FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 424 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU TK ISOL 3/4/5 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01; MC284-0430 REV E AMENDMENT SEQ. 7

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 425 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS AB1 AND MNA WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 426 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 3/4/5 VALVE USING CREW SWITCH. THE VALVE IS STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 427

HIGHEST CRITICALITY  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 428

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 2/1R
LIFTOFF:	3/3	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 3/4/5 VALVE USING CREW SWITCH. THE VALVE IS STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	429	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 430 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR19

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE OX TK ISOL 3/4/5 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 431 ABORT: 1/1

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR19

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE OX ISOL 3/4/5 VALVE FAILING MIDTRAVEL WHEN COMMANDED OPEN. THE EFFECT WOULD BE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 432 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR20

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU & OX TK ISOL 3/4/5 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOLD ISOL 3, 4 & 5 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4 AND 5, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 433 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR20

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 434

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 2/1R
LIFTOFF:	3/3	TAL: 3/1R
ONORBIT:	3/1R	AOA: 3/1R
DEORBIT:	3/1R	ATO: 3/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU ISOL 3/4/5 VALVE USING GPC CMDS. THE VALVE IS STILL FULLY OPERATIONAL USING CREW SWITCH. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	435	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 3 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 436 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OX ISOL 3/4/5 VALVE USING GPC CMDS. THE VALVE IS STILL FULLY OPERATIONAL USING CREW SWITCH. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSE. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 437

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 439 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR21

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "CLOSE" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 440

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3

HDW/FUNC

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU TK ISOL 3/4/5 VALVES USING GPC COMMANDS. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOLD ISOL 3, 4 & 5 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, AND 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	441	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH CLOSE CMDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF ABILITY TO CLOSE FU & OX TK ISOL 3/4/5 VALVES USING CREW SWITCH OR GPC. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOL ISOL 3, 4, OR 5 BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, OR 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 442 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU TK ISOL 3/4/5 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 443

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS AB1 AND MNA WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITON. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 444

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE FU TK ISOL 3/4/5 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 445

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE OX ISOL 3/4/5 VALVE FAILING MIDTRAVEL WHEN COMMANDED CLOSED. THE EFFECT COULD BE AND INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, OR 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 446

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU TK ISOL 3/4/5 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 447 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CONT BUS AB1 AND MNA WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 448 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR18

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE FU TK ISOL 3/4/5 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 449 ABORT: 1/1

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR18

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE FU ISOL 3/4/5 VALVE FAILING MIDTRAVEL WHEN COMMANDED OPEN. THE EFFECT WOULD BE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	450	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU TK ISOL 3/4/5 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOLD ISOL 3, 4 & 5 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, AND 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 451 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH CLOSE CMDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF ABILITY TO CLOSE FU & OX TK ISOL 3/4/5 VALVES USING CREW SWITCH OR GPC. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOL ISOL 3, 4, 5 BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, OR 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 452

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR16

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE OX TK ISOL 3/4/5 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOLD ISOL 3, 4 & 5 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, AND 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 453 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR16

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH CLOSE CMDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF ABILITY TO CLOSE FU & OX TK ISOL 3/4/5 VALVES USING CREW SWITCH OR GPC. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOL ISOL 3, 4, 5 BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, OR 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	454	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE OX TK ISOL 3/4/5 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 455 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A1111A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN FU & OX CONTROL FEEDBACKS. CONTROL FEEDBACKS INHIBIT VALVE OPERATION AFTER COMMAND HAS BEEN COMPLETED. THE FAILURE CAN RESULT IN THE FU ISOL 3/4/5 VALVE FAILING MIDTRAVEL WHEN COMMANDED CLOSED. THE EFFECT COULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, OR 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	456	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM OX TK ISOL 3/4/5 VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 457 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
LOSE DIODE ISOLATION BETWEEN CONT BUS AB2 AND MNA WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. NO EFFECT ON MISSION, ANY POSSIBLE CURRENT FLOW WILL BE LIMITED BY SERIES RESISTANCE.

REFERENCES: VS70-942099 REV D EO D01





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 459 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN GPC AND CREW SWITCH "OPEN" COMMANDS. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR CREW SWITCH TO CONTROL OX & FU TK ISOL 3/4/5 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN TK ISOL 1/2 AND 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO DEplete/USE PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 460 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 1/2 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO OPEN POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 461 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 1/2 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO CLOSE POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	462	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 1/2 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO CLOSE POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 463 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 1/2 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO OPEN POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	464	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 3/4/5 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO OPEN POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 465 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 3/4/5 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO CLOSE POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 466 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 3/4/5 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO CLOSE POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 467 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

HARDWIRED TALKBACK (BARBER POLE) TO CREW WILL FALSELY INDICATE FU & OX ISOL 3/4/5 VALVE MISMATCH WHEN VALVES ARE COMMANDED TO OPEN POSITION. GPC WILL INDICATE CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	468	ABORT:	3/3

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:            PNL 08 S23  
PART NUMBER:    33V73A8F41

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE FU & OX TK ISOL 1/2 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 1/2 AND MANIFOLD ISOL 1&2 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES:    VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 469

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8F36

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX ISOL 1/2 VALVE USING CREW SWITCH. THE VALVES ARE STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 & 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO USE/DEplete PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES: VS70-942099 REV D EO D01

**INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET**

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	470	ABORT:	3/3

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S24  
PART NUMBER: 33V73A8F16

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

**EFFECTS/RATIONALE:**

LOSE ABILITY TO CLOSE FU & OX TK ISOL 3/4/5 VALVES USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE. LOSS OF ALL REDUNDANCY RESULTS IN THE TK ISOL 3/4/5 AND MANIFOLD ISOL 3, 4 & 5 VALVES BECOMING STUCK IN THE OPEN POSITION. THE EFFECT WOULD BE AN INABILITY TO ISOLATE THE TANKS FROM MANIFOLDS 3, 4, AND 5. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	471	ABORT:	2/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL 08 S24  
PART NUMBER:    33V73A8F7

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX ISOL 3/4/5 VALVES USING CREW SWITCH. THE VALVES ARE STILL FULLY OPERATIONAL USING GPC CMDS. LOSS OF ALL REDUNDANCY RESULTS IN TK ISOL 1/2 & 3/4/5 VALVES FAILED CLOSED. THE EFFECT IS AN INABILITY TO USE/DEplete PROPELLANTS CONSEQUENTLY CG SAFETY BOUNDARIES WILL BE EXCEEDED DURING RTLS RESULTING IN LOSS OF VEHICLE/LIFE.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	472	ABORT:	1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ F ]      C [ P ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K1

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE FU TK ISOL 1/2 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES.

DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 473

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 474 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 475

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NO EFFECT ON FU TK ISOLATION 1/2 VALVE OPERATION. WHAT WAS LOST WAS A SAFEGUARD DESIGNED TO KEEP A SINGLE RELAY FAILURE FROM CAUSING AN IMMEDIATE LOSS OF MISSION CAPABILITY BY FAILING THE FU TK ISOL VALVE CLOSED. SECOND FAILURE (FAILURE OF REDUNDANT RELAY) RESULTS IN THE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 476 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 477 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 1/1
LIFTOFF:	3/3	TAL: 2/1R
ONORBIT:	2/1R	AOA: 2/1R
DEORBIT:	2/1R	ATO: 2/1R
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE FU TK ISOL 1/2 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES.

DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 478 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE OX TK ISOL 1/2 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES.

DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 479

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE OX TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 480

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K5

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE OX TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 481

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K5

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NO EFFECT ON OX TK ISOLATION 1/2 VALVE OPERATION. WHAT WAS LOST WAS A SAFEGUARD DESIGNED TO KEEP A SINGLE RELAY FAILURE FROM CAUSING AN IMMEDIATE LOSS OF MISSION CAPABILITY BY FAILING THE OX TK ISOL VALVE CLOSED. SECOND FAILURE (FAILURE OF REDUNDANT RELAY) RESULTS IN THE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 482

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3

HDW/FUNC

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K6

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE OX TK ISOL 1/2 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 1 OR 2 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS 1 OR 2. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 483 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K6

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE OX TK ISOL 1/2 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF EIGHT PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES.

DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 484 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE FU TK ISOL 3/4/5 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES AND STRUCTURAL CONSTRAINTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 485 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K3

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 3/4/5 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 3, 4 OR 5 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS FROM PROP TANKS. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	486	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111K4

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 3/4/5 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 3, 4 OR 5 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS FROM PROP TANKS. NO MISSION IMPACT.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 487 ABORT: 2/1R

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NO EFFECT ON FU TK ISOLATION 3/4/5 VALVE OPERATION. WHAT WAS LOST WAS A SAFEGUARD DESIGNED TO KEEP A SINGLE RELAY FAILURE FROM CAUSING AN IMMEDIATE LOSS OF MISSION CAPABILITY BY FAILING THE FU TK ISOL VALVE CLOSED. SECOND FAILURE (FAILURE OF REDUNDANT RELAY) RESULTS IN THE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	488	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111K5

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE FU TK ISOL 3/4/5 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 3, 4 OR 5 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS FROM PROP TANKS. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 489

HIGHEST CRITICALITY  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K5

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE FU TK ISOL 3/4/5 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES AND STRUCTURAL CONSTRAINTS.

REFERENCES: VS70-942099 REV D EO D01





INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 491 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K6

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE OX TK ISOL 3/4/5 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 3, 4 OR 5 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS FROM PROP TANKS. NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 492 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE OX TK ISOL 3/4/5 VALVE FAILING OPEN. THE VALVE IS NORMALLY OPEN. REDUNDANCY FOR THIS FUNCTION IS PROVIDED BY MANIFOLD 3, 4 OR 5 ISOLATION VALVE. LOSS OF THESE VALVES RESULTS IN AN INABILITY TO ISOLATE MANIFOLDS FROM PROP TANKS, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

## INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 493

HIGHEST CRITICALITY	HDW/FUNC
FLIGHT:	3/1R
ABORT:	2/1R

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) ELECTRICAL COMPONENTS  
2) CONTROLS  
3) PROP STOR & DIST SUBSYSTEM  
4) OX & FU TK ISOL VLV 3/4/5  
5) RELAY  
6)  
7)  
8)  
9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/1R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]            B [ F ]            C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

**EFFECTS/RATIONALE:**

EFFECTS/RATIONALE:  
NO EFFECT ON OX TK ISOLATION 3/4/5 VALVE OPERATION. WHAT WAS LOST WAS A SAFEGUARD DESIGNED TO KEEP A SINGLE RELAY FAILURE FROM CAUSING AN IMMEDIATE LOSS OF MISSION CAPABILITY BY FAILING THE FU TK ISOL VALVE CLOSED. SECOND FAILURE (FAILURE OF REDUNDANT (RELAY) RESULTS IN THE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES DURING DEORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 495

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	2/1R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K8

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE CAN RESULT IN THE OX TK ISOL 3/4/5 VALVE BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT WOULD BE LOSS OF SIX PRIMARY JETS CAUSING AN INABILITY TO EXPEL ENOUGH PROPELLANT TO MEET THE CG SAFETY BOUNDARIES DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ONORBIT. LOSS OF ALL REDUNDANCY WOULD RESULT IN LOSS OF VEHICLE/LIFE SINCE TRAPPED PROPELLANTS WOULD EXCEED CG SAFETY BOUNDARIES AND STRUCTURAL CONSTRAINTS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	496	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TALKBACKS TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACK FOR BOTH THE FU & OX ISOL 1/2 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 497 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO HARDWIRED AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 498 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TALKBACKS TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACK FOR BOTH THE FU & OX ISOL 1/2 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 499 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO HARDWIRED AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	500	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TALKBACKS TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACK FOR BOTH THE FU & OX ISOL 1/2 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 501 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO HARDWIRED AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	502	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE FU TK ISOL 1/2 VALVE TO GPC (OPEN POSITION ONLY). HARDWIRE TALKBACK TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 503 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	504	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R18

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR CREW SWITCH POSITION TO GPC (OPEN POSITION ONLY). NO EFFECT, SWITCH OPERATION CAN BE INDIRECTLY DETERMINED BY VALVE OPERATION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 505 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R18

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	506	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE FU TK ISOL 1/2 VALVE TO GPC (CLOSE POSITION ONLY). HARDWIRE TALKBACK TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 507 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	508	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR CREW SWITCH POSITION TO GPC (CLOSE POSITION ONLY). NO EFFECT, SWITCH OPERATION CAN BE INDIRECTLY DETERMINED BY VALVE OPERATION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 509 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	510	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE OX TK ISOL 1/2 VALVE TO GPC (OPEN POSITION ONLY). HARDWIRE TALKBACK TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 511 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 512 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R28

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE OX TK ISOL 1/2 VALVE TO GPC (CLOSE POSITION ONLY). HARDWIRE TALKBACK TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 513 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R28

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	514	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		3/3
LIFTOFF:	3/3	TAL:		3/3
ONORBIT:	3/3	AOA:		3/3
DEORBIT:	3/3	ATO:		3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACKS FOR BOTH FU & OX ISOL 3/4/5 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 515

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO HARDWIRE AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 516 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACKS FOR BOTH FU & OX ISOL 3/4/5 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 517

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO HARDWIRE AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 518 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ONE OF THREE REDUNDANT RESISTORS WHICH PROVIDE ISOLATION BETWEEN MAIN BUS AND VALVE POSITION TO GPC. FAILURE OF ALL THREE RESISTORS RESULTS IN LOSS OF ALL TALKBACKS FOR BOTH FU & OX ISOL 3/4/5 VALVE, NO EFFECT SINCE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 519

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, TALKBACK STILL AVAILABLE TO HARDWIRE AND GPC TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	520	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE FU TK ISOL 3/4/5 VALVE TO GPC (OPEN POSITION ONLY). HARDWIRE TALKBACK (BARBER POLE) TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 521

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	522	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR CREW SWITCH POSITION TO GPC (OPEN POSITION ONLY). NO EFFECT, SWITCH OPERATION CAN BE INDIRECTLY DETERMINED BY VALVE OPERATION.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 523 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	524	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE FU TK ISOL 3/4/5 VALVE TO GPC (CLOSE POSITION ONLY). HARDWIRE TALKBACK (BARBER POLE) TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 525

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	526	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR CREW SWITCH POSITION TO GPC (CLOSE POSITION ONLY). NO EFFECT, SWITCH OPERATION CAN BE INDIRECTLY DETERMINED BY VALVE OPERATION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 527 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	528	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE OX TK ISOL 3/4/5 VALVE TO GPC (OPEN POSITION ONLY). HARDWIRE TALKBACK (BARBER POLE) TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 529 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R22

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/27/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	530	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		3/3
LIFTOFF:	3/3	TAL:		3/3
ONORBIT:	3/3	AOA:		3/3
DEORBIT:	3/3	ATO:		3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE TALKBACK FOR THE OX TK ISOL 3/4/5 VALVE TO GPC (CLOSE POSITION ONLY). HARDWIRE TALKBACK (BARBER POLE) TO CREW WILL INDICATE CORRECT POSITION. LOSS OF ALL REDUNDANCY HAS NO IMPACT SINCE VALVE TALKBACK IS NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/27/87  
SUBSYSTEM: FRCS  
MDAC ID: 531

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, TALKBACK STILL AVAILABLE TO GPC.

REFERENCES: VS70-942099 REV D EO D01; MC284-0430 REV E AMENDMENT SEQ. 7

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 532 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM CLOSE COMMANDS. IF THE SWITCH FAILS IN THE OPEN POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY THE SWITCH OR BY THE MDM COMMANDS. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM CONTACTS SETS AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 533 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE SWITCH FAILS IN THE CLOSED POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY THE SWITCH OR BY THE MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	534	ABORT:	2/1R

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE GPC POSITION

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL 08 S23  
PART NUMBER:    33V73A8S23

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

VALVE CANNOT BE CONTROLLED BY SWITCH, ONLY BY MDM COMMANDS, TO OPERATE THE VALVE, THE CREW MUST USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WHILE THE VALVE IS IN THE CLOSED POSITION WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ENTRY AND ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES:    VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 535 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	3/1R
ONORBIT:	3/2R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL O8 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM COMMANDS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE OPENED BY THE SWITCH COMMANDS, ONLY BY MDM COMMANDS, AND CAN BE CLOSED BY SWITCH OR MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO BURN ENOUGH PROPELLANT DURING RTLS ABORTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 536 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM COMMANDS. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN OR GPC POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY MDM COMMAND, ONLY BY SWITCH COMMAND. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED POSITION, THE VALVE WILL REMAIN CLOSED, AND CANNOT BE OPENED BY MDM COMMANDS, ONLY BY SWITCH COMMANDS. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC; FLIGHT RULE 6-95

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 537 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 538 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 539 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM COMMANDS. IF THE CLOSDE CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSTION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE OPENED BY SWITCH OR MDM COMMANDS, AND CANNOT BE CLOSED BY SWITCH COMMANDS, ONLY BY MDM COMMANDS. FAILURE OF THE MDM CLOSE COMMANDS WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	540	ABORT:	2/1R

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ F ]      C [ P ]

LOCATION:      PNL 08 S23  
PART NUMBER:    33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE OTHER SWITCH CLOSE CONTACTS AND THE MDM CLOSE COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE CLOSED BY SWITCH OR MDM COMMAND, AND CANNOT BE OPENED BY SWITCH OR MDM COMMANDS. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY AND MAY CAUSE THE INABILITY TO BURN ENOUGH PROPELLANT DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 541 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 7, 8  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH OPEN CONTACTS 7, 8
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NO REDUNDANCY PROVIDED PROVIDED TO INHIBIT THE CLOSE RELAYS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, AND CAN BE OPENED OR CLOSED BY THE SWITCH OR MDM COMMANDS.

REFERENCES: VS70-943099 REV B EO B12, CC, DC



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 543 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 9, 10  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 9, 10
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 544 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 9, 10  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH GPC CONTACTS 9, 10
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 545 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 11,  
12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM COMMANDS. IF THE CLOSE CONTACTS FAIL  
OPEN WHILE THE SWITCH IS IN ANY POSTION, THE VALVE WILL REMAIN IN  
THAT POSITION, CAN BE OPENED BY SWITCH OR MDM COMMANDS, AND CANNOT  
BE CLOSED BY SWITCH COMMANDS,  
ONLY BY MDM COMMANDS. FAILURE OF THE MDM CLOSE COMMANDS WILL  
CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 546 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 11,  
12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 1/2
- 5) OX & FU TK ISOL VLV 1/2 SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S23  
PART NUMBER: 33V73A8S23

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE OTHER SWITCH CLOSE CONTACTS AND THE MDM CLOSE COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION AND CAN BE CLOSED BY SWITCH OR MDM COMMAND, BUT CANNOT BE OPENED BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ENTRY AND ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 547 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL O8 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM CLOSE COMMANDS. IF THE SWITCH FAILS IN THE OPEN POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY THE SWITCH OR BY THE MDM COMMANDS. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM CONTACTS SETS AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	548	ABORT:	2/1R

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL O8 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE SWITCH FAILS IN THE CLOSED POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY THE SWITCH OR BY THE MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 549 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH  
FAILURE MODE: SWITCH FAILS IN THE GPC POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	HDW/FUNC
		ABORT	
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

VALVE CANNOT BE CONTROLLED BY SWITCH, ONLY BY MDM COMMANDS. TO OPERATE THE VALVE, THE CREW MUST USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WHILE THE VALVE IS IN THE CLOSED POSITION WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ENTRY AND ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 550 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM COMMANDS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE OPENED BY THE SWITCH COMMANDS, ONLY BY MDM COMMANDS, AND CAN BE CLOSED BY SWITCH OR MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO BURN ENOUGH PROPELLANT DURING RTLS ABORTS TO MEET THE TANK LANDING WEIGHT CONSTRAINTS AND/OR THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 551 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM COMMANDS. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN OR GPC POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY MDM COMMAND, ONLY BY SWITCH COMMAND. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED POSITION, THE VALVE WILL REMAIN CLOSED, AND CANNOT BE OPENED BY MDM COMMANDS, ONLY BY SWITCH COMMANDS. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC; FLIGHT RULE 6-95

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 552 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 553 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 3, 4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	554	ABORT:	3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 5, 6

FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S24  
PART NUMBER:    33V73A8S24

CAUSES:    CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM COMMANDS. IF THE CLOSDE CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSTION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE OPENED BY SWITCH OR MDM COMMANDS, AND CANNOT BE CLOSED BY SWITCH COMMANDS, ONLY BY MDM COMMANDS. FAILURE OF THE MDM CLOSE COMMANDS WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES:    VS70-943099 REV B EO B12, CC, DC



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 555 ABORT: 3/1R

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 5,  
6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/1R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL O8 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE OTHER SWITCH CLOSE CONTACTS AND THE MDM CLOSE COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE CLOSED BY SWITCH OR MDM COMMAND, AND CANNOT BE OPENED BY SWITCH OR MDM COMMANDS. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY AND MAY CAUSE THE INABILITY TO BURN ENOUGH PROPELLANT DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	556	ABORT:	3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 7, 8  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 7, 8
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:            PNL 08 S24  
PART NUMBER:    33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NO REDUNDANCY PROVIDED PROVIDED TO INHIBIT THE CLOSE RELAYS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, AND CAN BE OPENED OR CLOSED BY THE SWITCH OR MDM COMMANDS.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 557 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 7, 8  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH OPEN CONTACTS 7, 8
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NO REDUNDANCY PROVIDED TO INHIBIT THE CLOSE RELAYS. IF THE OPEN CONTACTS FAIL WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE CLOSED BY SWITCH OR MDM COMMAND, AND CAN BE OPENED BY SWITCH OR MDM COMMANDS. TO CLOSE THE VALVE WITH THE MDM COMMAND, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE OPEN CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC; FLIGHT RULE 6-95

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 558 ABORT: 3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 9, 10  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 9, 10
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	559	ABORT:	3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 9, 10  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH GPC CONTACTS 9, 10
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	560	ABORT:	3/3

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 11, 12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM COMMANDS. IF THE CLOSE CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE OPENED BY SWITCH OR MDM COMMANDS, AND CANNOT BE CLOSED BY SWITCH COMMANDS, ONLY BY MDM COMMANDS. FAILURE OF THE MDM CLOSE COMMANDS WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 561 ABORT: 2/1R

ITEM: OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 11,  
12  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) OX & FU TK ISOL VLV 3/4/5
- 5) OX & FU TK ISOL VLV 3/4/5 SWITCH CLOSE CONTACTS 11, 12
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL O8 S24  
PART NUMBER: 33V73A8S24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE OTHER SWITCH CLOSE CONTACTS AND THE MDM CLOSE COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION AND CAN BE CLOSED BY SWITCH OR MDM COMMAND, BUT CANNOT BE OPENED BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING ENTRY AND ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CC, DC

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/2R
MDAC ID:	562	ABORT:	3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 3A, PCA 3  
PART NUMBER: 83V76A24RPC29

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVs.  
VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL  
REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVs  
FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 563 ABORT: 3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, PCA 3  
PART NUMBER: 83V76A24RPC29

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	564	ABORT:	3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, PCA 3  
PART NUMBER: 83V76A24RPC28

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVS CLOSE USING CREW SWITCH OR GPC. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVS BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVS. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 565 ABORT: 3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, PCA 3  
PART NUMBER: 83V76A24RPC28

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVS USING GPC.  
CREW SWITCH CAN STILL OPEN OR CLOSE VLVS. LOSS OF ALL REDUNDANCY  
(CREW SWITCH), WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS  
BECOMING STUCK IN THE CLOSED POSITION RESULTING IN  
LOSS OF VRCS CONTROL, THEREFORE LOSS OF MISSION CAPABILITY.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 566 ABORT: 3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22RPC28

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVS. VALVES CAN STILL BE OPENED USING GPC. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 567 ABORT: 3/3

ITEM: CONTROLLER, REMOTE POWER  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) CONTROLLER, REMOTE POWER
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22RPC28

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	568	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE MANIFOLD ISOL 1 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 569

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH CLOSE COMMANDS WHEN THE MANIFOLD ISOL 1 VALVES ARE IN THE OPEN POSITION. THE EFFECT WOULD BE AN INTERMITTENT CLOSE COMMAND CAUSING THE VALVES TO FAIL PARTIALLY CLOSED WHEN COMMANDED OPEN BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 570 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 1 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 571

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 1 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	572	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 2 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01; MC284-0420 REV C AMENDMENT SEQ. 8

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 573

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (CLOSE POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT. VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 574 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 1 VALVE USING GPC COMMANDS. CREW SWITCH IS STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 575 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 1 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	576	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE MANIFOLD ISOL 1 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 577

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH OPEN COMMANDS WHEN THE MANIFOLD ISOL 1 VALVES ARE IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INTERMITTENT OPEN COMMAND CAUSING THE VALVES TO FAIL PARTIALLY OPEN WHEN COMMANDED CLOSED BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 578 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 2 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 579

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (OPEN POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITION.  
CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 580 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS16  
PART NUMBER: 33V73A8CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 1 VALVES ARE COMMANDED OPEN. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 581 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS16  
PART NUMBER: 33V73A8CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 582 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS16  
PART NUMBER: 33V73A8CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 1 VALVES ARE COMMANDED CLOSED. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 583

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	
		ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS16  
PART NUMBER: 33V73A8CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 584 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 1 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 585

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 1 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	586	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 1 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 587

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 1 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 588 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 1 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 589

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1CR11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 1 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	590	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE MANIFOLD ISOL 2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 591 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2; MCA 2  
PART NUMBER: 82V76A112A1CR1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH CLOSE COMMANDS WHEN THE MANIFOLD ISOL 2 VALVES ARE IN THE OPEN POSITION. THE EFFECT WOULD BE AN INTERMITTENT CLOSE COMMAND CAUSING THE VALVES TO FAIL PARTIALLY CLOSED WHEN COMMANDED OPEN BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 592 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 2 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 593

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	594	ABORT:	3/3

LEAD ANALYST: V.J. BURKEMPER                      SUBSYS LEAD: D.J. PAUL

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR2

**EFFECTS/RATIONALE:**

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 2 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REPORT DATE 03/23/87



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 595

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR2

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (CLOSE POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION.  
CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT. VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	596	ABORT:	2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 2 VALVE USING GPC COMMANDS. CREW SWITCH IS STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 597

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	598	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE MANIFOLD ISOL 2 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 599

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR6

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH OPEN COMMANDS WHEN THE MANIFOLD ISOL 2 VALVES ARE IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INTERMITTENT OPEN COMMAND CAUSING THE VALVES TO FAIL PARTIALLY OPEN WHEN COMMANDED CLOSED BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 600 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 2 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 601

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR5

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (OPEN POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITION.

CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT. VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	602	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 DS17  
PART NUMBER: 33V73A8CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 2 VALVES ARE COMMANDED OPEN. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 603

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS17  
PART NUMBER: 33V73A8CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 604 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS17  
PART NUMBER: 33V73A8CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 2 VALVES ARE COMMANDED CLOSED. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 605

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS17  
PART NUMBER: 33V73A8CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 606 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 2 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 607

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 608

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 2 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 609

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR4

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	610	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 2 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 611

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1CR3

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

## EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 2 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 612

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE MANIFOLD ISOL 3 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 613

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR7

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH CLOSE COMMANDS WHEN THE MANIFOLD ISOL 3 VALVES ARE IN THE OPEN POSITION. THE EFFECT WOULD BE AN INTERMITTENT CLOSE COMMAND CAUSING THE VALVES TO FAIL PARTIALLY CLOSED WHEN COMMANDED OPEN BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 614 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR33

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 3 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 VALVE FAILING CLOSED CASE. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF LIFE/VEHICLE) OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 615

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR33

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 3 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 617

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (CLOSE POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 618 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR37

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 3 VALVE USING GPC COMMANDS. CREW SWITCH IS STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 619

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR37

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 3 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	620	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR34

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE MANIFOLD ISOL 3 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 621 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR34

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH OPEN COMMANDS WHEN THE MANIFOLD ISOL 3 VALVES ARE IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INTERMITTENT OPEN COMMAND CAUSING THE VALVES TO FAIL PARTIALLY OPEN WHEN COMMANDED CLOSED BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 622 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 4 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 623 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: SAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (OPEN POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITION.  
CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 624 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS18  
PART NUMBER: 33V73A8CR9

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE  
MISCOMPARE WHEN THE MANIFOLD ISOL 3 VALVES ARE COMMANDED OPEN.  
CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT VALVE POSITION  
TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 625

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS18  
PART NUMBER: 33V73A8CR9

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	626	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 DS18  
PART NUMBER: 33V73A8CR10

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 3 VALVES ARE COMMANDED CLOSED. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES:    VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 627

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS18  
PART NUMBER: 33V73A8CR10

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	628	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 3 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 AND TK ISO 3/4/5 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 629

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 3 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	630	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		3/3
LIFTOFF:	3/3	TAL:		3/3
ONORBIT:	3/3	AOA:		3/3
DEORBIT:	3/3	ATO:		3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1CR11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 3 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 AND TK ISO 3/4/5 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 631

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1CR11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 3 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	632	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 3 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 AND TK ISO 3/4/5 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 633 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 3 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	634	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR16

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "OPEN" COMMAND AND CLOSE THE MANIFOLD ISOL 4 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 635

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR16

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH CLOSE COMMANDS WHEN THE MANIFOLD ISOL 4 VALVES ARE IN THE OPEN POSITION. THE EFFECT WOULD BE AN INTERMITTENT CLOSE COMMAND CAUSING THE VALVES TO FAIL PARTIALLY CLOSED WHEN COMMANDED OPEN BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 636 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR36

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 4 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 637 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR36

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 4 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	638	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 1 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01; MC284-0420 REV C AMENDMENT SEQ. 8

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 639 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR15

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (CLOSE POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE CLOSE POSITION. CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 640 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	3/1R
ONORBIT:	3/2R		AOA:	3/1R
DEORBIT:	3/1R		ATO:	3/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 4 VALVE USING GPC COMMANDS. CREW SWITCH IS STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 641

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "OPEN" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 4 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 642 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR35

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OVERRIDE A GPC "CLOSE" COMMAND AND OPEN THE MANIFOLD ISOL 4 VALVE USING CREW SWITCH. NO EFFECT ON MISSION, GPC COMMANDS STILL AVAILABLE TO CLOSE VALVE.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 643 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR35

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN VALVE CONTROL FEEDBACK AND CREW SWITCH OPEN COMMANDS WHEN THE MANIFOLD ISOL 4 VALVES ARE IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INTERMITTENT OPEN COMMAND CAUSING THE VALVES TO FAIL PARTIALLY OPEN WHEN COMMANDED CLOSED BY GPC. NO MISSION EFFECT, VALVES ARE FULLY OPERATIONAL UTILIZING CREW SWITCH.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 644 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR29

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM FU & OX MANIFOLD 1 ISOL VALVE TO DE-ENERGIZE RELAY ONCE THE VALVE REACHES THE COMMANDED POSITION. NO EFFECT ON MISSION, AC MOTOR VALVE DESIGNED TO WITHSTAND CONTINUOUS POWER.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 645 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR29

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH (OPEN POSITION) AND VALVE TALKBACK FROM HYBRID DRIVER. THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE CREW SWITCH IS PLACED IN THE OPEN POSITION.  
CORRECT VALVE POSITIONS AVAILABLE THROUGH GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 646 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS19  
PART NUMBER: 33V73A8CR11

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE MISCOMPARE WHEN THE MANIFOLD ISOL 4 VALVES ARE COMMANDED OPEN. CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 647 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS19  
PART NUMBER: 33V73A8CR11

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 648 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS19  
PART NUMBER: 33V73A8CR12

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE WILL RESULT IN A FALSE INDICATION OF A VALVE  
MISCOMPARE WHEN THE MANIFOLD ISOL 4 VALVES ARE COMMANDED CLOSED.  
CORRECT VALVE POSITION AVAILABLE GPC. NO IMPACT, VALVE POSITION  
TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 649

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS19  
PART NUMBER: 33V73A8CR12

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	650	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 4 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 651

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 4 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 652

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 4 VALVE USING ONE OF TWO GPC COMMANDS. OTHER GPC COMMAND AND CREW SWITCH STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 AND TK ISOL 1/2 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 653 ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 4 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 654 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO CLOSE THE FU & OX MANIFOLD ISOL 4 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE TO CLOSE VALVE. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 AND TK ISO 3/4/5 VALVES FAILING OPEN. THE EFFECT WOULD BE AN INABILITY TO ISOLATE TANK FROM MANIFOLD, NO MISSION IMPACT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 655

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/1R  
ABORT: 2/1R

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE DIODE ISOLATION BETWEEN CREW SWITCH AND GPC "CLOSE" COMMAND. FAILURE COULD POSSIBLY RESULT IN LOSS OF GPC OR SWITCH TO CONTROL OX & FU MANIFOLD ISOL 4 VALVE OPERATION. LOSS OF ALL REDUNDANCY, WORST CASE, CAN RESULT IN THE MANIFOLD ISOL VALVE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 656 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18CR J1-93

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVs CLOSE USING GPC. CREW SWITCH CAN STILL OPEN OR CLOSE VLVs. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 657 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18CR J1-93

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN CREW SWITCH AND GPC CLOSE COMMANDS. THE FAILURE CAN RESULT IN LOSS OF GPC OR CREW SWITCH TO OPERATE THE MANIFOLD 5 FU & OX ISOL VLVS. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVS BECOMING STUCK IN THE OPEN POSITION.  
NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVS. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 658 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18CR J2-87

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN CREW SWITCH AND GPC CLOSE COMMANDS. THE FAILURE CAN RESULT IN LOSS OF GPC OR CREW SWITCH TO OPERATE THE MANIFOLD 5 FU & OX ISOL VLVS. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVS BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVS. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 659

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18CR J2-87

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN CREW SWITCH AND GPC CLOSE COMMANDS. THE FAILURE CAN RESULT IN LOSS OF GPC OR CREW SWITCH TO OPERATE THE MANIFOLD 5 FU & OX ISOL VLVs. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 660 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVS. VALVES CAN STILL BE OPENED USING GPC. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 661 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN MAIN BUSES WHEN THE GPC CMDS THE MANIFOLD 5 FU & OX ISOL VLVs OPEN. THE WORST CASE EFFECT IS LOSS OF THE GPC OR CREW SWITCH "OPEN" CMD. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE CLOSE POSITION RESULTING IN LOSS OF VRCS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 662 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		3/3
LIFTOFF:	3/3	TAL:		3/3
ONORBIT:	3/2R	AOA:		3/3
DEORBIT:	3/3	ATO:		3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22CR38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVS.  
VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL  
REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS  
FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 663

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/2R  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 3 ] B [ P ] C [ P ]

LOCATION: F BAY 1, PCA 1  
PART NUMBER: 81V76A22CR38

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ISOLATION BETWEEN MAIN BUSES WHEN THE CREW SWITCH CMDS THE MANIFOLD 5 FU & OX ISOL VLVS OPEN. THE WORST CASE EFFECT IS LOSS OF THE GPC OR CREW SWITCH "OPEN" CMD. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVS BECOMING STUCK IN THE CLOSE POSITION RESULTING IN LOSS OF VRCS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 664 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS20  
PART NUMBER: 33V73A8CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 FU & OX VLV POSITION (OPEN) TALKBACK TO GPC.  
VALVE POSITION TALKBACK NOT MISSION CRITICAL. THIS IS HARDWIRED  
TO CREW INDICATOR.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 665 ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS20  
PART NUMBER: 33V73A8CR13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	666	ABORT:	3/3

ITEM: DIODE  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 DS20  
PART NUMBER: 33V73A8CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 FU & OX VLV POSITION (CLOSED) TALKBACK TO GPC.  
VALVE POSITION TALKBACK NOT MISSION CRITICAL. THIS IS HARDWIRED TO CREW INDICATOR.

REFERENCES: VS70-943099 REV B EO B12



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 667

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DIODE  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DIODE
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 DS20  
PART NUMBER: 33V73A8CR14

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 668 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR2 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 1 VALVES (OPEN POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED OPEN. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 669

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR2 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 1 VALVES (OPEN POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE OPEN COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN CLOSED POSITION. THE EFFECT, AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	670	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR1 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 1 VALVES (CLOSE POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED CLOSED. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 671 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111AR1 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 1 VALVES (CLOSE POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE CLOSE COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN OPEN POSITION. NO MISSION EFFECT, VALVES ARE NORMALLOY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 1 FROM THE PROPELLANT TANKS, NO IMPACT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 672 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112AR1 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 2 VALVES (OPEN POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED OPEN. NO IMPACT ON MISSION. VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 673

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

## BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112AR1 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

## EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 2 VALVES (OPEN POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE OPEN COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN CLOSED POSITION. THE EFFECT, AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 674

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112AR2 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 2 VALVES (CLOSE POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED CLOSED. NO IMPACT ON MISSION. VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM: FRCS	FLIGHT:	3/3
MDAC ID: 675	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112AR2 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 2 VALVES (CLOSE POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE CLOSE COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN OPEN POSITION. NO MISSION EFFECT, VALVES ARE NORMALLOY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 2 FROM THE PROPELLANT TANKS, NO IMPACT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 676 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR4 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 3 VALVES (OPEN POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED OPEN. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 677

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR4 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 3 VALVES (OPEN POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE OPEN COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN CLOSED POSITION. THE EFFECT, AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 678 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR3 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 3 VALVES (CLOSE POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED CLOSED. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 679 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR3 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 3 VALVES (CLOSE POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE CLOSE COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN OPEN POSITION. NO MISSION EFFECT, VALVES ARE NORMALLOY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 3 FROM THE PROPELLANT TANKS, NO IMPACT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	680	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR6 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 4 VALVES (OPEN POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED OPEN. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 681 ABORT: 1/1

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR6 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 4 VALVES (OPEN POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE OPEN COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN CLOSED POSITION. THE EFFECT, AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS OR AN INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 682 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR5 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 4 VALVES (CLOSE POSITION). DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH WHEN THE VALVES ARE COMMANDED CLOSED. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 683 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113AR5 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE CONTROL FEEDBACK FROM MANIFOLD ISOL 4 VALVES (CLOSE POSITION) CONTINUALLY HIGH CAUSING LOSS OF ALL VALVE CLOSE COMMANDS. THE FINAL RESULT WOULD BE THE ISOL VALVES STUCK IN OPEN POSITION. NO MISSION EFFECT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 1 FROM THE PROPELLANT TANKS, NO IMPACT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 684 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 2  
PART NUMBER: 83V76A18AR J4-71 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVs CLOSE USING CREW SWITCH OR GPC. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 685

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/2R  
ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, LCA 2  
PART NUMBER: 83V76A18AR J4-71 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVs USING GPC.  
CREW SWITCH CAN STILL OPEN OR CLOSE VLVs. LOSS OF ALL REDUNDANCY  
(CREW SWITCH), WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVs  
BECOMING STUCK IN THE CLOSED POSITION RESULTING IN  
LOSS OF VRCS CONTROL, THEREFORE LOSS OF MISSION CAPABILITY.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 686 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/2R		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18AR J4-51 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE GPC COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVs.  
VALVES CAN STILL BE OPENED USING CREW SWITCH. LOSS OF ALL  
REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVs  
FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 687 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18AR J4-51 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 688 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A16AR J4-48 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CREW SWITCH COMMAND SIGNAL TO OPEN MANIFOLD 5 FU & OX ISOL VLVS. VALVES CAN STILL BE OPENED USING GPC. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS FAILED CLOSED RESULTING IN LOSS OF VRCS CONTROL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 689

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A16AR J4-48 TYPE I

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 690 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 2  
PART NUMBER: 83V76A18AR J4-53 TYPE II

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION OF MANIFOLD 5 FU & OX ISOL VLV MISMATCH (GPC HAS CORRECT POSITIONS); VALVE TALKBACK NOT MISSION CRITICAL. SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VLV ONCE IT HAS LATCHED: VALVE CAN WITHSTAND CONTINUOUS ENERGIZATION.

REFERENCES: VS70-943099 REV B EO B12; MC284-0420 REV C AMENDMENT  
SEQ. 8



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 691 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 2  
PART NUMBER: 83V76A18AR J4-53 TYPE II

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FAILURE RESULTS IN A FALSE CREW (BARBER POLE) INDICATION OF VLV CLOSURE AND A FALSE CONTROL FEEDBACK WHICH INHIBITS ALL GPC AND CREW SWITCH "CLOSE" COMMANDS. WORST CASE EFFECT WOULD BE THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANTS CAN BE ISOLATED FROM THRUSTER BY THE TK ISOL 3/4/5 VLVs.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	692	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, LCA 3  
PART NUMBER:    83V76A18AR J4-55 TYPE II

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION OF MANIFOLD 5 FU & OX ISOL VLV MISMATCH (GPC HAS CORRECT POSITIONS); VALVE TALKBACK NOT MISSION CRITICAL. SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VLV ONCE IT HAS LATCHED: VALVE CAN WITHSTAND CONTINUOUS ENERGIZATION.

REFERENCES:    VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/2  
MDAC ID: 693 ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	2/2	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18AR J4-55 TYPE II

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FAILURE RESULTS IN A FALSE CREW (BARBER POLE) INDICATION OF VLV OPENING AND A FALSE CONTROL FEEDBACK WHICH INHIBITS ALL GPC AND CREW SWITCH "OPEN" COMMANDS. WORST CASE EFFECT WOULD BE THE MANIFOLD 5 FU & OX ISOL VLVs BECOMING STUCK IN THE CLOSE POSITION RESULTING IN LOSS OF MISSION DUE TO LOSS OF VRCS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	694	ABORT:	3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, LCA 3  
PART NUMBER:    83V76A18AR J5-K TYPE III

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVs CLOSE USING CREW SWITCH OR GPC. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES:    VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87  
SUBSYSTEM: FRCS  
MDAC ID: 695

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: DRIVER, HYBRID  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) DRIVER, HYBRID
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18AR J5-K TYPE III

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CAPABILITY TO INHIBIT THE MANIFOLD 5 FU & OX ISOL VLV "CLOSE"  
CMD. THE INHIBIT FUNCTION IS USED FOR POWER SAVINGS AND IN CASE  
OF A GPC OR SWITCH FAILURE. NO EFFECT ON MISSION.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 696 ABORT: 2/1R

ITEM: FUSE,1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) FUSE,1A
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8F10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX MANIFOLD ISOL 1 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 1 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/1R
MDAC ID:	697	ABORT:	2/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      PNL 08 S31  
PART NUMBER: 33V73A8F27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX MANIFOLD ISOL 2 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 2 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 698 ABORT: 2/1R

ITEM: FUSE,1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) FUSE,1A
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	HDW/FUNC
PRELAUNCH:	3/3	ABORT	
LIFTOFF:	3/3	RTLS:	2/1R
ONORBIT:	3/2R	TAL:	3/1R
DEORBIT:	3/1R	AOA:	3/1R
LANDING/SAFING:	3/3	ATO:	3/1R

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8F38

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX MANIFOLD ISOL 3 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 3 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/1R  
MDAC ID: 699 ABORT: 2/1R

ITEM: FUSE, 1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) FUSE, 1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/1R
ONORBIT:	3/2R	AOA:	3/1R
DEORBIT:	3/1R	ATO:	3/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S33  
PART NUMBER: 33V73A8F43

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN OR CLOSE FU & OX MANIFOLD ISOL 4 VALVE USING CREW SWITCH. GPC COMMANDS ARE STILL AVAILABLE FOR VALVE OPERATION. LOSS OF ALL REDUNDANCY RESULTS IN MANIFOLD ISOL 4 VALVE FAILING CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	700	ABORT:	3/3

ITEM: FUSE,1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) FUSE,1A
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S34  
PART NUMBER: 33V73A8F39

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO COMMAND MANIFOLD 5 FU & OX ISOL VLVs CLOSE USING CREW SWITCH. GPC CAN STILL OPEN OR CLOSE VLVs. WORST CASE RESULTS IN MANIFOLD 5 FU & OX VLVs BECOMING STUCK IN THE OPEN POSITION. NO MISSION EFFECT, PROPELLANT CAN BE ISOLATED FROM THRUSTERS BY THE TK ISOL 3/4/5 VLVs. VERNIER THRUSTERS ARE NOT USED DURING ENTRY OR ABORTS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 701 ABORT: 3/3

ITEM: FUSE,1A  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) FUSE,1A
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/2R	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL O8 S34  
PART NUMBER: 33V73A8F44

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE ALL BUT ONE COMMAND (A GPC OPEN CMD) TO OPERATE MANIFOLD 5 FU & OX ISOL VLVS. LOSS OF ALL REDUNDANCY, WORST CASE, RESULTS IN MANIFOLD 5 FU & OX ISOL VLVS BECOMING STUCK IN THE CLOSED POSITION. THE EFFECT IS LOSS OF MISSION DUE TO LOSS OF VRCS.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 702 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		1/1
LIFTOFF:	3/3	TAL:		2/1R
ONORBIT:	3/2R	AOA:		2/1R
DEORBIT:	2/1R	ATO:		2/1R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 1 VALVES. THE FAILURE CAN RESULT IN THE ISOL VALVES BECOMING STUCK IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR INABILITY TO COMPLETE FULL MISSION REQUIREMENTS ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 703 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 1 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 2 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 704 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 1 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 2 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 705

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 2/1R  
ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FIRST FAILURE CAUSES FU & OX MANIFOLD ISOL 1 VALVES TO BE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	706	ABORT:	1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112K1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 2 VALVES. THE FAILURE CAN RESULT IN THE ISOL VALVES BECOMING STUCK IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR INABILITY TO COMPLETE FULL MISSION REQUIREMENTS ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 707 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112K1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 2 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 2 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	708	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 2 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 2 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 709 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112K2

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FIRST FAILURE CAUSES FU & OX MANIFOLD ISOL 2 VALVES TO BE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

**INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET**

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	2/1R
MDAC ID:	710	ABORT:	1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]      B [ P ]      C [ P ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K7

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

**EFFECTS/RATIONALE:**

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 3 VALVES. THE FAILURE CAN RESULT IN THE ISOL VALVES BECOMING STUCK IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR INABILITY TO PERFORM FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES:    VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	711	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 3 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 4 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	712	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K8

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 3 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 4 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 713 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K8

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

FIRST FAILURE CAUSES FU & OX MANIFOLD ISOL 3 VALVES TO BE FAILED CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 2/1R  
MDAC ID: 714 ABORT: 1/1

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K9

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE ABILITY TO OPEN FU & OX MANIFOLD ISOL 4 VALVES. THE FAILURE CAN RESULT IN THE ISOL VALVES BECOMING STUCK IN THE CLOSE POSITION. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR INABILITY TO COMPLETE FULL MISSION REQUIREMENTS ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 715 ABORT: 3/3

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K9

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 4 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 1 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	716	ABORT:	3/3

ITEM: RELAY  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K10

CAUSES:    CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

THE FAILURE RESULTS IN FU & OX MANIFOLD ISOL 4 VALVES BECOMING STUCK IN THE OPEN POSITION. NO MISSION IMPACT, VALVES ARE NORMALLY OPEN. LOSS OF ALL REDUNDANCY RESULTS IN AN INABILITY TO ISOLATE MANIFOLD 1 FROM PROPELLANT TANKS, NO EFFECT ON MISSION.

REFERENCES:    VS70-942099 REV D EO D01

# INDEPENDENT ORBITER ASSESSMENT ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 717

HIGHEST CRITICALITY	HDW/FUNC
FLIGHT:	2/1R
ABORT:	1/1

ITEM: RELAY  
FAILURE MODE: FAILS HIGH

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

**BREAKDOWN HIERARCHY:**

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RELAY
- 6)
- 7)
- 8)
- 9)

## CRITICALITIES

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	1/1
LIFTOFF:	3/3	TAL:	2/1R
ONORBIT:	3/2R	AOA:	2/1R
DEORBIT:	2/1R	ATO:	2/1R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [ 2 ]                    B [ P ]                    C [ P ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113K10

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

**EFFECTS/RATIONALE:**

EFFECTS/RATIONALE.  
FIRST FAILURE CAUSES FU & OX MANIFOLD ISOL 4 VALVES TO BE FAILED  
CLOSED. THE EFFECT WOULD BE AN INABILITY TO COMPLETE TIME  
CRITICAL PROPELLANT DUMPS DURING RTLS (LOSS OF VEHICLE/LIFE) OR AN  
INABILITY TO COMPLETE FULL MISSION OBJECTIVES ON ORBIT.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	718	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER                      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]                      B [    ]                      C [    ]

LOCATION:            F BAY 1, MCA 1  
PART NUMBER:    81V76A111A1R8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 1 VALVES.  
DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION, AND SECOND, THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 719 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	720	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 1 SWITCH TALKBACK (CLOSE POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 721

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R13

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	722	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 1 SWITCH TALKBACK (OPEN POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 723 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R12

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 724 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT, VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 725 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R17

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 726 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (OPEN POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 727 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R26

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	728	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (OPEN POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 729 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R27

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 730 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 731

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, MCA 1  
PART NUMBER: 81V76A111A1R25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 732 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 2 VALVES.  
DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION AND SECOND THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH. NO IMPACT ON MISSION. VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 733

HIGHEST CRITICALITY HDW/FUNC  
FLIGHT: 3/3  
ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R1

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/26/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	734	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 2 SWITCH TALKBACK (CLOSE POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 735 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R8

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 736 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 2 SWITCH TALKBACK (OPEN POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 737 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R9

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 738 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 2 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 739 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R10

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 740 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 2 ISOL VALVE POSITION TALKBACKS (OPEN POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 741 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R24

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 742 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 2 ISOL VALVE POSITION TALKBACKS (OPEN POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 743 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R25

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 744 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 2 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 745 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 2, MCA 2  
PART NUMBER: 82V76A112A1R11

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 746 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1R1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 3 VALVES.  
DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION, AND SECOND, THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 747 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3,  
PART NUMBER: 83V76A113A1R1

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 748 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R16

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 3 SWITCH TALKBACK (CLOSE POSITION) TO GPC. SWITCH POSITION CAN BE IN DIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 749 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R16

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87  
SUBSYSTEM: FRCS  
MDAC ID: 750

HIGHEST CRITICALITY  
FLIGHT: 3/3  
ABORT: 3/3

HDW/FUNC

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER  
SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		HDW/FUNC
	HDW/FUNC	ABORT	
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R19

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 3 SWITCH TALKBACK (OPEN POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 751 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R19

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 752 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R22

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 3 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 753 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R22

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 754 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R23

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 3 ISOL VALVE POSITION TALKBACKS (OPEN POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 755 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R23

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 756 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R31

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 3 ISOL VALVE POSITION TALKBACKS (OPEN POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 757 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R31

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 758 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R30

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 3 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 759 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R30

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 760 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		3/3
LIFTOFF:	3/3	TAL:		3/3
ONORBIT:	3/3	AOA:		3/3
DEORBIT:	3/3	ATO:		3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE CONTROL FEEDBACK FROM THE FU & OX MANIFOLD ISOL 4 VALVES.  
DUAL EFFECT: FIRST THE RELAY WILL NOT AUTOMATICALLY BE DE-ENERGIZED ONCE THE VALVES REACH THEIR COMMANDED POSITION, AND SECOND, THE CREW INDICATOR WILL FALSELY INDICATE A VALVE MISMATCH. NO IMPACT ON MISSION, VALVE'S AC MOTOR CAN WITHSTAND CONTINUOUS POWER AND VALVE TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 761 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R4

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 762 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R17

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 4 SWITCH TALKBACK (CLOSE POSITION) TO GPC. SWITCH POSITION CAN BE IN DIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 763 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R17

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 764 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R29

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FWD RCS MANIFOLD ISOL 4 SWITCH TALKBACK (OPEN POSITION) TO GPC. SWITCH POSITION CAN BE INDIRECTLY DETERMINED BY MONITORING VALVE POSITION TALKBACKS.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 765 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R29

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, SWITCH POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 766 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R6

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 767 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R6

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 768 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R24

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE FU MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (OPEN POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 769 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R24

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 770 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES

FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 1 ISOL VALVE POSITION TALKBACKS (OPEN POSITION) TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 771 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R32

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 772 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:

LOSE OX MANIFOLD 4 ISOL VALVE POSITION TALKBACKS (CLOSE POSITION)  
TO GPC. CREW POSITION INDICATOR WILL SUPPLY CORRECT VALVE  
POSITION. LOSS OF ALL REDUNDANCY IS LOSS OF ALL TALKBACKS. NO  
IMPACT VALVE POSITION TALKBACKS ARE NOT MISSION CRITICAL.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/26/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 773 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 4, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3  
PART NUMBER: 83V76A113A1R7

CAUSES: CONTAMINATION, VIBRATION, PIECE PART FAILURE, OVERLOAD

EFFECTS/RATIONALE:  
NONE, VALVE POSITION TALKBACK STILL AVAILABLE TO GPC & CREW.

REFERENCES: VS70-942099 REV D EO D01

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	774	ABORT:	3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-94 TO J2-87 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FRCS MANIFOLD 5 ISOL SWITCH POSITION TALKBACK TO GPC. NO IMPACT SWITCH TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 775 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-94 TO J2-87 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 776 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-94 TO J2-87 (A)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 777 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-94 TO GND (B)

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FRCS MANIFOLD 5 ISOL SWITCH POSITION TALKBACK TO GPC. NO IMPACT SWITCH TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 778 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1  
PART NUMBER: 81V76A16R J1-82

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE FRCS MANIFOLD 5 ISOL SWITCH POSITION TALKBACK TO GPC. NO IMPACT SWITCH TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 779 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES	
FLIGHT PHASE	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 1, LCA 1  
PART NUMBER: 81V76A16R J1-82

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 780 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-88

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 FU VLV POSITION TALKBACK TO GPC. VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 781 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-88

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 782 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-90

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 FU VLV POSITION TALKBACK TO GPC. VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 783 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-90

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 784 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-91

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 OX VLV POSITION TALKBACK TO GPC. VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 785 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-91

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 786 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVs
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-89

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

LOSE MANIFOLD 5 OX VLV POSITION TALKBACK TO GPC. VALVE POSITION TALKBACK NOT MISSION CRITICAL.

REFERENCES: VS70-943099 REV B EO B12



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 787 ABORT: 3/3

ITEM: RESISTOR, 5.1K 1/4W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 5.1K 1/4W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, LCA 3  
PART NUMBER: 83V76A18R J1-89

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, SWITCH TALKBACK STILL AVAILABLE.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/19/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	788	ABORT:	3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS OPEN

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	3/3
LIFTOFF:	3/3		TAL:	3/3
ONORBIT:	3/3		AOA:	3/3
DEORBIT:	3/3		ATO:	3/3
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      F BAY 3A, MCA 3,  
PART NUMBER: 83V76A18R J2-83, 104

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

DUAL EFFECT: FIRST, FALSE INDICATION; CREW HARDWIRED TALKBACK WILL INDICATE MANIFOLD 5 FU & OX ISOL VLV MISMATCH AND GPC WILL INDICATE BOTH VLVS STUCK PARTIALLY OPEN/PARTIALLY CLOSED; TALKBACKS ARE NOT MISSION CRITICAL. SECOND, LOSE CONTROL FEEDBACK TO REMOVE POWER FROM VALVE ONCE IT HAS LATCHED; VALVE CAN WITHSTAND CONTINUOUS POWER APPLICATION.

REFERENCES: VS70-943099 REV B EO B12; MC284-0420 REV C AMENDMENT SEQ. 8

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/19/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 789 ABORT: 3/3

ITEM: RESISTOR, 1.2K 2W  
FAILURE MODE: FAILS SHORT

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 5, OX & FU ISOL VLVS
- 5) RESISTOR, 1.2K 2W
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: F BAY 3A, MCA 3,  
PART NUMBER: 83V76A18R J2-83, 104

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, SWITCH TALKBACK STILL AVAILABLE TO HYBRID DRIVER LOGIC  
CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 790 ABORT: 3/3

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE SWITCH FAILS IN THE OPEN POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE OPEN CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 791 ABORT: 2/1R

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE SWITCH FAILS IN THE CLOSED POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE SWITCH'S CLOSE CONTACTS AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 792 ABORT: 2/1R

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE GPC POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

VALVE CAN NOT BE CONTROLLED BY SWITCH, ONLY BY MDM OPEN OR CLOSE COMMANDS. TO OPERATE THE VALVE, THE CREW MUST USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WHILE THE VALVE IS IN THE CLOSED POSITION WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTH DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 793 ABORT: 2/1R

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE OPENED BY SWITCH COMMAND, ONLY BY MDM COMMAND, AND CAN CLOSED BY THE SWITCH OR THE MDM. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 794 ABORT: 3/3

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES		
	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN OR GPC POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED POSITION, THE VALVE WILL REMAIN CLOSED AND CAN BE OPENED WITH THE SWITCH, BUT CANNOT BE CLOSED AGAIN BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 795 ABORT: 3/3

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 796 ABORT: 3/3

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 797 ABORT: 3/3

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH CLOSE CONTACTS  
5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVS
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM CLOSE COMMANDS. IF THE CLOSE CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CAN BE OPENED BY SWITCH OR MDM COMMAND, BUT CANNOT BE CLOSED BY SWITCH COMMAND, ONLY BY MDM COMMAND. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 798 ABORT: 2/1R

ITEM: MANIFOLD 1, OX & FU ISOL VLV SWITCH CLOSE CONTACTS  
5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 1, OX & FU ISOL VLVs
- 5) MANIFOLD 1, OX & FU ISOL VLV SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S30  
PART NUMBER: 33V73A8S30

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED OR GPC POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY SWITCH OR MDM COMMAND. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN POSITION, THE VALVE WILL REMAIN OPEN AND CAN BE CLOSED WITH THE SWITCH, BUT CANNOT BE OPENED AGAIN BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND THEN USE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 799 ABORT: 3/3

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE SWITCH FAILS IN THE OPEN POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE OPEN CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 800 ABORT: 2/1R

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE SWITCH FAILS IN THE CLOSED POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE SWITCH'S CLOSE CONTACTS AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 801 ABORT: 2/1R

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE GPC POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

VALVE CAN NOT BE CONTROLLED BY SWITCH, ONLY BY MDM OPEN OR CLOSE COMMANDS. TO OPERATE THE VALVE, THE CREW MUST USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WHILE THE VALVE IS IN THE CLOSED POSITION WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTH DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 802 ABORT: 2/1R

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2

FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	3/2R
ONORBIT:	3/2R		AOA:	3/2R
DEORBIT:	3/2R		ATO:	3/2R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE OPENED BY SWITCH COMMAND, ONLY BY MDM COMMAND, AND CAN CLOSED BY THE SWITCH OR THE MDM. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 803 ABORT: 3/3

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN OR GPC POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED POSITION, THE VALVE WILL REMAIN CLOSED AND CAN BE OPENED WITH THE SWITCH, BUT CANNOT BE CLOSED AGAIN BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 804 ABORT: 3/3

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	CRITICALITIES	
	HDW/FUNC	ABORT
PRELAUNCH:	3/3	RTLS: 3/3
LIFTOFF:	3/3	TAL: 3/3
ONORBIT:	3/3	AOA: 3/3
DEORBIT:	3/3	ATO: 3/3
LANDING/SAFING:	3/3	

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 805 ABORT: 3/3

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 806 ABORT: 3/3

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH CLOSE CONTACTS  
5, 6

FAILURE MODE: SWITCH CLOSE CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER

SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVS
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM CLOSE COMMANDS. IF THE CLOSE  
CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE  
WILL REMAIN IN THAT POSITION, CAN BE OPENED BY SWITCH OR MDM  
COMMAND, BUT CANNOT BE CLOSED BY SWITCH COMMAND, ONLY BY MDM  
COMMAND. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO  
CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 807 ABORT: 2/1R

ITEM: MANIFOLD 2, OX & FU ISOL VLV SWITCH CLOSE CONTACTS  
5, 6  
FAILURE MODE: SWITCH CLOSE CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 2, OX & FU ISOL VLVs
- 5) MANIFOLD 2, OX & FU ISOL VLV SWITCH CLOSE CONTACTS 5, 6
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT		HDW/FUNC
PRELAUNCH:	3/3	RTLS:		2/1R
LIFTOFF:	3/3	TAL:		3/2R
ONORBIT:	3/2R	AOA:		3/2R
DEORBIT:	3/2R	ATO:		3/2R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S31  
PART NUMBER: 33V73A8S31

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED OR GPC POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY SWITCH OR MDM COMMAND. IF THE CLOSE CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN POSITION, THE VALVE WILL REMAIN OPEN AND CAN BE CLOSED WITH THE SWITCH, BUT CANNOT BE OPENED AGAIN BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CLOSE CONTACTS, AND THEN USE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	808	ABORT:	3/3

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE OPEN POSITION

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:            PNL 08 S32  
PART NUMBER:    33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE SWITCH FAILS IN THE OPEN POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE OPEN CONTACTS, AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 809 ABORT: 2/1R

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE CLOSED POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE SWITCH FAILS IN THE CLOSED POSITION, THE VALVE WILL CLOSE AND CANNOT BE OPENED BY SWITCH OR MDM COMMAND. TO OPEN THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE SWITCH'S CLOSE CONTACTS AND THEN USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 810 ABORT: 2/1R

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH  
FAILURE MODE: SWITCH FAILS IN THE GPC POSITION

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	2/1R
LIFTOFF:	3/3	TAL:	3/2R
ONORBIT:	3/2R	AOA:	3/2R
DEORBIT:	3/2R	ATO:	3/2R
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ 2 ] B [ P ] C [ P ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

VALVE CAN NOT BE CONTROLLED BY SWITCH, ONLY BY MDM OPEN OR CLOSE COMMANDS. TO OPERATE THE VALVE, THE CREW MUST USE THE GPC READ/WRITE PROCEDURES. FAILURE OF THE MDM COMMAND PATH WHILE THE VALVE IS IN THE CLOSED POSITION WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTH DURING ABORTS AND ENTRY, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE



INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/2R  
MDAC ID: 811 ABORT: 2/1R

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

FLIGHT PHASE	HDW/FUNC	CRITICALITIES	ABORT	HDW/FUNC
PRELAUNCH:	3/3		RTLS:	2/1R
LIFTOFF:	3/3		TAL:	3/2R
ONORBIT:	3/2R		AOA:	3/2R
DEORBIT:	3/2R		ATO:	3/2R
LANDING/SAFING:	3/3			

REDUNDANCY SCREENS: A [ 2 ] B [ F ] C [ P ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY THE MDM OPEN COMMANDS. IF THE OPEN CONTACTS FAIL OPEN WHILE THE SWITCH IS IN ANY POSITION, THE VALVE WILL REMAIN IN THAT POSITION, CANNOT BE OPENED BY SWITCH COMMAND, ONLY BY MDM COMMAND, AND CAN CLOSED BY THE SWITCH OR THE MDM. FAILURE OF THE MDM COMMAND PATH WILL AFFECT ONORBIT OPERATIONS, PROPELLANT DUMP LENGTHS DURING ABORTS, AND MAY CAUSE THE INABILITY TO EXPEL ENOUGH PROPELLANTS DURING RTLS ABORTS TO MEET THE CG SAFETY BOUNDARIES.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE:	1/13/87	HIGHEST CRITICALITY	HDW/FUNC
SUBSYSTEM:	FRCS	FLIGHT:	3/3
MDAC ID:	812	ABORT:	3/3

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH OPEN CONTACTS  
1, 2  
FAILURE MODE: SWITCH OPEN CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER      SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH OPEN CONTACTS 1, 2
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS:    A [    ]      B [    ]      C [    ]

LOCATION:      PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL SHOCK, OVERLOAD

EFFECTS/RATIONALE:

REDUNDANCY PROVIDED BY MDM CLOSE COMMANDS. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE OPEN OR GPC POSITION, THE VALVE WILL OPEN AND CANNOT BE CLOSED BY SWITCH OR MDM COMMAND. IF THE OPEN CONTACTS FAIL CLOSED WHILE THE SWITCH IS IN THE CLOSED POSITION, THE VALVE WILL REMAIN CLOSED AND CAN BE OPENED WITH THE SWITCH, BUT CANNOT BE CLOSED AGAIN BY SWITCH OR MDM COMMAND. TO CLOSE THE VALVE, THE CREW MUST REMOVE CONTROL BUS POWER FROM THE CONTACTS, AND THEN USE GPC READ/WRITE PROCEDURES. FAILURE OF ALL REDUNDANCY WILL CAUSE THE INABILITY TO CLOSE THE VALVE.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 813 ABORT: 3/3

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL OPEN

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVS
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

	CRITICALITIES		
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE

INDEPENDENT ORBITER ASSESSMENT  
ORBITER SUBSYSTEM ANALYSIS WORKSHEET

DATE: 1/13/87 HIGHEST CRITICALITY HDW/FUNC  
SUBSYSTEM: FRCS FLIGHT: 3/3  
MDAC ID: 814 ABORT: 3/3

ITEM: MANIFOLD 3, OX & FU ISOL VLV SWITCH GPC CONTACTS 3,  
4  
FAILURE MODE: SWITCH GPC CONTACTS FAIL CLOSED

LEAD ANALYST: V.J. BURKEMPER SUBSYS LEAD: D.J. PAUL

BREAKDOWN HIERARCHY:

- 1) ELECTRICAL COMPONENTS
- 2) CONTROLS
- 3) PROP STOR & DIST SUBSYSTEM
- 4) MANIFOLD 3, OX & FU ISOL VLVs
- 5) MANIFOLD 3, OX & FU ISOL VLV SWITCH GPC CONTACTS 3, 4
- 6)
- 7)
- 8)
- 9)

CRITICALITIES			
FLIGHT PHASE	HDW/FUNC	ABORT	HDW/FUNC
PRELAUNCH:	3/3	RTLS:	3/3
LIFTOFF:	3/3	TAL:	3/3
ONORBIT:	3/3	AOA:	3/3
DEORBIT:	3/3	ATO:	3/3
LANDING/SAFING:	3/3		

REDUNDANCY SCREENS: A [ ] B [ ] C [ ]

LOCATION: PNL 08 S32  
PART NUMBER: 33V73A8S32

CAUSES: CONTAMINATION, VIBRATION, MECHANICAL SHOCK, THERMAL  
SHOCK, OVERLOAD

EFFECTS/RATIONALE:  
NONE, THESE CONTACTS ARE NOT IN A CIRCUIT.

REFERENCES: VS70-943099 REV B EO B12, CE, DE







**MCDONNELL DOUGLAS ASTRONAUTICS COMPANY - HOUSTON**  
**16055 SPACE CENTER BLVD, HOUSTON, TEXAS 77062**