


Prepared in cooperation with the West Virginia Department of Transportation, Division of Highways and the West Virginia Conservation Agency

Regional Curves for Bankfull Channel Characteristics in the Appalachian Plateaus, West Virginia



Scientific Investigations Report 2009–5242

U.S. Department of the Interior

U.S. Geological Survey



Regional Curves for Bankfull Channel Characteristics in the Appalachian Plateaus, West Virginia

By Terence Messinger	
Prepared in cooperation with the West Virginia Department of Transportation, Division of Highways and the West Virginia Conservation Agency	
Cojentifia Investigations Depart 2000, F242	
Scientific Investigations Report 2009–5242	

U.S. Department of the Interior KEN SALAZAR, Secretary

U.S. Geological Survey Marcia K. McNutt, Director

U.S. Geological Survey, Reston, Virginia: 2009

For more information on the USGS—the Federal source for science about the Earth, its natural and living resources, natural hazards, and the environment, visit http://www.usgs.gov or call 1-888-ASK-USGS

For an overview of USGS information products, including maps, imagery, and publications, visit http://www.usgs.gov/pubprod

To order this and other USGS information products, visit http://store.usgs.gov

Any use of trade, product, or firm names is for descriptive purposes only and does not imply endorsement by the U.S. Government.

Although this report is in the public domain, permission must be secured from the individual copyright owners to reproduce any copyrighted materials contained within this report.

Suggested citation:

Messinger, Terence, 2009, Regional curves for bankfull channel characteristics in the Appalachian Plateaus, West Virginia: U.S. Geological Survey Scientific Investigations Report 2009–5242, 43 p.

Contents

Abstract	
Introduction	1
Description of Study Area	1
Site Selection	3
Channel Measurements	4
Bankfull Features	4
High-Water-Mark Profiles	7
Relation of Profiles to Streamgages	11
Bankfull Flow Frequencies	17
Bankfull Characteristics and Regional Curves	18
Flow	18
Dimensions	18
Pattern and Profile	21
Stream Types	25
West Virginia Regional Curves Compared to Regional Curves from Surrounding Areas	25
Channel Dimensions from Flow Measurements at Streamgages in West Virginia	25
Valley and Ridge	25
Pennsylvania	26
Ohio	28
Summary and Conclusions	30
Acknowledgments	31
References Cited	31

Figures

1–3.	Ma	ps showing—	
	1.	West Virginia and surrounding states, their physiography, and selected cities and rivers	2
	2.	Regional curve planning regions, elevation, mean annual precipitation, and recent streamgages on unregulated streams in West Virginia	3
	3.	Regional curve sites in the Appalachian Plateaus Physiographic Province, West Virginia	е
4–6.	Gra	phs showing—	
	4.	Profiles of selected gaged stream channels in the Appalachian Plateaus Physiographic Province of West Virginia	12
	5.	Profiles of selected ungaged stream channels in the Appalachian Plateaus Physiographic Province of West Virginia	13
	6.	Selected profiles of high-water marks from near-bankfull peaks, bankfull features, low-water surface, and thalwegs for reaches at streamgages at (A) Middle Fork at Audra and (B) Panther Creek near Panther, West Virginia	14
7.	Pho	tograph of crest-stage streamgage at Marsh Fork at Maben, West Virginia	16
8–18.	Gra	phs showing—	
	8.	1.5-year peak flow at streamgages draining less than 240 square miles in the Appalachian Plateaus Physiographic Province, West Virginia, by region and end year of systematic record	17
	9.	Relation between bankfull flow and drainage area for selected wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	18
	10.	Bankfull flows compared to 1.5-year peak flows measured at streamgages on wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	19
	11.	Bankfull flows compared to regression lines for 1.2-, 1.4-, 1.5-, and 1.7-year peak flows measured at streamgages on wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	
	12.	Relation between bankfull area and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	
	13.	Relation between bankfull width and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	
	14.	Relation between bankfull depth and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia	22
	15.	Regional curve and 99-percent confidence interval for bankfull area of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas	26
	16.	Regional curve and 99-percent confidence interval for bankfull width of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas	27
	17.	Regional curve and 99-percent confidence interval for bankfull depth of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas	
	18.	Regional curve and 99-percent confidence interval for bankfull flow of wadable streams in the Appalachian Plateaus Province in West Virginia,	20

Tables

Station numbers, drainage areas, locations, and streamgaging periods of record for regional curve sites for the Appalachian Plateaus Physiographic Province,	
West Virginia	5
Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia	34
Dates of peak flows, flagging, description of storms, and quality and type of marks for high-water profiles and slope-area flow measurements made during regional curve development for the Appalachian Plateaus Physiographic Province,	8
Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia	39
Average bankfull characteristics of streams in the Appalachian Plateaus Physiographic Province in West Virginia	20
Bankfull characteristics and stream types of reaches in the Appalachian Plateaus Physiographic Province in West Virginia	23
	for regional curve sites for the Appalachian Plateaus Physiographic Province, West Virginia Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia Dates of peak flows, flagging, description of storms, and quality and type of marks for high-water profiles and slope-area flow measurements made during regional curve development for the Appalachian Plateaus Physiographic Province, West Virginia Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia Average bankfull characteristics of streams in the Appalachian Plateaus Physiographic Province in West Virginia

Conversion Factors and Datums

Ву	To obtain
Length	
0.3048	meter (m)
1.609	kilometer (km)
Area	
0.09290	square meter (m ²)
2.590	square kilometer (km²)
Flow rate	
0.02832	cubic meter per second (m³/s)
	Length 0.3048 1.609 Area 0.09290 2.590 Flow rate

Temperature in degrees Celsius (°C) may be converted to degrees Fahrenheit (°F) as follows:

Temperature in degrees Fahrenheit (°F) may be converted to degrees Celsius (°C) as follows:

Vertical coordinate information is referenced to the North American Vertical Datum of 1988 (NAVD 88).

Horizontal coordinate information is referenced to the North American Datum of 1983 (NAD 83). Altitude, as used in this report, refers to distance above the vertical datum.

[°]F=(1.8×°C)+32

[°]C=(°F-32)/1.8

Regional Curves for Bankfull Channel Characteristics in the Appalachian Plateaus, West Virginia

By Terence Messinger

Abstract

Streams in the Appalachian Plateaus Physiographic Province in West Virginia were classified as a single region on the basis of bankfull characteristics. Regression lines for annual peak flow and drainage area measured at streamgages in the study area at recurrence intervals between 1.2 and 1.7 years fell within the 99-percent confidence interval of the regression line for bankfull flow. Channel characteristics were intermediate among those from surrounding states and regions where comparable studies have been done.

The stream reaches that were surveyed were selected for apparent stability, and to represent gradients of drainage area, elevation, and mean annual precipitation. Profiles of high-water marks left by bankfull and near-bankfull peaks were surveyed, either as part of slope-area flow measurements at ungaged reaches, or to transfer known flow information to cross sections for gaged reaches. The slope-area measurements made it possible to include ungaged sites in the study, but still relate bankfull dimensions to peak flow and frequency.

Introduction

Regional curves (Dunne and Leopold, 1978) are regression equations that quantify relations within a region between bankfull channel characteristics and drainage area, and in some cases, other basin characteristics. They are used in natural channel design (NCD), which is a set of methods for restoring, rebuilding, or rerouting stream channels (Rosgen, 1996). Natural channel design practitioners use regional curves to design channels or to verify identification of bankfull features in reference reaches.

Stream restoration, of which NCD is a subset, is important in environmental management and policy and has become a growing business (Bernhardt and others, 2005). The National River Restoration Science Synthesis (NRRSS) project estimated that at least \$14 to \$15 billion was spent on restoration of streams and rivers within the continental United States between 1990 and 2005 (Bernhardt, 2006; Bernhardt and

others, 2005). Channel reconfiguration projects, a category which includes NCD, accounted for more than \$1.3 billion of the overall total.

The concept of bankfull flow is central to NCD (Leopold, 1994; Rosgen, 1996). Dimension, pattern, and profile of channels are considered to be maintained by bankfull flow, which is considered to be the effective flow or the flow that transports the most cumulative sediment over time (Rosgen, 1996). Bankfull flow, regardless of whether or not it is the effective flow, usually has a return period between 1 and 2 years when calculated from the annual-peak series, with 1.5 years close to average (Leopold and others, 1964). Stable channels, by definition, are changed little by flows of magnitudes that recur frequently, but channel instability can result from land-use and other changes that alter the magnitude of frequent peak flows.

The West Virginia Conservation Agency and the Division of Highways of the West Virginia Department of Transportation cooperated with the U.S. Geological Survey (USGS) in this project, one of a series of studies done in and near West Virginia, intended to provide information for NCD (Wiley and others, 2002; Messinger and Wiley, 2004; Keaton and others, 2005). The Canaan Valley Institute facilitated the task force that identified the need for this series of studies.

The purpose of this report is to provide regional equations (regional curves) for bankfull characteristics of stable stream channels within the part of the Appalachian Plateaus Physiographic Province in West Virginia. Supporting information is provided on the development of the regional curves. Bankfull stream-channel characteristics are compared to those of adjacent regions.

Description of Study Area

The study area was defined as the part of West Virginia within the Appalachian Plateaus Physiographic Province (fig. 1). The Appalachian Plateaus Physiographic Province is an area of flat-lying or gently folded rocks that formed when a peneplain was uplifted during the Appalachian Orogeny, and then was dissected by stream erosion in the ensuing




Figure 1. West Virginia and surrounding states, their physiography, and selected cities and rivers. The study area is the part of the Appalachian Plateaus Physiographic Province within West Virginia.

300 million years (Fenneman, 1938). Elevation is highest in the east, where some peaks are higher than 4,000 ft (NAVD 88), and lowest in the west, near the Ohio River, where the valley is lower than 600 ft (fig. 2). Relief is generally greatest at highest elevations. The Ohio River drains most of the study area (19,631 mi²), and the rest (329 mi²) is drained by the Potomac River.

Mean annual precipitation and maximum storm precipitation are not closely correlated. Maximum storm precipitation, as measured by any of several frequencies for storm intensity, is greatest in the southern and eastern parts of the study area and least in the northern and western parts of the study area (Hydrometeorological Design Studies Center, 2006a, 2006b).

The eastern part of the study area is more frequently affected by Atlantic hurricanes than is the west, which accounts, in part, for the difference. Distribution of mean annual precipitation is related closely to elevation, and the greatest annual precipitation is received in the highest parts of the study area. The lowest mean annual precipitation in the study area is in the Northern Panhandle and the southern Greenbrier River Basin in the southeastern part of the study area, which is behind a pronounced rain shadow (fig. 2).

Land use, surface geology, and soils all covary with elevation within the study area (Messinger and Hughes, 2000). Generally, the highest population density and concentration of urban land is in river valleys in the northern and western parts

of the study area. Commercial agriculture is limited in scope, and most commercial farms are near the downstream sections of the Ohio and Kanawha Rivers, and the Greenbrier River Basin. Forest cover is most dense in the mountains in central West Virginia. The largest cities in the study area, all with populations less than 51,000, are Charleston on the Kanawha River; Huntington, Parkersburg, and Wheeling on the Ohio River; and Morgantown on the Monongahela River (U.S. Census Bureau, 2009). Because the largest urban areas in the study area are in the valleys of major rivers, increases in peak storm runoff caused by impervious urban lands are generally localized and most pronounced on a few small streams.

Principal economic activities include coal mining, forestry, and oil and gas production, which are widespread throughout most of the study area; manufacturing, which is most common in areas near the Monongahela, Ohio, and Kanawha Rivers; and agriculture, which is most important commercially near the Ohio and Kanawha Rivers and in the

Greenbrier River Basin (Messinger and Hughes, 2000). Of these, forestry and surface coal mining are widespread within the study area and have well-established, strong effects on storm hydrographs and peak flows.

Site Selection

Planning regions were developed for this study on the basis of elevation and mean annual precipitation, which were the basin characteristics that explained the most variation in near-bankfull channel characteristics determined from analysis of flow measurements made at streamgages (Messinger and Wiley, 2004). The study area was divided into six planning regions, each representing areas with generally homogeneous elevation and mean annual precipitation (fig. 2). The site-selection goal was to have equal numbers of wadable sites draining small, medium, and large areas (less than 10, 10–100,




Figure 2. Regional curve planning regions, elevation, mean annual precipitation (shown in white contours), and recent streamgages on unregulated streams in West Virginia.

and greater than 100 mi²) from each planning region. Wadable sites were those where a detailed profile of the thalweg could be measured while wading; a drainage area of 240 mi² was adopted for planning, although several streams draining larger areas were reconnoitered and probably could have been surveyed during extreme low flows.

A competing goal for site selection was for all sites to have stable banks and readily identifiable bankfull features. Candidate reaches were excluded if banks were failing throughout most of their length, or if plausible bankfull features were not present. Gaged reaches were evaluated and included in the study if they met both these criteria.

Relatively few gaged reaches met these criteria, particularly when the streamgage was near a bridge or road. The majority of active streamgages were on non-wadable streams, although the majority of stream-restoration work is done on wadable streams. In addition, because available streamgages on wadable streams were disproportionately on the headwaters of major rivers, they were clustered in the central and eastern mountains of West Virginia (Messinger and Wiley, 2004).

Because not enough suitable gaged sites were available to build a network that could adequately represent the study area, ungaged sites were added. Two parts of the overall streamgaging record typically are used to develop regional curves: the high part of the stage-flow rating is used to determine bankfull flow, and the annual-peak series, based on 10 or more years of data, is used to confirm that bankfull flow is equivalent to a peak with an approximate recurrence interval of 1 to 2 years. Slope-area measurements, which define the high end of the stage-flow rating at the great majority of USGS streamgages, could be made for near-bankfull peaks during the 3-year duration of the project.

Determining the recurrence interval of a peak approximately equivalent to bankfull flow would normally be more problematic than determining its flow and would preclude using ungaged sites in a regional-curve network. However, regional frequency relations for frequent, low-magnitude annual peaks had already been developed for three regions in West Virginia and were published with a series of regression equations for estimating flows of frequencies ranging from the 1.1-year flow through the 5-year flow (Wiley and others, 2002).

Streams that cross public land, including national parks, national forests, state parks, and wildlife management areas, were preferred in selecting ungaged reaches because these reaches were less likely to undergo adverse change in stream management and land use than were reaches on private land.

Not enough public lands were present in several planning regions to fill the gaps in the planning-region matrix. When suitable streams on public lands were not available, streams identified as candidate sites for antidegradation protection (West Virginia Department of Environmental Protection, 2005), draining appropriately sized areas, and in the desired locations, were assessed for inclusion in the study. The remaining reaches were identified in consultation with water or public-service professionals who were familiar with the

area of interest. Only two suitable sites were identified in the Northern Panhandle after an extended reconnaissance effort, and this area remained underrepresented in the study (table 1; fig. 3).

Channel Measurements

Channels were surveyed with a total-station instrument. Second-order closure was achieved for all loops (Wolf and Ghilani, 2002). Longitudinal profiles were surveyed through a reach of at least 20 bankfull-channel widths. Reaches were comprised of two or more repeated sequences of riffles and pools. All profiles included thalwegs, water surface, plausible bankfull features, and high-water marks from a peak at or near apparent bankfull. Inner berms and point bars within the channel also were surveyed where they were present. Longitudinal stationing in the profiles was measured along the thalweg; a point in the thalweg was surveyed at the upstream and downstream bounds of the reach, at important changes in depth, and everywhere in the reach that other features were surveyed.

Cross sections were surveyed in riffles, preferably at the change in slope at the transition from pool to riffle. Two cross sections were surveyed at most gaged sites, although three were surveyed in reaches that included substantial changes in character. Cross sections were extended to an elevation of twice the maximum depth relative to the highest plausible bankfull feature. At some sites with wide forested or brushy flood plains (greater than 3 times bankfull width), the cross sections were surveyed for a minimum distance of 3 times bankfull width; the remaining distance to the edge of the flood plain was paced and its elevation was estimated.

At ungaged sites, cross sections were surveyed at major changes in the slope of the high-water profile for use in computing the slope-area measurement. At least four and as many as eight cross sections were surveyed at ungaged sites. At least two of the cross sections were surveyed according the same procedure used at gaged sites. The additional cross sections at ungaged sites were surveyed, at a minimum, to the higher of the high-water mark or the top of the bank.

Bankfull Features


For this study, the bankfull channel was defined as that part of the stream channel below the most distinct feature between the estimated elevations of the 1.1-year peak flow and the 2.0-year peak flow. Features used as indicators of the bankfull channel include, in order of preference and frequency used, rounded, vegetated, convex slope changes; bank substrate changes, particularly the edge of topsoil; sharp convex slope changes or those that showed other signs of instability; concave slope changes; and the elevation of an apparent flood plain. Each surveyed feature on a bank was described in written notes and assessed as to apparent quality (table 2 at end of report).

Table 1. Station numbers, drainage areas, locations, and streamgaging periods of record for regional curve sites for the Appalachian Plateaus Physiographic Province, West Virginia.

[mi², square miles; SF, State Forest; SP, State Park; WMA, Wildlife Management Area]

A 3831008100 23.5 03182700 144 381702080314401 3.51 375433080171001 3.06 03070500 200 03152200 2.91 03152200 2.91 03152200 2.91 03152200 2.91 03152500 80.4 03202750 80.4 03202750 80.4 0310830 394422080342601 10.9 383911080225201 11.5 390847079424801 2.31 03118800 A 383101081481401 10.78 SF 373054081080601 2.31 03153400 11.5 03052000 148 381543081401401 0.86 03199300 12.2 03052500 80.8 and Bend SP 39125308105591 1.111 onth Bend SP 391253081055901 0.759	(mi²) (decimal degrees) 23.5 38.141 144 37.908 3.51 38.284 3.06 37.909 200 39.616 85.9 39.124 32 37.504 126 39.124 32 37.504 126 37.623 80.4 38.295 37.5 38.017 51.5 39.154 2.31 37.422 48.9 40.436 10.9 39.740 11.5 38.653 20.1 39.147 112 38.517 2.31 37.515 2.31 37.515 2.31 37.515	decimal degrees -80.837 -80.292 -80.292 -80.529 -79.705 -79.469 -80.691 -81.128 -81.128 -81.128 -81.319 -82.296 -81.319 -81.319 -81.319 -81.319 -81.319 -81.319 -80.574 -80.574 -80.574 -80.574 -80.574 -80.381 -79.714	1998–2009 1972–1982 none 1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 none none none none none 1976–1978, 2002–2009 none none none
03190100 23.5 03182700 144 381702080314401 3.51 375433080171001 3.06 03070500 200 03066000 85.9 03152200 2.91 03178500 32. 03202750 126 03187500 80.4 03202501 125 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080235201 11.5 373054081080601 2.31 bwood 38131080234201 11.5 03052000 148 38131080234201 11.5 03052000 14.3 031575002300 14.3 03157500200 14.3 03157500200 14.3 03157500200 14.3 03157500200 14.3 03183000 12.2 03183000 12.2 03183000 11.11 ver at North Bend SP 391253081055901 0.759		-80.837 -80.292 -80.529 -80.529 -79.705 -79.469 -80.691 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.574 -80.574 -80.574	1998–2009 1972–1982 none 1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 1964–2009 none none none none none 1976–1978, 2002–2009 none none none
03182700 144 381702080314401 3.51 375433080171001 3.06 03066000 85.9 03152200 2.91 03178500 32 03202750 126 03187500 80.4 03187500 80.4 03187500 80.4 10.9 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 373654081080601 2.31 hwood 381311080234201 11.5 03052000 148 381311080234201 11.5 03177100 8.64 375743081010401 0.86 03199300 12.2 03183000 80.8 03183000 12.2 03183000 14.3 03183000 11.11 ver at North Bend SP 391253081055901 0.759		-80.292 -80.286 -79.705 -79.469 -80.691 -81.128 -81.128 -81.319 -82.296 -81.319 -81.865 -80.574 -80.574 -80.574	none none 1972–1982 none 1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 none none none none none none none non
381702080314401 3.51 375433080171001 3.06 03070500 200 03066000 85.9 03152200 2.91 03178500 32 03202750 126 03187500 80.4 03206600 37.5 390912081190901 5.1.5 372519081515301 2.31 03110830 39422080342601 10.9 383911080225201 11.5 390847079424801 2.0.1 ath WMA 383101081481401 10.78 p Creek SF 373054081080601 2.34 hwood 381311080234201 11.5 03052000 148 375041081054201 13.4 3815430810401401 0.86 03199300 12.2 03052500 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759		-80.529 -80.286 -79.705 -79.469 -80.691 -81.128 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.574 -80.574 -80.381 -79.714	none none 1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 none none none none none none none 1976–1978, 2002–2009 none none none
375433080171001 3.06 03070500 200 03152200 2.91 03152200 2.91 03152200 2.91 03178500 32 03202750 126 03187500 32 03206600 37.5 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 ath WMA 3831101081481401 10.78 p Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 03052000 148 375041081054201 13.4 381543081401401 0.86 03052500 14.3 03052500 14.3 03183000 10.1 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.952		-80.286 -79.705 -79.469 -80.691 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -81.865 -80.574 -80.574 -80.574	none 1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1964–2009 none none 1976–1978, 2002–2009 none 1976–1978, 2085–2009
03070500 200 03066000 85.9 03152200 2.91 03178500 32.9 03202750 126 03187500 37.5 03202750 126 03187500 37.5 390912081190901 37.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 38391108025201 11.5 att 03151400 112 att 03151400 11.5 by Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 03052000 148 375041081054201 381543081401401 0.86 03177100 8.64 37555082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.952		-79.705 -79.469 -80.691 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.574 -80.381 -79.714	1909–1918, 1921–2009 1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1964–2009 1964–2009 none none 1976–1978, 2002–2009 none 1976–1978, 2002–2009 1973–1983, 1985–2009
03066000 85.9 03152200 2.91 03178500 32 03202750 126 03187500 37.5 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 38391108025201 11.5 ap Creek SF 373054081080601 2.31 bt wwood 381311080234201 11.5 ab		-79.469 -80.691 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.574 -80.574	1921–2009 1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 1964–2009 none 1976–1978, 2002–2009 none 1976–1978, 1985–2009
03152200 2.91 03178500 32 03202750 126 03202750 126 03187500 80.4 Dunlow 03206600 37.5 370519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 at 03151400 11.5 b Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03153600 12.2 03183000 80.8 375541081054201 11.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759	_ ~ ~ ~	-80.691 -81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.575 -80.574 -80.381 -79.714	1970–1977; 1994–2006 1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 1964–2009 none 1976–1978, 2002–2009 none none none 1973–1983, 1985–2009
03178500 32 03202750 126 03187500 80.4 Dunlow 03206600 37.5 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 p Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 0315300 148 394137079490001 2.34 hwood 381311080234201 11.5 0315500 14.3 0315500 14.3 0315500 14.3 0315500 14.3 0315500 14.3 03155000 14.3 03155000 14.3 03155000 14.3 03155000 14.3 03155000 14.3	~ ~ ~	-81.128 -81.707 -80.527 -82.296 -81.319 -81.865 -80.575 -80.574	1947–1971 1974–2009 1944–1951, 1964–1982, 1984–2009 1964–2009 none none 1976–1978, 2002–2009 none none none 1973–1983, 1985–2009
03202750 126 03187500 80.4 Dunlow 03206600 37.5 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 ath 03151400 11.2 ath 03151400 11.2 b Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 hwood 381311080234201 11.5 03052000 148 375041081054201 13.4 375041081054201 13.4 381543081401401 0.86 03183000 14.3 03183000 80.8 37555082212101 1.11 ver at North Bend SP 391253081055901 0.759 et Cornstalk WMA 384449082012601 0.92	~ ~ ~	-81.707 -80.527 -82.296 -81.319 -81.865 -80.575 -80.574 -80.381 -79.714	1974–2009 1944–1951, 1964–1982, 1984–2009 1964–2009 none none 1976–1978, 2002–2009 none none none 1973–1983, 1985–2009
Dunlow 03187500 80.4 Dunlow 03206600 37.5 390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 38391108025201 11.5 ath 03151400 11.2 ath 03151400 112 ath 03151400 112 p Creek SF 373054081080601 2.31 hwood 38131080234201 11.5 hwood 38131080234201 11.5 394137079490001 2.34 hwood 38131080234201 13.4 381543081401401 0.86 0319300 12.2 03052500 14.3 o3183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	~ ~ ~ ~	-80.527 -82.296 -81.319 -81.865 -80.574 -80.381 -79.714	1944–1951, 1964–1982, 1984–2009 1964–2009 none none 1976–1978, 2002–2009 none none 1973–1983, 1985–2009
Dunlow 03206600 37.5 90912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 38391108025201 11.5 ath WMA 383101081481401 20.1 p Creek SF 373054081080601 2.31 p Creek SF 373054081080601 2.34 hwood 381311080234201 11.5 03052000 14.8 31 03177100 8.64 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	-	-82.296 -81.319 -81.865 -80.575 -80.574 -80.381 -79.714	1964–2009 none none 1976–1978, 2002–2009 none none 1973–1983, 1985–2009
390912081190901 51.5 372519081515301 2.31 03110830 48.9 394422080342601 10.9 383911080225201 11.5 art	-	-81.319 -81.865 -80.575 -80.574 -80.381 -79.714	none none 1976–1978, 2002–2009 none none none 1973–1983, 1985–2009
372519081515301 03110830 48.9 384422080342601 10.9 383911080225201 11.5 11 11.5 11 03151400 112 11 11.2 11 11.2 11 10.78 11 10.78 12 10.78 14 373054081080601 2.31 10 03052000 148 394137079490001 2.34 11.5 03052300 11.5 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	-	-81.865 -80.575 -80.574 -80.381 -79.714	none 1976–1978, 2002–2009 none none 1973–1983, 1985–2009
03110830 48.9 394422080342601 10.9 383911080225201 11.5 orge 390847079424801 20.1 ath WMA 383101081481401 10.78 p Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 orge at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	∞ -	-80.575 -80.574 -80.381 -79.714	1976–1978, 2002–2009 none none 1973–1983, 1985–2009
394422080342601 10.9 383911080225201 11.5 at 390847079424801 20.1 ath 03151400 112 ath 03151400 112 p Creek SF 373054081080601 2.31 p Creek SF 373054081080601 2.31 p Mwood 381311080234201 11.5 p Mwood 381311080234201 11.5 p Mwood 381311080234201 13.4 p Mwood 38154408104401 0.86 p Mwood 375041081054201 12.2 p Mwood 375755082212101 1.11 p Mwood 375755082212101 1.11 p Mwood 375755082212101 0.759 p Mwood 384449082012601 0.92	∞ -	-80.574 -80.381 -79.714	none none none 1973–1983, 1985–2009
383911080225201 11.5 orge 390847079424801 20.1 tt 03151400 112 b Creek SF 373054081080601 2.31 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 13.4 381543081401401 0.86 03199300 12.2 03052500 14.3 o3183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	8 -	-80.381 -79.714	none none 1973–1983, 1985–2009
orge 390847079424801 20.1 tt 03151400 112 anh WMA 383101081481401 10.78 p Creek SF 373054081080601 2.31 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 13.4 375041081054201 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759	8 T	-79.714	none 1973–1983, 1985–2009
tt 03151400 1112 ath WMA 383101081481401 10.78 p Creek SF 373054081080601 2.31 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 ay 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	8		1973–1983, 1985–2009
nth WMA 383101081481401 10.78 p Creek SF 373054081080601 2.31 p Creek SF 373054081080601 2.31 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759	8	-80.527	
p Creek SF 373054081080601 2.31 03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759	1	-81.804	none
03052000 148 394137079490001 2.34 hwood 381311080234201 11.5 03213500 3.1 03177100 8.64 375041081054201 13.4 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759		-81.135	none
394137079490001 2.34 hwood 381311080234201 11.5 03213500 31 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759		-80.069	1942–1979, 1988 –2009
hwood 381311080234201 11.5 03213500 3.1 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759	2.34 39.694	-79.817	none
03213500 31 03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	11.5 38.220	-80.395	none
03177100 8.64 375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	31 37.445	-81.871	1946–1986, 2002–2009
375041081054201 134 381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	8.64 37.358	-80.978	1999–2009
381543081401401 0.86 03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	134 37.845	-81.095	1987-2009 (low discharge measurements only)
03199300 12.2 03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	0.86 38.262	-81.671	none
03052500 14.3 03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	12.2 38.100	-81.830	1979–1984; 1999–2006
03183000 80.8 375755082212101 1.11 ver at North Bend SP 391253081055901 0.759 ef Cornstalk WMA 384449082012601 0.92	14.3 38.964	-80.153	1946–2009
375755082212101 1.11 iver at North Bend SP 391253081055901 0.759 iief Cornstalk WMA 384449082012601 0.92	80.8 37.685	-80.457	1946–1973; 1997–1998
391253081055901 0.759 384449082012601 0.92	1.11 37.965	-82.356	none
384449082012601 0.92	0.759 39.215	-81.100	none
	0.92 38.747	-82.024	none
	26.4 38.618	-79.808	none
205	205 38.844	-81.223	1928–1931, 1937–1975, 1975–2003
Williams River at Dyer 03186500 128 38	128 38.379	-80.484	1929–2009
Yellow Creek near Davis 39838079254101 2.28 39	2.28 39.144	-79.428	none





Base from U.S. Geological Survey, 2006, 1:2,000,000 digital files

Figure 3. Regional curve sites in the Appalachian Plateaus Physiographic Province, West Virginia.

Extra consideration was given to features when more than one was present at the same spot; for example, combinations of a distinct rounded convex slope change from the bank to the flood plain with mature plant growth, or a convex slope change at the edge of topsoil were regarded as especially good bankfull indicators.

In most reaches assessed in this study, there were one or more reaches with more than one feature on the bank at the same longitudinal station that could plausibly be regarded as the bankfull feature. In these cases, all the plausible bankfull features at the station of interest were surveyed, and the final determination of which to use was made with the profile plot used as a supplement to field notes.

High-Water-Mark Profiles

At all sites, a profile of high-water marks was flagged for a peak greater than half of apparent average bankfull depth, but inside the bank. At ungaged sites, the high-water marks were used to measure peak flow by the slope-area method (Dalrymple and Benson, 1967). Slope-area measurements were computed using the Slope-Area Computation program (Fulford, 1994) and checked using the HEC-RAS model (U.S. Army Corps of Engineers, 2009). At gaged sites, flow was determined for the flagged peak using the station rating or the stage-flow relation defined by current-meter and indirect-flow measurements (Rantz and others, 1982). The peak flow measured at the streamgage was used to verify roughness in the reach.

High-water marks were flagged as soon as practical after flow peaked or, in two cases, the high-water surface was flagged while still at near-bankfull flow (table 3). If distinct, continuous high-water-marks were present, high-water marks were flagged at minimum longitudinal distances equivalent to estimated bankfull width, and closer together in parts of the reach where slope appeared to change. If only a few high-water marks were distinct, all the distinct marks were flagged. The date and the type and quality of the mark were written on a strip of plastic survey flagging, then pinned to the mark with a nail. Once flagged, sites were surveyed when convenient.

The most commonly used high-water marks were wash lines in leaf litter on the bank. Other fairly common high-water marks were deposits of ground-up tree leaves, hemlock or spruce needles, and depending on season, seed lines. Mud stains on plants or fallen leaves were generally indistinct and used at only two or three sites, but at those sites, they were the predominant high-water mark. Roughness values for the ungaged sites were determined by comparing sections of stream channel to sections of stream channel from gaged sites with verified roughness values and to published photographs of reaches with verified roughness values (Barnes, 1967), then were compared with roughness values computed using two different formulas (Jarrett, 1984; Limerinos, 1970). Roughness values exceeding those calculated from the formulas were

used when field notes and photographs supported the higher values, for example, when a cross section was affected by backwater from a log or boulder downstream.

The high-water-mark profiles were used to supplement, or at most sites, replace the use of estimated channel dimensions from flow measurements at streamgages as a means of choosing among plausible bankfull features at the same longitudinal station. Instead of referring to estimated bankfull elevations and dimensions derived from flow measurements, the elevation of a plausible bankfull feature was compared to that of the high-water-mark profile, while considering the frequency of the peak. At gaged sites, the magnitude and frequency of peak flow at ungaged sites was estimated by comparison to flow at index streamgages, taking into account the differences in storm precipitation among basins.

For example, at Cranberry River near Richwood, flow peaked on the night of November 16, 2006, at 3,010 ft³/s, just less than the 1.2-year flow for the site and about the 2.0-year flow for the Southern Region (Wiley and others, 2002). The profile was flagged the next morning. Nine high-water marks, all wash lines, were flagged; seven were good, and two were fair. Identification of bankfull features was relatively simple at this site. All the bankfull features surveyed were points where a convex slope change from the narrow flood plain to the bank coincided with the edge of the topsoil. Because the bed and banks were dominated by large boulders (D84 (84th percentile of particle size) = 2.12 ft at one cross section and greater than 6.00 ft at the other), the bankfull features were not continuous for extended lengths in the reach, and in fact, identifiable bankfull features were not present in segments of the profile where they would have been useful to measure. Through most of the reach, flow peaked at or just above bankfull features, although the bankfull features in the riffles were lower relative to the high-water marks than were the features in the pools (fig. 4). At XS2, the upstream cross section, the primary bankfull feature was the edge of topsoil, which collected among jagged, poorly eroded rocks, coincident with a convex slope change on the left bank, and it was rated as fair. An additional bankfull feature on the right bank was only 0.17 ft higher and was described as a rounded convex slope change formed of topsoil and anchored by tree and mountain laurel roots. At XS1, the downstream cross section, the primary bankfull feature, on the left bank, was a lumpy, convex slope change from a depositional shelf to the bank that coincided with the edge of topsoil and was rated as good. The bankfull feature on the right bank also was surveyed; it was only 0.36 ft lower and was a rounded, distinct convex slope change from a gently sloping section of bank to a steeper section of bank, coincided with the edge of topsoil, and was covered with well-established moss. Bankfull flow was calculated to be 1,380 ft³/s at XS2, the upstream cross section, and 2,070 ft³/s at XS1, the downstream cross section, for an average of 1,720 ft³/s for the reach. Although the calculated bankfull flow was less than expected and inconsistent between the cross sections, the

Dates of peak flows, flagging, description of storms, and quality and type of marks for high-water profiles and slope-area flow measurements made during regional curve development for the Appalachian Plateaus Physiographic Province, West Virginia. Table 3.

freamoage.	nominação,	
l stage-flow rating at a s	and mountaine are	
on from established	on non comprising	
T flow determinati	c, non accommun	
area measurement. G	area measarement,	
t Area: SA slone.	ici iicu, or i, siope	
7ildlife Managemer	name managemen	
State Park: WMA W	Dinto I min, 11 title, 11	
SF State Forest SP S	, or, our rock, or,	ley and others, 2002]
H3/s cubic feet ner second	s, casic reer per second, or	requency region, from Wi
[H ³ /s C	(r, r)	redu

Site	Peak date	Flag date	Description of storm	Quality and type of marks	How (ft³/s)	Frequency region	Frequency	Method of flow measurement
Anglins Creek near Nallen	March 16, 2007	March 22, 2007	Statewide rain	Mostly poor. Mostly mud stains. Few usable marks overall.	786	South	1.3	Ð
Anthony Creek near Anthony	June 27, 2006	June 28, 2006	Locally heavy rain from widespread thunderstorms	Good. Wash lines.	8,480	South	3.0	Ð
Barrenshe Run near Woodbine	March 2, 2007	April 4, 2007	Statewide rain	Poor or fair. Mostly wash lines, a few seed lines.	166	South	1.3	SA
Big Draft near Anthony	March 16, 2007	March 22, 2007	Statewide rain	Mostly fair, a few good or excellent. Hemlock needle or fine leaf debris lines.	94	South	1.1	SA
Big Sandy Creek near Rockville August 21, 2007	August 21, 2007	August 22, 2007	Statewide rain	Good. Mostly fine leaf debris, a few wash lines.	6,370	East	2.5	Ü
Blackwater River at Davis	April 15, 2007	April 15, 2007	Statewide rain	Excellent. Flagged water surface during near-bankfull flow.	1,480	East	1.2	Ū
Buck Run at Leopold	January 21, 2006	January 24, 2006	Statewide rain	Fair. Wash lines and seedlines, but not generally continuous, and only a few were distinct.	201	North	1.3	Ð
Camp Creek near Camp Creek	June 27, 2006	June 28, 2006	Locally heavy rain from widespread thunderstorms	Mostly fair or good, a few poor. Mostly wash lines.	1,550	South	2.5	Ð
Clear Fork at Clear Fork	April 7, 2006	April 11, 2006	Statewide rain	Good. Mostly wash lines.	3,270	South	1.4	Ð
Cranberry River near Richwood November 16, 2006	November 16, 2006	November 17, 2006	Locally heavy rain	Excellent, good, or fair. Nearly all wash lines.	3,010	South	2.0	Ü
East Fork Twelvepole Creek near Dunlow	October 30, 2006	October 31, 2006	Intense local thunder- storm	Good to excellent. Fine debris, mud stains.	829	South	1.1	Ð
Goose Creek near Petroleum	April 15, 2007	May 17, 2007	Statewide rain	Fair or good fine leaf debris lines; a few poor wash lines.	1,580	North	1.2	Ð
Hurricane Branch at Panther SF March 16, 2007	March 16, 2007	March 19, 2007	Statewide rain	Good. Mostly wash lines.	65	South	1.1	$_{ m SA}$

Table 3. Dates of peak flows, flagging, description of storms, and quality and type of marks for high-water profiles and slope-area flow measurements made during regional curve development for the Appalachian Plateaus Physiographic Province, West Virginia.—Continued

[ft³/s, cubic feet per second; SF, State Forest; SP, State Park; WMA, Wildlife Management Area; SA, slope-area measurement; G, flow determination from established stage-flow rating at a streamgage; Frequency region, from Wiley and others, 2002]

Site	Peak date	Flag date	Description of storm	Quality and type of marks	Flow (ft³/s)	Frequency region	Frequency	Method of flow measurement
Kings Creek near Weirton	December 17, 2007	December 17, 2007 December 18, 2007	Widespread system throughout Northern Panhandle and West- ern Pennsylvania	Mostly good, some fair or excellent. Mostly wash lines, some mixed fine leaf debris/seed lines.	604	North	1.7	SA
Knob Creek near Wade	August 21, 2007	August 22, 2007	Intense local thunder- storms	Good. Two profiles, mostly fine leaf debris on lower, wash lines or fine leaf debris on higher.	449	North	1.2	SA
Laurel Fork near Hacker Valley March 16, 2007	March 16, 2007	April 17, 2007	Statewide rain	Mostly fair, a few poor or good. Wash lines.	340	South	1.1	SA
Left Fork Clover Run near St. George	April 15, 2007	August 9, 2007	Statewide rain	Good. Mix of wash lines, fine leaf debris, and seed lines. Marks were old but distinct, and lined up well when surveyed.	616	East	1.5	SA
Little Kanawha River near Wildcat	April 7, 2006; June 27, 2006	April 20, 2006; June 29, 2006	Statewide rain; lo- cally heavy rain from widespread thunder- storms	Good or fair. Wash lines, fine leaf debris lines.	4,200	North	2.0	Ð
Manilla Creek at Amherst- Plymouth WMA	January 21, 2006	January 25, 2006	Statewide rain	Excellent. A nearly continuous wash line on left bank throughout the reach.	699	South	2.5	SA
Marsh Fork of Mash Fork at Camp Creek SF	June 27, 2006	June 27, 2006	Locally heavy rain from widespread thunderstorms	Excellent. Flagged high water surface as flow peaked.	66	South	1.1	SA
Middle Fork at Audra	March 16, 2007	March 22, 2007	Statewide rain	Mostly good. Wash lines or fine leaf debris.	3,130	North	1.1	Ð
Morgan Run near Cheat Lake	August 21, 2007	August 22, 2007	Local thunderstorm	Poor. Mix of wash lines and seed lines.	53	East	1.1	SA
North Fork Cherry River near Richwood	November 16, 2006	November 17, 2006	Locally heavy rain	Excellent. Most were clean wash lines.	535	South	1.5	SA
Panther Creek near Panther	March 16, 2007	March 19, 2007	Statewide rain	Fair or poor. Mix of wash lines and fine leaf debris lines.	1,280	South	1.7	Ð
Payne Branch near Oakvale	March 16, 2007	March 21, 2007	Statewide rain	Mostly fair, a few good or excellent. Mostly wash lines, a few fine leaf debris lines.	306	South	1.2	9

Dates of peak flows, flagging, description of storms, and quality and type of marks for high-water profiles and slope-area flow measurements made during regional curve development for the Appalachian Plateaus Physiographic Province, West Virginia.—Continued Table 3.

State Park; WMA, Wildlife Management Area; SA	, Wildlife Management Area; SA	State Park; WMA, Wildlife Management Area; SA	State Park; WMA, Wildlife Management Area; SA	SF, State Forest; SP, State Park; WMA, Wildlife Management Area; SA Wiley and others, 2002]	, slope-area measurement; G, flow determination from established stage-flow rating at a streamgage;	
State Park; WMA, Wildlife Mana	State Park; WMA, Wildlife Mana	State Park; WMA, Wildlife Mana	nd; SF, State Forest; SP, State Park; WMA, Wildlife Mana, Wiley and others, 2002]	et per second; SF, State Forest; SP, State Park; WMA, Wildlife Mana, ion, from Wiley and others, 2002]	SA	
State Park; W	State Park; W	State Park; W	nd; SF, State Forest; SP, State Park; W Wiley and others, 2002]	et per second; SF, State Forest; SP, State Park; Wion, from Wiley and others, 2002]	fe Management	
State Park; W	State Park; W	State Park; W	nd; SF, State Forest; SP, State Park; W Wiley and others, 2002]	et per second; SF, State Forest; SP, State Park; Wion, from Wiley and others, 2002]	A, Wildli	
State Pa	Forest; SP, State Parers, 2002]	SF, State Forest; SP, State Page and others, 2002]	nd; SF, State Fore Wiley and others,	et per second; SF, State Foreion, from Wiley and others,	ark; WM	
	Forest; SI ners, 2002	SF, State Forest; SI ey and others, 2002	nd; SF, State Fore Wiley and others,	et per second; SF, State Foreion, from Wiley and others,	State Pa	_

Site	Peak date	Flag date	Description of storm	Quality and type of marks	Flow (ft³/s)	Frequency region	Frequency	Method of flow measurement
Piney Creek near McCreery	April 7, 2006	April 13, 2006	Locally heavy rain	Poor. Mix of wash lines and seed lines.	2,253	South	1:1	SA
Polly Hollow at Kanawha SF	April 15, 2007	April 16, 2007	Statewide rain	Poor, fair, and good wash lines.	38	South	1.1	SA
Rock Creek near Danville	April 15, 2007	April 17, 2007	Statewide rain	Fair or good. Wash lines or fine leaf debris lines. Few marks overall.	705	South	2.0	Ð
Sand Run near Buckhannon	November 29, 2005	December 1, 2005	Locally heavy rain	Fair or poor. Mix of wash lines, trash lines.	623	North	1.3	Ð
Second Creek near Second Creek	June 27, 2006	June 28, 2006	Locally heavy rain from widespread thunderstorms	Locally heavy rain from Mostly good, a few fair. Wash lines. widespread thunder-storms	2,660	South	1.7	Ð
Spruce Fork at Cabwaylingo SF April 15, 2007	April 15, 2007	April 17, 2007	Statewide rain	Most fair or good, a few poor or excellent. Seed lines, wash lines, and fine leaf debris lines.	31	South	11	SA
Unnamed Tributary to Hughes River at North Bend SP	April 15, 2007	May 16, 2007	Statewide rain	Good. Seed lines.	17	North	1.7	SA
Upper Nineteenmile Creek at Chief Comstalk WMA	January 21, 2006	January 25, 2006	Statewide rain	Good. All marks at cross sections were wash lines; trash and leaf debris lines elsewhere in reach.	91	South	2.0	SA
West Fork Greenbrier River above Durbin	March 16, 2007	August 7, 2007	Statewide rain	Mostly poor or fair. Wash lines and a few fine leaf debris lines. Only marks at upstream end of reach lined up well.	1,188	South	1.9	SA
West Fork Little Kanawha River April 15, 2007 near Rocksdale	April 15, 2007	April 18, 2007	Statewide rain	Fair or good. Mud stains.	5,880	South	1.8	Ð
Williams River at Dyer	March 16, 2007	March 23, 2007	Statewide rain	Good or fair. Wash lines.	7,780	South	3.0	Ð
Yellow Creek near Davis	June 27, 2006	June 29, 2006	Locally heavy rain	Fair. Mix of wash lines, fine leaf debris, and hemlock needle lines.	160	East	3.0	SA

features at the cross sections were good, consistent on both banks, and comparable to the high-water-mark profile, and so were used for computing bankfull dimensions.

At another site, West Fork Little Kanawha River near Rocksdale, on April 15, 2007, flow peaked at 5,880 ft³/s, corresponding to the 1.8-year flow for the Southern Region of West Virginia or the 1.4-year flow calculated for that site (Wiley and others, 2002; table 1). The peak was flagged 2 days later, and the marks, mostly mud stains on grass, were generally fair, although a few were good. In contrast to Cranberry River near Richwood, identifying bankfull features at West Fork Little Kanawha River near Rocksdale was problematic. The channel was incised; through most of the reach, the banks were complex, and several depositional features, any of which might plausibly have been bankfull features, were present (fig. 4; table 2). The most distinct bankfull features were in the pools, which made up most of the reach, but these features were not continuous into the riffles. Throughout most of the reach, the top of the bank was noted to be an exceptionally distinct convex slope change from a wide, generally flat wooded area to a steep bank; this feature was judged to be a terrace because it was several feet above the high-water-mark profile. At both cross sections, several plausible bankfull features were present. At the upstream cross section, four features were surveyed and described, but three of them were judged to be poor. The most distinct of them, a convex slope change on the left bank, anchored by tree roots and rated as fair, was chosen as the bankfull feature to determine cross-sectional dimensions, although it was higher than the trend line for bankfull features through the reach. At the downstream cross section, three plausible bankfull features were surveyed and described. Two of the three were judged to be poor; both were abrupt convex slope changes. The feature which best fit the trendline of bankfull features was at the top of a recent slump and was judged to be poor. The feature chosen to determine cross-sectional dimensions was at the top of the left bank—a sharp convex slope change from flood plain to a steeply sloping bank. Established weed growth was noted, and the feature was judged to be fair.

Bankfull features were compared to high-water-mark profiles at all sites, even if, as at East Fork Twelvepole Creek near Dunlow (fig. 4, table 3), the high-water-mark profile was left by a storm peak that was substantially lower than expected for bankfull flow. The high-water-mark profile was used in generally the same way at ungaged sites. At Manilla Creek near Poca, for instance, the top of the bank was judged as the apparent bankfull feature during site reconnaissance. Flow peaked at 669 ft³/s on January 21, 2006, which corresponded to about the 2.5-year flow for West Virginia's Southern Region (Wiley and others, 2002). The feature at the top of the bank was at the high-water-mark profile through the upstream part of the reach but about a foot higher than the high-water-mark profile for the downstream part of the reach (fig. 5). That feature was judged to be a terrace, and a different, lower set of features identified in reconnaissance as the inner berm was chosen as the bankfull feature. At Laurel Fork near Hacker Valley, at least two plausible bankfull features were present

through most of the reach. The high-water-mark profile was left by a peak of 340 ft³/s, about the 1.1-year flow for the Southern Region of West Virginia (Wiley and others, 2002), and the peak was near the lower of the two features (fig. 5). At sites like Big Draft near Anthony, where, similar to Cranberry River near Richwood, the flagged peak was very near bankfull and only one set of plausible features was present (fig. 5), identification of bankfull features would probably have been straightforward using any procedure.

Relation of Profiles to Streamgages

In addition to this difference in confirming the identification of bankfull features, the other major departure from methods described by Leopold (1994) and Rosgen (1996) was a difference in the way data collected at the streamgage were used to determine bankfull flow. Typically, a profile of bankfull features is surveyed upstream and downstream from a streamgage, a line is fit through a plot of the profile, and the elevation of the line at the streamgage is compared to the stage-flow rating. However, this approach can give inaccurate results under common, predictable conditions.

First, the use of a fitted line assumes that bankfull elevation falls through the reach in a more or less linear manner. Although this is true in some streams—particularly lowgradient, meandering streams—a common pattern in rifflepool streams is for profiles to be stepped, with relatively little fall in pools and most of the fall in riffles (fig. 6; Leopold, 1994). Plots of bankfull features are nearly parallel to plots of high-water marks. Steps are less pronounced at bankfull flow than at lower flows but are still clear. High-water-mark profiles show the stepped pattern more clearly than do bankfull profiles because, in most streams, bankfull features form at a greater range of elevations through a reach than do marks left by a single peak. In addition, bankfull features are more difficult to identify precisely than high-water marks left by bankfull flow. (Exceptions might include high-water marks in steep streams with turbulent flow and a substrate of mobile boulders, where standing waves move through the reach as the boulders they form over move downstream.)

If all the pools and riffles in a reach had approximately the same slopes and lengths, then the principal source of error in profile-rating relations in a stepped profile with correctly identified features would be the position of a streamgage on its pool relative to the positions within the reach of the features selected for identification. If features are identified at equal intervals through a stepped reach, a line fit through them will pass through features near the center of pools and riffles. Features at the upstream end of a pool will fall below the line, and features near the downstream end of a pool will fall above the line. This idea is confirmed by field observations of high-water marks left by a pair of near-bankfull peak flows. The Middle Fork at Audra streamgage is near the upstream end of its pool, and an observed peak gage height confirmed by a good highwater mark at the streamgage structure was 0.91 ft below a trendline fit through the profile of high-water marks (fig. 6a).




Figure 4. Profiles of selected gaged stream channels in the Appalachian Plateaus Physiographic Province of West Virginia.




Figure 5. Profiles of selected ungaged stream channels in the Appalachian Plateaus Physiographic Province of West Virginia.




Figure 6. Selected profiles of high-water marks from near-bankfull peaks, bankfull features, low-water surface, and thalwegs for reaches at streamgages at (A) Middle Fork at Audra and (B) Panther Creek near Panther, West Virginia. High-water marks, bankfull features, and low-water surface all have slope changes at approximately the same location. Differences in stage, flow, and frequency are shown between water-surface elevation of a measured high-water mark and a line fit through the high-water-mark profile.




Figure 6. Selected profiles of high-water marks from near-bankfull peaks, bankfull features, low-water surface, and thalwegs for reaches at streamgages at (A) Middle Fork at Audra and (B) Panther Creek near Panther, West Virginia. High-water marks, bankfull features, and low-water surface all have slope changes at approximately the same location. Differences in stage, flow, and frequency are shown between water-surface elevation of a measured high-water mark and a line fit through the high-water-mark profile. —Continued

The Panther Creek at Panther streamgage is at the downstream end of its pool, and an observed peak gage height confirmed by a good high-water mark at the streamgage structure was 0.52 ft above a trendline fit through the profile of high-water marks (fig. 6b). Errors of these magnitudes in the near-bankfull part of ratings correspond to large errors in flow estimates. At Middle Fork at Audra, a 0.91 ft difference in gage height (between an estimate of 10.03 ft and an observation of 9.12 ft) corresponds to an overestimation of peak flow of 1,220 ft³/s (estimating 6,620 ft³/s when the measured flow was 5,400 ft³/s, or 23 percent). The frequency for the estimated peak is about 2.5 years, but 1.7 years for the measured peak. At Panther Creek at Panther, a 0.52 ft difference in gage height (between an estimate of 6.16 ft and an observation of 6.68 ft) corresponds to an underestimation of peak flow of 243 ft³/s (estimating 757 ft³/s when the measured flow was 1,000 ft³/s, or about 24 percent). However, the frequency of this estimated peak is about 1.2 years and, for the measured peak, 1.4 years.

If features are identified primarily at the same position in pools and riffles as the streamgage is located, then a line fit through them will accurately reflect the profile elevation at the streamgage. If more features are identified near the upstream ends of pools and riffles than near the downstream ends, then the profile will be shifted artificially upward, and the profile will be shifted artificially downward if disproportionate numbers of features are identified near the downstream ends of pools and riffles.

In the field, the investigator may have little choice as to where to identify features along a profile, especially in problematic reaches with few identifiable features or features that are not continuous through the reach. Selecting additional, poorly defined features because they are at a position in the profile where they would be convenient is unlikely to increase the accuracy of estimated flow.

Another major source of variation in the relation between the profile and rating is the effect of bridges and culverts on ratings. Streamgages are built where a stable feature controls the stage-flow rating throughout the range of stages. The highwater control is typically a constriction in the channel, and a box culvert or bridge with piers at mid-channel often makes an ideal high-water control. Furthermore, streamgages are deliberately installed near roads because easy access not only saves effort and money but improves the quality of the flow record by making it faster and easier to reach the site to measure flow and service instruments. If a streamgage can be built where the stream can be measured from a bridge, then the expense and risk of building a cableway is spared. Often, streamgages are attached to bridges.

Locating streamgages upstream from bridges that control water-surface elevation puts the streamgage in backwater at bankfull, or lower, flow. This means that depth is artificially greater at the streamgage than elsewhere in the reach. Bridges also may cause streambeds to scour and banks to erode, so banks near bridges and culverts are frequently armored with riprap or gabions (fig. 7). In these cases, natural bankfull features at the streamgage no longer exist, the channel at the

streamgage may be unrepresentative of the rest of the reach, and bankfull elevations from elsewhere in the reach are unrelated to elevations at the streamgage.

At gaged sites, slope and roughness values were calculated from the high-water-mark profile using the flow measured at the streamgage. At ungaged sites, the slope and roughness values determined in the slope-area flow measurement were used to calculate bankfull flow. For all reaches, roughness values were adjusted for differences in depth between the high-water-mark and the bankfull profile before computing bankfull flow. The adjustment for depth was made by calculating a theoretical roughness value for each cross section in the high-water-mark and bankfull profiles using the formula of Jarrett (1984). The ratio of these two roughness values was computed, then multiplied by the roughness values determined for the high-water-mark profiles to obtain bankfull roughness. These bankfull roughness values were used in Manning's equation to compute bankfull flow for each cross section. The bankfull flows were then averaged for the reach.



Figure 7. Crest-stage streamgage at Marsh Fork at Maben, West Virginia.

Bankfull Flow Frequencies

Regional peak-flow magnitudes with frequencies between 1.1 and 3.0 years had been previously computed for West Virginia (Wiley and others, 2002), which was split into three regions, the Northern, Southern, and Eastern Regions, on the basis of geographic analysis of regression residuals. The Northern and Southern Regions are entirely within the study area for this project, as is part of the Eastern Region.

The regression equations were developed with the goal of providing information to be used in NCD and related studies. The equations for each of the regions are significantly different (p < 0.05; Wiley and others, 2002) from those of the other two regions. However, for the purposes of this study, new regression equations were developed by combining annual-peak flow data from all the streamgages within the Appalachian Plateaus on streams draining less than 240 mi². Regional regression equations from the previous study were not used because of four reasons. First, among the smaller streams, a group of short-term streamgages operated approximately from 1966

through 1977, a period that included a major drought, are clustered closely together on a plot of 1.5-year annual peak flow as a function of drainage area and are among the stations with the lowest 1.5-year annual peak flow (fig. 8). Although stations in all three regions are in this cluster, there are fewer long-term streamgages in the Southern Region than in the other regions, so the streamgages from this cluster had an exaggerated effect on the Southern Region's regression equation. Second, the regional equations appear to have been strongly influenced by larger streams, which both accounted for most of the available data and were much more likely to have long periods of record and, therefore, to have data collected through wet and dry climatic periods. Third, R2 and standard error for the regional equations were only slightly different than for the aggregated equation. Fourth, and most important, geographic analysis of bankfull characteristics, as discussed later in this report, showed no regional difference within the Appalachian Plateaus, and a comparison of bankfull characteristics from a single region to a single peak-flow frequency relation was simpler and more relevant.




Figure 8. 1.5-year peak flow at streamgages draining less than 240 square miles in the Appalachian Plateaus Physiographic Province, West Virginia, by region and end year of systematic record.

Bankfull Characteristics and Regional Curves

Bankfull flow and dimensions were determined from cross sections surveyed at riffles (table 4 at end of report). A single set of regional curves was developed, on the basis of simple linear regression of bankfull characteristics as a function of drainage area. All the bankfull characteristics that were determined were strongly correlated with drainage area. Enough of the variation was explained by that single independent variable that exploring finer regional variation, or effects of other basin characteristics, was unlikely to provide meaningful results.

Flow

At the 10 active streamgages with more than 10 years of record, bankfull flows ranged from less than the 1.1-year flow to greater than the 2.0-year flow. The other streamgages that were available were one continuous streamgage with less than 10 years of data; crest-stage streamgages, which had relatively short periods of record; and discontinued streamgages. Furthermore, the periods of record were not concurrent among short-term stations. These factors complicate direct comparison of peak-flow frequencies among the sites, so an approach was adopted of comparing bankfull flow to peak flows of specific frequencies from all the streamgages in the study area in the comparable size range.

Drainage area accounted for slightly more of the variation for bankfull flows ($R^2 = 0.9592$; Standard error (SE) = 13.7 percent) than it did for the variation in 1.5-year peak flows measured at streamgages on wadable streams in the Appalachian Plateaus ($R^2 = 0.9326$; SE = 19.5 percent; table 5; figs. 9, 10). The regression lines for flows at the 1.2-, 1.3-, 1.4-, 1.5-, 1.6-, and 1.7-year recurrence intervals, computed for streamgages on wadable streams in the Appalachian Plateaus (fig. 11), all fell within the 99-percent confidence interval of the regression line for bankfull flow (for legibility, the lines for the 1.3- and 1.6-year flows are not depicted on fig. 11). The closest match to the regression line for bankfull flows is the line for the 1.4-year peak flow for the Appalachian Plateaus.

Dimensions

Bankfull area strongly ($R^2 = 0.9768$; SE = 8.5 percent) and significantly (P < 0.001) correlated with drainage area (table 4; fig. 12). An R^2 value of 0.9768 for bankfull area indicates that little additional variation can be explained by subdividing the study area by region, stream type, geology, or other characteristics. West Fork Little Kanawha River near Rocksdale, the site with the greatest positive residual value for bankfull area, was initially selected as a candidate site for a possible subregion, the Western Foothills. However, the banks at this site were among the least stable, and bankfull features at this site were among the least distinct included in the study, both of which increase the possibility that bankfull dimensions for this site might be wrong. Because the other sites in this




Figure 9. Relation between bankfull flow and drainage area for selected wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.




Figure 10. Bankfull flows compared to 1.5-year peak flows measured at streamgages on wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.




Figure 11. Bankfull flows compared to regression lines for 1.2-, 1.4-, 1.5-, and 1.7-year peak flows measured at streamgages on wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.

20 Regional Curves for Bankfull Channel Characteristics in the Appalachian Plateaus, West Virginia

 Table 5.
 Average bankfull characteristics of streams in the Appalachian Plateaus Physiographic Province in West Virginia.

[ft, feet; ft², square feet; ft³/s, cubic feet per second; SF, State Forest; SP, State Park; WMA, Wildlife Management Area]

Site	Area (ft²)	Width (ft)	Wetted perimeter (ft)	Depth (ft)	Bankfull flow (ft³/s)
Anglins Creek near Nallen	267	58.7	62.5	4.54	831
Anthony Creek near Anthony	610	136	139	4.50	6,220
Barrenshe Run near Woodbine	50.3	30.8	34.5	1.63	180
Big Draft near Anthony	43.7	34.1	37.5	1.28	187
Big Sandy Creek near Rockville	871	164	174	5.30	7,430
Blackwater River at Davis	612	109	114	5.61	1,630
Buck Run at Leopold	46.8	35.8	37.8	1.31	101
Camp Creek near Camp Creek	233	90.9	96.0	2.56	2,260
Clear Fork at Clear Fork	582	110	113	5.28	4,250
Cranberry River near Richwood	390	108	115	3.60	1,720
East Fork Twelvepole Creek near Dunlow	238	68.0	71.3	3.50	962
Goose Creek near Petroleum	404	78.3	83.1	5.17	2,330
Hurricane Branch at Panther SF	34.7	32.3	35.2	1.08	244
Kings Creek at Weirton	326	94.5	98.6	3.45	1,960
Knob Creek near Wade	120	48.6	50.7	2.47	402
Laurel Fork near Hacker Valley	103	51.4	55.4	2.00	595
Left Fork Clover Run near St. George	203	62.6	69.7	3.23	837
Little Kanawha River near Wildcat	681	160	162	4.27	3,240
Manilla Creek at Amherst-Plymouth WMA	121	46.7	48.9	2.60	365
Marsh Fork of Mash Fork at Camp Creek SF	40.6	29.2	33.9	1.39	142
Middle Fork at Audra	644	147	161	4.37	3,600
Morgan Run near Cheat Lake	36.3	24.0	26.4	1.51	199
North Fork Cherry River near Richwood	140	57.2	61.6	2.44	426
Panther Creek near Panther	173	56.3	61.2	3.07	1,200
Payne Branch near Oakvale	62.3	38.3	42.1	1.63	326
Piney Creek near McCreery	557	131	142	4.26	4,850
Polly Hollow at Kanawha SF	13.6	12.4	13.7	1.10	31.6
Rock Creek near Danville	162	41.4	43.7	3.91	718
Sand Run near Buckhannon	92.3	51.3	54.4	1.80	400
Second Creek near Second Creek	337	114	117	2.94	2,620
Spruce Fork at Cabwaylingo SF	25.9	19.7	22.2	1.31	83
Unnamed Tributary to Hughes River at North Bend SP	20.5	23.5	24.5	0.87	50.0
Upper Nineteenmile Creek at Chief Cornstalk WMA	24.1	19.8	20.6	1.22	48.4
West Fork Greenbrier River above Durbin	208	74.9	78.2	2.78	703
West Fork Little Kanawha River near Rocksdale	1410	154	160	9.16	4,520
Williams River at Dyer	743	148	153	5.02	3,960
Yellow Creek near Davis	33.5	22.2	25.0	1.51	73.1

planning region fit the regression equation well, West Fork Little Kanawha River near Rocksdale was considered more likely to be an outlier or an artifact than to be representative of another region. Payne Branch near Oakvale, the site with the greatest negative residual value, is near the boundary of the Appalachian Plateaus and Valley and Ridge Physiographic Provinces and is in the rain shadow; it plots closer to the regional curve for the Valley and Ridge than it does to the regional curve for the Appalachian Plateaus.

The relation between bankfull width and drainage area varied more than the relation between bankfull flow and drainage area ($R^2 = 0.9492$; SE = 7.1 percent; fig. 13). The relation between bankfull depth and drainage area varied the most of the bankfull dimensions ($R^2 = 0.8783$; SE = 8.9 percent; fig. 14).

Pattern and Profile

Near-bankfull high-water-surface slopes ranged from 0.0004 ft/ft (West Fork Little Kanawha River near Rocksdale) to 0.0544 ft/ft (Barrenshe Run near Woodbine) (table 6). Generally, mountain streams are steeper than lowland streams, and headwater streams are steeper than higher-order streams. Among the streams that were surveyed, smaller streams were generally steeper than larger streams. This rule had exceptions, such as Piney Creek near McCreery, which is among both the largest and steepest reaches in the study. Some of

the flattest reaches in the study (Blackwater River at Davis, Anglins Creek near Nallen, and Williams River at Dyer) are in the most mountainous parts of the study region, and one of the steepest reaches in the study (Polly Hollow at Kanawha State Forest) is at a relatively low elevation.

Sinuosity, the percentage of the reach as either pool or riffle, and near-bankfull high-water-surface slope, at most, weakly correlated between each other. R² values ranged from 0.02 for the relation between sinuosity and percentage of the reach as riffle to 0.25 for the relation between slope and percentage of reach as riffle.

High-water-mark profiles greatly clarified identification of bankfull features in the field. Because the flagged marks were associated with either a known flow and frequency, or an estimated flow and frequency based on data from nearby streamgages, they provided a second elevation with a known flow, along with the low-water surface, to compare to plausible bankfull characteristics. Although differences in elevation between a feature and the low-water surface can be measured quickly during a survey, the elevation difference alone fails to take into account changes in the other geometric and hydraulic characteristics of the channel, such as width and slope.

Requiring high-water-mark profiles before surveying a site also greatly increased logistic complexity in the study. All sites were visited at least two times. Because peak flows at many sites were uncorrelated with peak flows at gaged index sites, many of the sites were visited three or four times before a near-bankfull peak could be flagged.




Figure 12. Relation between bankfull area and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.




Figure 13. Relation between bankfull width and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.




Figure 14. Relation between bankfull depth and drainage area for wadable streams in the Appalachian Plateaus Physiographic Province in West Virginia.

Table 6. Bankfull characteristics and stream types of reaches in the Appalachian Plateaus Physiographic Province in West Virginia.

[ft, feet; D50, median particle size]

Site	Reach Iength (ft)	Riffle length (ft)	Riffle length, as percentage	Combined pool and run length (ft)	Combined pool and run length, as percentage	Riffle/pool sequences	Stream type ¹	D50, substrate class¹	Reach	Sinuosity
Anglins Creek near Nallen	1,121	166	15	955	85	3	E/C	Gravel	0.001	1.09
Anthony Creek near Anthony	1,562	9//	50	786	50	2	В	Cobble	0.002	1.07
Barrenshe Run near Woodbine	573	400	70	173	30	9	В	Cobble	0.054	1.14
Big Draft near Anthony	695	468	82	101	18	3	В	Cobble	0.028	1.06
Big Sandy Creek near Rockville	2,478	1,757	71	721	29	4	В	Boulder	0.007	1.13
Blackwater River at Davis	1,952	362	19	1,590	81	3	В	Boulder	0.001	1.18
Buck Run at Leopold	512	180	35	332	65	4	C	Gravel	0.005	1.24
Camp Creek near Camp Creek	1,405	644	46	761	54	3	C	Cobble	0.007	1.13
Clear Fork at Clear Fork	1,522	385	25	1,137	75	2	В	Cobble	0.003	1.09
Cranberry River near Richwood	2,490	1,837	74	653	26	2	В	Cobble	0.008	1.22
East Fork Twelvepole Creek near Dunlow	1,679	1,431	85	248	15	2	В	Gravel	0.001	1.34
Goose Creek near Petroleum	1,602	412	26	1,190	74	2	В	Cobble	0.002	1.57
Hurricane Branch at Panther SF	533	425	80	108	20	7	В	Cobble	0.036	1.05
Kings Creek at Weirton	1,909	787	41	1,122	59	4	В	Cobble	0.004	1.17
Knob Creek near Wade	1,085	334	31	751	69	5	В	Cobble	0.005	1.09
Laurel Fork near Hacker Valley	698	443	51	426	49	5	В	Cobble	0.016	1.06
Left Fork Clover Run near St. George	970	553	57	417	43	7	В	Cobble	900.0	1.13
Little Kanawha River near Wildcat	3,802	1,072	28	2,730	72	2	В	Cobble	0.002	1.49
Manilla Creek at Amherst-Plymouth WMA	1,436	521	36	915	64	3	В	Gravel	0.002	1.18

Table 6. Bankfull characteristics and stream types of reaches in the Appalachian Plateaus Physiographic Province in West Virginia.—Continued

[ft, feet; D50, median particle size]

Site	Reach Iength (ft)	Riffle length (ft)	Riffle length, as percentage	Combined pool and run length (ft)	Combined pool and run length, as percentage	Riffle/pool sequences	Stream type ¹	D50, substrate class¹	Reach	Sinuosity
Marsh Fork of Mash Fork at Camp Creek SF	652	391	09	261	40	9	B/F	Cobble	0.032	1.07
Middle Fork at Audra	2,094	1,342	64	752	36	2	В	Boulder	0.004	1.16
Morgan Run near Cheat Lake	550	308	56	242	44	S	В	Cobble	0.026	1.10
North Fork Cherry River near Richwood	1,336	938	70	398	30	8	В	Boulder	900.0	1.35
Panther Creek near Panther	1,021	618	61	403	39	2	В	Gravel	0.008	1.14
Payne Branch near Oakvale	711	362	51	349	49	4	В	Cobble	0.026	1.10
Piney Creek near McCreery	1,419	689	49	730	51	4	B/F	Cobble	0.016	1.06
Polly Hollow at Kanawha SF	399	220	55	179	45	4	В	Gravel	0.031	1.14
Rock Creek near Danville	862	211	26	587	74	8	ш	Cobble	0.004	1.03
Sand Run near Buckhannon	915	682	75	233	25	7	C	Cobble	900.0	1.03
Second Creek near Second Creek	1,679	167	46	912	54	4	C	Cobble	0.005	1.10
Spruce Fork at Cabwaylingo SF	356	241	89	115	32	S	B/F	Gravel	0.015	1.27
Unnamed Tributary to Hughes River at North Bend SP	382	250	99	132	35	7	В	Cobble	0.014	1.21
Upper Nineteenmile Creek at Chief Cornstalk WMA	587	153	26	434	74	4	В	Gravel	0.009	1.27
West Fork Greenbrier River above Durbin	1,398	353	25	1,045	75	8	В	Cobble	0.004	1.19
West Fork Little Kanawha River near Rocksdale	2,893	489	17	2,404	83	2	C	Gravel	0.000	1.16
Williams River at Dyer	3,312	1,005	30	2,307	70	4	В	Cobble	0.002	1.44
Yellow Creek near Davis	383	93	24	290	92	2	В	Gravel	0.008	1.18
(a)	2001									

'Stream type according to the Rosgen classification system (Rosgen, 1996).

Stream Types

Rosgen (1985, 1996) has published a set of criteria for classifying streams into types, on the basis of, in order of priority: (1) the entrenchment ratio, or the ratio of the flood-prone area to bankfull width; (2) the ratio of bankfull width to bankfull mean depth; (3) sinuosity, or the ratio of stream length to valley distance; (4) slope; and (5) channel material. Of the stream reaches surveyed in this study, 27 met criteria of type B, 5 of type C, and 1 of type E (table 6). Three reaches had characteristics that met some criteria for type B and some of type F, and one met some criteria of type C and of type E.

West Virginia Regional Curves Compared to Regional Curves from Surrounding Areas

Comparisons with regional curves from previous studies and surrounding areas showed general consistency. Bankfull channel characteristics from West Virginia were intermediate between those from Ohio and Virginia.

Differences in results from among a group of studies are likely to reflect real differences among the study areas when methods and implementation are identical. However, identification of bankfull characteristics is somewhat subjective, and differences have been documented among observers (Roper and others, 2008). Leopold (1994) considered bankfull width to be the most conservative bankfull characteristic, in the sense that when bankfull features are misidentified, the incorrect bankfull width is still likely to be close to the correct value in most streams. Therefore, as the characteristic that is least prone to observer bias, bankfull width is probably the most robust indicator of differences among study areas assessed by different investigators.

Channel Dimensions from Flow Measurements at Streamgages in West Virginia

Channel dimensions for the 1.5-year flow were determined from current-meter flow measurements made at streamgages in West Virginia to provide an estimate of bankfull dimensions (Messinger and Wiley, 2004). Bankfull flow was not determined in this study. Dimensions were determined for the cross section at each streamgage where high flows were measured, and regional regression equations were developed for the relation between channel dimensions and drainage area. The regression line for the relations between crosssectional area at the 1.5-year flow and drainage area for the Appalachian Plateaus Physiographic Province are within the 99-percent confidence interval of the regional curve for bankfull area for drainage areas less than about 10 mi² (figs.15–17). The areas for the 1.5-year flow were smaller than bankfull areas for the smallest drainage areas considered, but larger for the larger drainage areas, with the greatest difference at the largest drainage areas. Many, if not most, of the cross sections

used to develop the estimated areas were in pools, which generally are greater in area than adjacent riffle cross sections. Regional curves were developed from measurements made at riffle cross sections.

Width for the 1.5-year flow at streamgages is slightly less than bankfull width, but the regression line for the width at the 1.5-year flow is within the 99-percent confidence interval for the regional curve for bankfull width (fig. 16). Depth for the 1.5-year flow at streamgages was greater than bankfull depth, and the regression line for depth at the 1.5-year flow was outside the 99-percent confidence interval for the regional curve for bankfull depth in the Appalachian Plateaus (fig.17). Both these relations would be expected when comparing data exclusively from riffles to data predominantly from pools in the same streams.

Valley and Ridge

Bankfull flow, area, and depth were greater in the Appalachian Plateaus Physiographic Province in West Virginia than in the Valley and Ridge Physiographic Province in Maryland, Virginia, and West Virginia (figs. 15–18; Keaton and others, 2005). The Valley and Ridge receives less mean annual precipitation than does the Appalachian Plateaus in West Virginia, although storm intensity in the Valley and Ridge is greater, as measured by, for example, the 2-year 1-hour maximum precipitation (Hydrometeorological Design Studies Center, 2006a, 2006b).

The Valley and Ridge Physiographic Province in Maryland, Virginia, and West Virginia was to have been studied simultaneously with the Appalachian Plateaus Province in those three states. As a principal study goal, regions were to be determined empirically, based on analysis of bankfull channel characteristics. However, while ongoing, the study was reduced in scope to only the Valley and Ridge Physiographic Province, effectively but arbitrarily setting the boundary between bankfull-channel regions at the boundary between physiographic provinces (Keaton and others, 2005). The present study was undertaken to fill the gap in spatial coverage of bankfull-channel characteristics and, while it concentrated on characterizing the area that had not been studied, offered the opportunity to revisit the previous study's goal of determining regional boundaries. Comparison of bankfull channel characteristics determined in the Valley and Ridge study to those from the present study shows no compelling reason to redraw the existing arbitrary bankfull-channel regional boundary.

Evidence had already been available to suggest that the arbitrary boundary was reasonable; channel dimensions determined for the 1.5-year flow at streamgages in West Virginia were different in the Valley and Ridge and Appalachian Plateaus (Messinger and Wiley, 2004). Bankfull channel characteristics determined in the present study compared to those from the Valley and Ridge regional curve study (Keaton and others, 2005) are clearly different, considering the two areas broadly, but appear to show a transition area between them. Two streams in the Greenbrier or Bluestone River Basins at




Figure 15. Regional curve (shown in black) and 99-percent confidence interval (shown as gray fill) for bankfull area of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas.

the southeastern edge of the study area—Second Creek near Second Creek and Payne Branch near Oakvale—are within the Appalachian Plateaus Province but have bankfull flow, area, width, and depth similar to streams in the Valley and Ridge. However, Anthony Creek near Anthony, which drains parts of both the Appalachian Plateaus and Valley and Ridge, plots at the edge of the main body of values for the Appalachian Plateaus. In contrast, the West Fork of the Greenbrier River above Durbin and Big Draft near Anthony, both in the Greenbrier River Basin, and Marsh Fork at Camp Creek State Forest and Camp Creek near Camp Creek, both in the Bluestone River Basin, all plot well within the main body of bankfull area and depth values for the Appalachian Plateaus. This is not particularly strong support for redrawing the boundary between bankfull channel regions. Parts of the Greenbrier River Basin

and the eastern part of the Bluestone River Basin appear to be a transition zone between the two provinces and bankfull-channel regions, where average bankfull channel characteristics are intermediate between the larger regions. This region was identified by Fenneman (1938) as being atypical, in that the boundary between the Valley and Ridge and Appalachian Plateaus Provinces was indistinct here, unlike most of the rest of the boundary from New York to Alabama.

Pennsylvania

Within Pennsylvania, bankfull channel characteristics of the Appalachian Plateaus were not significantly different from those of other regions that had previously been studied




Figure 16. Regional curve (shown in black) and 99-percent confidence interval (shown as gray fill) for bankfull width of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas.

(Chaplin, 2005). Separate regional curves had previously been published for rural parts of the Piedmont and the Valley and Ridge in and near Pennsylvania. After field surveys for rural parts of the Appalachian Plateaus were complete, comparisons were made for bankfull flow and area, and drainage area, among the Piedmont, Valley and Ridge, and Appalachian Plateaus. Differences were not significant, and a single set of regional curves was published for these regions as a unit.

The regression line for bankfull flow in Pennsylvania fell below the lower limit of the 99-percent confidence interval for that in the Appalachian Plateaus of West Virginia (fig. 18). The regression lines for both bankfull area and width in Pennsylvania fall below the 99-percent confidence interval of the comparable regressions for West Virginia in streams draining relatively smaller areas (greater than 20 mi² for width,

and greater than 50 mi² for area; figs. 15, 16). The regression line for bankfull depth in Pennsylvania was less than that for West Virginia but mostly fell within the 99-percent confidence interval (fig. 17).

Precipitation is not homogeneous in either West Virginia or Pennsylvania, both of which are mountainous states where the terrain complicates movement of storm fronts and timing and intensity of precipitation. However, most of West Virginia is subject to more intense precipitation than is most of Pennsylvania (Hydrometeorological Design Studies Center, 2006b). Although other differences between the two study areas are abundant and other factors undoubtedly are at play, differences in precipitation intensity and resulting differences in peak flow seem among the most likely factors to cause the differences in bankfull characteristics.




Figure 17. Regional curve (shown in black) and 99-percent confidence interval (shown as gray fill) for bankfull depth of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas.

Regional curves for bankfull flow, area, width, and depth for Pennsylvania (Chaplin, 2005) are all intermediate between those for the Appalachian Plateaus in West Virginia and the Valley and Ridge for Maryland, Virginia, and West Virginia (Keaton and others, 2005; figs. 15–18). The Pennsylvania regional curves represent large sections of the Appalachian Plateaus and Valley and Ridge, in addition to the Piedmont. Some of the differences in basin characteristics between the Valley and Ridge and Appalachian Plateaus may be less pronounced in Pennsylvania than farther south. Geology and topography are similar for West Virginia and unglaciated parts of Pennsylvania, but there are differences in climatic factors between the two study areas that determine the frequency and

magnitude of bankfull flows. Pennsylvania has a generally colder climate than West Virginia and Virginia and receives relatively more snow and less rain in the winter. Parts of Pennsylvania receive major lake-effect snow storms that can cause snow-melt floods which are uncommon in West Virginia and Virginia.

Ohio

Regional curves for Ohio were developed following statewide data collection; two regions were delineated using analysis of bankfull characteristics (Sherwood and Huitger, 2005). Sets of equations were published for two regions in




Figure 18. Regional curve and 99-percent confidence interval for bankfull flow of wadable streams in the Appalachian Plateaus Province in West Virginia, compared to curves developed for adjacent areas.

Ohio. For both regions, simple regressions were published for bankfull characteristics in relation to drainage area, and multiple regressions were published for relations between bankfull characteristics, drainage area, and other basin characteristics. The following comparison is drawn with the simple regression equations developed for Ohio Region A, which is composed of the parts of the state within the Appalachian Plateaus and Central Lowlands Physiographic Provinces (Sherwood and Huitger, 2005).

Bankfull area of wadable streams is about the same in West Virginia and Ohio; the Ohio Region A regression line is within the 99-percent confidence interval for the West Virginia equation between about 3 and 200 mi², although the slopes

of the two lines diverge with greater drainage areas (fig. 15). Streams in Ohio are deeper and narrower; the Ohio regression line for depth plots above the 99-percent confidence interval for the West Virginia equation at drainage areas less than about 100 mi², but the Ohio regression for width plots below the 99-percent confidence interval for the West Virginia equation for drainage areas greater than about 5 mi² (figs. 16, 17).

The relation between the regression lines for bankfull flow (fig. 18) in Ohio and West Virginia is generally similar to those for bankfull area (fig. 15), although the difference in the slope of the lines is somewhat more pronounced. The bankfull flow equation was developed for a different group of stations than were the equations for the other bankfull characteristics;

bankfull area, width, and depth were determined for a group of 10 ungaged stations on small streams in Ohio where bankfull flow was not determined. Because of this, bankfull dimensions were not related to flow at the ungaged stations, and the equation for bankfull flow was developed from a group of stations that excluded the small streams.

Part of the difference among regional curves developed in West Virginia and the surrounding states arises from the piecemeal nature of the development of the curves. The curves were developed on a region-by-region basis, and the boundaries of regions were either assumed during study design or delineated within states. The benefit of this approach is that sufficient data were collected to describe conditions in each of the states, and the data were analyzed by individuals familiar with hydrologic and geomorphic conditions within their own state and thus well-positioned to emphasize local concerns. The weaknesses are that (1) questions concerning the most appropriate boundaries between different regions remain unanswered and (2) insufficient evidence may be available to determine whether outliers at the edge of a smaller study area, such as West Fork Little Kanawha River near Rocksdale in this study, are representative of a different region. If sites that should be included in other regions are inappropriately classified, regional curves will be skewed. Investigators and NCD practitioners working in transition areas, regions underrepresented within states, or in some cases even near state lines are left in ambiguous situations as to the most appropriate set of regional curves to use. Examining the results of all available regional curves in transition areas to see if they provide compatible results for a particular drainage area would be a prudent step in a channel-restoration project.

Summary and Conclusions

Regional curves for bankfull channel characteristics were developed for the part of West Virginia within the Appalachian Plateaus Physiographic Province. Regional curves are regression equations that quantify relations within a region between bankfull channel characteristics and drainage area, and in some cases, other basin characteristics. Natural channel design practitioners use regional curves to design channels or to verify identification of bankfull features in reference reaches. The USGS developed these regional curves in cooperation with the Division of Highways of the West Virginia Department of Transportation and the West Virginia Conservation Agency.

The study area was defined as the part of West Virginia within the Appalachian Plateaus Physiographic Province. Regional-curve planning regions were developed using elevation and mean annual precipitation, the basin characteristics that explained the most variation in a previous study that estimated bankfull channel characteristics by analyzing flow measurements at streamgages. Sites were selected at wadable streams in each of the planning regions across a gradient of drainage areas; a competing goal was for all sites to have

stable banks and readily identifiable bankfull features. Because not enough gaged sites were available to meet study goals in size, location, and stability, ungaged sites were added and a slope-area measurement was made of a bankfull or near-bankfull peak. High-water-mark profiles were surveyed at all sites. At ungaged sites, they were used in the slope-area measurement; at gaged sites, they were used to calculate roughness, which in turn was used with the measured slope to determine bankfull flow.

Longitudinal profiles were surveyed through a stream-reach length of at least 20 bankfull widths and were composed of two or more riffle-pool sequences. All profiles included thalwegs, water surface, plausible bankfull features, and highwater marks. All cross sections were surveyed in riffles. At least two cross sections were surveyed at gaged sites. These cross sections were extended to an elevation of twice the maximum depth relative to the highest plausible bankfull feature. At ungaged sites, additional cross sections were surveyed at all substantial changes in the slope of the high-water profile.

The high-water-mark profiles were used to supplement or, at most sites, replace the use of channel characteristics estimated from flow measurements at streamgages as a means of choosing among plausible bankfull features at the same station. The frequency of peak flow at ungaged sites was initially estimated by comparison to flow at index streamgages, taking into account local differences in precipitation. The elevation of the high-water mark was then compared to the elevation of the presumptive bankfull feature. All bankfull features surveyed in this study were described and sketched in field notes.

At gaged sites, bankfull flows ranged from less than the 1.1-year peak flow to greater than the 2.0-year peak flow. Regression lines developed for peak flows of wadable (less than 240 mi²) streams at frequencies ranging from 1.2 to 1.7 years were all within the 99-percent confidence interval of the regression line for bankfull flow. The closest match to the regression equation for bankfull flows was the equation for the 1.4-year peak flow. Drainage area explained slightly more of the variation for bankfull flows ($R^2 = 0.9592$) than it did for 1.5-year flows measured at streamgages on wadable streams (less than 240 mi²; $R^2 = 0.9326$).

An R² value of 0.9768 for bankfull area and of 0.9592 for bankfull flow indicates that little additional variation can be explained by subdividing the study area by region, stream type, geology, or other characteristics. As is typical, the relation between bankfull width and drainage area varied slightly more than those between drainage area and bankfull flow and drainage area and bankfull area. The relation between depth and drainage area varied more than the other bankfull characteristics determined in this study.

Reach slopes ranged from 0.0004 ft/ft (West Fork Little Kanawha River near Rocksdale) to 0.0544 ft/ft (Barrenshe Run near Woodbine). Generally, mountain streams are expected to be steeper than lowland streams, and headwater streams are expected to be steeper than higher-order streams, although in this study, both of these generalizations had exceptions.

Comparisons with regional curves developed in this study with those from previous studies and surrounding areas showed general consistency. Channel dimensions for the 1.5-year flow were determined from current-meter flow measurements made at streamgages in the Appalachian Plateaus of West Virginia, to provide an estimate of bankfull dimensions. The regression line from these estimates for bankfull area fell within the 99-percent confidence interval of the regional curve for bankfull area for drainage areas less than about 10 mi². Cross-sectional area for the 1.5-year flow at streamgages was smaller than bankfull area for the smallest drainage areas considered, but larger for the larger drainage areas, with the greatest difference at the largest drainage areas. Width at the 1.5-year flow at streamgages was slightly less than bankfull width, but the regression line for the estimate fell within the 99-percent confidence interval for the regression line for bankfull width. Depth at the 1.5-year flow at streamgages was significantly greater than bankfull depth, likely because, at most sites, high-flow current-meter measurements are made in pools.

The regression lines for bankfull flow, area, and depth from the Valley and Ridge in Maryland, Virginia, and West Virginia fell outside the 99-percent confidence interval of regression lines for the Appalachian Plateaus in West Virginia. Channel dimensions at the 1.5-year flow at streamgages in West Virginia had also been significantly different between the Valley and Ridge and Appalachian Plateaus Provinces. When the Valley and Ridge was originally studied, arbitrary regional boundaries were set at the physiographic province boundaries. Although some ambiguity remains as to the precise location of the regional boundary in the Greenbrier River Basin in West Virginia, the present study did not find compelling evidence to redraw the existing regional boundary.

Streams in the part of Pennsylvania outside the Coastal Plain were generally less wide, less deep, and their bankfull flow and area were somewhat smaller than in the Appalachian Plateaus of West Virginia. The parts of the regression lines for bankfull characteristics representing small streams in Pennsylvania fall below the 99-percent confidence interval of the regression lines for the Appalachian Plateaus in West Virginia. Regional curves for bankfull flow, area, width, and depth for Pennsylvania are all intermediate between those for the Appalachian Plateaus in West Virginia and the Valley and Ridge for Maryland, Virginia, and West Virginia. The Pennsylvania curves represent large sections of the Appalachian Plateaus and Valley and Ridge Physiographic Provinces.

Ohio streams are generally deeper and narrower than streams in the Appalachian Plateaus in West Virginia. Bankfull area of wadable streams is about the same in West Virginia and Ohio; the Ohio Region A regression line is within the 99-percent confidence interval for the West Virginia regression line between about 3 and 200 mi², the lines cross at about 20 mi², and the two lines diverge with greater drainage areas. The divergence of the West Virginia and Ohio regression lines for bankfull flow is greater than for bankfull area.

Acknowledgments

James D. Scott of the USGS West Virginia Water Science Center was instrumental in completing field work for this study. The study was designed following discussions with Jefferson N. Keaton, then of the USGS Virginia Water Science Center, and after Douglas B. Chambers of the USGS West Virginia Water Science Center helped the author survey a reach in a previous study, shortly after a bankfull peak flow. Edward J. Doheny of the USGS Maryland Water Science Center and Jennifer L. Krstolic of the USGS Virginia Water Science Center reviewed the report and provided helpful comments.

References Cited

- Barnes, H.H., 1967, Roughness characteristics of natural channels: U.S. Geological Survey Water-Supply Paper 1849, 213 p.
- Bernhardt, E.S., 2006, National river restoration science synthesis (NRRSS) statistics page for all node areas, accessed November 18, 2009, at http://nrrss.nbii.gov/info/statistics.html.
- Bernhardt, E. S., Palmer, M. A., Allan, J. D., Alexander,
 G., Barnas, K., Brooks, S., Carr, J., Clayton, S., Dahm,
 C., Follstad-Shah, J., Galat, D., Gloss, S., Goodwin, P.,
 Hart, D., Hassett, B., Jenkinson, R., Katz, S., Kondolf, G.
 M., Lake, P. S., Lave, R., Meyer, J. L., O'Donnell, T. K.,
 Pagano, L., Powell, B., and Sudduth, E., 2005, Synthesizing U.S. river restoration efforts: Science, v. 308. no. 5722,
 p. 636–637.
- Chaplin, J.J., 2005, Development of regional curves relating bankfull-channel geometry and discharge to drainage area for streams in Pennsylvania and selected areas of Maryland: U.S. Geological Survey Scientific Investigations Report 2005–5147, 34 p.
- Dalrymple, T., and Benson, M.A., 1967, Measurement of peak discharge by the slope-area method: U.S. Geological Survey Techniques of Water-Resources Investigations, book 3, chapter A2.
- Dunne, T., and Leopold, L.B., 1978, Water in environmental planning: New York, W.H. Freeman and Company, 818 p.
- Fenneman, N.M., 1938, Physiography of Eastern United States: New York, McGraw-Hill, 714 p.
- Fenneman, N.M., and Johnson, D.W., 1946, Physical divisions of the United States: U.S. Geological Survey Physiography Committee Special Map, scale 1:7,000,000.
- Fulford, J.M., 1994, User's guide to SAC, a computer program for computing discharge by slope-area method: U.S. Geological Survey Open-File Report 94-360.

- Hydrometeorological Design Studies Center, 2006a, Isopluvials of 60 minute precipitation (inches) with average recurrence interval of 2 years, Delaware, District of Columbia, Maryland, New Jersey, Ohio, Pennsylvania, West Virginia: National Oceanic and Atmospheric Administration Atlas 14, Volume 2, Version 3, Ohio River Basin and Surrounding States, accessed November 18, 2009, at http://hdsc.nws.noaa.gov/hdsc/pfds/pfds maps.html.
- Hydrometeorological Design Studies Center, 2006b, Isopluvials of 60 minute precipitation (inches) with average recurrence interval of 2 years, Illinois, Indiana, Ohio: National Oceanic and Atmospheric Administration Atlas 14, Volume 2, Version 3, Ohio River Basin and Surrounding States, accessed November 18, 2009, at http://hdsc.nws.noaa.gov/hdsc/pfds/pfds maps.html.
- Jarrett, R.D., 1984, Hydraulics of high-gradient streams: Journal of Hydraulic Engineering, v. 110, no. 11, p. 1519–1539.
- Keaton, J.N., Messinger, T., and Doheny, E.J., 2005, Development and analysis of regional curves for streams in the non-urban Valley and Ridge Physiographic Province, Maryland, Virginia, and West Virginia: U.S. Geological Survey Scientific Investigations Report 2005–5076, 116 p.
- Leopold, L.B., 1994, A view of the river: Cambridge, MA, Harvard University Press, 298 p.
- Leopold, L.B., Wolman, M.G., and Miller, J.P., 1964, Fluvial processes in geomorphology: New York, Dover Publications, 522 p.
- Limerinos, J.T., 1970, Determination of the Manning coefficient from measured bed roughness in natural channels: U.S. Geological Survey Water-Supply Paper 1898-B, 47 p.
- Messinger, Terence, and Hughes, C.A., 2000, Environmental setting and its relations to water quality in the Kanawha River Basin: U.S. Geological Survey Water-Resources Investigations Report 00-4020, 57 p.
- Messinger, Terence, and Wiley, J.B., 2004, Regional relations in bankfull channel characteristics at selected stream-gaging stations in West Virginia, 1911-2002: U.S. Geological Survey Water-Resources Investigations Report 03-4276, 43 p.
- Rantz, S.E., and others, 1982, Measurement and computation of streamflow—Volume 1. Measurement of stage and discharge; Volume 2. Computation of discharge: U.S. Geological Survey Water-Supply Paper 2175, 631 p.
- Roper, B., Buffington, J.M., Archer, E., Moyer, C., and Ward,
 M., 2008, The role of observer variation in determining
 Rosgen stream types in northeastern Oregon mountain
 streams: Journal of American Water Resources Association,
 v. 44, no. 2, p. 417–427.

- Rosgen, D. L., 1985, A stream classification system: Riparian Ecosystems and their Management: Proceedings of the First North American Riparian Conference, April 16–18, Tucson, Arizona, USDA Forest Service General Technical Report No. RM-120, p. 91–95.
- Rosgen, D.L., 1996, Applied river morphology: Pagosa Springs, CO, Wildland Hydrology, variously paged.
- Sherwood, J.M., and Huitger, C.A., 2005, Bankfull characteristics of Ohio streams and their relation to peak streamflows: U.S. Geological Survey Scientific Investigations Report 2005–5153, 38 p.
- U.S. Army Corps of Engineers, 2009, HEC-RAS, accessed November 18, 2009, at http://www.hec.usace.army.mil/software/hec-ras/.
- U.S. Census Bureau, 2009, West Virginia quick facts, accessed November 18, 2009, at http://quickfacts.census.gov/qfd/states/54000.html.
- U.S. Census Bureau, 2001, 2000 Incorporated Places/Census Designated Places, accessed November 18, 2009, at http://www.census.gov/geo/www/cob/pl2000.html.
- US Department of Commerce, 1960, Climate of the States, West Virginia: Weather Bureau, Climatography of the U.S., no. 60-46, 15 p.
- U.S. Geological Survey, 2006, National Atlas of the United States, State Boundaries of the United States, accessed November 18, 2009, at http://nationalatlas.gov/atlasftp.html.
- U.S. Geological Survey, 1999, National Elevation Dataset, accessed November 18, 2009, at http://ned.usgs.gov/.
- U.S. Geological Survey, 1991, 1:2,000,000-scale Digital Line Graph files of streams, accessed November 18, 2009, at http://water.usgs.gov/lookup/getspatial?stream.
- West Virginia Department of Environmental Protection, 2005, Updated list of waters of special concern being proposed for tier 2.5 anti-degradation protection status, accessed November 18, 2009, at http://www.wvdep.org/dwwm/antideg/new4web.htm.
- Wiley, J.B., Atkins, J.T., and Newell, D.A., 2002, Estimating the magnitude of annual peak discharges with recurrence intervals between 1.1 and 3.0 years for rural, unregulated streams in West Virginia: U.S. Geological Survey Water-Resources Investigations Report 02-4164, 73 p.
- Wolf, P.R., and Ghilani, C.D., 2002, Elementary surveying—an introduction to geomatics: Upper Saddle River, NJ, Prentice-Hall, 900 p.

Tables 2 and 4

Table 2. Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia.

Site	XS	Description of bankfull feature	D84 (ft)	D50 (ft)	n
Anglins Creek near Nallen	XS1	Very distinct, rounded convex slope change from apparent FP to bank. Good.	0.02	0.02	0.055
	XS2	Very distinct. Convex slope change on bank, sloughing slightly	0.24	0.05	0.032
Anthony Creek near Anthony	XS1	RBF1	1.18	0.42	0.020
	XS2	LBF	1.28	0.75	0.018
Barrenshe Run near Woodbine	XS1	Edge of boulder aligned w. other boulders in a clear line parallel to the stream. Poor, because the extremely coarse substrate here won't sort out into a fine-detail feature. However, the overall feature is distinct.	nd	nd	0.149
	XS2	ш	1.40	0.64	
	XS4	u	2.73	0.78	0.038
Big Draft near Anthony	XS1	LBF, subtle slope change, edge topsoil, fair.	nd	nd	0.065
	XS2	LBF, subtle slope change, edge topsoil, fair.	1.45	0.48	0.100
	XS3	Distinct, rounded convex slope change from FP to bar. Change of substrate, edge of moss. Good.	nd	nd	0.112
	XS5	Very distinct, rounded convex slope change. Edge of topsoil, vegetation change. Excellent	1.00	0.38	0.041
	XS6	Distinct convex slope change, held in place by roots. Still at the change in substrate and vegetative cover.	nd	nd	0.070
Big Sandy Creek near Rockville	XS1	Very distinct, stable convex slope change. Most distinct slope change. Excellent.	>6.00	2.14	0.045
	XS2	Most distinct convex slope change, from FP to bar. Good.	>6.00	1.44	0.042
Blackwater River at Davis	XS1	Very distinct, rounded convex slope change, from apparent FP to steeply sloping bank. Fair.	1.66	0.60	0.031
	XS2	RBF2. Distinct convex slope change from FP to bank. Good.	>6.00	1.83	0.029
Buck Run at Leopold	XS1	LBF	0.16	0.09	0.049
	XS2	LBF	0.37	0.15	0.073
Camp Creek near Camp Creek	XS1	Fair. Rounded but still distinct convex slope change from FP to bank	0.67	0.34	0.035
	XS2	Determined graphically, in office	1.70	0.75	0.029
Clear Fork at Clear Fork	XS1	RBF. Convex slope change.	nd	nd	0.050
	XS2	Possible berm or RBF. Convex slope change.	nd	nd	0.016
Cranberry River near Richwood	XS1	Lumpy, convex slope change from shelf to bank. Edge of topsoil. Good.	>6.00	0.89	0.065
	XS2	Edge of topsoil, collected among jagged, poorly eroded, rocks. Convex slope change. Fair.	2.12	0.51	0.074
East Fork Twelvepole Creek	XS1	Very distinct convex slope change from FP to bank. Good.	0.27	0.18	0.028
near Dunlow	XS2	Convex slope change, fair.	0.72	0.19	0.024
Goose Creek below Petroleum	XS1	Top of bank. Very distinct, rounded convex slope change from FP to bank. Weedy, topsoil/clay. Good.	0.94	0.30	0.024
	XS2	RBF, top of bank, distinct rounded convex slope change. Good.	0.96	0.29	0.042

Table 2. Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia.—Continued

Site	XS	Description of bankfull feature	D84 (ft)	D50 (ft)	n
Hurricane Branch at Panther SF	XS1	Determined graphically, in office	nd	nd	0.033
	XS2	Determined graphically, in office	nd	nd	0.023
	XS3	Determined graphically, in office	nd	nd	0.037
	XS4	Poor. Distinct convex slope change from poorly defined FP to extremely steep bank, recovering from being undercut.	nd	nd	0.042
	XS6	LBF	nd	nd	0.086
Kings Creek at Weirton	XS1	Top of bank. Very distinct, stable, convex slope change. Most distinct feature. Good	0.86	0.43	0.023
	XS2	Top of bank. Most distinct, stable of the features. Good	BR	BR	0.059
	XS3	Top of bank, only distinct feature. Good	nd	nd	0.042
	XS4	Most distinct feature of XS. Good	nd	nd	0.044
	XS5	Distinct but gradual, stable convex slope change from FP to bank. Good. Most distinct feature.	nd	nd	0.030
Knob Creek near Wade	XS1	RBF. Subtle, convex slope change. Near edge of moss. Poor	nd	nd	0.079
	XS2	A break in the bedrock ledge. Edge of very thin topsoil. Extremely poor.	>6.00	0.36	0.067
	XS3	Most distinct of several convex slope changes. Edge of grass. Fair.	nd	nd	0.050
	XS4	Lumpy; convex slope change in soil. Poor.	nd	nd	0.042
	XS5	Rounded, convex slope change. Fair.	0.87	0.30	
	XS7	Indistinct convex slope change. Poor.	nd	nd	0.056
	XS8	Fairly distinct, gradual, convex slope change. Fair.	nd	nd	0.048
Laurel Fork near Hacker Valley	XS1	Bank top. Abrupt slope change from FP to bank; some slumping. Lower of the two banks.	nd	nd	0.067
	XS2	Very distinct convex slope change in cobble/boulder bar. Continuous. Good.	nd	nd	0.049
	XS4	Very distinct convex slope change in cobble/boulder bar. Continuous. Good.	0.84	0.45	0.058
	XS5	RBF. Very distinct, gently rounded convex slope change from FP to bank. Good.	nd	nd	0.063
	XS6	Convex slope change.	0.81	0.29	0.067
Left Fork Clover Run near St.	XS1	Most distinct slope change, from FP to apparent bank.	nd	nd	0.054
George	XS2	Fairly distinct convex slope change; at edge of tree line; part of nice continuous line clearly visible from across stream. Fair.	nd	nd	0.040
	XS3	Rounded, mossy. Just above high-water mark. Fair.	0.58	0.28	0.048
	XS4	Top of bank.	nd	nd	0.048
	XS5	Top of bank. Most distinct convex slope change.	0.60	0.32	0.042
Little Kanawha River near	XS1	RBF. Convex slope change on a complex bank. Fair.	0.68	0.27	0.039
Wildcat	XS2	LBF. Convex slope change on a complex bank. Fair.	0.48	0.33	0.036

Table 2. Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia.—Continued

Site	XS	Description of bankfull feature	D84 (ft)	D50 (ft)	n
Manilla Creek at Amherst- Plymouth WMA	XS1	Sketch, field notes show this as berm. Lower of 2 convex slope changes.	nd	nd	0.048
	XS2	Sketch, field notes show this as berm. Lower of 2 convex slope changes.	nd	nd	0.037
	XS3	Sketch, field notes show this as berm. Lower of 2 convex slope changes.	nd	nd	0.049
	XS4	Determined graphically, in office.	nd	nd	0.051
Marsh Fork of Mash Fork at	XS1	Determined graphically, in office.	1.35	0.35	0.077
Camp Creek SF	XS3	Determined graphically, in office.	nd	nd	0.081
	XS4	Good. Convex slope change from FP to bank. Change of substrate, soil to rock.	nd	nd	0.080
	XS5	Fair. Convex slope change at edge of a very narrow FP.	0.72	0.41	0.105
	XS6	Determined graphically, in office.	nd	nd	0.123
	XS7	Determined graphically, in office.	nd	nd	0.095
Middle Fork at Audra	XS1	Between HWM3 & 4. Distinct, rounded convex slope change held by large hemlock root. Fair.	5.08	1.92	0.042
	XS2	Edge of boulder. Effective LBF; some boulders to its left	>6.00	2.65	0.047
Morgan Run near Cheat Lake	XS1	Distinct, stable-looking convex slope change, anchored by roots. Fair.	BR	BR	0.047
	XS2	Very distinct, stable-looking convex slope change from gently sloping to very steep. Rocky bank, with accumulated topsoil. Good.	nd	nd	0.047
	XS3	Very distinct, stable convex slope change from FP to bank. Excellent.	nd	nd	0.078
	XS5	Mossy topsoil accumulated on huge boulder; convex slope change. Good.	nd	nd	0.115
	XS6	Distinct convex slope change from FP to bank. Good. More gradual than downstream; looks very stable.	nd	nd	0.087
	XS7	Gradual, stable convex slope change. Good.	1.01	0.44	0.057
North Fork Cherry River near	XS1	Fair at best. High point on bar.	nd	nd	0.055
Richwood	XS2	Distinct, rounded convex slope change; edge of soil. Mossy. Fair.	nd	nd	0.091
	XS3	Distinct convex slope change. Mossy soil. Good	nd	nd	0.067
	XS4	Distinct, rounded slope change. Mossy soil. Good	nd	nd	0.072
	XS5	Distinct, rounded slope change. Mossy soil. Good	nd	nd	0.070
	XS6	Very poor. Convex slope change, thin layer of mossy dirt on a boulder in outside of bend.	nd	nd	0.074
	XS7	Rounded, edge of soil. Fair.	nd	nd	0.128
Panther Creek near Panther	XS1	Convex slope change. Poor. Determined from plot.	nd	nd	0.037
	XS2	Edge of topsoil. Poor	2.43	0.85	0.035
	XS3	Subtle convex slope change on a gently sloping bank. Fair	1.54	0.55	0.043

Table 2. Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia.—Continued

Site	xs	Description of bankfull feature	D84 (ft)	D50 (ft)	n
Payne Branch near Oakvale	XS1	RBF. Convex slope change, fair	1.38	0.80	0.057
	XS2	RBF. Convex slope change, fair	nd	nd	0.083
	XS3	Rounded, gradual but distinct convex slope change at top of the bank. Fair.	nd	nd	0.054
	XS4	Rounded, gradual but distinct convex slope change at top of the bank. Fair.	nd	nd	0.067
	XS5	Rounded, gradual but distinct convex slope change at top of the bank. Fair.	nd	nd	0.064
	XS6	Convex slope change. Poor. Determined from plot.	0.98	0.47	0.044
Piney Creek near McCreery	XS1	Change of substrate. Poor.	nd	nd	0.068
	XS2	Convex slope change. Poor. Determined from plot.	nd	nd	0.057
	XS3	Edge of pointy, entrained boulder. Boulder tops form an acceptable line. Fair. One of the best features in this reach.	nd	nd	0.091
	XS4	Edge of apparent terrace. Most distinct of several convex slope changes.	nd	nd	0.063
	XS5	Top of boulder. Part of a line, fairly distinct, along right bank. Boulder has an exceptionally distinct convex slope change at this point, appears to be shaped by water. Poor.	nd	nd	0.060
Polly Hollow at Kanawha SF	XS1	Lower of two convex slope changes. LBF? berm? Most distinct feature on left side.	0.50	0.17	0.119
	XS2	RBF. Good. Distinct change in slope at edge of FP	0.76	0.21	0.105
	XS3	LBF, edge of topsoil, convex slope change, fair.	nd	nd	0.091
	XS4	LBF, very distinct convex slope change anchored by tree roots. Good.	nd	nd	0.151
	XS5	Convex slope change. Poor. Determined from plot.	nd	nd	0.101
	XS6	Convex slope change. Poor. Determined from plot.	nd	nd	0.095
	XS7	Fair at best cobble at edge of gravelly soil.	nd	nd	0.104
Rock Creek near Danville	XS1	Abrupt convex slope change from FP to bank. Poor.	0.40	0.26	0.049
	XS2	Rounded convex slope change from FP to bank. Good.	0.47	0.21	0.052
Sand Run near Buckhannon	XS1	RBF. One of several convex slope changes, below the top of bank. Fair.	0.55	0.33	0.038
	XS2	LBF. Convex slope change. Fair.	0.70	0.36	0.039
Second Creek near Second	XS1	Good. Very clear, distinct convex slope change between bank and FP.	0.65	0.35	0.027
Creek	XS2	Good. Distinct convex slope change from FP to bank.	0.99	0.48	0.029
Spruce Fork at Cabwaylingo SF	XS1	RBF. Fair. Very distinct change in slope; edge of soil on a small over- hanging rock shelf.	nd	nd	0.057
	XS2	Distinct convex slope change on bank. Continuous. Good.	nd	nd	0.052
	XS3	Convex slope change. Fair.	nd	nd	0.098
	XS4	RBF. Convex slope change. Fair.	nd	nd	0.076
	XS5	Top of bank. Distinct convex slope change. Good.	nd	nd	0.084
	XS6	Top of bank. Distinct convex slope change. Good.	nd	nd	0.054

Table 2. Description of bankfull features, sediment particle size, and Manning's roughness coefficient for stream cross sections in the Appalachian Plateaus Physiographic Province, West Virginia.—Continued

Site	XS	Description of bankfull feature	D84 (ft)	D50 (ft)	n
Unnamed Tributary to Hughes River	XS1	RBF. Very distinct, rounded convex slope change from FP to bank. Good.	nd	nd	0.067
	XS2	LBF. Very distinct convex slope change from FP to bar. Good. High?	nd	nd	0.065
	XS3	LBF. Very distinct convex slope change from FP to bar. Good. High?	nd	nd	0.066
	XS4	LBF. Very distinct convex slope change from FP to bar. Good. High?	0.27	0.14	0.129
	XS5	Distinct, rounded convex slope change at edge of FP. Good.	0.44	0.23	0.058
Upper Nineteenmile Creek at	XS1	Lowest convex slope change. Poor. Determined from plot.	0.23	0.14	0.057
Chief Cornstalk WMA	XS2	Lowest convex slope change. Poor. Determined from plot.	0.26	0.13	0.047
	XS3	LBF or berm. Convex slope change. Lowest distinct feature	nd	nd	0.085
	XS4	Lowest convex slope change. Poor. Determined from plot.	nd	nd	0.100
	XS5	Distinct convex slope change. Mossy dirt; obvious fluvial sand below. Good.	nd	nd	0.123
	XS6	Lowest convex slope change. Poor. Determined from plot.	nd	nd	0.066
West Fork Greenbrier River above Durbin	XS1	Very distinct, formerly eroded convex slope change from FP to bank. Very mossy, rounded, anchored by roots. Good.	nd	nd	0.046
	XS2	Lower inflection of a wide, gradual convex slope change from FP to bank. Good.	0.94	0.61	0.033
	XS3	Very distinct, rounded, convex slope change from FP to bank, just above apparent bar. Good.	nd	nd	0.046
	XS4	Very distinct, rounded, convex slope change from FP to bank, just above apparent bar. Good.	nd	nd	0.046
	XS5	Bermish, lumpy soil, moss-covered; convex slope change, fairly distinct. Fair.	nd	nd	0.057
	XS6	Rounded, convex slope change from FP to bank. Held by roots, topsoil. Good.	1.35	0.69	0.066
	XS7	Most distinct, and lower, inflection in a gradual convex slope change. Fair.	nd	nd	0.044
	XS8	Convex slope change. Fair.	nd	nd	0.055
West Fork Little Kanawha River near Rocksdale	XS1	Top of bank. Sharp convex slope change from FP to steeply sloping bank. Old slump that has weeded up and stabilized. Fair	0.35	0.16	0.039
	XS2	Top of bank. Very distinct, rounded. Good.	0.36	0.10	0.040
Williams River at Dyer	XS1	Rounded convex slope change on lower bank, anchored by roots. Field-identified as berm. Fair.	6.00	2.61	0.035
	XS2	Rounded convex slope change on lower bank. Field-identified as berm. Fair.	1.09	0.29	0.055
	XS3	Edge of FP; level for long way. Inside of bend.	nd	nd	0.039
Yellow Creek near Davis	XS1	Convex slope change at edge of FP. Some sloughing. Poor.	1.27	0.27	0.081
	XS2	LBF, Lower of two convex slope changes. Fair.	nd	nd	0.080
	XS3	RBF. Convex slope change. Fair.	0.95	0.12	0.113
	XS4	Convex slope change at edge of FP. Good.	nd	nd	0.047
	XS5	LBF. Distinct convex slope change. Good.	nd	nd	0.048

Table 4. Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia.

l and	
surveye	
ections were	Width-
ned. Some cross se	Flood-prone Width-
a; nd, not determi s table.]	Bankfull
nagement Area itted from this	
, Wildlife Mar ections are om	Wetted
e Forest; WMA t; these cross so	Bankfull
Park; SF, Statess were presen	Bankfull
[XS, cross-section number; ft, feet; ft², square feet; ft³/s, cubic feet per second; SP, State Park; SF, State Forest; WMA, Wildlife Management Area; nd, not determined. Some cross sections were surveyed and numbered for the slope-area flow measurements although no identifiable bankfull features were present; these cross sections are omitted from this table.]	Bankfull Bankfull Wetted

		Bankfull	Bankfull	Bankfull	Wetted	i	Bankfull	Flood-prone	Width-	
Site	×	area (ft²)	width (ft)	mean depth (ft)	perimeter (ft)	Flow (ft³/s)	maximum depth (ft)	width (ft)	depth ratio	Entrench- ment ratio
Anglins Creek near Nallen	XS1	287	62.0	4.63	64.4	669	6.77	173	13.4	2.8
	XS2	246	55.4	4.44	9.09	963	5.86	168	12.5	3.0
Anthony Creek near Anthony	XS1	551	120	4.60	124	5,420	6.94	194	26.0	1.6
	XS2	699	152	4.41	155	7,030	8.87	345	34.4	2.3
Barrenshe Run near Woodbine	XS1	57.2	29.1	1.97	32.5	195	3.05	40	14.8	1.4
	XS2	46.0	27.1	1.70	31.5	166	2.94	47	16.0	1.7
	XS4	32.9	27.8	1.18	31.0	pu	2.40	<i>L</i> 9	23.4	2.4
Big Draft near Anthony	XS1	27.8	31.4	0.88	33.7	94.0	1.78	43	35.5	1.4
	XS2	41.2	45.4	0.91	47.7	94.0	2.05	52	50.1	1.2
	XS3	33.8	26.1	1.30	32.7	77.4	2.26	54	20.1	2.1
	XS5	9.99	32.1	1.77	33.9	482	2.68	53	18.2	1.6
	9SX	59.0	35.6	1.66	39.3	pu	2.40	46	21.5	1.3
Big Sandy Creek near Rockville	XS1	909	123	4.94	127	4,770	7.85	206	24.9	1.7
	XS2	1,136	206	5.51	221	10,100	9.78	239	37.4	1.2
Blackwater River at Davis	XS1	347	7.66	3.48	104	1,220	5.09	134	28.6	1.3
	XS2	434	89.7	4.84	94.3	2,040	7.18	248	18.5	2.8
Buck Run at Leopold	XS1	53.6	33.8	1.59	35.3	147	2.51	109	21.3	3.2
	XS2	40.1	37.8	1.06	40.4	56.1	2.71	51	35.6	1.4
Camp Creek near Camp Creek	XS1	301	99.5	3.03	103	2,210	5.95	361	32.9	3.6
	XS2	268	80.7	3.32	95.3	2,320	6.20	168	24.3	2.1
Clear Fork at Clear Fork	XS1	787	123	6.38	127	4,040	09.6	197	19.4	1.6
	XS2	377	97.1	3.88	9.66	4,470	5.82	144	25.0	1.5
Cranberry River near Richwood	XS1	430	112	3.84	121	2,070	6.47	154	29.1	1.4
	XS2	349	105	3.34	108	1,380	4.85	144	31.3	1.4
East Fork Twelvepole Creek near Dunlow	XS1	229	68.1	3.36	9.07	826	5.42	118	20.3	1.7
	XS2	247	6.79	3.64	72.1	1,100	5.89	129	18.7	1.9
Goose Creek near Petroleum	XS1	421	79.9	5.26	84.3	3,080	6.85	154	15.2	1.9
	XS2	388	9.92	5.06	81.9	1,580	6.62	130	15.1	1.7

[XS, cross-section number; ft, feet; ft², square feet; ft²/s, cubic feet per second; SP, State Park; SF, State Forest; WMA, Wildlife Management Area; nd, not determined. Some cross sections were surveyed and numbered for the slope-area flow measurements although no identifiable bankfull features were present; these cross sections are omitted from this table.] Table 4. Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia.—Continued

Site	XX	Bankfull area (ft²)	Bankfull width (ft)	Bankfull mean depth (ft)	Wetted perimeter (ft)	Flow (ft³/s)	Bankfull maximum depth (ft)	Flood-prone width (ft)	Width- depth ratio	Entrench- ment ratio
Hurricane Branch at Panther SF	XS1	23.6	31.4	0.75	34.4	pu	1.83	38	41.6	1.2
	XS2	21.6	27.9	0.77	29.3	pu	2.11	44	36.1	1.6
	XS3	38.8	40.3	96.0	46.6	pu	1.67	39	41.7	1.0
	XS4	30.5	32.5	0.94	34.3	192	2.22	38	34.5	1.2
	9SX	58.9	29.2	2.02	31.1	296	3.56	50	14.5	1.7
Kings Creek at Weirton	XS1	345	95.9	3.60	100	3,270	5.17	290	26.6	3.0
	XS2	308	82.4	3.74	92.7	1,120	5.92	109	22.0	1.3
	XS3	365	98.2	3.72	102	1,950	6.15	pu	26.4	pu
	XS4	325	107	3.03	109	1,480	4.92	pu	35.5	pu
	XS5	286	9.88	3.22	89.7	1,970	4.00	182	27.5	2.0
Knob Creek near Wade	XS1	138	44.9	3.07	48.4	pu	3.97	pu	14.6	pu
	XS2	119	42.1	2.83	44.6	368	4.14	61	14.9	1.4
	XS3	0.06	43.1	2.09	44.7	307	2.92	55	20.7	1.3
	XS4	131	49.7	2.64	53.6	613	4.24	89	18.8	1.4
	XS5	151	59.4	2.55	9.09	pu	3.73	82	23.3	1.4
	XS7	132	53.9	2.45	55.4	449	3.11	88	22.0	1.6
	XS8	78.5	47.2	1.66	47.9	241	2.48	74	28.3	1.6
Laurel Fork near Hacker Valley	XS1	86.7	41.9	2.07	44.7	pu	3.24	pu	20.3	pu
	XS2	105	37.5	2.81	43.3	722	4.30	pu	13.3	pu
	XS4	105	66.4	1.59	8.69	448	3.77	124	41.8	1.9
	XS5	119	47.5	2.50	51.1	617	3.52	pu	19.0	pu
	9SX	97.4	63.6	1.53	68.4	pu	2.93	145	41.5	2.3
Left Fork Clover Run near St. George	XS1	232	58.1	3.99	62.7	pu	69:9	pu	14.6	pu
	XS2	129	51.3	2.51	59.7	604	3.77	pu	20.4	1.4
	XS3	161	68.5	2.35	74.5	629	4.03	212	29.1	3.1
	XS4	232	9.99	4.10	63.3	1,280	99.5	pu	13.8	pu
	XS5	258	78.7	3.29	88.3	pu	4.79	260	23.9	3.3
Little Kanawha River near Wildcat	XS1	622	133	4.70	135	3,040	69:9	220	28.2	1.7
	XS2	740	187	3.97	189	3,440	6.54	341	47.0	1.8

[XS, cross-section number; ft, feet; ft², square feet; ft²/s, cubic feet per second; SP, State Park; SF, State Forest; WMA, Wildlife Management Area; nd, not determined. Some cross sections were surveyed and numbered for the slope-area flow measurements although no identifiable bankfull features were present; these cross sections are omitted from this table.] Table 4. Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia.—Continued

Site	XS	Bankfull area (ft²)	Bankfull width (ft)	Bankfull mean depth (ft)	Wetted perimeter (ft)	Flow (ft³/s)	Bankfull maximum depth (ft)	Flood-prone width (ft)	Width- depth ratio	Entrench- ment ratio
Manilla Creek at Amherst-Plymouth WMA	XS1	120	45.2	2.66	49.0	pu	3.10	70	17.0	1.5
	XS2	107	45.7	2.34	47.8	367	3.37	69	9.61	1.5
	XS3	119	50.6	2.35	51.6	314	2.94	71	21.5	1.4
	XS4	139	45.5	3.06	47.1	413	3.74	89	14.8	1.5
Marsh Fork of Mash Fork at Camp Creek SF	XS1	30.8	25.6	1.20	27.6	pu	1.99	32	21.3	1.2
	XS3	31.2	30.3	1.03	32.0	100	1.63	37	29.4	1.2
	XS4	62.4	29.1	2.15	39.5	282	3.09	pu	13.5	pu
	XS5	44.2	31.3	1.41	36.1	129	2.25	43	22.2	1.4
	9SX	40.0	30.4	1.32	32.9	0.66	2.33	pu	23.0	pu
	XS7	35.3	28.8	1.22	35.1	0.66	2.01	pu	23.5	pu
Middle Fork at Audra	XS1	744	158	4.72	171	4,580	7.90	306	33.5	1.9
	XS2	545	137	3.98	152	2,620	8.12	212	34.4	1.5
Morgan Run near Cheat Lake	XS1	45.3	26.6	1.70	28.4	316	2.66	37	15.6	1.4
	XS2	41.9	22.5	1.86	26.8	285	3.01	41	12.1	1.8
	XS3	9.79	34.9	1.93	39.6	294	3.43	39	18.1	1.1
	XS5	24.5	22.8	1.07	24.2	51.3	1.60	26	21.2	1.1
	9SX	17.7	17.9	0.99	19.1	46.1	2.94	34	18.0	1.5
	XS7	20.7	19.3	1.07	20.1	pu	2.07	30	17.9	1.6
North Fork Cherry River near Richwood	XS1	62.5	40.1	1.56	44.2	171	3.34	58	25.7	1.4
	XS2	140	6.65	2.34	62.5	317	3.21	73	25.6	1.2
	XS3	235	71.0	3.31	72.7	917	4.40	80	21.5	1.1
	XS4	141	63.0	2.24	64.2	pu	3.55	82	28.1	1.3
	XS5	97.4	59.4	1.64	63.8	pu	2.08	84	36.2	1.4
	9SX	154	43.0	3.58	54.8	496	5.93	87	12.0	2.0
	XS7	147	63.8	2.30	8.89	226	3.44	87	27.8	1.4
Panther Creek near Panther	XS1	146	42.1	3.47	45.6	1,150	5.44	73	12.1	1.7
	XS2	162	51.4	3.15	57.9	1,220	5.34	74	16.3	1.4
	XS3	211	75.3	2.80	80.1	1,240	4.42	142	26.9	1.9

[XS, cross-section number; ft, feet; ft², square feet; ft²/s, cubic feet per second; SP, State Park; SF, State Forest; WMA, Wildlife Management Area; nd, not determined. Some cross sections were surveyed and numbered for the slope-area flow measurements although no identifiable bankfull features were present; these cross sections are omitted from this table.] Table 4. Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia.—Continued

Site	XX	Bankfull area (ft²)	Bankfull width (ft)	Bankfull mean depth (ft)	Wetted perimeter (ft)	Flow (ft³/s)	Bankfull maximum depth (ft)	Flood-prone width (ft)	Width- depth ratio	Entrench- ment ratio
Payne Branch near Oakvale	XS1	54.8	36.2	1.51	40.7	281	2.72	50	23.9	1.4
	XS2	60.3	34.7	1.74	38.2	236	3.23	pu	20.0	pu
	XS3	8.65	42.2	1.42	53.0	290	2.80	50	29.8	1.2
	XS4	72.0	52.5	1.37	55.4	306	3.37	pu	38.3	pu
	XS5	48.6	25.9	1.87	26.6	272	3.03	99	13.9	2.2
	9SX	70.9	35.5	2.00	38.8	572	3.49	pu	17.8	pu
Piney Creek near McCreery	XS1	710	162	4.39	173	4,990	8.22	224	36.9	1.4
	XS2	431	113	3.81	127	pu	8.01	pu	29.8	pu
	XS3	478	140	3.42	144	pu	6.92	202	40.9	1.4
	XS4	788	131	5.99	154	6,930	8.03	pu	22.0	pu
	XS5	378	107	3.53	114	2,620	6.93	127	30.3	1.2
Polly Hollow at Kanawha SF	XS1	16.2	16.9	96.0	17.4	pu	1.39	30	17.7	1.8
	XS2	20.4	12.7	1.60	14.4	pu	2.01	120	7.9	9.4
	XS3	14.1	14.8	0.95	15.8	38.0	1.33	21	15.6	1.4
	XS4	17.5	12.2	1.44	12.6	38.0	2.02	pu	8.5	pu
	XS5	9.54	10.3	0.93	12.0	21.4	1.72	14	11.0	1.3
	9SX	11.5	12.1	0.94	13.3	28.8	1.60	pu	12.8	pu
	XS7	80.9	7.93	0.77	10.5	pu	1.60	14	10.3	1.7
Rock Creek near Danville	XS1	174	41.0	4.25	42.6	839	5.37	213	9.6	5.2
	XS2	149	41.8	3.57	44.7	969	4.85	80	11.7	1.9
Sand Run near Buckhannon	XS1	80.7	42.0	1.92	45.5	353	2.53	132	21.8	3.1
	XS2	103	53.6	1.92	55.4	448	3.51	243	27.9	4.5
Second Creek near Second Creek	XS1	443	144	3.08	147	3,630	6.11	554	46.6	3.9
	XS2	230	85.1	2.70	86.7	1,600	3.80	354	31.5	4.2
Spruce Fork at Cabwaylingo SF	XS1	28.5	19.6	1.45	22.3	105	2.17	26	13.6	1.3
	XS2	31.7	24.6	1.29	25.4	128	2.03	34	19.1	1.4
	XS3	26.1	19.2	1.36	20.3	pu	2.37	pu	14.1	pu
	XS4	20.2	18.3	1.10	19.4	49.4	1.68	pu	16.5	pu
	XS5	29.1	9.61	1.49	28.5	63.8	2.11	pu	13.1	pu
	9SX	19.6	17.2	1.14	17.3	71.2	1.86	pu	15.1	pu

[XS, cross-section number; ft, feet; ft², square feet; ft²/s, cubic feet per second; SP, State Park; SF, State Forest; WMA, Wildlife Management Area; nd, not determined. Some cross sections were surveyed and numbered for the slope-area flow measurements although no identifiable bankfull features were present; these cross sections are omitted from this table.] Table 4. Bankfull dimensions and other characteristics of stream cross sections in the Appalachian Plateaus Physiographic Province in West Virginia.—Continued

Unnamed Tributary to Hughes River	SX	area (ft²)	width (ft)	Bankfull mean depth (ft)	Wetted perimeter (ft)	Flow (ft³/s)	maximum depth (ft)	Flood-prone width (ft)	Width- depth ratio	Entrench- ment ratio
	XS1	18.2	19.4	0.94	20.9	44.0	1.67	pu	20.7	pu
^	XS2	24.6	19.1	1.29	20.0	9.77	1.92	pu	14.9	pu
^	XS3	19.4	22.9	0.85	23.6	46.1	1.58	pu	26.9	pu
^	XS4	28.1	35.5	0.79	36.9	32.5	1.59	52	44.9	3.0
^	XS5	12.2	20.6	0.59	21.2	pu	0.91	26	34.7	1.3
Upper Nineteenmile Creek at Chief Cornstalk WMA	XS1	29.6	19.5	1.52	20.8	pu	2.26	33	12.9	1.7
^	XS2	14.7	14.7	1.00	14.9	43.4	1.75	36	14.7	2.4
^	XS3	43.3	25.3	1.72	25.9	99.3	2.10	50	14.7	2.0
^	XS4	21.9	25.1	0.87	25.6	27.5	2.33	36	28.7	1.4
^	XS5	23.3	22.4	1.04	23.2	pu	1.62	26	21.5	1.1
*	9SX	12.0	11.9	1.00	13.3	23.4	1.79	18	11.9	1.5
West Fork Greenbrier River above Durbin	XS1	179	65.7	2.72	9.89	pu	3.76	pu	24.2	pu
^	XS2	195	70.9	2.75	9.77	pu	3.89	139	25.7	2.0
^	XS3	242	96.5	2.51	102	pu	4.57	111	38.5	1.1
	XS4	262	100	2.62	102	1,050	4.14	114	38.3	1.1
^	XS5	122	71.2	1.71	73.1	294	2.42	95	41.6	1.3
^	9SX	279	9.97	3.64	79.2	pu	5.66	96	21.0	1.2
^	XS7	175	61.4	2.85	63.8	692	4.83	71	21.5	1.2
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	XS8	213	8.95	3.75	58.5	pu	6.58	pu	15.2	pu
West Fork Little Kanawha River near Rocksdale	XS1	1,372	152	00.6	158	4,370	11.80	396	16.9	2.6
\(\)	XS2	1,453	156	9.33	162	4,660	13.70	362	16.7	2.3
Williams River at Dyer	XS1	722	141	5.12	147	4,150	7.30	278	27.5	2.0
^	XS2	809	185	3.29	191	1,650	4.50	207	56.2	1.1
\	XS3	901	118	7.61	122	080,9	10.19	pu	15.6	pu
Yellow Creek near Davis	XS1	44.1	25.5	1.73	30.2	96.4	3.07	pu	14.7	pu
	XS2	21.9	20.3	1.08	21.3	pu	2.06	28	18.8	1.4
	XS3	61.0	31.0	1.97	33.4	pu	3.60	pu	15.8	pu
	XS4	25.1	24.2	1.04	27.8	69.3	2.82	29	23.3	1.2
	XS5	15.6	10.0	1.56	12.0	53.5	2.22	22	6.4	2.2

For additional information call or write to:

Director, U.S. Geological Survey

West Virginia Water Science Center

11 Dunbar Street, Charleston, WV 25301

(304) 347-5130

http://wv.usgs.gov

